PHASE I ENVIRONMENTAL SITE ASSESSMENT

Grim Hotel
301 North State Line Avenue
Texarkana, Texas 75501

Swift Creek Environmental, Inc.

Corporate Office: 8201 County Dr. - Disputanta, Virginia 23842-6144
Telephone: 804-721-6955
E-mail: swiftcreekinc@aol.com

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Grim Hotel
301 North State Line Avenue
Texarkana, Texas 75501
Latitude: 33°25’22.77"N
Longitude: 94°2'36.61"W

Prepared for:

Mr. Jay Johnson
Development Director - Texas
Cohen-Esrey Development Group, LLC
301 E Cevallos, Suite 318
San Antonio, Texas 78204
Cohen-Esrey Company
817.902.7430

Prepared by:

B. Thomas Houghton, Principal
Swift Creek Environmental, Incorporated
8201 County Drive
Disputanta, Virginia 23842
804.721.6955

SCE Project #18-063

September 18, 2018

Swift Creek Environmental, Inc.

8201 County Drive
Disputanta, Virginia 23842-6144
Phone: 804-721-6955
E-mail: swiftcreekinc@aol.com

September 18, 2018
Project #18-063

Mr. Jay Johnson
Development Director - Texas
Cohen-Esrey Development Group, LLC
301 E Cevallos, Suite 318
San Antonio, Texas 78204
Cohen-Esrey Company

RE: ***Phase I Environmental Site Assessment***
Grim Hotel
301 North State Line Avenue
Texarkana, Texas 75501

Dear Mr. Johnson:

Swift Creek Environmental, Incorporated has performed this *Phase I ESA (Environmental Site Assessment)* in conformance with the scope and limitations of 40 CFR. 312, ASTM (American Society for Testing Materials) E1527-13 and the AAI (All Appropriate Inquiry) Ruling for the Grim Hotel located at 301 North State Line Avenue in Texarkana, Texas, *the property*. Any deviations from this practice are described in Sections 2.3, 2.4, 2.5 and 9.0 of this report.

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in §312.10 of 40 CFR 312. I have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with standards and practices set forth in 40 CFR 312 § 312.10(b).

We are pleased to have had the opportunity to provide these services. Should you have any questions concerning the enclosed materials, please do not hesitate to contact me at 804.721.6955.

Sincerely,

B. Thomas Houghton

B. Thomas Houghton, Principal

TABLE OF CONTENTS

1.0 SUMMARY 5

2.0 INTRODUCTION 7
- 2.1 Purpose 7
- 2.2 Detailed Scope of Services 8
- 2.3 Significant Assumptions 8
- 2.4 Limitations and Exceptions 8
- 2.5 Special or Additional Conditions or Contract Terms 8
- 2.6 *User* Reliance/Certification 9
- 2.7 Qualifications 9

3.0 SITE DESCRIPTION 10
- 3.1 Location and Legal Description 10
- 3.2 Site and Vicinity General Characteristics 10
  - 3.2.1 Hydrogeology 10
  - 3.2.2 Geologic Setting 11
  - 3.2.3 Surface Drainage 11
  - 3.2.4 Wetlands 11
  - 3.2.5 Flood Plain 11
- 3.3 Current Use of the Property 11
- 3.4 Improvements to the Property 11
- 3.5 Current Uses of the Adjoining Properties 12

4.0 *USER* PROVIDED INFORMATION 13
- 4.1 Title Records 13
- 4.2 Environmental Liens or Activity and Use Limitations 13
- 4.3 Specialized Knowledge of the *User* 13
- 4.4 Commonly Known/Reasonably Ascertainable Information 13
- 4.5 Valuation Reduction for Environmental Issues 13
- 4.6 Reason for Performing the Phase I 13

5.0 RECORDS REVIEW 14
- 5.1 Standard Environmental Record Sources 14
  - 5.1.1 Sites Listed in Sec 8 ASTM E1527-13 14
  - 5.1.2 Orphan/Unmappable Sites 19
- 5.2 Additional Environmental Record Sources 19
  - 5.2.1 Local Brownfield Lists 19
  - 5.2.2 Local Lists of Landfill/Solid Waste Disposal Sites 19
  - 5.2.3 Local Lists of Hazardous Waste/Contaminated Sites 19
  - 5.2.4 Local Lists of Registered USTs 19
  - 5.2.5 Local Land Records 19
  - 5.2.6 Records of Emergency Release Reports 20
  - 5.2.7 City of Texarkana Community Development Department Records 20
  - 5.2.8 Local/Regional Pollution Control Agency Records 20
  - 5.2.9 Local/Regional Water Quality Agency Records 20
- 5.3 Historical Use Information on the Property 20
  - 5.3.1 Aerial Photographs and Topographic Maps 20
  - 5.3.2 Sanborn Maps 21
  - 5.3.3 City Directories 21
  - 5.3.4 Previous Environmental Studies 21
- 5.4 Historical Use Information on Adjoining Properties 22

6.0 SITE RECONNAISSANCE 23
6.1 Site Reconnaissance Methodology and Limiting Conditions 23
6.2 General Site Setting 23
6.3 Observations 23
6.3.1 Storage Tanks 23
6.3.1.1 Thermal and Explosive Hazards 23
6.3.2 Chemical and Hazardous Materials 23
6.3.3 Solid Waste 23
6.3.4 Sewage Disposal/Septic Tanks 24
6.3.5 Hydraulic Equipment 24
6.3.6 Contracted Maintenance 24
6.3.7 PCBs 24
6.3.8 Water Supply and Wells 24
6.3.9 Drains and Sumps 24
6.3.10 Pits, Ponds, Lagoons, Standing Water, Pools 24
6.3.11 Stressed Vegetation 24
6.3.12 Stains/Odors 24
6.3.13 Utilities 25
6.3.14 Endangered Species 25
6.3.15 Other 25

7.0 INTERVIEWS 26
7.1 Interview with Previous Owner 26
7.2 Interview with Owner/Site Manager/Tenants/*User* 26
7.3 Interviews with Local Government Officials 26

8.0 ADDITIONAL SERVICES 27
8.1 Radon 27
8.2 Lead Base Paint 27
8.3 Asbestos 28
8.4 Noise 28
8.5 Vapor Intrusion 28
8.6 Soil and Ground Water 29

9.0 DEVIATIONS 30
9.1 Identification of Data Gaps 30
9.2 Sources of Information Consulted to Address Data Gaps 30
9.3 Significance of Data Gaps 30

10.0 FINDINGS, OPINION AND CONCLUSIONS 31

11.0 REFERENCES 33

APPENDICES

Appendix A - EP Resume
Appendix B - Maps/Figures
Appendix C - Property Record Card/Tax Information
Appendix D - Site Photographs
Appendix E - Regulatory Data Search

LIST OF FIGURES

Figure 1 - Site Vicinity Map (2013 Topographic Map)
Figure 2 - Detailed Site Map
Figure 3 - NWI Map
Figure 4 - Flood Insurance Rate Map
Figure 5 - 1948 Aerial Photograph
Figure 6 - 1953 Aerial Photograph
Figure 7 - 1960 Aerial Photograph
Figure 8 - 1970 Aerial Photograph
Figure 9 - 1975 Aerial Photograph
Figure 10 - 1989 Aerial Photograph
Figure 11 - 1994 Aerial Photograph
Figure 12 - 2001 Aerial Photograph
Figure 13 - 2004 Aerial Photograph
Figure 14 - 2005 Aerial Photograph
Figure 15 - 2006 Aerial Photograph
Figure 16 - 2008 Aerial Photograph
Figure 17 - 2009 Aerial Photograph
Figure 18 - 2010 Aerial Photograph
Figure 19 - 2012 Aerial Photograph
Figure 20 - 1909 Topographic Map
Figure 21 - 1954 Topographic Map
Figure 22 - 1970 Topographic Map
Figure 23 - 1975 Topographic Map
Figure 24 - 1985 Topographic Map
Figure 25 - 2001 Topographic Map
Figure 26 - 1885 Sanborn Map
Figure 27 - 1888 Sanborn Map
Figure 28 - 1896 Sanborn Map
Figure 29 - 1900 Sanborn Map
Figure 30 - 1905 Sanborn Map
Figure 31 - 1909 Sanborn Map
Figure 32 - 1915 Sanborn Map
Figure 33 - 1924 Sanborn Map
Figure 34 - 1950 Sanborn Map
Figure 35 - 1951 Sanborn Map
Figure 36 - 1953 Sanborn Map
Figure 37 - 1963 Sanborn Map
Figure 38 - 1964 Sanborn Map
Figure 39 - 1969 Sanborn Map 1
Figure 40 - 1969 Sanborn Map 2

1.0 SUMMARY

On September 4, 2018 Swift Creek Environmental, Incorporated received authorization from Mr. Mr. Jay Johnson, Development Director – Texas for the Cohen-Esrey Development Group, LLC to complete a Phase I Environmental Site Assessment in accordance with requirements set forth in ASTM E1527-13 for the Grim Hotel located at 301 North State Line Avenue in Texarkana, Texas. The subject property is situated in a long established downtown setting of Texarkana, Texas, encompassing 80% of the block on which the building is situated. The subject property consists of 1-0.89 acre tax parcel containing one $^{+}/_{-}$135,000 ft^2, 8-story concrete reinforced; brick faced building with basement located on the southern portion of the subject property with the northern portion of the subject property containing concrete building pads associated with former structures and a vacant lot enclosed by chain-link fencing. The remaining portion of the city block contains a vacant; 3-story masonry constructed commercial building which is not part of the subject property.

The objectives of this ESA were to evaluate the potential for the presence of major environmental liabilities at the site and to document that "due diligence" was exercised in attempting to discover any such impairment. No ASTM Scope *RECs* (*Recognized Environmental Conditions)*, *HRECs* (*Historical Recognized Environmental Conditions), CRECs* (*Controlled Recognized Environmental Conditions)* or environmental *AULs* (*Activity Use Limitations)* were discovered or associated with the *property.*

ASTM Non-Scope Issues:

- Asbestos containing materials and LBP is present throughout the subject building and will require mitigation. A *Technical Specifications Asbestos and Lead Hazard Abatement Workplan* for the subject property detailing the methodologies to be employed to mitigate the asbestos have been completed by Texas licensed professionals. This *Workplan* should be implemented for the commencement of the planned abatement.

- Based on the age of the subject building, one uncategorized environmental concern may be the potential presence of Lead within the potable water lines. It is our understanding that all water lines are to be replaced during property redevelopment; thus eliminating this *REC*.

- No offensive odors (other than mildew odor) or significant staining was observed/noticed on the subject property with the exception of black mold on the debris and construction members. The mold would be mitigated during select building demolition and should not pose as an *REC* upon site redevelopment.

ASTM Scope Issues:

- According to the *Phase II ESA* Report prepared by Terracon dated, May 27, 2015, the subject property has been negatively affected by heavy metal impacts to surficial soil and ground water at concentrations exceeding TCEQ (Texas Commission of Environmental Quality) Action Levels. Mercury, Arsenic and Lead concentrations in soil and Lead concentrations in ground water exceeded the respective Action Levels. Action Level exceedances would subject the site to environmental cleanup requirements under TCEQ TRRP (Texas Risk Reduction Program) Rules; requiring the obtainment of a MSD (Municipal Site Designation) for the ground water and either remedial activities or engineering/institutional controls for the soil. Terracon's 2015 *Phase II ESA* Report states that the ground water samples collected were Turbid. High Turbidity frequently skews metal results in ground water in which adsorbed metal concentrations in the soil particulates do not accurately reflect "true" dissolved phase metal concentrations in the ground water. Since the results are based on one sampling event and the monitor wells have been abandoned; thus not allowing for the collection of subsequent sampling events, Swift Creek Environmental recommends that new monitor wells be installed and the ground water and soil be retested to verify the 2015 findings. On May 24, 2017 a *Designation (MSD) Workplan* was completed to address the specific ground water and soil issues at the subject property. Swift Creek Environmental, Incorporated

recommends that this *Workplan* be implemented in order to fulfill the potential outstanding soil and ground water at the subject property.

- An estimated 500 yd^3 of un-containerized scattered trash, debris, rubble and solid waste was observed throughout the interior of the subject building. The materials observed included, but were not limited to; fallen plaster, beds, bed frames, furniture, refrigerators, stoves, wood, paper, metal, glass and plastics. Also, minor amounts of pigeon guano and a select few pigeon carcasses were observed on the upper floors of the subject building. These materials should be handled and disposed of off-site consistent with applicable, local, state and federal regulations.

- Hydraulic dampers and reservoir tanks may be located at the bottom of the elevator shafts within the subject building. The bottoms of elevator shafts are presently inaccessible. Additional funding should be set aside to evaluate these shafts once they are accessible.

- The northern portion of the subject property contained a gasoline filling station, circa 1924 through 1951. The status of the gasoline tanks when the subject property operated as filling station could not be determined. This facility would predate any reporting requirements for the storage of gasoline. Based on the age when the subject property operated as a filing station it is highly probable that the gasoline tanks were small (<2,000 gallons) and situated aboveground. Based on the findings of Terracon's 2015 *Phase II ESA* completed at the subject property, it has been quantitatively demonstrated that petroleum compounds have not adversely affected the subject property. However, it cannot be ruled out that USTs (underground Storage Tanks) may still exist in the area of the subject property that once housed the filling station. Swift Creek Environmental, incorporated recommends that a GPR Survey be conducted in this area of the subject property to confirm the existence or absence of USTs

2.0 INTRODUCTION

The purpose of this practice is to define good commercial and customary practice in the United States of America for conducting an *environmental site assessment* for a parcel of commercial real estate with respect to the range of contaminants within the scope of *Comprehensive Environmental Response*. Comprehensive and Liability Act (CERCLA)(42 U.S.C§9601) and *petroleum products*. As such, this practice is intended to permit a *User* to satisfy one of the requirements to qualify for the *innocent landowner, contiguous property owner* or *bona fide prospective purchaser limitations on* CERCLA *liability* (hereinafter, the "*landowner liability protections*." or "LLPs"; that is, the practice that constitutes "all *appropriate inquiry* into the previous ownership and uses of the *property* consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35) (B). Controlled substances are not included within the scope of this standard. Persons conducting and *environmental site assessment* as part of the EPA (Environmental Protection Agency) Brownfield's Assessment and Characterization Grant awarded under CERCLA 42 U.S.C §9604 (k)(2)(B) must include controlled substances as defined in the Controlled Substances Act (21 U.S.C §802) within the scope of the assessment investigations to the extent directed In the terms and conditions of the specific grant or cooperative agreement. Additionally, an evaluation of *business environmental risk* associated with a parcel of *commercial real estate* may necessitate investigation beyond that identified in this practice.

Recognized Environmental Conditions - In defining a standard of good commercial and customary practice for conducting and *environmental site assessment* of a parcel of property, the goal of the processes established by this practice is to identify *recognized environmental conditions*. The term *recognized environmental conditions* means the presence or likely presence of *hazardous substances* or *petroleum products* in, on, or at a *property* conditions indicative of a release to the environment under conditions that pose a material threat of a future release to the environment. *De minimis* are not recognized *environmental conditions.*

Petroleum Products are included within the scope of this practice because they are a concern with respect to many parcels of *commercial real estate* and current custom and usage is to include an inquiry into the presence of *petroleum products* when doing and *environmental site assessment* of *commercial real estate*. Inclusion of *petroleum products* within the scope of this practice is not based upon the applicability, if any, of CERCLA to petroleum products.

CERCLA *Requirements Other Than Appropriate Inquiries* - This practice does not address whether requirements in addition to *all appropriate inquiries* have been met in order to qualify for the LLP's.

Other Federal, State, and Local Environmental Laws - This practice does not address requirements of any state or local laws or of any federal laws other than all state or local laws of any federal laws other than the all *appropriate inquiries* provisions of LLPs. *Users* are cautioned that federal, state and local laws may impose environmental assessment obligations that are beyond the scope of this practice. *Users* should also be aware that there are likely to be other legal obligations with regard to *hazardous substances* or *petroleum products* discovered on the property that are not addressed in this practice and that may pose risks of civil and/or criminal sanctions for non-compliance.

Documentation - The scope of this practice includes research and reporting requirements that support the user's ability to qualify for the LLPs. As such, sufficient documentation of all sources, records and resources utilized in conducting the inquiry required by this practice must be provided in the written report.

Objectives - Objectives guiding the development of this practice are (1) to synthesize and put in writing good commercial and customary practice of *environmental site assessments* for *commercial real estate*, (2) to facilitate high quality, standardized environments site assessments, (3) provide a practical and reasonable standard for conducting all appropriate inquiries and (4) to clarify an industry standard for all appropriate inquiries in an effort to guide legal interpretation of the LLPs.

2.2 Detailed Scope of Services

The objectives of this assessment are to provide information relating to the site's environmental integrity that may be useful to the client during real estate transactions and appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice. The Phase I Environmental Site Assessment was performed in accordance with the American Society for Testing and Materials (ASTM E1527-13) *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process and the Final All Appropriate Inquiries Standard* and is intended to demonstrate that the client has exercised due diligence in accordance with accepted industry practices and to identify potential environmental liabilities or areas for further investigation.

The tasks comprising this assessment were conducted as a screening to provide a reasonable level of investigation to identify recognized environmental conditions. The scope of this assessment included:

a. Completion of Phase I ESA in accordance with ASTM Standard E1527-13 and the AAI "All Appropriate Inquiries" Ruling.

2.3 Significant Assumptions

While this report provides an assessment of potential and recognized environmental concerns, both past and present, the environmental assessment is limited by the availability of information at the time of the assessment. It is possible that unreported disposal of waste or illegal activities at the subject site may have occurred which were not identified. The conclusions and recommendations regarding the environmental conditions that are presented in this report are based on the scope of work authorized by the client and the requirements of ASTM E1527-13 (7.5.2 and 7.5.2.1). Note, that virtually no scope of work, no matter how exhaustive, can identify all contaminants or all conditions above and below ground.

2.4 Limitations and Exceptions

This report was prepared as a result of a contractual agreement with the client that defined the approach and scope of services to be employed during the course of the investigation. The opinions and conclusions expressed in this study have been based strictly on the results of these contracted services. As per ASTM, Swift Creek Environmental, Incorporated as a recognized environmental professional consulting firm, has completed this study by addressing the recognized environmental conditions/concerns of the property as per ASTM standards E1527-13, and the AAI Ruling 40 CFR part 312. Swift Creek Environmental, Incorporated is not affiliated with the owner/developer/lessee/buyer or seller of the property.

Changes in the condition of the site may occur with time due to either natural processes or human activities. The findings presented in this report are based on site conditions existing at the time of the investigation. In addition, Swift Creek Environmental, Incorporated has relied, in part, on representations made to Swift Creek Environmental, Incorporated regarding conditions at the site or adjoining properties. Swift Creek Environmental, Incorporated cannot be responsible for any errors or omissions in this investigation resulting from incomplete or inaccurate disclosures by the individuals or agencies contacted. Furthermore, this report has been based only on information that became available over the study period.

2.5 Special or Additional Conditions or Contract Terms

Neither the environmental professional nor the *User* (as defined by ASTM E1527-13 section 6) are aware of any special or additional conditions or contract terms other than that the report would be prepared in accordance with ASTM Standards E1527-13 and the AAI "All Appropriate Inquiries" Ruling.

2.6 *User* Reliance/Certification

As per ASTM definition, the *User*, " Cohen-Esrey Development Group, LLC" located at 301 E Cevallos, Suite 318 in San Antonio, Texas as well as TDHCA (Texas Department of Housing and Community Affairs) and City of Texarkana has the right to rely upon this report prepared for the property. This is to permit the above referenced entities and assigns to use the contents of this report to assist in the evaluation of the property.

2.7 Qualifications

Mr. B. Thomas Houghton performed all portions of the ESA. Mr. Houghton has been conducting environmental investigations since 1985 and is a licensed professional geologist in the states of; Virginia, North Carolina, South Carolina, Florida and Tennessee. In addition, Mr. Houghton is an Army Corps of Engineers approved Wetland Delineator. Presented in Appendix A is Mr. Houghton's resume. Mr. Houghton is defined as the *EP (Environmental Professional)* for this project. Pursuant to section ASTM E1527-13 section 3.2.32 an EP is a person meeting the education, training and experience requirements as set forth in §312.10(b) of 40 CFR 312 and defined as follows:

> (1) a person who possesses sufficient specific education, training, and experience necessary to exercise professional judgment to develop opinions and conclusions regarding conditions indicative of releases or threatened releases (312.1(c)) on, at, in, or to a property, sufficient to meet the objectives and performance factors in 312.20(e) and (f).
>
> (2) Such a person must:
>
> > (i) Hold a current Professional Engineer's or Professional Geologist's license or registration from a state, tribe, or U.S. territory (or the Commonwealth of Puerto Rico) and have the equivalent of 3 years of full-time relevant experience; or (ii) Be licensed or certified by the federal government, a state, tribe, or U.S. territory (or the Commonwealth of Puerto Rico) to perform environmental inquiries as defined in 312.21 and have the equivalent of 3 years of full-time relevant experience or (iii) Have a Baccalaureate or higher degree from an accredited institution of higher education in a discipline of engineering or science and the equivalent of 5 years of full-time relevant experience or (iv) Have the equivalent of 10 years of full-time relevant experience.
>
> (3) An environmental professional should remain current in his or her field through participation in continuing education or other activities.
>
> (4) The definition of environmental professional provided above does not preempt state professional licensing or registration requirements such as those for a professional geologist, engineer, or site remediation professional. Before commencing work, a person should determine the applicability of state professional licensing or registration laws to the activities to be undertaken as part of the inquiry identified in 312.21(b).
>
> (5) A person who does not qualify as an environmental professional under the foregoing definition may assist in the conduct of all appropriate inquiries in accordance with this part if such person is under the supervision or responsible charge of a person meeting the definition of an environmental professional provided above when conducting such activities. Relevant experience, as used in the definition of environmental professional in this section, means: participation in the performance of all appropriate inquiries investigations, environmental site assessments, or other site investigations that may include environmental analyses, investigations and remediation which involve the understanding of surface and subsurface environmental conditions and the processes used to evaluate these conditions and for which professional judgment was used to develop opinions regarding conditions indicative of releases or threatened releases to the subject property.

3.0 SITE DESCRIPTION

3.1 Location and Legal Description

On September 4, 2018 Swift Creek Environmental, Incorporated received authorization from Mr. Mr. Jay Johnson, Development Director – Texas for the Cohen-Esrey Development Group, LLC to complete a Phase I Environmental Site Assessment in accordance with requirements set forth in ASTM E1527-13 for the Grim Hotel located at 301 North State Line Avenue in Texarkana, Texas. The location of the subject property is presented as Figure 1 - Site Vicinity Map in Appendix B. A Detailed Site Map is presented in Appendix B as Figure 2. The Bowie County Property Record Card and Tax Map are included in Appendix C.

The subject property is situated in a long established downtown setting of Texarkana, Texas, encompassing 80% of the block on which the building is situated. The subject property consists of 1-0.89 acre tax parcel containing one $^{+}/_{-}$135,000 ft^2, 8-story concrete reinforced; brick faced building with basement located on the southern portion of the subject property with the northern portion of the subject property containing concrete building pads associated with former structures and a vacant lot enclosed by chain-link fencing. The remaining portion of the city block contains a vacant; 3-story masonry constructed commercial building which is not part of the subject property.

The parcel descriptions are as follows:

301 North State Line Avenue – Parcel Account Number 03840008900
Legal Description: CITY/TRIGGS ADDN – Lots 7-12 Grim Hotel – BLK/TRACT 13
Owner: Rivergate Properties, LLC
Land Use: Central Business
Parcel Size: 0.89 Acres
Building Size: $^{+}/_{-}$135,000 ft^2
Year Built: circa 1925
Construction: 8-story concrete reinforced; brick faced with basement
Total Taxable/Appraised Value 2018: $55,600.00
Recorded Date and Deed, Book/Page: 12/14/1998 – 2972/9

3.2 Site and Vicinity General Characteristics

The subject site is situated within a long established downtown setting of Texarkana, Texas. The general topographic relief surrounding the subject site is flat sloping slightly to the south. The subject property encompasses approximately 80% of the city block, with West 4th Street and vacant 3-story building bordering the subject property to the north, North State Line Avenue to the east, West 3rd Street to the south and Pine Street to the west. A photographic representation of the subject property is included in Appendix D as Photographs #1 through #12.

3.2.1 Hydrogeology

According to the U.S. Geological Survey (USGS) *7.5-Minute Topographic Map of the Gastonia, North, North Carolina Quadrangle* (2013) and our site reconnaissance, the site is sloping gently to the south. The closest remaining natural water body is Nix Creek located in excess of 1,700 feet south from the subject property. The average elevation across the subject property is 315 feet above mean sea level. Based on a previously completed *Phase II ESA* by Terracon on May 27, 2015, the depth to the shallow water table aquifer was 12.19 feet to 13.97 feet BGS (Below Ground Surface) trending in a southwest direction. Ground water is not used as a potable drinking water source. The subject site and area surrounding the sites receive municipally supplied water from city sources.

3.2.2 Geologic Setting

The subject property is located within the Coastal Plain Physiographic Region of Texas. The site is underlain by the Paleocene deposits of the Wilcox and Midway Groups. The Wilcox consists of a thick series of non-marine sands, silty sands, clays and gravels with some thick deposits of lignite. The thickness of the Wilcox ranges from about 100 to 450 feet. The Wilcox is underlain by the Midway Group, which consists of calcareous shale, arenaceous limestone, calcareous glauconitic sandstone, conglomerate, and clay shale (*Arkansas State Water Plan - ASWCC, 1987*). The general soil lithology encountered during Terracon's execution of the *Phase II ESA* consisted of:

- 0 to 0.5 feet BGS - Asphalt and fill
- 0.5 feet to 8 feet BGS - Silty clay
- 8 feet bgs to 25 feet BGS - Silty fine-grained sand with some clay

3.2.3 Surface Drainage

Based on the site inspection, storm water runoff at the subject site is controlled primarily by sheet water flow being directed toward the adjacent city streets. The subject building's downspouts discharge into underground storm water pipes stands at the surface. These structures are presumably connected to the city's underground storm water management system.

3.2.4 Wetlands

Based upon our site reconnaissance and review of the NWI (National Wetland Inventory), no wetlands are present on the subject site. Presented as Figure 3 in Appendix B is the NWI Map.

3.2.5 Flood Plain

The subject site is situated in Zone X. Zone X is classified as being outside the 100 and 500 flood zone. Presented as Figure 4 in Appendix B is the Flood Insurance Rate Maps 480370C0370E and 05091C0120D.

3.3 Current Use of the Property

The subject property is currently vacant, in disrepair and uninhabitable. Vandalism of the subject building is an on-going issue.

3.4 Improvements to the Property

Improvements on the subject site include available utilities (water, sewer, gas, cable, telephone and electric), the subject buildings and surrounding pavement. Available utilities are located underground.

3.5 Current Uses of the Adjoining Properties

The location of the adjacent properties or nearby properties in relationship to the subject property is depicted on Figure 2 and on the provided aerial photographs. The adjoining/nearby properties are depicted on Photographs #13 through #18 in Appendix D. The adjacent/nearby properties surrounding the subject site consists of the following:

North: Vacant 3-story commercial building, West 4th Street with a church and parking lot located on the north side of West 4th Street

South: East 3rd Street with the Museum of Regional History, a parking lot and municipal parking garage located on the south side of East 3rd Street

East: North State Line Avenue with the Harrelson Building located on the east side of North State Line Avenue

West: Pine Street with vacant 2-story commercial buildings located on the east side of Pine Street

4.0 *USER* PROVIDED INFORMATION

4.1 Title Records

A chain of title was not provided by the *User* to Swift Creek Environmental, Incorporated for review. Swift Creek Environmental, Incorporated obtained title Information from the Bowie County Tax Appraisal Office and Courthouse. A chain of title was performed in order to determine if past ownership may indicate any past environmental concerns. Based on past ownership and usage and our review of the chain of title, no *HRECs* were identified. The chain of title researched by Swift Creek Environmental, Incorporated is as follows:

Grantee	Dates of Ownership	Deed Reference
Rivergate Property, LLC	1998 - Present	297279
Grim Hotel Company	1968-1998	131426
Mayor George T. Conway, et al	1956-1968	983179
William M. Rhoads Grim, Estate	1925-1956	PG143
Texas and Pacific Railroad	1922-1925	149735

4.2 Environmental Liens or Activity and Use Limitations

The interviewees and the environmental professional are not aware of nor discovered any environmental liens in connection with the subject site. Our research did not discover any environmental liens in connection with the subject property.

4.3 Specialized Knowledge of the *User*

The *User* is unaware of any specialized knowledge in connection with the subject property which was not previously ascertained during the completion of the past completed assessments for this property. As Brownfields Program Manager and Community Development Planner for the City of Texarkana, Ms. Daphne Ryan has made multiple visits to the subject property, reviewed previously completed the *Phase I ESA and Phase II ESA Reports* (prepared for the City of Texarkana) and has conducted extensive research on the property. Ms. Ryan has specialized knowledge of the subject property and as such and Ms. Ryan was interviewed for the completion of this report. The previously completed reports are and on file with the *User* and the City of Texarkana.

4.4 Commonly Known/Reasonably Ascertainable Information

Neither the *User* nor *EP* is aware of *Undisclosed Commonly Known/Reasonably Ascertainable Information* in connection with the subject property.

4.5 Valuation Reduction for Environmental Issues

Based on our inspection and the current assessed value, it is of our opinion that there is no valuation reduction for known or unknown environmental issues at the subject property. The subject property is currently assessed at $55,660.00

4.6 Reason for Performing the Phase I

It is our understanding this *Phase I ESA* was declared as a requirement for a potential property transaction.

5.0 RECORDS REVIEW

5.1 Standard Environmental Record Sources

In order to determine if any Superfund sites, hazardous waste generators or TCEQ/ADEQ (Arkansas Department of Environmental Quality)/EPA regulated establishments are present in the vicinity or if any hazardous materials spills have occurred nearby, Swift Creek Environmental, Incorporated reviewed several databases and lists compiled by the EPA, TCEQ and ADEQ (as per ASTM E1527-13 section 8.1 and 8.2), performed an area site reconnaissance and contacted various governmental agencies.

5.1.1 Sites Listed in Sec 8 ASTM 1527-13

Swift Creek Environmental, Incorporated reviewed databases with the required search distances which were provided by EDR, TCEQ, ADEQ and the EPA that included, but were not limited to:

Federal NPL site list
Federal Delisted NPL site list
Federal CERCLIS site list
Federal CERCLIS NFRAP site list
Federal CORRACTS facilities list
Federal RCRA non-CORRACTS TSD facilities list
Federal generators list
Federal institutional control/engineering control registries
Federal ERNS list
Federal Brownfields
State Ground Water Incidents and Spills
State and Tribal lists of hazardous waste sites identified for investigation or remediation
State and Tribal equivalent NPL
State and Tribal equivalent CERCLIS
State and Tribal landfill or solid waste sites
State and Tribal leaking storage tank sites
State and Tribal institutional control/engineering control registries
State and Tribal voluntary cleanup sites
State and Tribal Brownfield sites
FINDS list
TRI List
OSHA

The search of available records was obtained from EDR Incorporated of Shelton, Connecticut. A copy of this search is provided in Appendix E. The provided search report meets or exceeds the regulatory search requirements of ASTM E-1527-13. As presented in the regulatory file search and listed below, there are 52 environmentally regulated facility(s) and/or releases within ASTM search distances, including the subject property. Presented below is a listing of regulated facilities within ASTM search distances:

1. Subject Property – Brownfield Site – Under an EPA Grant, the City of Texarkana completed a *Phase I ESA, Phase II ESA* and *Phase I ESA Update* between August 25, 2014 and February 2, 2017. The findings contained within these reports concluded the following *RECs:*
    a) *Asbestos and Lead Base Paint throughout the Subject Building*
    b) *Elevated metal concentrations in the soil (Arsenic, Lead and Mercury) and ground water (Lead) above TQEQ Risk Reduction Standards*

c) *The potential for a vapor intrusion hazards, based on unknown and adjoining property uses and the REC identified below.*
d) *A UST data gap for the northern portion of the subject property*

The documented RECs are further addressed in appropriate sections of this report

2. Sears Building – 301 Pine Street – Brownfield Site – *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site - 110 feet south, southwest of subject site – considered downgradient

3. Eximius Parking Lot and Garage – 211-217 &219 West 3rd Street – Brownfield Site - *Phase I & II ESA* completed - Based on the findings, the subsurface soil was affected with metals, no MSD was required – 206 feet south, southwest of subject site – considered downgradient

4. Capital One Building – 100-104 West Broad Street – Brownfield Site – *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site – 329 feet south of subject site – considered downgradient

5. Helms Liquor Store – UST Site – petroleum USTs permanently closed, no reportable releases – 351 feet east of subject site – considered cross to downgradient

6. Kress Building – 116 West Broad Street – Brownfield Site – Asbestos documented within Building – Building has been demolished – 466 feet south of subject site – considered downgradient

7. Kline Bakers Building – 207 East Broad Street – Brownfield Site – *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 470 feet west, southwest of subject site – considered downgradient

8. Twin City Cab – 317 Main Street - UST Site – petroleum USTs permanently closed, no reportable releases – 478 feet west, southwest of subject site - considered downgradient

9. Main Street & Texas Boulevard Parking Lot – 200 to 330 Blocks Main Street - Brownfield Site – *Phase I ESA* completed - Reportedly, an unknown media was affected with contaminants - Due to the facility's downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject – 481 feet southwest of subject site – considered downgradient

10. Vacant Ruth Building – 120 West Broad Street - Brownfield Site – *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 491 feet south of subject site – considered downgradient

11. Garner Cleaners – 424 Main Street – Drycleaners Site – Active, registered drycleaning facility – 500 feet west, northwest of subject site – considered cross to downgradient

12. Mabel Bryan Morriss Building – 124 West Broad Street - Brownfield Site – *Phase I & II ESA* completed – Reportedly, media was affect by asbestos, lead contaminants, and other contaminants. Due to the facility's downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject site – 508 feet southwest of subject site – considered downgradient

13. Tex-Rep – 213 Main Street - Brownfield Site – *Phase I ESA* completed - Reportedly, an unknown media was affected with contaminants - Due to the facility's downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the

environmental integrity of the subject – 520 feet south, southwest of subject site – considered downgradient

14. Vacant Regency House – 110 East Broad Street - *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 527 feet southeast of subject site – considered downgradient

15. Curley's Dry Cleaners – 306 Wood Street – EDR Historic Drycleaners Site – Inactive dryleaning facility – 575 east, northeast of subject site – considered upgradient

16. Tekarkana Central Office – 507 Olive Street - UST Site – Active, 6,000 gallon emergency generator diesel UST – in compliance with TQEQ UST Regulations – no reportable releases – 478 petroleum USTs permanently closed, no reportable releases – 631 feet north of subject site – considered upgradient

17. Ritchie Grocery Store – 215 East Front Street – Brownfield Site - *Phase I & II ESA* completed - Reportedly, an unknown media was with contaminants - Due to the facility's downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 781 feet south, southeast of subject site – considered downgradient

18. Union Station – 100 West Front Street – Brownfield Site - *Phase I & II ESA* completed - Reportedly, asbestos was found and soils and ground water affected with metals, PAHs, PCBs, petroleum products and VOC contaminants found; other media affected building materials - Due to the facility's downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject - 840 feet south of subject site – considered downgradient

19. Tekarkana Uniform – 315 Texas Boulevard – UST/LPST (Leaking Petroleum Storage Tank) Site – petroleum USTs permanently closed – LPST case closed by TCEQ, no ground water impacts – 849 feet west, southwest of subject site - considered downgradient

20. Uptown Antiques – 221 Texas Boulevard - Brownfield Site – *Phase I ESA* completed - Reportedly, an unknown media was affected with contaminants - Due to the facility's downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject – 863 feet southwest of subject site – considered downgradient

21. Red River Army Depot – 100 Main Street – AST (Aboveground Storage Tank)/SWF-LF (State Waste Facility-Landfill) Site – Petroleum ASTs Active and in compliance with current TCEQ AST Regulations – SWF-LF, closed – permit revoked – 892 feet south of subject site - considered downgradient

22. East Funeral Home – 120 West 6th Street – UST Site – petroleum USTs permanently closed – no reportable releases – 845 feet north of subject site - considered upgradient

23. Sandefur Parking Lot – 202-222 Front Street - *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 950 feet south of subject site – considered downgradient

24. Vacant Lot – 301 West Broad Street - *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 977 feet south, southwest of subject site – considered downgradient

25. TRAHC Building/PJ Mathews – 410 West 3rd Street – UST/LPST (Leaking Petroleum Storage Tank) Site – petroleum USTs permanently closed – LPST case closed by TCEQ, no significant ground water impacts – 998 feet southwest of subject site - considered downgradient

26. Burch Motor – 501 Texas Boulevard – UST Site – petroleum USTs permanently closed – no reportable releases – 1006 feet west of subject site - considered downgradient

27. Wilson Motors – 801 North State Line Avenue – UST Site – petroleum USTs permanently closed – no reportable releases – 1014 feet north of subject site - considered upgradient

28. Union Pacific/Southern Pacific – 612 Main Street – THWS (Texas Hazardous Waste Site)/SQG (Small Quantity Generator) Site – SQG, no longer generates, no violations noted – THWS, no longer handles hazardous waste – 1025 feet northwest of subject site – considered cross to upgradient

29. Southwest Arkansas Community Punish – 506 Walnut Center – UST Site – petroleum USTs permanently closed – no reportable releases – 1067 feet north, northeast of subject site - considered upgradient

30. Tire City – 418 West 4th Street – UST Site – petroleum USTs permanently closed – no reportable releases – 1072 feet west, southwest of subject site - considered downgradient

31. Dang Good Used Cars - 410 West 7th Street – UST/LPST Site – petroleum USTs inactive closed – LPST case underwent a prerelease determination – 1122 feet northwest of subject site - considered cross to downgradient

32. Cal Williams Used Car Lot – 423 7th Street – UST Site – petroleum USTs permanently closed – no reportable releases – 1072 feet northwest of subject site - considered cross to downgradient

33. Robbins Toyota – 601 Texas Boulevard – UST Site – petroleum USTs permanently closed – no reportable releases – 1204 feet west, northwest of subject site - considered downgradient

34. Beals Service – 201 West 7th Street – UST/LPST Site – petroleum USTs permanently closed – LPST case closed by TCEQ, no significant ground water impacts – 998 feet southwest of subject site - considered downgradient

35. Swift Building – 410 East Broad Street - Brownfield Site – *Phase I ESA* completed - Reportedly, an unknown media was affected with contaminants - Due to the facility's cross to downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject – 1212 feet east of subject site – considered cross to downgradient

36. Montgomery Ward – 10 Oaklawn Shopping Center – LPST Site – LPST case closed by TCEQ, no significant ground water impacts – 1251 feet west, northwest of subject site - considered cross to downgradient

37. Griffin Shell – 404 West 7th Street – UST/LPST Site – petroleum USTs active and in compliance with TCEQ UST Regulations – LPST case closed by TCEQ – 998 feet southwest of subject site - considered downgradient

38. Union Pacific – Front Street – AST/LAST (Leaking Above Ground Storage Tank) Site – ASTs permanently closed – LAST case closed by ADEQ in 1993 – 1279 feet east, southeast of subject site – considered downgradient

39. AAA Auto and Truck Sales – 429 West 7th Street – UST Site – petroleum USTs permanently closed – no reportable releases – 1281 feet northwest of subject site - considered cross to downgradient

40. SWBT Tekarkana Toll Central – 429 Spruce Street – UST Site – petroleum USTs permanently closed – no reportable releases – 1289 feet west of subject site - considered downgradient

41. Quinns Nodel Cleaner 411 Hazel Street – SQG Site – No longer generates, no violations noted – 1293 feet northeast of subject site – considered upgradient

42. Union Supply Grocery – 418 East Broad Street – Brownfield Site - *Phase I & II ESA* completed - Reportedly, asbestos was found and soils and ground water affected with metals, PAHs, petroleum products and VOC contaminants found; other media affected building materials - Due to the facility's distance and downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject - 1301 feet east of subject site – considered downgradient

43. Modern Cleaners – 210 West 7th Street – Drycleaners Site – Active, registered drycleaning facility – Reportedly, PCE Tank closed – 1312 feet west, north of subject site – considered upgradient

44. Southern Pacific – 319 West Front Street – LPST Site – Site underwent ground water remediation – LPST case closed by TCEQ – 1340 feet south, southwest of subject site - considered downgradient

45. Antique Mall – 621 Texas Boulevard - *Phase I ESA* completed - Reportedly, small containers of chemical stored at facility (i.e. paints/varnishes) - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site - 1341 feet west, northwest of subject site – considered cross to downgradient

46. UPBR – East Broad Street - Brownfield Site – *Phase I ESA* completed - Reportedly, an unknown media was affected with contaminants - Due to the facility's cross to downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject – 1366 feet east of subject site – considered downgradient

47. Morrissey Property – East Broad Street - Brownfield Site – *Phase I ESA* completed - Reportedly, an unknown media was affected with contaminants - Due to the facility's cross to downgradient location to the subject site, the environmental concerns that exist for this site that would not jeopardize the environmental integrity of the subject – 1419 feet east of subject site – considered downgradient

48. 999 Station – 107 West 7th Street – LPST Site – Groundwater was not impacted – LPST case closed by TCEQ – 1432 feet north of subject site - considered upgradient

49. Robbins Vacant Lot – East Broad Street - Brownfield Site – *Phase I ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site - 1445 feet west of subject site – considered cross to downgradient

50. Jameson Building - 523 West 3rd Street - Brownfield Site – *Phase I & II ESA* completed - Based on the findings, no environmental concerns exist for this site that would jeopardize the environmental integrity of the subject site – 1553 feet southwest f subject site – considered downgradient

51. Texarkana Electric Light and Gas – Jefferson Road – MGP (Manufactured Gas Plant) Site – 1796 feet south, southwest of subject site – considered downgradient

52. EZ Mart – 424 East 7th Street - LPST Site – LPST case closed by ADEQ in 1997 – 2113 feet north, northeast of subject site - considered downgradient

Per ASTM, the term *REC* means the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. Based on the findings of the *Phase II ESA* completed at the subject property on by Terracon on May 8, 2015, the topographic setting and property usage of the above listed facilities, it is Swift Creek Environmental, Incorporated opinion that the off-site above referenced sites do not pose a realistic threat to the environmental integrity of the subject site.

5.1.2 Orphan/Unmappable Sites

The 3 orphan/unmappable facilities identified by EDR are not connected with the subject property.

5.2 Additional Environmental Record Sources

5.2.1 Local Brownfield Lists

The subject property is currently registered as a Brownfield Site as registered to the City of Texarkana under EPA Cooperative Agreement BF-00F19501-0. United States EPA Brownfield Grant funds were utilized for the completion of the original *Phase I and II ESAs* and associated update between 2014 and 2017. These reports documented known environmental issues with regards to the subject site. These reports are on-file with the *User* and the City of Texarkana. In addition there are several Brownfield sites within ASTM search distances which are managed under the auspices of the City of Texarkana. These facilities are listed in section 5.1.1 of this report.

5.2.2 Local Lists of Landfill/Solid Waste Disposal Sites

No landfills were identified within ASTM search distances.

5.2.3 Local Lists of Hazardous Waste/Contaminated Sites

According to the EDR report, Red River Army Depot landfill, located 892 feet south of the subject site was identified in the Texas Solid Waste Facilities/Landfill. Based on it's downgradient location in relationship to the subject property, it is Swift Creek Environmental, Incorporated opinion that this property does not pose a realistic threat to the environmental integrity of the subject site.

5.2.4 Local Lists of Registered USTs

The UST site list is maintained by the TCEQ and ADEQ. Only nearby sites situated north and northeast of the subject property represents a potential *REC* to the subject property. However, based on the findings of the *Phase II ESA* completed at the subject property by Terracon on May 8, 2015, it has been quantitatively demonstrated that petroleum compounds have not adversely affected the subject property. All of the known UST sites with ASTM search distances are addressed in section 5.1.1 of this report.

5.2.5 Local Land Records

No local lands records associated with potential environmental issues at the subject site were discovered.

5.2.6 Records of Emergency Release Reports

No listings of emergency environmental release reports for the subject property were discovered.

5.2.7 City of Texarkana Community Development Department Records

Ms. Daphne Ryan of the City of Texarkana supplied the following reports for our review as well as providing information with regards to other area Brownfield projects that are being overseen by the City of Texarkana.

Terracon *Phase I ESA Report*, August 25, 2014
Terracon *Phase II ESA Report*, May 8, 2015
Daniel B. Stephens and Associates, Incorporated *Phase I ESA Report*, February 21, 2017
HUD *Heros Forms and Associated Documents/Reports*
Brady Environmental *Technical Specifications Asbestos and Lead Hazard Abatement Report,* May 24, 2017
EviroPhase *Designation (MSD) Workplan,* May 24, 2017

5.2.8 Local/Regional Pollution Control Agency Records

No local pollution control records for the subject site were discovered.

5.2.9 Local/Regional Water Quality Agency Records

The EDR Report identified 125 water supply wells and 1 oil/gas well within a 1 mile radius of the subject property. The subject site is not permitted as having a permitted water supply well. Location of the off-site wells is depicted in the provided Regulatory Data Search Map in Appendix E.

5.3 Historical Use Information on the Property

Historical information indicates the subject property was first developed circa 1885 which was occupied by various dwellings, boarding houses and businesses. During the early 1900s, the subject property was utilized as a cotton yard with associated cotton storage operations. The Grim Hotel was constructed circa 1925 which operated until the early 1990s. Since that time the Grim Hotel became vacant and has deteriorated to it's present condition.

Between circa 1924 through 1951 the northern portion of the subject property was occupied by an automotive repair, filling station and battery storage facility with all structures on the northern portion of the subject property being subsequently demolished. The northern portion of subject property the site appears to have been vacant since at least 1969.

5.3.1 Aerial Photographs and Topographic Maps

Swift Creek Environmental, Incorporated reviewed aerial photographs of the subject property for the years 1948, 1953, 1960, 1970, 1975, 1989, 1994, 2001, 2004, 2005, 2006, 2008, 2009, 2010 and 2012. The photographs reveal no environmental concerns in connection with the subject property. The subject site land use through these decades is described in section 5.3 of this report. The subject footprint and layout of the Grim Hotel has remained relatively unchanged. The northern portion of the subject property last observable building is in the 1960 aerial photograph. Since at least 1970, the northern portion of the subject property has remained in it's current configuration. Due to the altitude in which the historical aerial photographs were taken, discernable details of the subject property are of poor quality. Included in Appendix B are the Aerial Photographs.

Historic topographic maps for the years 1909, 1954, 1970, 1975, 1985 and 2013 were reviewed. No environmental concerns were noted based on the topographic map review. Included in Appendix B are the historical topographic maps.

5.3.2 Sanborn Maps

Review of the Sanborn Maps yielded the following information:

1885 thru 1900: Various shops and boarding houses.
1905: The northern portion of the subject property is vacant. A cotton platform and shops are located on the southern portion of the subject site.
1909: The northern portion of the subject property is a cotton yard while the southern portion of the subject property appears to be occupied by a theatre.
1915: The north portion of the subject property is vacant while the south portion of the subject property appears to be occupied by a milk depot with public parking.
1924: An auto repair service station, battery station and filling station are located on the northern portion of the site subject site, while the southern portion of the subject property is a public park.
1951: An auto repair service station is located on the northern portion of the subject property while southern portion of the subject property contains the Grim Hotel and associated shops.
1969: The northern portion of the subject property is vacant while the southern portion of the subject property contains the Grim Hotel.

The status of the gasoline tanks when the subject property operated as filling station could not be determined. This facility would predate any reporting requirements for the storage of gasoline. Based on the age when the subject property operated as a filing station it is highly probable that the gasoline yanks were small (<2,000 gallons) and situated aboveground. Again, based the findings of the *Phase II ESA* completed at the subject property by Terracon on May 8, 2015, it has been quantitatively demonstrated that petroleum compounds have not adversely affected the subject property. However, it cannot be ruled out that USTs may still exist in the area of the subject property that once housed the filling station.

5.3.3 City Directories

City directory abstract reports were reviewed in order to determine past usage of the subject property. The 1937 Worley's City Directory is the first record to display the Grim Hotel. From the directories, it appears that during its duration, the Grim Hotel building housed multiple businesses (i.e. barber shop, drug store, cigar store). These types of business operations do not indicate a potential *REC.* However, site historical use indicates the northern portion of the subject property e was occupied by an automotive repair, filling station and battery storage operations between circa 1924 through 1951, but there were no directories identifying their existence.

5.3.4 Previous Environmental Studies

Previously completed environmental studies or reports for the subject property are listed in section 5.2.7 of this report. Swift Creek Environmental, Incorporated utilized all of these documents for the completion of this report.

5.4 Historical Use Information on Adjoining Properties

Historical land use surrounding the subject property is documented in sections 5.3.1, 5.3.2, 5.3.3 and Appendix B of this report. The historical use of adjoining properties was evaluated relying on the Sanborn Maps. No off-site *RECs* were identified. Our findings revealed the following information:

North: 1885 thru 1969 - 4th Street with various offices dwellings and a church located on north side of 4th Street

East: 1885 thru 1969 - State Line Avenue with various offices and shops located on east side of State Line Avenue

South: 1885 thru 1969 – 3rd Street, Pine Street and State Line Avenue with various offices and shops located on south side of 3rd Street, Pine Street and State Line Avenue

West: 1885 thru 1900 - Pine Street with various dwellings and a livestock business located on west side of Pine Street

1905 thru 1915 - Pine Street with a vacant lot and dwellings located on west side of Pine Street

1924 - Pine Street with an auto sales facility, a dwelling and public parking located on west side of Pine Street

1951 thru 1969 - Pine Street with an auto sales facility Texarkana Gazette and various stores located on west side of Pine Street

6.0 SITE RECONNAISSANCE

6.1 Site Reconnaissance Methodology and Limiting Conditions

Site reconnaissance methodology was adhered to following ASTM E1527-13 Section 9.0. Specifically, the methodology entailed sectionalizing the properties into a systematic grid and traversing the properties along these grids. The on and off-site reconnaissance was conducted on September 6, 2018. Photographs depicted in Appendix D were collected on this date.

As per ASTM E1527-13 section 9.4, the uses and conditions specified in ASTM E1527-13 section 9.4.4.1 through 9.4.4.7 were noted to the extent visually and/or physically observed during the site visits and the records review process. These were also the subject of questions as part of the interviews conducted. No limiting conditions were encountered other than the ability to inspect the bottom of the elevator shafts. The elevators are inoperable and access to the bottom of the elevator shafts could not be accomplished.

6.2 General Site Setting

The subject property is situated in a long established downtown, commercial/retail/residential use setting of Texarkana, Texas. According to the 2010 population census, the population of Texarkana, Texas was 36,411.

6.3 Observations

6.3.1 Storage Tanks

There was no visual or ancillary evidence to suggest that USTs are or were ever located on the subject site other than the possibility of the gasoline tanks when the subject property operated as filling station between circa 1924 and 1951. The status of the gasoline tanks could not be determined. This facility would predate any reporting requirements for the storage of gasoline. Based on the age when the subject property operated as a filing station it is highly probable that the gasoline tanks were small (<2,000 gallons) and situated aboveground.

The one AST located in the basement of the subject building is a water tank associated with the subject buildings former hot water boiler system.

6.3.1.1 Thermal and Explosive Hazards

No large petroleum ASTs were observed within close proximity of the subject site that would be considered a thermal or overblast hazard.

6.3.2 Chemical and Hazardous Materials

No containers of chemicals or hazardous materials were identified in the subject building other than small containers of various paints and varnishes and a few (20 to 30 gallon size) drums (Photographs #19 and #20) of what appears to be associated with the subject buildings former boiler system (boiler treatment). The select few drums observed within the basement of the subject building appeared to be empty.

6.3.3 Solid Waste

An estimated 500 yd^3 of un-containerized scattered trash, debris, rubble and solid waste was observed throughout the interior of the subject building (Photographs #21 through #25). The materials observed included, but were not limited to; fallen plaster, beds, bed frames, furniture, refrigerators, stoves, wood, paper, metal, glass and plastics. Currently there are no contracted services for solid waste removal at the subject property. The exterior ground surface of the subject

property appeared neat and orderly with no scattered or un-containerized solid waste.

6.3.4 Sewage Disposal/Septic Tanks

There was no evidence to suggest that any septic systems or OWS (Oil Water Separator)/grease traps are located on the subject site. The subject property is connected to the municipality's sewer system.

6.3.5 Hydraulic Equipment

Hydraulic dampers and reservoir tanks may be located at the bottom of the elevator shafts. The bottoms of elevator shafts are presently inaccessible. Additional funding should be set aside to evaluate these shafts once they are accessible. No other potential hydraulic equipment was observed on the subject property.

6.3.6 Contracted Maintenance

There is no contracted building maintenance currently being performed at the subject property.

6.3.7 PCBs

No potential PCB containing electrical equipment was observed on the subject property other than the potential for PCBs contained within the subject building's fluorescent lighting ballasts (Photograph #26). During building rehabilitation any ballast not containing the UL (Underwriters Laboratory) stamp affixed to the ballasts, should be assumed as PCB containing an disposed of in accordance with applicable local, state and federal regulations. The transformer casings observed to be located in the basement of the subject building appeared to have been decommissioned. .

6.3.8 Water Supply and Wells

No water supply or gas wells were identified on the subject property.

6.3.9 Drains and Sumps

Other than drains associated with sinks and toilets; no sumps/drains identified on or in the subject property. Small sumps may exist in the basement area of the subject building, but due to poor lighting and the amounts of scattered debris; none were observed.

6.3.10 Pits, Ponds, Lagoons, Standing Water, Pools

No pits, ponds, lagoons or standing water/pools were observed on the subject property.

6.3.11 Stressed Vegetation

The limited vegetation (parking lot grass area) on the subject property appeared healthy with no visible signs of stress.

6.3.12 Stains/Odors

No offensive odors (other than mildew odor) or significant staining was observed/noticed on the subject property with the exception of black mold on the debris and construction members. The mold would be mitigated during select building demolition and should not pose as an *REC* upon site redevelopment.

6.3.13 Utilities

Available utilities include:

a. Electricity
b. Telephone/cable
c. Sewer/Storm water
d. Municipal water
e. Natural gas

6.3.14 Endangered Species

Endangered species preservation is not considered a concern since the subject site is located within the city limits of Texarkana, North Carolina.

6.3.15 Other

Based on the age of the subject building, one uncategorized environmental concern may be the potential presence of Lead within the potable water lines. Minor amounts of pigeon guano and a select few pigeon carcasses were observed on the upper floors of the subject building.

7.0 INTERVIEWS

7.1 Interview with Previous Owner

The whereabouts of the former property owners could not be ascertained.

7.2 Interview with Owner/Site Manager/Tenants/*USER*

In speaking with the current owner in 2016, Mr. Harrell was unaware of any environmental concerns associated with the subject property other than those items addressed in Terracon's *Phase I and II ESA Reports*.

7.3 Interviews with Local Government Officials

Besides the agencies identified in section 4.3 and 5.0 of this report, the following agencies were contacted via in person regarding potential environmental issues relating to the subject site.

a. City of Texarkana Fire Department
b. Bowie County Health Department

Neither department listed above had any environmental reports relating to the subject property.

8.0 ADDITIONAL SERVICES

8.1 Radon

No radiological materials were observed on the subject site. A quantitative Radon assessment was beyond the scope of services and therefore not conducted. Radon is unlikely to be present. Published literature from the EPA concludes that for 4 sites tested in Bowie County, 0% of the facilities had readings exceeding the 4pCi/L safe indoor standard with an average Radon concentration of 0.5 pCi/L and a maximum Radon concentration of 1.8 pCi/L. The EPA has placed Bowie County in Zone 3 for Radon Potential (Zone 3 - Low Radon Potential).

8.2 Lead Base Paint

A quantitative LBP assessment was beyond the scope of services and therefore not conducted. A quantitative LBP survey was conducted for completion of Terracon's 2015 *Phase II ESA Report*. There have been no significant changes to the subject property to invalidate these findings. With regards to the LBP issues at the subject property, Terracon concluded:

"The analytical results indicate that five of the seven paint samples are considered lead based paint, including the following:

- Pink paint in lobby entrance
- Brown paint in lobby entrance and trim throughout hotel
- Green paint in south store rooms on first floor
- Blue in north portion of lobby
- White paint on plaster walls throughout hotel

These five samples contained lead at concentrations greater than 5,000 ppm. The remaining two samples contained lead concentrations below the 5,000 ppm standard for lead-based paint, but are considered lead-containing paint. Therefore, if these materials are to be disturbed during the proposed renovation project, the following procedures should be implemented:

1. Care must be taken by the contractor to not exceed the OSHA established Action Level of 30 ug/m^3 during the renovation process that may impact the lead-containing painted materials. Detection of these levels can be accomplished by personal air monitoring. Continual wetting of the construction materials should be performed during any demolition activities and material clean-up process.

2. In addition, representative samples of lead-based waste generated during renovation activities should be tested to determine if the waste is hazardous. Waste will be considered hazardous if it contains leachable lead at concentrations greater than 5.0 mg/l, or at lower concentrations as provided by applicable federal, state, or local regulations. Waste sampling and disposal shall be conducted in accordance with applicable federal, state, and local regulations."

In order to further evaluate LBP at the subject property and formulate a mitigation strategy, on May 24, 2017 Brady Environmental prepared a *Technical Specifications Asbestos and Lead Hazard Abatement Workplan* for the subject property detailing the methodologies to be employed to mitigate the LBP. This report as well as Terracon's 2015 *LBP Survey Report* is on-file with the *User* and the City of Texarkana.

8.3 Asbestos

A quantitative asbestos survey was beyond the scope of services and therefore not conducted. Based on visual observations friable and non-friable asbestos containing materials are present throughout the subject building and in many locations have and comingle with the solid waste that is scattered throughout the building (Photographs #27 through #xxx).

A quantitative asbestos survey was conducted for completion of Terracon's 2015 Phase *II ESA Report* (Asbestos Survey subcontracted by Terracon to HEC Environmental Group, LLC). There have been no significant changes to the subject property to invalidate these findings. With regards to the asbestos issues at the subject property, HEC concluded and recommended:

"That the entire Hotel Grim complex be considered asbestos contaminated for demolition and asbestos abatement purposes due to the observed loose or deteriorated ACTSI debris inside pipe chases, inside crawlspaces, inside the exposed hotel room walls, along exposed corridors throughout the building interior, and ACTSI loose debris laying on corridor floors where "tracking" has occurred. Plaster walls and ceilings must be demolished to properly gain access to the vertical pipe chases and crawlspaces."

"That before any demolition or renovation operation can be performed, all contaminated materials must be removed from facility by Texas Department State Health Services licensed asbestos personnel in accordance with the current version of Texas Asbestos Health Protection Rules. This includes a site specific project design specifications be developed addressing the project management responsibilities, asbestos abatement protocols, air monitoring protocols, along with the transportation and disposal of all contaminated waste materials. That during any demolition or renovation, any suspect asbestos containing material not previously identified is observed, the operation is halted and that material sampled or it must be presumed to be asbestos containing material and proper procedures are followed to abate this material."

In order to further evaluate asbestos containing materials at the subject property and formulate a mitigation strategy, on May 24, 2017 Brady Environmental prepared a *Technical Specifications Asbestos and Lead Hazard Abatement Workplan* for the subject property detailing the methodologies to be employed to mitigate the asbestos. This report as well as HEC's 2015 Asbestos S*urvey Report* is on-file with the *User* and the City of Texarkana.

8.4 Noise

A quantitative NAS (Noise Assessment Survey) survey was beyond the scope of services and therefore not conducted. A Noise Exposure Assessment following HUD Nosie Assessment Guidelines for the subject property was completed by ERI Consulting, Incorporated in May, 2017. There have been no significant changes to the subject property to invalidate these findings. Results of this assessment documented a DNL of 62.7 db; below the HUD residential threshold of 65 db. This report is on-file with the *User* and the City of Texarkana.

Since noise levels at the subject property do not exceed HUD requirements, no further actions should be required.

8.5 Vapor Intrusion

A quantitative vapor intrusion survey was beyond the scope of services and therefore not conducted. Based the findings of the *Phase II ESA* completed at the subject property by Terracon on May 8, 2015, it has been quantitatively demonstrated that volatile organic compounds have not adversely affected the subject property. The *Phase II ESA* documented no volatile organic compounds either in the soil or water above the laboratory's MDL (Method Detection Limits).

8.6 Soil and Ground Water

According to the *Phase II ESA* Report prepared by Terracon dated, May 27, 2015, the subject property has been negatively affected by heavy metal impacts to surficial soil and ground water at concentrations exceeding TCEQ Action Levels. Mercury, Arsenic and Lead concentrations in soil and Lead concentrations in ground water exceeded the respective Action Levels. Action Level exceedances would subject the site to environmental cleanup requirements under TCEQ TRRP Rules; requiring the obtainment of a MSD for the ground water and either remedial activities or engineering/institutional controls for the soil. Terracon's 2015 *Phase II ESA* Report states that the ground water samples collected were Turbid. High Turbidity frequently skews metal results in ground water in which adsorbed metal concentrations in the soil particulates do not accurately reflect "true" dissolved phase metal concentrations in the ground water.

On May 24, 2017 a *Designation (MSD) Workplan* was completed for the subject property by Envirophase to in order to fulfill potential regulatory requirements regarding the soil and ground water at the subject site. This report is on-file with the *User* and the City of Texarkana.

9.0 DEVIATIONS

9.1 Identification of Data Gaps

As per ASTM E1527-13 section 3.2.20, a data gap is defined as a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. No data gaps were encountered during this investigation other than being able to access the elevator shafts.

9.2 Sources of Information Consulted to Address Data Gaps

No additional sources could be obtained to evaluate the elevator shafts.

9.3 Significance of Data Gaps

This data gap would be considered significant. Hydraulic dampers and reservoir tanks may be located at the bottom of the elevator shafts. The bottoms of elevator shafts are presently inaccessible. Additional funding should be set aside to evaluate these shafts once they are accessible.

10.0 FINDINGS, OPINION AND CONCLUSIONS

We have performed a *Phase I Environmental Site Assessment* in conformance with the scope and limitations of ASTM Practice E1527-13 for the Grim Hotel located at 310 State Line Avenue in Texarkana, Texas. Any exceptions to, or deletions from, this practice are described in Sections 2.3, 2.4, 2.5 and 9.0 of this *report*. This assessment has revealed no evidence of *ASTM Scope/Non Scope RECs*, *HRECs, CRECs* or environmental *AULs* in connection with the *property* with exception to:

ASTM Non-Scope Issues:

- Asbestos containing materials and LBP is present throughout the subject building and will require mitigation. A *Technical Specifications Asbestos and Lead Hazard Abatement Workplan* for the subject property detailing the methodologies to be employed to mitigate the asbestos have been completed by Texas licensed professionals. This *Workplan* should be implemented for the commencement of the planned abatement.

- Based on the age of the subject building, one uncategorized environmental concern may be the potential presence of Lead within the potable water lines. It is our understanding that all water lines are to be replaced during property redevelopment; thus eliminating this *REC*.

- No offensive odors (other than mildew odor) or significant staining was observed/noticed on the subject property with the exception of black mold on the debris and construction members. The mold would be mitigated during select building demolition and should not pose as an *REC* upon site redevelopment.

ASTM Scope Issues:

- According to the *Phase II ESA* Report prepared by Terracon dated, May 27, 2015, the subject property has been negatively affected by heavy metal impacts to surficial soil and ground water at concentrations exceeding TCEQ (Texas Commission of Environmental Quality) Action Levels. Mercury, Arsenic and Lead concentrations in soil and Lead concentrations in ground water exceeded the respective Action Levels. Action Level exceedances would subject the site to environmental cleanup requirements under TCEQ TRRP (Texas Risk Reduction Program) Rules; requiring the obtainment of a MSD (Municipal Site Designation) for the ground water and either remedial activities or engineering/institutional controls for the soil. Terracon's 2015 *Phase II ESA* Report states that the ground water samples collected were Turbid. High Turbidity frequently skews metal results in ground water in which adsorbed metal concentrations in the soil particulates do not accurately reflect "true" dissolved phase metal concentrations in the ground water. Since the results are based on one sampling event and the monitor wells have been abandoned; thus not allowing for the collection of subsequent sampling events, Swift Creek Environmental recommends that new monitor wells be installed and the ground water and soil be retested to verify the 2015 findings. On May 24, 2017 a *Designation (MSD) Workplan* was completed to address the specific ground water and soil issues at the subject property. Swift Creek Environmental, Incorporated recommends that this *Workplan* be implemented in order to fulfill the potential outstanding soil and ground water at the subject property.

- An estimated 500 yd^3 of un-containerized scattered trash, debris, rubble and solid waste was observed throughout the interior of the subject building. The materials observed included, but were not limited to; fallen plaster, beds, bed frames, furniture, refrigerators, stoves, wood, paper, metal, glass and plastics. Also, minor amounts of pigeon guano and a select few pigeon carcasses were observed on the upper floors of the subject building. These materials should be handled and disposed of off-site consistent with applicable, local, state and federal regulations.

- Hydraulic dampers and reservoir tanks may be located at the bottom of the elevator shafts within the subject building. The bottoms of elevator shafts are presently inaccessible. Additional funding should be set aside to evaluate these shafts once they are accessible.

- The northern portion of the subject property contained a gasoline filling station, circa 1924 through 1951. The status of the gasoline tanks when the subject property operated as filling station could not be determined. This facility would predate any reporting requirements for the storage of gasoline. Based on the age when the subject property operated as a filing station it is highly probable that the gasoline tanks were small (<2,000 gallons) and situated aboveground. Based on the findings of Terracon's 2015 *Phase II ESA* completed at the subject property, it has been quantitatively demonstrated that petroleum compounds have not adversely affected the subject property. However, it cannot be ruled out that USTs (underground Storage Tanks) may still exist in the area of the subject property that once housed the filling station. Swift Creek Environmental, incorporated recommends that a GPR Survey be conducted in this area of the subject property to confirm the existence or absence of USTs

11.0 REFERENCES

- ASTM E1527-13.
- City of Texarkana/Bowie County, Planning, Fire, Health, Tax Office and Courthouse. *Tax Maps and Deeds*, Interviews.
- Soil Conservation Service SCS data.
- Texas Geological Survey.
- TCEQ and ADEQ.
- EDR, Inc. *Information Search Results-Radius Map*.
- Federal Emergency Management Agency (FEMA).
- U.S. Department of the Interior, Geological Survey. 7.5-Minute Topographic Maps of the Texarkana, Texas Quadrangles.
- Geologic Map of Texas, 1985.
- National Wetland Inventory Maps.
- Aerial Photographs.
- City Directory & National Register of Historic Places.
- EPA Hazardous Waste Sites, *A Methods Manual - Volume II (PB85-168771).*
- EPA Texas Radon Map.
- Merck Index, Eleventh Edition.
- USGS Ground Water Atlas.
- HUD NAS Notebook/Guidelines.
- Ms. Daphne Ryan.
- Mr. Jim Sari.
- NWI.
- Mr. Harrell.
- Mr. Jay Johnson.
- Terracon *Phase I ESA Report*, August 25, 2014.
- Terracon *Phase II ESA Report*, May 8, 2015.
- Daniel B. Stephens and Associates, Incorporated *Phase I ESA Report*, February 21, 2017.
- HUD *Heros Forms and Associated Documents/Reports for Grim Hotel.*
- Brady Environmental *Technical Specifications Asbestos and Lead Hazard Abatement Report,* May 24, 2017.
- EviroPhase *Designation (MSD) Workplan,* May 24, 2017

APPENDIX A

EP Resume

B. THOMAS HOUGHTON, PG

CURRENT POSITION

Swift Creek Environmental, Inc.
President
1994-Present

PROJECT EXPERIENCE/RESPONSIBILITIES

Manages proposal preparation, budgeting, cost analysis, business development, corporate planning, scheduling, field work, data analysis, report writing, ground water modeling and remediation design. Specific field experience includes: Delineation and remediation of pesticide/herbicides contaminates incorporated in surface and subsurface soils; Containerization and remediation of sodium hydroxide and MEK spills; Burial recovery and disposal of drums containing low grade radioactive materials, PCB oil's, diesel fuels, motor oils, and volatile organic solvents; Evaluation of potential risks and damage to the surrounding environment resulting from methane gas migration at landfills; Nutrient management and groundwater/soil leachability studies for sanitary, agricultural and industrial lagoons; Coal mine delineations; Water resource investigations; Characterization, removal and disposal of hazardous sludges; Delineation of a 2,000,000 gallon gasoline subsurface spill at an AST facility; Delineation of carcinogenic materials spilled at airline crash sites; Soil and ground water remediation of heavy metal contamination at RCRA facilities; Permanent closure of USTs; Assessments and clean-ups of LUST sites; Phase I and Phase II Site Assessments; Lead Brownfields Contractor ; State VRP and HSI Site Investigations and Clean-ups, Compliance Audits; Well Point Designs, Wetland delineations, designs and constructions; Hydrogeologic modeling for potential potable water usage, Municipal water supply studies; Contaminant transport modeling, Hurricane Isabel and Gloria Environmental Disaster Relief for the Virginia Department of Environmental Quality, Virginia State Lead LUST Contractor 1999-2004; Wildlife Studies, Macroinvertebrate Identification and Studies; Stream Quality Studies, Storm Water Compliance Studies, Sound Studies, HOME/HUD Lead Environmental Investigator.

PREVIOUS EMPLOYMENT

GES Environmental Services, Inc.
Richmond, Virginia
Senior Project Manager
1990 - 1994

Soil Mechanics Environmental Services
Seaford, New York
Geologist/Project Manager
1985 - 1990

EDUCATION

State University of New York at Oswego
Oswego, New York - B.S. Geology 1985

PROFESSIONAL DEVELOPMENT

SC Geological Symposium
Clemson, SC April 2018

Sustainable Ground Water
Las Vegas, Nevada, 2006, 2008

NGWA Expo
Las Vegas, Nevada, 2004, 2006, 2008, 2010, 2011, 2012, 2014, 2016

Virginia Brownfields
Harrisonburg, Virginia 2011

Water Resources
Las Vegas, Nevada 2010

Geochemistry of Ground Water
Las Vegas, Nevada, 2004

Focus Conference on Eastern Ground Water Issues
Burlington, Vermont, 1993

Focus Conference on Eastern Ground Water Issues
Boston Mass., 1992

Overview of the Federal, State and Local Regulatory Programs Governing Storage Facilities
Uniondale, New York, June 1990

Ground Water Aspects of Tanks and Spills
West Chester, Pennsylvania, March 1990

Speaker: American Tire Association, Virginia Landmark, and Bower Nelms, 1994-1998
Aspects of USTs and ASTs - PHASE I Environmental Aspects - Risks To Human Health 1994, 996, 1998

CERTIFICATIONS

Certified Professional Geologist, No. 2542, Tennessee, 1992
Certified Professional Geologist, No. 950, Virginia, 1993
Certified Professional Geologist, No. 1291, North Carolina, 1994
Certified Professional Geologist, No. 2029, Florida, 1998
Certified Professional Geologist, No. 2343, South Carolina, 2003
Eight Hour OSHA Health and Safety Refresher Training (29 CFR 1910.120), 1990-2017
Forty Hour OSHA Health and Safety Training Course (29 CFR 1910.120), 1987
Army Corps of Engineers Certified Wetland Delineator, 1999
HUD Environmental Training Certification, 2009

APPENDIX B

Maps/Figures



NOT TO SCALE

Swift Creek Environmental, Inc

FIGURE 1 – SITE VICINITY MAP

USGS TEXARKANA, TEXAS QUADRANGLE MAP - 2013

CLIENT:	PROJECT NO.:
Cohen-Esrey Development	18-063
SITE: 301 North State Line Avenue Texarkana, Texas	DATE: 09/2018



Swift Creek Environmental, Inc.

8201 County Drive, Disputanta, VA 23842-6144

FIGURE NO: 2	
FIGURE NAME: DETAILED SITE MAP	
CLIENT: COHEN-ESREY	JOB NO: 18-063
SITE: GRIM HOTEL 301 N. STATE LINE AVE	DATE: 09/18

U.S. Fish and Wildlife Service
National Wetlands Inventory

Figure 3 - NWI Map

September 17, 2018

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

National Flood Hazard Layer FIRMette

FEMA

FIGURE 4 - FIRM

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 / 17.5 Cross Sections with 1% Annual Chance / Water Surface Elevation
- Coastal Transect
- 513 Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 9/17/2018 at 11:21:43 AM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

INQUIRY #: 4008707.5
YEAR: 1948
= 500'
N
EDR

INQUIRY #: 4008707.5
YEAR: 1953
= 500'
N
EDR

INQUIRY #: 4008707.5

YEAR: 1960

= 500'

N

EDR

INQUIRY #: 4008707.5
YEAR: 1970
= 500'
N
EDR

INQUIRY #: 4008707.5
YEAR: 1979
= 500'
N
EDR



INQUIRY #: 4008707.5

YEAR: 1989

= 500'

N

EDR

INQUIRY #: 4008707.5
YEAR: 1994
= 500'
N
EDR

INQUIRY #: 4008707.5
YEAR: 2001
= 500'
N
EDR

INQUIRY #: 4008707.5

YEAR: 2004

= 500'

N

EDR

INQUIRY #: 4008707.5
YEAR: 2008
= 500'
N
EDR


INQUIRY #: 4008707.5
YEAR: 2012
= 500'
N
EDR



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Texarkana, 1909, 15-minute

SITE NAME: Grim Hotel
ADDRESS: 301 North Stateline Avenue
Texarkana, TX 75501
CLIENT: Daniel B. Stephens

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Texarkana, 1954, 7.5-minute

SITE NAME: Grim Hotel
ADDRESS: 301 North Stateline Avenue
Texarkana, TX 75501
CLIENT: Daniel B. Stephens

N

Historical Topo Map

1970



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Texarkana, 1970, 7.5-minute

SITE NAME: Grim Hotel
ADDRESS: 301 North Stateline Avenue
Texarkana, TX 75501
CLIENT: Daniel B. Stephens

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Texarkana, 1975, 7.5-minute

SITE NAME: Grim Hotel
ADDRESS: 301 North Stateline Avenue
Texarkana, TX 75501
CLIENT: Daniel B. Stephens

N

Historical Topo Map

1985



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, TEXARKANA, 1985, 15-minute

SITE NAME: Grim Hotel
ADDRESS: 301 North Stateline Avenue
Texarkana, TX 75501
CLIENT: Daniel B. Stephens

N

Historical Topo Map

2001



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Texarkana, 2001, 7.5-minute

SITE NAME: Grim Hotel
ADDRESS: 301 North Stateline Avenue
Texarkana, TX 75501
CLIENT: Daniel B. Stephens

N

1885 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1



Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1885

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 3
Volume 1, Sheet 4

0 Feet 150 300 600

N

1888 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 7

0 Feet 150 300 600

N

1896 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1896

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 9

N

1900 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1900

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 9
Volume 1, Sheet 10

N

1905 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1905

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 5
Volume 1, Sheet 10
Volume 1, Sheet 11

N

1909 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1909

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 10
Volume 1, Sheet 11
Volume 1, Sheet 5

0 Feet 150 300 600

N

1915 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1915

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 4
Volume 1, Sheet 9
Volume 1, Sheet 10

N

1924 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1924

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 12
Volume 1, Sheet 13

0 Feet 150 300 600

N

1950 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 13

0 Feet 150 300 600

N

1951 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 12
Volume 1, Sheet 13

N

1953 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1953

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 13
Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 12
Volume 1, Sheet 13

0 Feet 150 300 600

N

1953 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1953

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 13
Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 12
Volume 1, Sheet 13

0 Feet 150 300 600

N

1963 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1963

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 13

0 Feet 150 300 600

N

1964 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name:	Grim Hotel
Address:	300-371 N STATE LINE AVE
City, ST, ZIP:	Texarkana TX 75501
Client:	Genesis Env. Inc./Terracon
EDR Inquiry:	4008707.3
Order Date:	7/17/2014 1:09:53 PM
Certification #	D625-4820-9CC1
Copyright:	1964

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 13

0 Feet 150 300 600

N

1969 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1969

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 13
Volume 1, Sheet 12

0 Feet 150 300 600

N

1969 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D625-4820-9CC1

Site Name: Grim Hotel
Address: 300-371 N STATE LINE AVE
City, ST, ZIP: Texarkana TX 75501
Client: Genesis Env. Inc./Terracon
EDR Inquiry: 4008707.3
Order Date: 7/17/2014 1:09:53 PM
Certification # D625-4820-9CC1
Copyright: 1969

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 4
Volume 1, Sheet 5
Volume 1, Sheet 13
Volume 1, Sheet 12

0 Feet 150 300 600

N

APPENDIX C

Property Record Card/Tax Information

Property Account Report

BOWIE CENTRAL APPRAISAL DISTRICT
Date Updated: Saturday, April 21, 2018

Appraisal Year: 2018
Account Number: 03840008900 (7935-1/12040)

Owner Info

Owner Name	RIVERGATE PROP LLC
Mailing Address	803 PINE ST TEXARKANA, TX 755015111
Situs Address	301 STATE LINE N TEXARKANA
Legal Description	CITY/TRIGGS ADDN LOTS 7-12 GRIM HOTEL 2972/009 12/14/98 BLK/TRACT 13 0.89 ACRES

Account Info

Deed Date	
Owner Percentage	100.0%
Exemptions	

Property Value Information

Land	55,650
Improvements	10
Personal	
Mineral	
Market Value	55,660
Ag Market	
Ag Productivity	
Timber Market	
Timber Productivity	
Productivity Loss	
Homesite Cap Loss	
Appraised Value	55,660

Current Year Jursidiction Values

Code	Jurisdiction Name	Appraised	Exemptions	Taxable
	BOWIE APPRAISAL DIS	55,660		55,660
	TEXARKANA COLLEGE	55,660		55,660
	TEXARKANA ISD	55,660		55,660
	TEXARKANA CITY T2	55,660		55,660
	BOWIE COUNTY T2	55,660		55,660

Five Year Historical Values

Year	Code	Jurisdiction Name	Appraised	Exemptions	Taxable
2017		BOWIE APPRAISAL DIS	55,660		55,660
2017		TEXARKANA COLLEGE	55,660		55,660
2017		TEXARKANA ISD	55,660		55,660
2017		TEXARKANA CITY T2	55,660		55,660
2017		BOWIE COUNTY T2	55,660		55,660
2016		BOWIE APPRAISAL DIS	55,660		55,660
2016		TEXARKANA COLLEGE	55,660		55,660
2016		TEXARKANA ISD	55,660		55,660
2016		TEXARKANA CITY T2	55,660		55,660
2016		BOWIE COUNTY T2	55,660		55,660
2015		BOWIE APPRAISAL DIS	55,660		55,660
2015		TEXARKANA COLLEGE	55,660		55,660
2015		TEXARKANA ISD	55,660		55,660
2015		TEXARKANA CITY T2	55,660		55,660
2015		BOWIE COUNTY T2	55,660		55,660
2014		BOWIE APPRAISAL DIS	55,660		55,660
2014		TEXARKANA COLLEGE	55,660		55,660
2014		TEXARKANA ISD	55,660		55,660
2014		TEXARKANA CITY T2	55,660		55,660
2014		BOWIE COUNTY T2	55,660		55,660
2013		BOWIE APPRAISAL DIS	55,660		55,660
2013		TEXARKANA COLLEGE	55,660		55,660
2013		TEXARKANA ISD	55,660		55,660
2013		TEXARKANA CITY T2	55,660		55,660
2013		BOWIE COUNTY T2	55,660		55,660
2012		BOWIE APPRAISAL DIS	74,201		74,201
2012		TEXARKANA COLLEGE	74,201		74,201
2012		TEXARKANA ISD	74,201		74,201
2012		TEXARKANA CITY T2	74,201		74,201
2012		BOWIE COUNTY T2	74,201		74,201

Land Seg	Mkt Class	Ag Class	Use Code	Land Use	Size	Units
1	LSCM		F1		37100.000	SQFT

Improvement Seg	Class	Use Code	Year Built
1	NOCLAS	F1	0

Texarkana Water Utility - GIS

APPENDIX D

Site Photographs

PHOTOGRAPHIC RECORD

Photograph 1 – Subject Building – South and East Face

Photograph 2 – Subject Building – North and East Face

Photograph 3 – Subject Building – North Face

PHOTOGRAPHIC RECORD

Photograph 4 – Subject Building West and East Face

Photograph 5 – Subject Property – Northern Portion

Photograph 6 – Subject Building – Ground Floor – Entrance

Photograph 7 – Subject Building – Ground Floor

Photograph 8 – Subject Building – Typical Upper Floor Hallway

Photograph 9 – Subject Building – Typical Upper Floor Room

PHOTOGRAPHIC RECORD

Photograph 10 – Subject Building –Typical Basement Hallway

Photograph 11 – Subject Building –Typical Basement Storage Room

Photograph 12 – Top Floor – Ceiling/Damaged Roof

PHOTOGRAPHIC RECORD

Photograph 13 –North View From Subject Building

Photograph 14 – Northeastern Adjacent Properties

Photograph 15 – North View Along North State Line Avenue

PHOTOGRAPHIC RECORD

Photograph 16 – Southern Adjacent Property – Across West 3rd Street

Photograph 17 – Eastern Adjacent Property From Subject Building – Across North State Line Avenue

Photograph 18 – Western Adjacent Property – Across Pine Street

Photograph 19 – Subject Building – Drums

Photograph 20 – Subject Building – Paint Can

Photograph 21 – Subject Building – Typical Debris

Photograph 22 – Subject Building – Typical Debris

Photograph 23 – Subject Building – Typical Debris

Photograph 23 – Subject Building – Typical Debris

Photograph 24 – Subject Building – Typical Debris

Photograph 25 – Subject Building – Typical Debris

Photograph 26 – Subject Building – Fluorescent Lighting

Photograph 26 – Subject Building – ACM Floor Tile

Photograph 27 – Subject Building – ACM Pipe Wrap

Photograph 28 – Subject Building – ACM Pipe Wrap

Photograph 29 – Subject Building – ACM Pipe and Boiler Wrap

Photograph 30 – Subject Building – ACM Pipe Wrap

APPENDIX E

Regulatory Data Search

Grim Hotel
301 North State Line
Texarkana, TX 75501

Inquiry Number: 5425918.2s
September 17, 2018

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	328
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-13
Physical Setting Source Map Findings	A-15
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

301 NORTH STATE LINE
TEXARKANA, TX 75501

COORDINATES

Latitude (North):	33.4229590 - 33° 25' 22.65''
Longitude (West):	94.0435110 - 94° 2' 36.63''
Universal Tranverse Mercator:	Zone 15
UTM X (Meters):	402983.0
UTM Y (Meters):	3698472.0
Elevation:	316 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5934377 TEXARKANA, TX
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140814, 20150715
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
301 NORTH STATE LINE
TEXARKANA, TX 75501

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	HOTEL GRIM	301 N. STATE LINE AV	FINDS		TP
A2	GRIM HOTEL	301 N STATE LINE AVE	TX BROWNFIELDS		TP
A3	HOTEL GRIM	301 N. STATE LINE AV	US BROWNFIELDS		TP
A4	TEXARKANA GAZZETTE-N	315 PINE ST	TX Ind. Haz Waste	Lower	35, 0.007, SSE
A5	SEARS BUILDING	301 PINE STREET X	US BROWNFIELDS	Lower	110, 0.021, SSW
B6	EXIMIUS PARKING LOT	211 WEST 3RD STREET	US BROWNFIELDS	Lower	206, 0.039, SSW
B7	EXIMIUS PARKING GARA	217-219 PINE STREET	US BROWNFIELDS	Lower	233, 0.044, South
C8	REGIONS BANK-TEXARKA	300 OLIVE ST	AR VCP, AR ASBESTOS, AR ENF	Lower	240, 0.045, East
B9	CAPITAL ONE BUILDING	100 WEST BROAD	US BROWNFIELDS	Lower	329, 0.062, South
C10	HELMS LIQUOR STORE	218 EAST 3RD STREET	AR UST	Lower	351, 0.066, East
D11	CAPITAL ONE BUILDING	100-104 BROAD STREET	US BROWNFIELDS, FINDS	Lower	428, 0.081, South
E12	DOWNTOWN STORAGE CO	215-21 OLIVE	EDR Hist Auto	Lower	429, 0.081, SE
D13	KRESS BUILDING ES#16	116 W BROAD ST	TX BROWNFIELDS, TX ASBESTOS	Lower	466, 0.088, South
D14	VACANT KRESS BUILDIN	116 W. BROAD STREET	US BROWNFIELDS	Lower	466, 0.088, South
D15	KRESS BUILDING	116 W BROAD ST	TX BROWNFIELDS	Lower	466, 0.088, South
E16	VACANT KLINE BAKERS	207 EAST BROAD STREE	US BROWNFIELDS, FINDS	Lower	470, 0.089, ESE
F17	FORMER TWIN CITY CAB	317 MAIN ST	TX UST	Lower	478, 0.091, WSW
F18	MAIN ST. & TEXAS BLV	301 MAIN STREET AND	US BROWNFIELDS	Lower	481, 0.091, SW
D19	VACANT RUTH BUILDING	120 WEST BROAD STREE	US BROWNFIELDS	Lower	491, 0.093, South
G20	GARNER CLEANERS	424 MAIN ST	EDR Hist Cleaner	Lower	500, 0.095, WNW
G21	GARNER CLEANERS	424 MAIN ST	TX DRYCLEANERS	Lower	500, 0.095, WNW
D22	MABEL BRYAN MORRISS	124 WEST BROAD STREE	US BROWNFIELDS	Lower	508, 0.096, SSW
H23	TEX-REP	213 MAIN STREET	US BROWNFIELDS	Lower	520, 0.098, SSW
D24	VACANT REGENCY HOUSE	110 E. BROAD STREET	US BROWNFIELDS, FINDS	Lower	527, 0.100, SE
25	CURLEYS CLEANERS & F	306 WOOD ST	EDR Hist Cleaner	Higher	575, 0.109, ENE
I26	TEXARKANA CENTRAL OF	507 OLIVE ST	TX UST, TX Financial Assurance	Higher	631, 0.120, North
F27	MAIN ST AND TEXAS BL	301 MAIN ST & 302 TE	TX BROWNFIELDS	Lower	658, 0.125, WSW
H28	203 WEST BROAD STREE	203 WEST BRAOD STREE	US BROWNFIELDS, FINDS	Lower	698, 0.132, SSW
H29	203 W BROAD ST TEXAR	203 W BROAD ST	TX BROWNFIELDS	Lower	698, 0.132, SSW
J30	205 W BROAD ST TEXAR	205 W BROAD ST	TX BROWNFIELDS	Lower	717, 0.136, SSW
J31	205 WEST BROAD STREE	205 WEST BROAD STREE	US BROWNFIELDS	Lower	717, 0.136, SSW
32	ABANDONED RITCHIE GR	215 EAST FRONT STREE	US BROWNFIELDS, FINDS	Lower	781, 0.148, SSE
K33	UNION STATION	100 W. FRONT STREET	US BROWNFIELDS	Lower	840, 0.159, South
L34	TEXARKANA UNIFORM	315 TEXAS BLVD	TX UST	Lower	849, 0.161, WSW
L35	TEXARKANA UNIFORM	315 TEXAS BLVD	TX LPST	Lower	849, 0.161, WSW
M36	UPTOWN ANTIQUES	221 TEXAS BLVD.	US BROWNFIELDS	Lower	863, 0.163, SW
M37	UPTOWN ANTIQUES	221 TEXAS BLVD	TX BROWNFIELDS	Lower	863, 0.163, SW
K38	RED RIVER ARMY DEPOT	100 MAIN ST	TX AST	Lower	892, 0.169, South
K39	RED RIVER ARMY DEPOT	100 MAIN DRIVE AMSTA	TX SWF/LF	Lower	892, 0.169, South

MAPPED SITES SUMMARY

Target Property Address:
301 NORTH STATE LINE
TEXARKANA, TX 75501

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K40	UNITED STATES MILITA	100 JAMES CARLOW DR	NY MANIFEST	Lower	892, 0.169, South
I41	EAST FUNERAL HOME	120 W 6TH ST	TX UST	Higher	895, 0.170, North
K42	SANDEFUR PARKING LOT	202, 208 AND 222 FRO	US BROWNFIELDS	Lower	950, 0.180, South
43	VACANT LOT AT 301 W	301 W. BROAD STREET	US BROWNFIELDS	Lower	977, 0.185, SSW
L44	THE T R A H C BUILDI	410 W 3RD ST	TX LPST	Lower	998, 0.189, SW
L45	PJ MATHEWS	410 W 3RD ST	TX UST	Lower	998, 0.189, SW
46	BURCH MOTOR	501 TEXAS BLVD	TX UST	Lower	1006, 0.191, West
N47	WILSON TIRE CENTER	601 N STATE LINE AVE	TX UST	Higher	1014, 0.192, North
O48	UNION PACIFIC RAILRO	612 MAIN ST	TX Ind. Haz Waste	Lower	1025, 0.194, NW
O49	SOUTHERN PACIFIC TRA	612 MAIN STREET	RCRA NonGen / NLR, FINDS, ECHO	Lower	1025, 0.194, NW
O50	SOUTHERN PACIFIC TRA	612 MAIN ST	TX Ind. Haz Waste	Lower	1025, 0.194, NW
51	SOUTHWEST ARK COMMUN	506 WALNUT	AR UST, FINDS	Higher	1067, 0.202, NNE
P52	TIRE CITY	418 W 4TH ST	TX UST	Lower	1072, 0.203, WSW
O53	DANG GOOD USED CARS	401 W 7TH ST	TX LPST, TX UST, TX Financial Assurance, TX GCC	Lower	1122, 0.213, NW
O54	CAL WILLIAMS USED CA	423 W 7TH ST	TX UST	Lower	1154, 0.219, NW
Q55	ROBBINS TOYOTA	601 TEXAS BLVD	TX UST	Lower	1204, 0.228, WNW
N56	BEALS SERVICE	201 W 7TH ST	TX LPST, TX UST	Higher	1209, 0.229, North
R57	SWIFT BUILDING	410 E. BROAD ST.	US BROWNFIELDS, FINDS	Lower	1212, 0.230, East
Q58	MONTGOMERY WARD	10 OAKLAWN SHOPPING	TX LPST	Lower	1251, 0.237, WNW
S59	GRIFFIN SHELL	404 W 7TH ST	TX LPST, TX UST	Lower	1253, 0.237, NW
T60	UNION PACIFIC RAILRO	WALNUT & FRONT ST	AR UST	Lower	1279, 0.242, ESE
T61	UNION PACIFIC RAILRO	WALNUT & FRONT ST	AR LTANKS	Lower	1279, 0.242, ESE
S62	AAA AUTO & TRUCK SAL	420 W 7TH ST	TX UST	Lower	1281, 0.243, NW
P63	SWBT TEXARKANA TOLL	429 SPRUCE ST	TX UST	Lower	1289, 0.244, West
64	QUINNS MODEL CLEANER	411 HAZEL	RCRA NonGen / NLR, FINDS, ECHO	Higher	1293, 0.245, NE
R65	UNION SUPPLY GROCERY	418 E. BROAD ST.	US BROWNFIELDS, FINDS	Lower	1301, 0.246, East
U66	MODERN CLEANERS	210 W 7TH ST	TX DRYCLEANERS	Higher	1312, 0.248, North
U67	MODERN CLEANERS	210 W 7TH ST	TX UST	Higher	1312, 0.248, North
68	SOUTHERN PACIFIC TRA	319 W FRONT ST	TX LPST, TX GCC	Lower	1340, 0.254, SSW
Q69	ANTIQUE MALL	621 TEXAS BLVD	US BROWNFIELDS, FINDS	Lower	1341, 0.254, WNW
Q70	621 TEXAS	621 TEXAS BLVD.	US BROWNFIELDS	Lower	1341, 0.254, WNW
R71	UPRR	E. BROAD ST. BETWEEN	US BROWNFIELDS, FINDS	Lower	1366, 0.259, East
R72	COMBINED MORRISSEY P	EAST BROAD AND EAST	US BROWNFIELDS, FINDS	Lower	1419, 0.269, East
U73	999 STATION	102 W 7TH ST	TX LPST	Higher	1432, 0.271, North
74	ROBBINS VACANT LOT	521 SPRUCE STREET	US BROWNFIELDS	Lower	1445, 0.274, West
V75	523 W 3RD STREET	523 W 3RD STREET	US BROWNFIELDS	Lower	1553, 0.294, SW
V76	JAMESON BUILDING	523 WEST 3RD STREET	US BROWNFIELDS, FINDS	Lower	1553, 0.294, SW
V77	CITY OF TEXARKANA	523 W 3RD ST	TX BROWNFIELDS	Lower	1553, 0.294, SW
78	USED CAR LOT	706 W 7TH ST	TX LPST	Lower	1706, 0.323, WNW

MAPPED SITES SUMMARY

Target Property Address:
301 NORTH STATE LINE
TEXARKANA, TX 75501

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
79	TEXARKANA ELECTRIC L	JEFFERSON RD	EDR MGP	Lower	1796, 0.340, SSE
80	E - Z MART #167	424 E. 7TH ST.	AR LTANKS	Higher	2113, 0.400, NNE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
HOTEL GRIM 301 N. STATE LINE AV TEXARKANA, TX 75501	FINDS Registry ID:: 110067221269	N/A
GRIM HOTEL 301 N STATE LINE AVE TEXARKANA, TX 75501	TX BROWNFIELDS BF Grant Number: G180	N/A
HOTEL GRIM 301 N. STATE LINE AV TEXARKANA, TX 75501	US BROWNFIELDS ACRES property ID: 208665	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

EXECUTIVE SUMMARY

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-LQG RCRA - Large Quantity Generators
RCRA-SQG RCRA - Small Quantity Generators
RCRA-CESQG RCRA - Conditionally Exempt Small Quantity Generator

Federal institutional controls / engineering controls registries

LUCIS Land Use Control Information System
US ENG CONTROLS Engineering Controls Sites List
US INST CONTROL Sites with Institutional Controls

Federal ERNS list

ERNS Emergency Response Notification System

State- and tribal - equivalent NPL

TX SHWS State Superfund Registry
AR SHWS Hazardous Substance Remedial Action Trust Fund Priority List

State and tribal landfill and/or solid waste disposal site lists

AR SWF/LF Solid Waste Facility Permit Database
TX DEBRIS DEBRIS
TX CLI Closed Landfill Inventory
TX WASTE MGMT Commercial Hazardous & Solid Waste Management Facilities

State and tribal leaking storage tank lists

INDIAN LUST Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST Underground Storage Tank Listing
AR AST Aboveground Tank Database
INDIAN UST Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

TX AUL Sites with Controls

State and tribal voluntary cleanup sites

TX VCP Voluntary Cleanup Program Database
INDIAN VCP Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

AR BROWNFIELDS Brownfields Projects

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

TX SWRCY ..... Recycling Facility Listing
AR SWRCY ..... Recycling Directory
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
ODI ..... Open Dump Inventory
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register
TX CDL ..... CDL
AR CDL ..... Methamphetamine Contaminated Properties Listing
TX PRIORITYCLEANERS ..... Dry Cleaner Remediation Program Prioritization List
TX DEL SHWS ..... Deleted Superfund Registry Sites
US CDL ..... National Clandestine Laboratory Register

Local Land Records

TX HIST LIENS ..... Environmental Liens Listing
TX LIENS ..... Environmental Liens Listing
LIENS 2 ..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ..... Hazardous Materials Information Reporting System
TX SPILLS ..... Spills Database
AR SPILLS ..... Emergency Response Incidents
TX SPILLS 90 ..... SPILLS 90 data from FirstSearch
AR SPILLS 90 ..... SPILLS 90 data from FirstSearch
TX SPILLS 80 ..... SPILLS 80 data from FirstSearch
AR SPILLS 80 ..... SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ..... Formerly Used Defense Sites
DOD ..... Department of Defense Sites
SCRD DRYCLEANERS ..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ..... Financial Assurance Information
EPA WATCH LIST ..... EPA WATCH LIST
2020 COR ACTION ..... 2020 Corrective Action Program List
TSCA ..... Toxic Substances Control Act
TRIS ..... Toxic Chemical Release Inventory System
SSTS ..... Section 7 Tracking Systems
ROD ..... Records Of Decision
RMP ..... Risk Management Plans
RAATS ..... RCRA Administrative Action Tracking System
PRP ..... Potentially Responsible Parties
PADS ..... PCB Activity Database System
ICIS ..... Integrated Compliance Information System

FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US AIRS ---- Aerometric Information Retrieval System Facility Subsystem
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
TX AIRS ---- Current Emission Inventory Data
AR AIRS ---- Permitted Facility Emission & Stack Data
TX APAR ---- Affected Property Assessment Report Site Listing
TX COAL ASH ---- Coal Ash Disposal Sites
AR COAL ASH ---- Coal Ash Disposal Site Listing
TX ED AQUIF ---- Edwards Aquifer Permits
TX ENF ---- Notice of Violations Listing
AR Financial Assurance ---- Financial Assurance Information Listing
TX IHW CORR ACTION ---- IHW CORR ACTION
TX IOP ---- Innocent Owner/Operator Program
TX LEAD ---- LEAD
TX MSD ---- Municipal Settings Designations Database
TX NPDES ---- NPDES Facility List
TX RWS ---- Radioactive Waste Sites
TX TIER 2 ---- Tier 2 Chemical Inventory Reports
AR TIER 2 ---- Tier 2 Information Listing
TX UIC ---- Underground Injection Wells Database Listing
AR UIC ---- Underground Injection Wells Database Listing

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

TX RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
AR RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
TX RGA LF ---- Recovered Government Archive Solid Waste Facilities List
AR RGA LF ---- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

State and tribal landfill and/or solid waste disposal site lists

TX SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Texas Commission on Environmental Quality's permitted Solid Waste Facilities list.

A review of the TX SWF/LF list, as provided by EDR, and dated 04/25/2018 has revealed that there is 1 TX SWF/LF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RED RIVER ARMY DEPOT Facility Status: CLOSED Estimated Closure Date: 6/1/1984 Permit Number: 1313	100 MAIN DRIVE AMSTA	S 1/8 - 1/4 (0.169 mi.)	K39	133

State and tribal leaking storage tank lists

AR LTANKS: Leaking Storage Tank Locations

A review of the AR LTANKS list, as provided by EDR, and dated 06/18/2018 has revealed that there are 2 AR LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
E - Z MART #167	424 E. 7TH ST.	NNE 1/4 - 1/2 (0.400 mi.)	80	325

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNION PACIFIC RAILRO NFA Issued: 1993-08-20 00:00:00	WALNUT & FRONT ST	ESE 1/8 - 1/4 (0.242 mi.)	T61	266

TX LPST: The Leaking Petroleum Storage Tank Incident Reports contain an inventory of reported leaking petroleum storage tank incidents. The data come from the Texas Commission on Environmental Quality's Leaking Petroleum Storage Tank Database.

A review of the TX LPST list, as provided by EDR, and dated 06/08/2018 has revealed that there are 9 TX LPST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BEALS SERVICE Facility ID: 0048891 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 113938 CA Status: 6A - FINAL CONCURRENCE ISSUED	***201 W 7TH ST***	***N 1/8 - 1/4 (0.229 mi.)***	***N56***	***232***
999 STATION Facility ID: 0068781 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	102 W 7TH ST	N 1/4 - 1/2 (0.271 mi.)	U73	313

LPST Id: 111842
CA Status: 6A - FINAL CONCURRENCE ISSUED

Lower Elevation	Address	Direction / Distance	Map ID	Page
TEXARKANA UNIFORM Facility ID: 0008926 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 103637 CA Status: 6A - FINAL CONCURRENCE ISSUED	315 TEXAS BLVD	WSW 1/8 - 1/4 (0.161 mi.)	L35	117
THE T R A H C BUILDI Facility ID: 0056052 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 96254 CA Status: 6A - FINAL CONCURRENCE ISSUED	410 W 3RD ST	SW 1/8 - 1/4 (0.189 mi.)	L44	146
DANG GOOD USED CARS Facility ID: 0010627 Status Code: PREASSESSMENT/RELEASE DETERMINATION LPST Id: 96657 CA Status: 1 - RELEASE DETERMINATION	***401 W 7TH ST***	***NW 1/8 - 1/4 (0.213 mi.)***	***O53***	***207***
MONTGOMERY WARD Facility ID: 0019051 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 93895 CA Status: 6A - FINAL CONCURRENCE ISSUED	10 OAKLAWN SHOPPING	WNW 1/8 - 1/4 (0.237 mi.)	Q58	249
GRIFFIN SHELL Facility ID: 0006689 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 114099 CA Status: 6A - FINAL CONCURRENCE ISSUED	***404 W 7TH ST***	***NW 1/8 - 1/4 (0.237 mi.)***	***S59***	***249***
SOUTHERN PACIFIC TRA Facility ID: 0053907 Status Code: CORRECTIVE ACTION PLAN Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 118317 LPST Id: 102408 CA Status: 5 - REMEDIAL ACTION PLAN CA Status: 6A - FINAL CONCURRENCE ISSUED	***319 W FRONT ST***	***SSW 1/4 - 1/2 (0.254 mi.)***	***68***	***296***
USED CAR LOT Facility ID: 0057970 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED LPST Id: 98795 CA Status: 6A - FINAL CONCURRENCE ISSUED	706 W 7TH ST	WNW 1/4 - 1/2 (0.323 mi.)	78	325

State and tribal registered storage tank lists

TX UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Texas Commission on Environmental Quality's Petroleum Storage Tank Database.

A review of the TX UST list, as provided by EDR, and dated 06/01/2018 has revealed that there are 16

EXECUTIVE SUMMARY

TX UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TEXARKANA CENTRAL OF Facility Id: 8021 Facility Num: 40079 AI Number: 549530672002087 Facility Status: ACTIVE	***507 OLIVE ST***	***N 0 - 1/8 (0.120 mi.)***	***I26***	***79***
EAST FUNERAL HOME Facility Id: 42685 Facility Num: 82131 AI Number: 875183462002139 Facility Status: INACTIVE	120 W 6TH ST	N 1/8 - 1/4 (0.170 mi.)	I41	135
WILSON TIRE CENTER Facility Id: 43572 Facility Num: 86292 AI Number: 245311312002086 Facility Status: INACTIVE	601 N STATE LINE AVE	N 1/8 - 1/4 (0.192 mi.)	N47	164
BEALS SERVICE Facility Id: 48891 Facility Num: 80612 AI Number: 682623882003100 Facility Status: INACTIVE	***201 W 7TH ST***	***N 1/8 - 1/4 (0.229 mi.)***	***N56***	***232***
MODERN CLEANERS Facility Id: 1686 Facility Num: 39638 AI Number: 392540552002087 Facility Status: INACTIVE	210 W 7TH ST	N 1/8 - 1/4 (0.248 mi.)	U67	293

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER TWIN CITY CAB Facility Id: 57640 Facility Num: 87689 AI Number: 302370332003197 Facility Status: INACTIVE	317 MAIN ST	WSW 0 - 1/8 (0.091 mi.)	F17	54
TEXARKANA UNIFORM Facility Id: 8926 Facility Num: 48736 AI Number: 518589292002275 Facility Status: INACTIVE	315 TEXAS BLVD	WSW 1/8 - 1/4 (0.161 mi.)	L34	112
PJ MATHEWS Facility Id: 56052 Facility Num: 85886 AI Number: 405622272002087 Facility Status: INACTIVE	410 W 3RD ST	SW 1/8 - 1/4 (0.189 mi.)	L45	146
BURCH MOTOR Facility Id: 11989 Facility Num: 51079 AI Number: 914446992002087 Facility Status: INACTIVE	501 TEXAS BLVD	W 1/8 - 1/4 (0.191 mi.)	46	158
TIRE CITY	418 W 4TH ST	WSW 1/8 - 1/4 (0.203 mi.)	P52	201

Facility Id: 71137
Facility Num: 108340
AI Number: 561788582002087
Facility Status: INACTIVE

DANG GOOD USED CARS	***401 W 7TH ST***	***NW 1/8 - 1/4 (0.213 mi.)***	***O53***	***207***
Facility Id: 10627 Facility Num: 49968 AI Number: 587426792002089 Facility Status: ACTIVE				
CAL WILLIAMS USED CA	423 W 7TH ST	NW 1/8 - 1/4 (0.219 mi.)	O54	224
Facility Id: 60808 Facility Num: 91169 AI Number: 114384602002089 Facility Status: INACTIVE				
ROBBINS TOYOTA	601 TEXAS BLVD	WNW 1/8 - 1/4 (0.228 mi.)	Q55	229
Facility Id: 10522 Facility Num: 49889 AI Number: 330689992002088 Facility Status: INACTIVE				
GRIFFIN SHELL	***404 W 7TH ST***	***NW 1/8 - 1/4 (0.237 mi.)***	***S59***	***249***
Facility Id: 6689 Facility Num: 45667 AI Number: 11290792002087 Facility Status: ACTIVE				
AAA AUTO & TRUCK SAL	420 W 7TH ST	NW 1/8 - 1/4 (0.243 mi.)	S62	267
Facility Id: 61157 Facility Num: 95387 AI Number: 502666072002087 Facility Status: INACTIVE				
SWBT TEXARKANA TOLL	429 SPRUCE ST	W 1/8 - 1/4 (0.244 mi.)	P63	278
Facility Id: 19488 Facility Num: 76598 AI Number: 803770622002150 Facility Status: INACTIVE				

AR UST: RST Owner & Facilities.

A review of the AR UST list, as provided by EDR, and dated 06/18/2018 has revealed that there are 3 AR UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUTHWEST ARK COMMUN	***506 WALNUT***	***NNE 1/8 - 1/4 (0.202 mi.)***	***51***	***199***
Tank Status: PO Facility Id: 46000084 Facility Id: 46000084 ADEQ Facility ID: 46-00425				

Lower Elevation	Address	Direction / Distance	Map ID	Page
HELMS LIQUOR STORE	218 EAST 3RD STREET	E 0 - 1/8 (0.066 mi.)	C10	37
Tank Status: PO				

Facility Id: 46001626 Facility Id: 46001626 ADEQ Facility ID: 46-00515				
UNION PACIFIC RAILRO Tank Status: PO Facility Id: 46001660 Facility Id: 46001660 ADEQ Facility ID: 46-00589	WALNUT & FRONT ST	ESE 1/8 - 1/4 (0.242 mi.)	T60	264

TX AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Texas Commission on Environmental Quality's Petroleum Storage Tank Database.

A review of the TX AST list, as provided by EDR, and dated 06/01/2018 has revealed that there is 1 TX AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RED RIVER ARMY DEPOT Facility Id: 58196 Facility Id: 79642062002205 Facility Id: 21468 Facility Status: ACTIVE	100 MAIN ST	S 1/8 - 1/4 (0.169 mi.)	K38	121

State and tribal voluntary cleanup sites

AR VCP: Voluntary Cleanup Program site.

A review of the AR VCP list, as provided by EDR, and dated 04/30/2018 has revealed that there is 1 AR VCP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
REGIONS BANK-TEXARKA Project Status: Complete AFIN Num: 46-00566	***300 OLIVE ST***	***E 0 - 1/8 (0.045 mi.)***	***C8***	***34***

State and tribal Brownfields sites

Brownfield site assessments that are being cleaned under EPA grant monies.

A review of the TX BROWNFIELDS list, as provided by EDR, and dated 06/21/2018 has revealed that there are 7 TX BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
KRESS BUILDING ES#16 BF Grant Number: G113	***116 W BROAD ST***	***S 0 - 1/8 (0.088 mi.)***	***D13***	***44***
KRESS BUILDING BF Grant Number: G093	116 W BROAD ST	S 0 - 1/8 (0.088 mi.)	D15	51
MAIN ST AND TEXAS BL	301 MAIN ST & 302 TE	WSW 0 - 1/8 (0.125 mi.)	F27	92

BF Grant Number: G168				
203 W BROAD ST TEXAR BF Grant Number: G099	203 W BROAD ST	SSW 1/8 - 1/4 (0.132 mi.)	H29	95
205 W BROAD ST TEXAR BF Grant Number: G100	205 W BROAD ST	SSW 1/8 - 1/4 (0.136 mi.)	J30	96
UPTOWN ANTIQUES BF Grant Number: G182	221 TEXAS BLVD	SW 1/8 - 1/4 (0.163 mi.)	M37	120
CITY OF TEXARKANA BF Grant Number: G104	523 W 3RD ST	SW 1/4 - 1/2 (0.294 mi.)	V77	324

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 06/18/2018 has revealed that there are 28 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SEARS BUILDING ACRES property ID: 94605	301 PINE STREET X	SSW 0 - 1/8 (0.021 mi.)	A5	19
EXIMIUS PARKING LOT ACRES property ID: 133210	211 WEST 3RD STREET	SSW 0 - 1/8 (0.039 mi.)	B6	24
EXIMIUS PARKING GARA ACRES property ID: 133209	217-219 PINE STREET	S 0 - 1/8 (0.044 mi.)	B7	29
CAPITAL ONE BUILDING ACRES property ID: 133211	100 WEST BROAD	S 0 - 1/8 (0.062 mi.)	B9	35
CAPITAL ONE BUILDING ACRES property ID: 87301	***100-104 BROAD STREET***	***S 0 - 1/8 (0.081 mi.)***	***D11***	***41***
VACANT KRESS BUILDIN ACRES property ID: 69901	116 W. BROAD STREET	S 0 - 1/8 (0.088 mi.)	D14	46
VACANT KLINE BAKERS ACRES property ID: 69921	***207 EAST BROAD STREE***	***ESE 0 - 1/8 (0.089 mi.)***	***E16***	***51***
MAIN ST. & TEXAS BLV ACRES property ID: 185042	301 MAIN STREET AND	SW 0 - 1/8 (0.091 mi.)	F18	58
VACANT RUTH BUILDING ACRES property ID: 74741	120 WEST BROAD STREE	S 0 - 1/8 (0.093 mi.)	D19	60
MABEL BRYAN MORRISS ACRES property ID: 69861	124 WEST BROAD STREE	SSW 0 - 1/8 (0.096 mi.)	D22	68
TEX-REP ACRES property ID: 151361	213 MAIN STREET	SSW 0 - 1/8 (0.098 mi.)	H23	70
VACANT REGENCY HOUSE	***110 E. BROAD STREET***	***SE 0 - 1/8 (0.100 mi.)***	***D24***	***75***

ACRES property ID: 69881				
203 WEST BROAD STREE	***203 WEST BRAOD STREE***	***SSW 1/8 - 1/4 (0.132 mi.)***	***H28***	***93***
ACRES property ID: 72421				
205 WEST BROAD STREE	205 WEST BROAD STREE	SSW 1/8 - 1/4 (0.136 mi.)	J31	97
ACRES property ID: 72441				
ABANDONED RITCHIE GR	***215 EAST FRONT STREE***	***SSE 1/8 - 1/4 (0.148 mi.)***	***32***	***99***
ACRES property ID: 231341				
UNION STATION	100 W. FRONT STREET	S 1/8 - 1/4 (0.159 mi.)	K33	107
ACRES property ID: 208663				
UPTOWN ANTIQUES	221 TEXAS BLVD.	SW 1/8 - 1/4 (0.163 mi.)	M36	117
ACRES property ID: 235932				
SANDEFUR PARKING LOT	202, 208 AND 222 FRO	S 1/8 - 1/4 (0.180 mi.)	K42	138
ACRES property ID: 133213				
VACANT LOT AT 301 W	301 W. BROAD STREET	SSW 1/8 - 1/4 (0.185 mi.)	43	141
ACRES property ID: 69821				
SWIFT BUILDING	***410 E. BROAD ST.***	***E 1/8 - 1/4 (0.230 mi.)***	***R57***	***244***
ACRES property ID: 94602				
UNION SUPPLY GROCERY	***418 E. BROAD ST.***	***E 1/8 - 1/4 (0.246 mi.)***	***R65***	***286***
ACRES property ID: 94603				
ANTIQUE MALL	***621 TEXAS BLVD***	***WNW 1/4 - 1/2 (0.254 mi.)***	***Q69***	***299***
ACRES property ID: 151362				
621 TEXAS	621 TEXAS BLVD.	WNW 1/4 - 1/2 (0.254 mi.)	Q70	302
ACRES property ID: 158582				
UPRR	***E. BROAD ST. BETWEEN***	***E 1/4 - 1/2 (0.259 mi.)***	***R71***	***305***
ACRES property ID: 94601				
COMBINED MORRISSEY P	***EAST BROAD AND EAST***	***E 1/4 - 1/2 (0.269 mi.)***	***R72***	***310***
ACRES property ID: 69841				
ROBBINS VACANT LOT	521 SPRUCE STREET	W 1/4 - 1/2 (0.274 mi.)	74	313
ACRES property ID: 208661				
523 W 3RD STREET	523 W 3RD STREET	SW 1/4 - 1/2 (0.294 mi.)	V75	316
ACRES property ID: 88341				
JAMESON BUILDING	***523 WEST 3RD STREET***	***SW 1/4 - 1/2 (0.294 mi.)***	***V76***	***318***
ACRES property ID: 133214				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there are 2 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
QUINNS MODEL CLEANER	***411 HAZEL***	***NE 1/8 - 1/4 (0.245 mi.)***	***64***	***284***

EPA ID:: ARD103970778

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC TRA	***612 MAIN STREET***	***NW 1/8 - 1/4 (0.194 mi.)***	***O49***	***195***
EPA ID:: TXT490011194				

TX DRYCLEANERS: Drycleaner Registration Database Listing.

A review of the TX DRYCLEANERS list, as provided by EDR, and dated 05/01/2018 has revealed that there are 2 TX DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MODERN CLEANERS	210 W 7TH ST	N 1/8 - 1/4 (0.248 mi.)	U66	291
AR Number: 24002065				
AR Number: 24003619				
CN Number: CN600281836				
CN Number: CN602985467				
RN Number: RN101804904				
Site Status: ACTIVE				

Lower Elevation	Address	Direction / Distance	Map ID	Page
GARNER CLEANERS	424 MAIN ST	WNW 0 - 1/8 (0.095 mi.)	G21	63
AR Number: 24007188				
AR Number: 24000910				
AR Number: 24006772				
CN Number: CN604733931				
CN Number: CN602460115				
CN Number: CN604253187				
RN Number: RN103959565				
Site Status: ACTIVE				

TX Ind. Haz Waste: The Industrial and Hazardous Waste Database contains summary reports by waste handlers, generators and shippers in Texas.

A review of the TX Ind. Haz Waste list, as provided by EDR, and dated 07/06/2018 has revealed that there are 3 TX Ind. Haz Waste sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TEXARKANA GAZZETTE-N	315 PINE ST	SSE 0 - 1/8 (0.007 mi.)	A4	16
Registration Number: 31566				
UNION PACIFIC RAILRO	612 MAIN ST	NW 1/8 - 1/4 (0.194 mi.)	O48	193
Registration Number: 67024				
SOUTHERN PACIFIC TRA	612 MAIN ST	NW 1/8 - 1/4 (0.194 mi.)	O50	196
Registration Number: 35726				

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 07/01/2018 has revealed that there is 1 NY MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNITED STATES MILITA EPA ID: TX3213820738	100 JAMES CARLOW DR	S 1/8 - 1/4 (0.169 mi.)	K40	133

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TEXARKANA ELECTRIC L	JEFFERSON RD	SSE 1/4 - 1/2 (0.340 mi.)	79	325

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there is 1 EDR Hist Auto site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DOWNTOWN STORAGE CO	215-21 OLIVE	SE 0 - 1/8 (0.081 mi.)	E12	44

EXECUTIVE SUMMARY

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 2 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CURLEYS CLEANERS & F	306 WOOD ST	ENE 0 - 1/8 (0.109 mi.)	25	78

Lower Elevation	Address	Direction / Distance	Map ID	Page
GARNER CLEANERS	424 MAIN ST	WNW 0 - 1/8 (0.095 mi.)	G20	63

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 3 records.

Site Name	Database(s)
KOPPERS CO., INC. (TEXARKANA PLANT	TX SHWS
ABANDINED LANDFILL	SEMS-ARCHIVE
TEXARKANA GAZETTE PROPERTY	TX LPST

OVERVIEW MAP - 5425918.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands
- Upgradient Area

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Grim Hotel	CLIENT:	Swift Creek Environmental, Inc
ADDRESS:	301 North State Line Texarkana TX 75501	CONTACT:	B Houghton
		INQUIRY #:	5425918.2s
LAT/LONG:	33.422959 / 94.043511	DATE:	September 17, 2018 12:47 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5425918.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

County Boundary

100-year flood zone

500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Grim Hotel	CLIENT:	Swift Creek Environmental, Inc
ADDRESS:	301 North State Line Texarkana TX 75501	CONTACT:	B Houghton
		INQUIRY #:	5425918.2s
LAT/LONG:	33.422959 / 94.043511	DATE:	September 17, 2018 12:48 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	0.001		0	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-CESQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
TX SHWS	1.000		0	0	0	0	NR	0
AR SHWS	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
TX SWF/LF	0.500		0	1	0	NR	NR	1
AR SWF/LF	0.500		0	0	0	NR	NR	0
TX DEBRIS	0.500		0	0	0	NR	NR	0
TX CLI	0.500		0	0	0	NR	NR	0
TX WASTE MGMT	0.001		0	NR	NR	NR	NR	0
State and tribal leaking storage tank lists								
AR LTANKS	0.500		0	1	1	NR	NR	2

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
TX LPST	0.500		0	6	3	NR	NR	9
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
TX UST	0.250		2	14	NR	NR	NR	16
AR UST	0.250		1	2	NR	NR	NR	3
TX AST	0.250		0	1	NR	NR	NR	1
AR AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
TX AUL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
TX VCP	0.500		0	0	0	NR	NR	0
AR VCP	0.500		1	0	0	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
TX BROWNFIELDS	0.500	1	3	3	1	NR	NR	8
AR BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500	1	12	9	7	NR	NR	29
Local Lists of Landfill / Solid Waste Disposal Sites								
TX SWRCY	0.500		0	0	0	NR	NR	0
AR SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
TX CDL	0.001		0	NR	NR	NR	NR	0
AR CDL	0.001		0	NR	NR	NR	NR	0
TX PRIORITYCLEANERS	0.500		0	0	0	NR	NR	0
TX DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
Local Land Records								
TX HIST LIENS	0.001		0	NR	NR	NR	NR	0
TX LIENS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
TX SPILLS	0.001		0	NR	NR	NR	NR	0
AR SPILLS	0.001		0	NR	NR	NR	NR	0
TX SPILLS 90	0.001		0	NR	NR	NR	NR	0
AR SPILLS 90	0.001		0	NR	NR	NR	NR	0
TX SPILLS 80	0.001		0	NR	NR	NR	NR	0
AR SPILLS 80	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		0	2	NR	NR	NR	2
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	0.001		0	NR	NR	NR	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.001		0	NR	NR	NR	NR	0
FINDS	0.001	1	0	NR	NR	NR	NR	1
ECHO	0.001		0	NR	NR	NR	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
TX AIRS	0.001		0	NR	NR	NR	NR	0
AR AIRS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
TX APAR	0.001		0	NR	NR	NR	NR	0
TX ASBESTOS	0.001		0	NR	NR	NR	NR	0
AR ASBESTOS	0.001		0	NR	NR	NR	NR	0
TX COAL ASH	0.500		0	0	0	NR	NR	0
AR COAL ASH	0.500		0	0	0	NR	NR	0
TX DRYCLEANERS	0.250		1	1	NR	NR	NR	2
TX ED AQUIF	0.001		0	NR	NR	NR	NR	0
TX ENF	0.001		0	NR	NR	NR	NR	0
AR ENF	0.001		0	NR	NR	NR	NR	0
TX Financial Assurance	0.001		0	NR	NR	NR	NR	0
AR Financial Assurance	0.001		0	NR	NR	NR	NR	0
TX GCC	0.001		0	NR	NR	NR	NR	0
TX Ind. Haz Waste	0.250		1	2	NR	NR	NR	3
TX IHW CORR ACTION	0.250		0	0	NR	NR	NR	0
TX IOP	0.001		0	NR	NR	NR	NR	0
TX LEAD	0.001		0	NR	NR	NR	NR	0
NY MANIFEST	0.250		0	1	NR	NR	NR	1
TX MSD	0.500		0	0	0	NR	NR	0
TX NPDES	0.001		0	NR	NR	NR	NR	0
TX RWS	0.001		0	NR	NR	NR	NR	0
TX TIER 2	0.001		0	NR	NR	NR	NR	0
AR TIER 2	0.001		0	NR	NR	NR	NR	0
TX UIC	0.001		0	NR	NR	NR	NR	0
AR UIC	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		1	NR	NR	NR	NR	1
EDR Hist Cleaner	0.125		2	NR	NR	NR	NR	2
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
TX RGA HWS	0.001		0	NR	NR	NR	NR	0
AR RGA HWS	0.001		0	NR	NR	NR	NR	0
TX RGA LF	0.001		0	NR	NR	NR	NR	0
AR RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		3	24	43	13	0	0	83

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **HOTEL GRIM** **FINDS** **1023395301**
Target **301 N. STATE LINE AVENUE** **N/A**
Property **TEXARKANA, TX 75501**

Site 1 of 5 in cluster A

Actual: **316 ft.**

FINDS:

Registry ID: 110067221269

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A2 **GRIM HOTEL** **TX BROWNFIELDS** **S119135219**
Target **301 N STATE LINE AVE** **N/A**
Property **TEXARKANA, TX 75501**

Site 2 of 5 in cluster A

Actual: **316 ft.**

BROWNFIELDS:

BF Site Assessment Received:	12/14/2016
PCA number:	99690
BF Grant Number:	G180
Facility Type:	HOTEL
Lead Type:	CITY
Project manager:	KLIVINGS
Phase:	INVESTIGATION
Lat/Long:	33.422551 / -94.043096
Lat/Long (deg):	33.422551 / -94.043096
Acres:	0.89
TCEQ Region:	5
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	CITY OF TEXARKANA
Applicant Title:	BROWNFIELD PROGRAM MANAGER
Applicant Address:	PO BOX 1967
Applicant City,St,Zip:	TEXARKANA, TX 75504
Applicant Phone:	903-798-3934
Applicant Fax:	903-798-3913
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported

GRIM HOTEL (Continued) **S119135219**

Conditional Or Final Certificate: Not reported
Institutional Controls: Not reported
Type Remedy: Not reported

A3 Target Property **HOTEL GRIM** **US BROWNFIELDS** **1018163870**
301 N. STATE LINE AVENUE **N/A**
TEXARKANA, TX 75501

Site 3 of 5 in cluster A

Actual: 316 ft.

US BROWNFIELDS:

Property Name:	HOTEL GRIM
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	03840008900
Parcel size:	.89
Latitude:	33.4225508
Longitude:	-94.0431149
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	208665
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F20201
Start Date:	06/09/2014 00:00:00
Ownership Entity:	Private
Completion Date:	09/18/2014 00:00:00
Current Owner:	Rivergate Property, LLC
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N

HOTEL GRIM (Continued) **1018163870**

State/tribal program date:	12/30/2016 00:00:00
State/tribal program ID:	BSA G180
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.89
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported

HOTEL GRIM (Continued) **1018163870**

Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Y
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Y
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site is a 0.89 acre parcel with an approximate 135,000 sf eight-story former hotel, Hotel Grim, with a basement. The structure sits on the southern portion of the site with the northern portion of the parcel containing concrete building pads associated with former structures and a vacant lot enclosed by chain-link fencing. The hotel is boarded up and the site is currently vacant.
Below Poverty Number:	329
Below Poverty Percent:	19.3%
Meidan Income:	9972
Meidan Income Number:	516
Meidan Income Percent:	30.3%
Vacant Housing Number:	121
Vacant Housing Percent:	30.9%
Unemployed Number:	70
Unemployed Percent:	4.1%

Property Name:	HOTEL GRIM
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	03840008900
Parcel size:	.89
Latitude:	33.4225508
Longitude:	-94.0431149
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	208665
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported

HOTEL GRIM (Continued) **1018163870**

Cleanup Funding Source:	Not reported
Assessment Funding:	41575
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F20201
Start Date:	01/28/2015 00:00:00
Ownership Entity:	Private
Completion Date:	05/27/2015 00:00:00
Current Owner:	Rivergate Property, LLC
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	12/30/2016 00:00:00
State/tribal program ID:	BSA G180
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported

HOTEL GRIM (Continued) **1018163870**

Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.89
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Y
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Y
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site is a 0.89 acre parcel with an approximate 135,000 sf eight-story former hotel, Hotel Grim, with a basement. The structure sits on the southern portion of the site with the northern portion of the parcel containing concrete building pads associated with former structures and a vacant lot enclosed by chain-link fencing. The hotel is boarded up and the site is currently vacant.
Below Poverty Number:	329

HOTEL GRIM (Continued) **1018163870**

Below Poverty Percent:	19.3%
Meidan Income:	9972
Meidan Income Number:	516
Meidan Income Percent:	30.3%
Vacant Housing Number:	121
Vacant Housing Percent:	30.9%
Unemployed Number:	70
Unemployed Percent:	4.1%

Property Name:	HOTEL GRIM
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	03840008900
Parcel size:	.89
Latitude:	33.4225508
Longitude:	-94.0431149
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	208665
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	5275
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F67501
Start Date:	01/10/2017 00:00:00
Ownership Entity:	Private
Completion Date:	04/19/2017 00:00:00
Current Owner:	Rivergate Property, LLC
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	12/30/2016 00:00:00

HOTEL GRIM (Continued) **1018163870**

State/tribal program ID:	BSA G180
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.89
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported

HOTEL GRIM (Continued) **1018163870**

SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Y
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Y
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site is a 0.89 acre parcel with an approximate 135,000 sf eight-story former hotel, Hotel Grim, with a basement. The structure sits on the southern portion of the site with the northern portion of the parcel containing concrete building pads associated with former structures and a vacant lot enclosed by chain-link fencing. The hotel is boarded up and the site is currently vacant.
Below Poverty Number:	329
Below Poverty Percent:	19.3%
Meidan Income:	9972
Meidan Income Number:	516
Meidan Income Percent:	30.3%
Vacant Housing Number:	121
Vacant Housing Percent:	30.9%
Unemployed Number:	70
Unemployed Percent:	4.1%

A4 **TEXARKANA GAZZETTE-NEWS** **TX Ind. Haz Waste** **S102739457**
SSE **315 PINE ST** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.007 mi.
35 ft. **Site 4 of 5 in cluster A**

Relative: Ind. Haz Waste:
Lower

Actual: Registration Number:	31566
313 ft. Registration Initial Notification Date:	09/13/1979
Registration Last Amendment Date:	08/11/1998
EPA Identification:	Not reported
Primary NAICS Code:	511110
Status Change Date:	19790913
Land Type:	Not reported
Description of Facility Site Location:	315 Pine St, Texarkana, TX
Site Primary Standard Industrial Code:	Not reported
Site Primary SIC Description:	Not reported
Registration is Generator of Waste:	Yes
Registration is Receivers of Waste:	No
Registration is Transporter of Waste:	No
Registration is Transfer Facility:	No

TEXARKANA GAZZETTE-NEWS (Continued) **S102739457**

Facility is STEERS Reporter: No
Reqired to Submit Annual Waste Summary: No
Facility Involved In Recycling: No
Revcr Has Monthly Reporting Requirement: 0
Mexican Facility: Not reported
Type of Generator: Not reported
TNRCC Region: Not reported
Company Name: TEXARKANA GAZETTE-NEWS
Contact Name: GENE FIELDS
Contact Telephone Number: 214-7943311
Mailing Address: PO BOX 621
Mailing Address2: Not reported
Mailing City,St,Zip: TEXARKANA, TX 755040621
Mailing County: UNITED STATES
Facility Country: UNITED STATES
TNRCC Facility ID: 9119
Site Owner Tax ID: 0
Site Location Latitude: -00.000
Site Location Longitude: -000.000
Last Update to NOR Data: 20100604
Ind. waste permit Number: Not reported
Mun waste permit Number: Not reported
Non Notifier: No

Business Records Not Found for this RegNo/Year:

Owner:
Owner Mailing Address: PO BOX 621
Owner Mailing Address2: Not reported
Owner Mailing Address3: Not reported
Owner City,St,Zip: TEXARKANA, TX 75504 0621
Owner Country: UNITED STA
Owner Phone Number: 1-214-7943311
Owner Fax Number: Not reported
Owner Email Address: Not reported
Owner Business Type: Unknown
Owner Tax Id: Not reported
Owner Bankruptcy Code: Not reported

Operator Records Not Found for this RegNo/Year:

Contact:
Contact Name: GENE FIELDS
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: PO BOX 621
Contact Address2: Not reported
Conact City,St,Zip: TEXARKANA, TX 75504 0621
Contact Phone: 1-214-7943311
Contact Fax: Not reported
Contact Email: Not reported

Contact:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: PO BOX 621
Contact Address2: Not reported
Conact City,St,Zip: TEXARKANA, TX 75504 0621
Contact Phone: 1-214-7943311

TEXARKANA GAZZETTE-NEWS (Continued) **S102739457**

Contact Fax: Not reported
Contact Email: Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:
Receiver Type: Not reported
Transporter for hire: 0
Transport own waste: 0
Eq 01, if transport waste type = 1: Not reported
Eq 02, if transport waste type = 2: Not reported
Eq 03, if transport waste type = 3: Not reported
Eq 04, if transport waste type = H: Not reported
Target TCEQ unique facid for discarded(merged) facility: Not reported

Waste:
Waste ID: 259454
Waste Description: Not reported
Desc of Waste: Not reported
Texas Waste Code: Not reported
Texas Waste Code 2: B2LX219H
Waste Code Status: Not reported
Waste Form: Not reported
Waste Classification: H
Waste is Radioactive: No
Waste Treated Off Site: Not reported
Standard Industrial Classification: Not reported
Primary Source: Not reported
Primary Measurenent Point: Not reported
Primary Origin: Not reported
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: No
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen.: Not reported
EPA Haz Waste: Not reported

Waste:
Waste ID: 136087
Waste Description: Waste cleaning solvent/ NAPTHA. Generated from parts cleaning operation. Initia
Desc of Waste: Not reported
Texas Waste Code: Not reported
Texas Waste Code 2: 3004203H
Waste Code Status: INACTIVE
Waste Form: Not reported
Waste Classification: H
Waste is Radioactive: No
Waste Treated Off Site: 1
Standard Industrial Classification: Not reported
Primary Source: Not reported
Primary Measurenent Point: Not reported
Primary Origin: Not reported
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: No
Company Waste ID: Not reported

TEXARKANA GAZZETTE-NEWS (Continued) **S102739457**

Primary NAICS Code:	511110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen.:	UNKNOWN
EPA Haz Waste:	Not reported

A5 **SEARS BUILDING** **US BROWNFIELDS** **1014350787**
SSW **301 PINE STREET X** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.021 mi.
110 ft. **Site 5 of 5 in cluster A**

Relative: **Lower**
Actual: **314 ft.**

US BROWNFIELDS:

Property Name:	SEARS BUILDING
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	03840007900
Parcel size:	.16
Latitude:	33.4223755
Longitude:	-94.0434753
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94605
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2600
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F20201
Start Date:	07/31/2015 00:00:00
Ownership Entity:	Private
Completion Date:	12/02/2015 00:00:00
Current Owner:	David Potter
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported

SEARS BUILDING (Continued) **1014350787**

IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported

SEARS BUILDING (Continued) **1014350787**

Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Large concrete and steel 3 story building with full basement that was the former Sears Building in downtown Texarkana, Texas.
Below Poverty Number:	327
Below Poverty Percent:	19.3%
Meidan Income:	10200
Meidan Income Number:	509
Meidan Income Percent:	30.1%
Vacant Housing Number:	120
Vacant Housing Percent:	31.1%
Unemployed Number:	70
Unemployed Percent:	4.1%
Property Name:	SEARS BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	03840007900
Parcel size:	.16
Latitude:	33.4223755
Longitude:	-94.0434753
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94605
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3000
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement

SEARS BUILDING (Continued) **1014350787**

Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	12/10/2008 00:00:00
Ownership Entity:	Private
Completion Date:	01/06/2009 00:00:00
Current Owner:	David Potter
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported

SEARS BUILDING (Continued) **1014350787**

Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Large concrete and steel 3 story building with full basement that was the former Sears Building in downtown Texarkana, Texas.
Below Poverty Number:	327
Below Poverty Percent:	19.3%
Meidan Income:	10200
Meidan Income Number:	509
Meidan Income Percent:	30.1%
Vacant Housing Number:	120
Vacant Housing Percent:	31.1%
Unemployed Number:	70

SEARS BUILDING (Continued) **1014350787**

Unemployed Percent: 4.1%

B6 **EXIMIUS PARKING LOT** **US BROWNFIELDS** **1016159148**
SSW **211 WEST 3RD STREET** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.039 mi.
206 ft. **Site 1 of 3 in cluster B**

Relative: **Lower**
Actual: **313 ft.**

US BROWNFIELDS:

Property Name:	EXIMIUS PARKING LOT
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7952
Parcel size:	.16
Latitude:	33.422313
Longitude:	-94.0435914
HCM Label:	Address Matching-House Number
Map Scale:	1
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133210
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F19501
Start Date:	06/25/2012 00:00:00
Ownership Entity:	Not reported
Completion Date:	11/05/2013 00:00:00
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported

EXIMIUS PARKING LOT (Continued) **1016159148**

State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	.16
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported

EXIMIUS PARKING LOT (Continued) **1016159148**

Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	326
Below Poverty Percent:	19.4%
Meidan Income:	10144
Meidan Income Number:	506
Meidan Income Percent:	30.1%
Vacant Housing Number:	119
Vacant Housing Percent:	31.1%
Unemployed Number:	70
Unemployed Percent:	4.2%

Property Name:	EXIMIUS PARKING LOT
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7952
Parcel size:	.16
Latitude:	33.422313
Longitude:	-94.0435914
HCM Label:	Address Matching-House Number
Map Scale:	1
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133210
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported

EXIMIUS PARKING LOT (Continued) **1016159148**

Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F19501
Start Date:	07/05/2011 00:00:00
Ownership Entity:	Not reported
Completion Date:	08/31/2011 00:00:00
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported

EXIMIUS PARKING LOT (Continued) **1016159148**

Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	.16
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	326
Below Poverty Percent:	19.4%
Meidan Income:	10144
Meidan Income Number:	506
Meidan Income Percent:	30.1%
Vacant Housing Number:	119
Vacant Housing Percent:	31.1%
Unemployed Number:	70
Unemployed Percent:	4.2%

B7 **EXIMIUS PARKING GARAGE** **US BROWNFIELDS** **1016159147**
South **217-219 PINE STREET** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.044 mi.
233 ft. **Site 2 of 3 in cluster B**

Relative: **Lower**

Actual: **311 ft.**

US BROWNFIELDS:

Property Name:	EXIMIUS PARKING GARAGE
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7937
Parcel size:	.32
Latitude:	33.4217942
Longitude:	-94.0431108
HCM Label:	Address Matching-House Number
Map Scale:	1
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133209
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	52968
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F19501
Start Date:	06/25/2012 00:00:00
Ownership Entity:	Private
Completion Date:	11/05/2013 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported

EXIMIUS PARKING GARAGE (Continued) **1016159147**

Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

EXIMIUS PARKING GARAGE (Continued) **1016159147**

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	325
Below Poverty Percent:	19.4%
Meidan Income:	10102
Meidan Income Number:	504
Meidan Income Percent:	30.1%
Vacant Housing Number:	119
Vacant Housing Percent:	31.2%
Unemployed Number:	69
Unemployed Percent:	4.1%

Property Name:	EXIMIUS PARKING GARAGE
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7937
Parcel size:	.32
Latitude:	33.4217942
Longitude:	-94.0431108
HCM Label:	Address Matching-House Number
Map Scale:	1
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133209
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous

EXIMIUS PARKING GARAGE (Continued) **1016159147**

Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F19501
Start Date:	07/06/2011 00:00:00
Ownership Entity:	Private
Completion Date:	08/25/2011 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported

EXIMIUS PARKING GARAGE (Continued) **1016159147**

Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	325
Below Poverty Percent:	19.4%
Meidan Income:	10102
Meidan Income Number:	504
Meidan Income Percent:	30.1%
Vacant Housing Number:	119
Vacant Housing Percent:	31.2%
Unemployed Number:	69
Unemployed Percent:	4.1%

C8 **REGIONS BANK-TEXARKANA VCP SIT** **AR VCP** **S108195006**
East **300 OLIVE ST** **AR ASBESTOS** **N/A**
< 1/8 **TEXARKANA, AR 71854** **AR ENF**
0.045 mi.
240 ft. **Site 1 of 2 in cluster C**

Relative:
Lower

Actual:
311 ft.

VCP:

AFIN Num:	46-00566
District:	4
Project Status:	Complete

ASBESTOS:

Building Owner:	American Financial Realty Trust
Location Specifics:	Bank
Contractor:	AMX Environmental, Ltd.
Type:	Renovation
Rating:	Low
Postmark:	09/15/2006
Start Date:	09/27/2006
Start Month:	M 9
Start Year:	Y 2006
End Date:	09/29/2006
Revisions:	Not reported
Fees Paid:	$100.00
Initails:	SKA
Notice of Deficiency:	No
Key:	2333
Status:	Not reported

ENFORCEMENT:

Afin or Facility ID:	4600566
Afindash:	46-00566
Type:	IA
Media:	Haz Waste
CAO Executed Date:	03/28/2008
Case Type Description:	Implementing Agreement
Media Description:	HW
Site ID:	5835
Case Title:	Regions Bank - Texarkana
Case Contact First Name:	Holcomb
Case Contact Last Name:	Regions Financial Corp
Case Company Name:	Joe
Case Contact Address One:	250 Riverchase Parkway
Case Contact Address Two:	South Building 6th Floor
Case Contact City:	Birmingham
Case Contact State:	AL
Case Contact Zip:	35244
Violation Comments:	Not reported

B9 **CAPITAL ONE BUILDING** **US BROWNFIELDS** **1016139313**
South **100 WEST BROAD** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.062 mi.
329 ft. **Site 3 of 3 in cluster B**

Relative: **Lower**

Actual: **310 ft.**

US BROWNFIELDS:

Property Name:	CAPITAL ONE BUILDING
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7939
Parcel size:	.22
Latitude:	33.4215765
Longitude:	-94.0433297
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133211
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F19501
Start Date:	07/05/2011 00:00:00
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported

CAPITAL ONE BUILDING (Continued) **1016139313**

Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

CAPITAL ONE BUILDING (Continued) **1016139313**

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	302
Below Poverty Percent:	19.2%
Meidan Income:	9498
Meidan Income Number:	472
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	30.9%
Unemployed Number:	66
Unemployed Percent:	4.2%

C10 **HELMS LIQUOR STORE** **AR UST** **U002273631**
East **218 EAST 3RD STREET** **N/A**
< 1/8 **TEXARKANA, AR 75502**
0.066 mi.
351 ft. **Site 2 of 2 in cluster C**

Relative: UST:
Lower

Actual:
311 ft.

Facility Id:	46001626
ADEQ Facility ID:	46-00515
Active Site:	Not reported
Above Ground:	Not reported
Below Ground:	Yes
Aboveground in Use:	UST
Underground in Use:	UST
Date Reg Cert Issued:	08/09/1995
Lust Flag:	UST
Leak ID Number:	Not reported
Date Received:	08/01/1995
Location SIC:	Not reported
Federal Flag:	Yes
Contact Name:	BECKY BOYD
Contact Title:	OWNER
Contact Phone:	501-772-6776
Certified Name:	JON FOUNTAIN
Certified Title:	AUTHORIZED REP
Date Signed:	07/28/1995
Amended:	No
No Bill:	Not reported
Facility Entry Clerk:	MARSH
Facility Update Date:	Not reported

HELMS LIQUOR STORE (Continued) **U002273631**

Facility Update Clerk: Not reported
Latitude: Not reported
Longitude: Not reported

Owner:
Owner ID: 006893
Owner Name: BOYD, BECKY
Owner Address: 1301 GRAND AVE
Owner City,St,Zip: TEXARKANA, TX 75502
Owner County: BOWIE
Owner Phone: 5017726776
Owner Type: Private Industry

Tank Info:
Facility ID: 46001626
Record Created By: MARSH
Record Created Date: 08/07/1995
Record Modified By: MARSH
Record Modified Date: 8/16/1995
Site Assessment Date: Not reported
Site Assessment Leak: No
Certificate of Compliance Final Test Date: Not reported
Certificate of Compliance Test Company License: Not reported
Certificate of Compliance Tester License: Not reported
Certificate of Compliance Installation Date: Not reported
Certificate of Compliance Install Company License: Not reported
Certificate of Compliance Installer License: Not reported

Tank ID: 1
Tank Status: Permanently Out of Service 08/08/1995
Install Date: Not reported
Tank Contents: Gasoline
Cerclis Name: Not reported
Tank Material: Unknown
GIS Location: Not reported
Federal Flag: Not reported
Hazardous: Not reported
Capacity in Gallons: 1000
Number of Compartments: 1
Decode for Tstatus: Permanently Out of Use
Release Detection: Unknown
Release Detection Install Date: Not reported
Tank External Corrosion Protection: Unknown
Tank Ext Corrosion Protection Install Date: Not reported
Pipe Material: Unknown
Pipe Type: Unknown
Pipe Release Detection: Unknown
Pipe Corrosion Protection: Unknown
Tank Spill and Overfill Protection: Unknown
Pipe Repaired: Not reported
Pipe Corrosion Protection: Unknown
Corrosion Protection: Not reported
Spill and Overflow: Not reported
Release Detection: Not reported
Tank Comments: Not reported

Facility ID: 46001626

HELMS LIQUOR STORE (Continued) **U002273631**

Record Created By: MARSH
Record Created Date: 08/07/1995
Record Modified By: MARSH
Record Modified Date: 8/16/1995
Site Assessment Date: Not reported
Site Assessment Leak: No
Certificate of Compliance Final Test Date: Not reported
Certificate of Compliance Test Company License: Not reported
Certificate of Compliance Tester License: Not reported
Certificate of Compliance Installation Date: Not reported
Certificate of Compliance Install Company License: Not reported
Certificate of Compliance Installer License: Not reported

Tank ID: 2
Tank Status: Permanently Out of Service 08/08/1995
Install Date: Not reported
Tank Contents: Used Oil
Cerclis Name: Not reported
Tank Material: Steel
GIS Location: Not reported
Federal Flag: Not reported
Hazardous: Not reported
Capacity in Gallons: 1000
Number of Compartments: 1
Decode for Tstatus: Permanently Out of Use
Release Detection: Unknown
Release Detection Install Date: Not reported
Tank External Corrosion Protection: Unknown
Tank Ext Corrosion Protection Install Date: Not reported
Pipe Material: Unknown
Pipe Type: Unknown
Pipe Release Detection: Unknown
Pipe Corrosion Protection: Unknown
Tank Spill and Overfill Protection: Unknown
Pipe Repaired: Not reported
Pipe Corrosion Protection: Unknown
Corrosion Protection: Not reported
Spill and Overflow: Not reported
Release Detection: Not reported
Tank Comments: Not reported

Facility ID: 46001626
Record Created By: MARSH
Record Created Date: 08/07/1995
Record Modified By: MARSH
Record Modified Date: 8/16/1995
Site Assessment Date: Not reported
Site Assessment Leak: No
Certificate of Compliance Final Test Date: Not reported
Certificate of Compliance Test Company License: Not reported
Certificate of Compliance Tester License: Not reported
Certificate of Compliance Installation Date: Not reported
Certificate of Compliance Install Company License: Not reported
Certificate of Compliance Installer License: Not reported

Tank ID: 3
Tank Status: Permanently Out of Service 08/08/1995

HELMS LIQUOR STORE (Continued) **U002273631**

Install Date:	Not reported
Tank Contents:	Gasoline
Cerclis Name:	Not reported
Tank Material:	Unknown
GIS Location:	Not reported
Federal Flag:	Not reported
Hazardous:	Not reported
Capacity in Gallons:	1000
Number of Compartments:	1
Decode for Tstatus:	Permanently Out of Use
Release Detection:	Unknown
Release Detection Install Date:	Not reported
Tank External Corrosion Protection:	Unknown
Tank Ext Corrosion Protection Install Date:	Not reported
Pipe Material:	Unknown
Pipe Type:	Unknown
Pipe Release Detection:	Unknown
Pipe Corrosion Protection:	Unknown
Tank Spill and Overfill Protection:	Unknown
Pipe Repaired:	Not reported
Pipe Corrosion Protection:	Unknown
Corrosion Protection:	Not reported
Spill and Overflow:	Not reported
Release Detection:	Not reported
Tank Comments:	Not reported

Facility ID:	46001626
Record Created By:	MARSH
Record Created Date:	08/07/1995
Record Modified By:	MARSH
Record Modified Date:	8/16/1995
Site Assessment Date:	Not reported
Site Assessment Leak:	No
Certificate of Compliance Final Test Date:	Not reported
Certificate of Compliance Test Company License:	Not reported
Certificate of Compliance Tester License:	Not reported
Certificate of Compliance Installation Date:	Not reported
Certificate of Compliance Install Company License:	Not reported
Certificate of Compliance Installer License:	Not reported

Tank ID:	4
Tank Status:	**Permanently Out of Service 08/08/1995**
Install Date:	Not reported
Tank Contents:	Gasoline
Cerclis Name:	Not reported
Tank Material:	Unknown
GIS Location:	Not reported
Federal Flag:	Not reported
Hazardous:	Not reported
Capacity in Gallons:	1000
Number of Compartments:	1
Decode for Tstatus:	Permanently Out of Use
Release Detection:	Unknown
Release Detection Install Date:	Not reported
Tank External Corrosion Protection:	Unknown
Tank Ext Corrosion Protection Install Date:	Not reported
Pipe Material:	Unknown

HELMS LIQUOR STORE (Continued) **U002273631**

Pipe Type:	Unknown
Pipe Release Detection:	Unknown
Pipe Corrosion Protection:	Unknown
Tank Spill and Overfill Protection:	Unknown
Pipe Repaired:	Not reported
Pipe Corrosion Protection:	Unknown
Corrosion Protection:	Not reported
Spill and Overflow:	Not reported
Release Detection:	Not reported
Tank Comments:	Not reported

D11 **CAPITAL ONE BUILDING** **US BROWNFIELDS 1012098746**
South **100-104 BROAD STREET** **FINDS N/A**
< 1/8 **TEXARKANA, TX 75501**
0.081 mi.
428 ft. **Site 1 of 7 in cluster D**

Relative: **Lower**
Actual: **309 ft.**

US BROWNFIELDS:

Property Name:	HIBERNIA NATIONAL BANK
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.32
Latitude:	33.251680
Longitude:	-94.235200
HCM Label:	GPS (Pseudo Range) Differential
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	87301
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4274
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97642001
Start Date:	06/03/2008 00:00:00
Ownership Entity:	Private
Completion Date:	08/25/2008 00:00:00
Current Owner:	Capital One Bank
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported

CAPITAL ONE BUILDING (Continued) **1012098746**

Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.32
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

CAPITAL ONE BUILDING (Continued) **1012098746**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Y
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	51,480-square foot, eight story office building. Past uses included a bank, drug store, jewelry store, and a book store.
Below Poverty Number:	302
Below Poverty Percent:	19.2%
Meidan Income:	9498
Meidan Income Number:	472
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	30.9%
Unemployed Number:	66
Unemployed Percent:	4.2%

FINDS:

Registry ID: 110038764325

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

CAPITAL ONE BUILDING (Continued) **1012098746**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

E12 **DOWNTOWN STORAGE CO** **EDR Hist Auto** **1020196890**
SE **215-21 OLIVE** **N/A**
< 1/8 **TEXARKANA, AR 75501**
0.081 mi.
429 ft. **Site 1 of 2 in cluster E**

Relative: EDR Hist Auto
Lower

Actual:
306 ft.

Year:	Name:	Type:
1969	DOWNTOWN STORAGE CO	Not reported
1970	DOWNTOWN STORAGE CO	Not reported
1971	DOWNTOWN STORAGE CO	Not reported
1972	DOWNTOWN STORAGE CO	Not reported
1973	DOWNTOWN STORAGE CO	Not reported
1974	DOWNTOWN STORAGE CO	Not reported
1975	DOWNTOWN STORAGE CO	Not reported

D13 **KRESS BUILDING ES#16-612** **TX BROWNFIELDS** **S110119989**
South **116 W BROAD ST** **TX ASBESTOS** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.088 mi.
466 ft. **Site 2 of 7 in cluster D**

Relative: BROWNFIELDS:
Lower

Actual:
312 ft.

BF Site Assessment Received:	08/21/2009
PCA number:	78226
BF Grant Number:	G113
Facility Type:	Municipality
Lead Type:	Owner
Project manager:	KLIVINGS
Phase:	COMPLETED
Lat/Long:	33.251567 / -94.237900
Lat/Long (deg):	33.251567 / -94.237900
Acres:	0.15
TCEQ Region:	05
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Texarkana Texas
Applicant Title:	Executive Director
Applicant Address:	220 Texas Boulevard
Applicant City,St,Zip:	Texarkana, TX 75501
Applicant Phone:	903-798-3903
Applicant Fax:	903-798-3913
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported

KRESS BUILDING ES#16-612 (Continued) **S110119989**

LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported

ASBESTOS:

Date of inspection:	Not reported
Reason for Inspection:	LARRY SNODGRASS
Violation:	Not reported
Complaint Date:	09/29/2017
Notification Number:	2017003529
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	04/28/2017
Certification Statement Phone:	903-534-5001
Is The Facility a School or K-12?:	N
Region:	04
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	Y
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

KRESS BUILDING ES#16-612 (Continued) **S110119989**

Start Date: 05/15/2017

D14 **VACANT KRESS BUILDING** **US BROWNFIELDS** **1011860856**
South **116 W. BROAD STREET** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.088 mi.
466 ft. **Site 3 of 7 in cluster D**

Relative: **Lower**

Actual: **312 ft.**

US BROWNFIELDS:

Property Name:	VACANT KRESS BUILDING
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.15
Latitude:	33.4213
Longitude:	-94.0439
HCM Label:	Not reported
Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69901
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3292
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	TCEQ
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	96671601
Start Date:	10/01/2009 00:00:00
Ownership Entity:	Government
Completion Date:	02/01/2010 00:00:00
Current Owner:	Bi-State Women’s Center, Inc.
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	08/21/2009 00:00:00
State/tribal program ID:	G113

VACANT KRESS BUILDING (Continued) **1011860856**

State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.15
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported

VACANT KRESS BUILDING (Continued) **1011860856**

Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Reconstructed after a fire in 1933. Operated as S.H. Kress & Co. department store until the 1970s.
Below Poverty Number:	302
Below Poverty Percent:	19.2%
Meidan Income:	9483
Meidan Income Number:	471
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	30.9%
Unemployed Number:	66
Unemployed Percent:	4.2%
Property Name:	VACANT KRESS BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.15
Latitude:	33.4213
Longitude:	-94.0439
HCM Label:	Not reported
Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69901
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

VACANT KRESS BUILDING (Continued) **1011860856**

Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	11/22/2006 00:00:00
Ownership Entity:	Government
Completion Date:	03/21/2007 00:00:00
Current Owner:	Bi-State Women's Center, Inc.
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	08/21/2009 00:00:00
State/tribal program ID:	G113
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported

VACANT KRESS BUILDING (Continued) **1011860856**

Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.15
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Reconstructed after a fire in 1933. Operated as S.H. Kress & Co. department store until the 1970s.
Below Poverty Number:	302
Below Poverty Percent:	19.2%
Meidan Income:	9483
Meidan Income Number:	471
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	30.9%
Unemployed Number:	66
Unemployed Percent:	4.2%

D15 **KRESS BUILDING** **TX BROWNFIELDS** **S107632290**
South **116 W BROAD ST** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.088 mi.
466 ft. **Site 4 of 7 in cluster D**

Relative: **Lower**
Actual: **312 ft.**

BROWNFIELDS:

BF Site Assessment Received:	12/15/2005
PCA number:	78226
BF Grant Number:	G093
Facility Type:	Abandoned Building
Lead Type:	Owner
Project manager:	KLIVINGS
Phase:	REJECTED
Lat/Long:	33.140763 / -96.107744
Lat/Long (deg):	33.140763 / -96.107744
Acres:	1
TCEQ Region:	05
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	Ark-Tex Council of Governments
Applicant Title:	Environmental Resource Planner
Applicant Address:	P.O. Box 5307
Applicant City,St,Zip:	Texarkana, TX 75505-5307
Applicant Phone:	903-832-8636
Applicant Fax:	903-832-2672
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported

E16 **VACANT KLINE BAKERS BUILDING** **US BROWNFIELDS** **1016349498**
ESE **207 EAST BROAD STREET** **FINDS** **N/A**
< 1/8 **TEXARKANA, AR 71854**
0.089 mi.
470 ft. **Site 2 of 2 in cluster E**

Relative: **Lower**
Actual: **306 ft.**

US BROWNFIELDS:

Property Name:	VACANT KLINE BAKERS BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	1013450
Parcel size:	.07
Latitude:	33.42236
Longitude:	-94.04142
HCM Label:	Not reported

VACANT KLINE BAKERS BUILDING (Continued) **1016349498**

Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69921
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	10/31/2007 00:00:00
Ownership Entity:	Private
Completion Date:	12/20/2007 00:00:00
Current Owner:	Mr. Clifton A. Jones
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported

VACANT KLINE BAKERS BUILDING (Continued) **1016349498**

Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.07
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported

VACANT KLINE BAKERS BUILDING (Continued) **1016349498**

Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	A three-story building originally operated as bakery and later as various retail stores. Currently unoccupied and in extreme state of disrepair.
Below Poverty Number:	330
Below Poverty Percent:	19.5%
Meidan Income:	10231
Meidan Income Number:	512
Meidan Income Percent:	30.2%
Vacant Housing Number:	120
Vacant Housing Percent:	31.1%
Unemployed Number:	69
Unemployed Percent:	4.1%

FINDS:

Registry ID: 110038760542

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

F17 **FORMER TWIN CITY CAB** **TX UST** **U003406878**
WSW **317 MAIN ST** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.091 mi.
478 ft. **Site 1 of 3 in cluster F**

Relative: UST:
Lower

Actual: AI Number:	57640
313 ft. Facility Type:	FLEET REFUELING
Facility Begin Date:	02/26/1991
Facility Status:	INACTIVE
Additional ID:	302370332003197
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75503
Contact Name/Title:	,
Contact Organization Name:	FORMER TWIN CITY CAB COMPANY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9038322000

FORMER TWIN CITY CAB (Continued) **U003406878**

Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/12/1991
Signature Name/Title On Earliest Reg Form:	BURNEY JONES,VP
Application Received Date On Earliest Reg Form:	02/21/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602256695
Owner Last Name:	RTC SECURITY FEDERAL SAVINGS
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	329370312003197
Additional ID:	302370332003197
AI Number:	57640
Owner Effective Begin Date:	02/26/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	02/21/1991
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	138116
Facility ID:	87689
Ai Number:	57640
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

FORMER TWIN CITY CAB (Continued) **U003406878**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	01/24/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	148752
UST ID:	138116
AI Number:	57640
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

FORMER TWIN CITY CAB (Continued) **U003406878**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	RTC SECURITY FEDERAL SAVINGS
Contact Mailing Address (Delivery):	5080 SPECTRUM DR STE 1000E
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ADDISON, TX 75001 6444
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87689
Additional ID:	302370332003197
Princ ID:	329370312003197
AI Number:	57640
Facility Name:	FORMER TWIN CITY CAB
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

F18 **MAIN ST. & TEXAS BLVD. PARKING LOTS** **US BROWNFIELDS** **1018273264**
SW **301 MAIN STREET AND 302 TEXAS BOULEVARD** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.091 mi.
481 ft. **Site 2 of 3 in cluster F**

Relative: **Lower**
Actual: **313 ft.**

US BROWNFIELDS:

Property Name:	MAIN ST. & TEXAS BLVD. PARKING LOTS
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.71
Latitude:	33.42188490965984
Longitude:	-94.04533298672481
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	185042
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4323
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F67501
Start Date:	11/18/2014 00:00:00
Ownership Entity:	Government
Completion Date:	12/12/2014 00:00:00
Current Owner:	City of Texarkana, Texas
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	10/14/2014 00:00:00
State/tribal program ID:	G168
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported

MAIN ST. & TEXAS BLVD. PARKING LOTS (Continued) **1018273264**

Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.71
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	.71
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

MAIN ST. & TEXAS BLVD. PARKING LOTS (Continued) **1018273264**

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	No structures are located at the paved site. Historical documents indicate the site has previously consisted of residential structures, outbuildings, a burned area, opera house, stables, hotel, movie theatre, parking lots, and stores. The City of Texarkana, Texas, indicated that they have owned the site since January 14, 1981 and 301 Main St. used to be a pharmacy and 302 Texas Blvd. used to be the Bowie County Economic Advancement Organization office.
Below Poverty Number:	613
Below Poverty Percent:	28.9%
Meidan Income:	4150
Meidan Income Number:	916
Meidan Income Percent:	43.2%
Vacant Housing Number:	21
Vacant Housing Percent:	2.9%
Unemployed Number:	127
Unemployed Percent:	6.0%

D19 **VACANT RUTH BUILDING** **US BROWNFIELDS** **1011855551**
South **120 WEST BROAD STREET** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.093 mi.
491 ft. **Site 5 of 7 in cluster D**

Relative: **Lower**

Actual: **312 ft.**

US BROWNFIELDS:

Property Name:	VACANT RUTH BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	3840010400
Parcel size:	.07
Latitude:	33.4212
Longitude:	-94.0438
HCM Label:	Not reported
Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	74741
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported

VACANT RUTH BUILDING (Continued) **1011855551**

Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3200
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	01/23/2008 00:00:00
Ownership Entity:	Private
Completion Date:	02/21/2008 00:00:00
Current Owner:	Ms. Elnoria Ruth
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported

VACANT RUTH BUILDING (Continued) **1011855551**

Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.07
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	A two-story commercial structure located in downtown Texarkana. The structure is currently owned by Ms. Elnoria Ruth and primarily used for storage.
Below Poverty Number:	302
Below Poverty Percent:	19.2%

VACANT RUTH BUILDING (Continued) **1011855551**

Meidan Income:	9483
Meidan Income Number:	471
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	30.9%
Unemployed Number:	66
Unemployed Percent:	4.2%

G20 **GARNER CLEANERS** **EDR Hist Cleaner** **1019993918**
WNW **424 MAIN ST** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.095 mi.
500 ft. **Site 1 of 2 in cluster G**

Relative: EDR Hist Cleaner
Lower

Actual: **309 ft.**

Year:	Name:	Type:
1969	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1970	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1971	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1972	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1973	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1974	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1975	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1977	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1978	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1979	GARNER CLEANERS	Drycleaning Plants, Except Rugs
1980	GARNER CLEANERS	Drycleaning Plants, Except Rugs

G21 **GARNER CLEANERS** **TX DRYCLEANERS** **S108995238**
WNW **424 MAIN ST** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.095 mi.
500 ft. **Site 2 of 2 in cluster G**

Relative: DRYCLEANERS:
Lower

Actual: **309 ft.**

RN Number:	RN103959565
Region:	REGION 05 - TYLER
CN Number:	CN604733931
DCR Number:	DCR11691
AR Number:	24007188
Principal Name:	COBEL INVESTMENT GROUP LLC
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	REMAXCUSTOMHOMES@YAHOO.COM
Phone Number:	214 9245062
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	1300
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

GARNER CLEANERS (Continued) **S108995238**

RN Number:	RN103959565
Region:	REGION 05 - TYLER
CN Number:	CN604733931
DCR Number:	DCR11691
AR Number:	24007188
Principal Name:	COBEL INVESTMENT GROUP LLC
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	REMAXCUSTOMHOMES@YAHOO.COM
Phone Number:	214 9245062
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	330
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

RN Number:	RN103959565
Region:	5
CN Number:	CN602460115
DCR Number:	Not reported
AR Number:	24000910
Principal Name:	MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $200,000

RN Number:	RN103959565
Region:	5
CN Number:	CN602460115
DCR Number:	Not reported
AR Number:	24000910
Principal Name:	MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	2860

GARNER CLEANERS (Continued) **S108995238**

Part Stat:	NO
Gross Receipts:	> $200,000
RN Number:	RN103959565
Region:	5
CN Number:	CN602460115
DCR Number:	Not reported
AR Number:	24000910
Principal Name:	MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	1430
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS
RN Number:	RN103959565
Region:	5
CN Number:	CN602460115
DCR Number:	Not reported
AR Number:	24000910
Principal Name:	MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	2805
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS
RN Number:	RN103959565
Region:	5
CN Number:	CN602460115
DCR Number:	Not reported
AR Number:	24000910
Principal Name:	MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

GARNER CLEANERS (Continued) **S108995238**

Fiscal Year: FY2008
Solvent: PETROLEUM
Gallons: 1650
Part Stat: NO
Gross Receipts: $150,000 OR LESS

RN Number: RN103959565
Region: 5
CN Number: CN602460115
DCR Number: Not reported
AR Number: 24000910
Principal Name: MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1: 424 MAIN ST
Bill Addr2: Not reported
Bill City/State/Zip: TEXARKANA, TX 75501 5502
EMail: Not reported
Phone Number: 903 4907338
Site Name: GARNER CLEANERS
Site Type: FACILITY REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2009
Solvent: PETROLEUM
Gallons: 1430
Part Stat: NO
Gross Receipts: $150,000 OR LESS

RN Number: RN103959565
Region: 5
CN Number: CN602460115
DCR Number: Not reported
AR Number: 24000910
Principal Name: MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1: 424 MAIN ST
Bill Addr2: Not reported
Bill City/State/Zip: TEXARKANA, TX 75501 5502
EMail: Not reported
Phone Number: 903 4907338
Site Name: GARNER CLEANERS
Site Type: FACILITY REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2010
Solvent: PETROLEUM
Gallons: 1430
Part Stat: NO
Gross Receipts: $150,000 OR LESS

RN Number: RN103959565
Region: 5
CN Number: CN602460115
DCR Number: Not reported
AR Number: 24000910
Principal Name: MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1: 424 MAIN ST
Bill Addr2: Not reported
Bill City/State/Zip: TEXARKANA, TX 75501 5502
EMail: Not reported
Phone Number: 903 4907338

GARNER CLEANERS (Continued) **S108995238**

Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PETROLEUM
Gallons:	1320
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS
RN Number:	RN103959565
Region:	5
CN Number:	CN602460115
DCR Number:	Not reported
AR Number:	24000910
Principal Name:	MICHAEL ROY WILSON DBA GARNER CLEANERS
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	1320
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS
RN Number:	RN103959565
Region:	5
CN Number:	CN604253187
DCR Number:	Not reported
AR Number:	24006772
Principal Name:	ROBICO LLC
Bill Addr1:	424 MAIN ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5502
EMail:	Not reported
Phone Number:	903 4907338
Site Name:	GARNER CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	1320
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

D22
SSW
< 1/8
0.096 mi.
508 ft.

MABEL BRYAN MORRISS BUILDING
124 WEST BROAD STREET
TEXARKANA, TX 75501

Site 6 of 7 in cluster D

US BROWNFIELDS **1011855505**
N/A

Relative:
Lower

Actual:
312 ft.

US BROWNFIELDS:

Property Name:	MABEL BRYAN MORRISS BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.07
Latitude:	33.4212
Longitude:	-94.0438
HCM Label:	Not reported
Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69861
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	07/23/2007 00:00:00
Ownership Entity:	Private
Completion Date:	09/21/2007 00:00:00
Current Owner:	Mr. Thomas Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported

MABEL BRYAN MORRISS BUILDING (Continued) **1011855505**

Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y
Other contams found description:	Mold
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.07
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

MABEL BRYAN MORRISS BUILDING (Continued) **1011855505**

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	A two-story commercial structure constructed in approximately 1904. The structure is currently leased by the Bi-State Women's Center for office space.
Below Poverty Number:	302
Below Poverty Percent:	19.2%
Meidan Income:	9483
Meidan Income Number:	471
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	30.9%
Unemployed Number:	66
Unemployed Percent:	4.2%

H23 **TEX-REP** **US BROWNFIELDS** **1016139641**
SSW **213 MAIN STREET** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.098 mi.
520 ft. **Site 1 of 3 in cluster H**

Relative: US BROWNFIELDS:
Lower

Actual:
313 ft.

Property Name:	TEX-REP
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	03840011200
Parcel size:	.16
Latitude:	33.4214046
Longitude:	-94.04455300000001
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	151361
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300

TEX-REP (Continued) **1016139641**

Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F19501
Start Date:	01/20/2012 00:00:00
Ownership Entity:	Private
Completion Date:	04/25/2012 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y

TEX-REP (Continued) **1016139641**

Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site consists of a 0.16-acre parcel located at 213 Main Street in Texarkana, Bowie County, Texas. The parcel is developed with a two-story building which is adjoined to the Texarkana Repertory Company (theater) building in a manner typical of historic downtown development. The subject building is currently vacant and is being used as a storage facility for the above-mentioned theater. Historical information indicates the site and surrounding areas have historically consisted of commercial development. It appears the site was developed as an auto repair shop as early as 1924. The site has since been used

TEX-REP (Continued) **1016139641**

	for financial businesses, commercial shops, and theaters.
Below Poverty Number:	304
Below Poverty Percent:	19.1%
Meidan Income:	9580
Meidan Income Number:	476
Meidan Income Percent:	29.9%
Vacant Housing Number:	112
Vacant Housing Percent:	30.9%
Unemployed Number:	67
Unemployed Percent:	4.2%
Property Name:	TEX-REP
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	03840011200
Parcel size:	.16
Latitude:	33.4214046
Longitude:	-94.04455300000001
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	151361
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	29920
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F19501
Start Date:	05/31/2013 00:00:00
Ownership Entity:	Private
Completion Date:	03/24/2014 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported

TEX-REP (Continued) **1016139641**

IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported

TEX-REP (Continued) **1016139641**

Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site consists of a 0.16-acre parcel located at 213 Main Street in Texarkana, Bowie County, Texas. The parcel is developed with a two-story building which is adjoined to the Texarkana Repertory Company (theater) building in a manner typical of historic downtown development. The subject building is currently vacant and is being used as a storage facility for the above-mentioned theater. Historical information indicates the site and surrounding areas have historically consisted of commercial development. It appears the site was developed as an auto repair shop as early as 1924. The site has since been used for financial businesses, commercial shops, and theaters.
Below Poverty Number:	304
Below Poverty Percent:	19.1%
Meidan Income:	9580
Meidan Income Number:	476
Meidan Income Percent:	29.9%
Vacant Housing Number:	112
Vacant Housing Percent:	30.9%
Unemployed Number:	67
Unemployed Percent:	4.2%

D24 **VACANT REGENCY HOUSE** **US BROWNFIELDS** **1016349497**
SE **110 E. BROAD STREET** **FINDS** **N/A**
< 1/8 **TEXARKANA, AR 71854**
0.100 mi.
527 ft. **Site 7 of 7 in cluster D**

Relative: **Lower**
Actual: **305 ft.**

US BROWNFIELDS:

Property Name:	VACANT REGENCY HOUSE
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	24324
Parcel size:	.16
Latitude:	33.4216
Longitude:	-94.0425
HCM Label:	Not reported

VACANT REGENCY HOUSE (Continued) **1016349497**

Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69881
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	01/22/2006 00:00:00
Ownership Entity:	Not reported
Completion Date:	02/28/2007 00:00:00
Current Owner:	Mr. Thomas G. Dunn
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported

VACANT REGENCY HOUSE (Continued) **1016349497**

Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported

VACANT REGENCY HOUSE (Continued) **1016349497**

Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Constructed in 1885 and a dry goods store until the 1940s, then a department store until the 1980s.
Below Poverty Number:	324
Below Poverty Percent:	19.4%
Meidan Income:	10084
Meidan Income Number:	504
Meidan Income Percent:	30.1%
Vacant Housing Number:	119
Vacant Housing Percent:	31.3%
Unemployed Number:	69
Unemployed Percent:	4.1%

FINDS:

Registry ID: 110038760533

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

25
ENE
< 1/8
0.109 mi.
575 ft.

CURLEYS CLEANERS & FURRIER **EDR Hist Cleaner** **1019966638**
306 WOOD ST **N/A**
TEXARKANA, AR 75501

Relative: Higher

Actual: 319 ft.

EDR Hist Cleaner

Year:	Name:	Type:
1969	CURLEYS CLEANERS & FURRIERS	Drycleaning Plants, Except Rugs
1970	CURLEYS CLEANERS & FURRIERS	Drycleaning Plants, Except Rugs
1971	CURLEYS CLEANERS & FURRIER	Drycleaning Plants, Except Rugs
1972	CURLEYS CLEANERS & FURRIER	Drycleaning Plants, Except Rugs
1973	CURLEYS CLEANERS & FURRIER	Drycleaning Plants, Except Rugs
1974	CURLEYS CLEANERS & FURRIER	Drycleaning Plants, Except Rugs
1975	CURLES CLEANERS & FURRIER	Drycleaning Plants, Except Rugs

I26 **TEXARKANA CENTRAL OFFICE** **TX UST** **U004119043**
North **507 OLIVE ST** **TX Financial Assurance** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.120 mi.
631 ft. **Site 1 of 2 in cluster I**

Relative:
Higher

Actual:
321 ft.

UST:

AI Number:	8021
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	07/09/1986
Facility Status:	ACTIVE
Additional ID:	549530672002087
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	GREG MARCHESANI,AREA MGR
Contact Organization Name:	TEXARKANA CENTRAL OFFICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9032234635
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	GREG.MARCHESANI@WINDSTREAM.COM
Signature Date On Earliest Reg Form:	12/12/2017
Signature Name/Title On Earliest Reg Form:	KRIS RAMON,MGR
Application Received Date On Earliest Reg Form:	12/27/2017
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	680283442002031
Additional ID:	549530672002087
Ai Number:	8021
Operator CN:	CN600752125
Operator Name:	VALOR TELECOMMUNICATIONS OF TEXAS LLC
Operator Effective Begin Date:	08/31/2000
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	/
Contact Organization Name:	VALOR TELECOMMUNICATIONS OF TEXAS LP
Contact Mailing Address (Delivery):	4001 N RODNEY PARHAM RD
Contact Mailing Address (Internal Delivery):	1170B1-F03-28B
Contact Mailing City/State/Zip:	LITTLE ROCK AR 72212-2459
Contact Phone Country Code:	1
Contact Phone Area Code:	501
Contact Phone Number:	7485765
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600752125
Owner Last Name:	VALOR TELECOMMUNICATIONS OF TEXAS LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	4001 N RODNEY PARHAM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	LITTLE ROCK
Contact Mailing State:	AR
Contact Mailing Zip:	72212
Contact Mailing Zip5:	2459
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	680283442002031
Additional ID:	549530672002087
AI Number:	8021
Owner Effective Begin Date:	08/31/2000
State Tax ID:	15221942194
Contact Role:	OWNCON
Contact Name/Title:	CHRISTOPHER BARTLEY/
Contact Organization Name:	VALOR TELECOMMUNICATIONS OF TEXAS LLC

Self Certification:

Self Cert ID:	40079
Cert ID:	296352
AI Number:	8021
Self Certification Date:	12/12/2017
Signature Name/Title:	KRIS RAMON MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40079
Cert ID:	281305
AI Number:	8021
Self Certification Date:	11/28/2016
Signature Name/Title:	KRIS RAMON ENV PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40079
Cert ID:	264229
AI Number:	8021
Self Certification Date:	12/11/2015
Signature Name/Title:	KRIS RAMON ENVIRONMENTAL ENG
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40079
Cert ID:	247563
AI Number:	8021
Self Certification Date:	11/24/2014
Signature Name/Title:	ANDREW HANER ES & H ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40079
Cert ID:	231181
AI Number:	8021
Self Certification Date:	01/17/2014
Signature Name/Title:	NATHAN WILLIAMS ES & H ENG
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40079
Cert ID:	6865
AI Number:	8021
Self Certification Date:	12/28/2012
Signature Name/Title:	NATHAN WILLIAMS ES & H ENG
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6864
AI Number:	8021
Self Certification Date:	11/02/2011
Signature Name/Title:	STEPHANIE M MILLER SR ENV CONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6863
AI Number:	8021
Self Certification Date:	03/01/2011
Signature Name/Title:	STEPHANIE M MILLER SR ENV CONSULTANT
Signature Type Role:	OWNER
Filing Status:	RENEWAL

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6862
AI Number:	8021
Self Certification Date:	01/12/2010
Signature Name/Title:	STEPHANIE M MILLER SR ENV CONSULTANT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6861
AI Number:	8021
Self Certification Date:	11/06/2008
Signature Name/Title:	STEPHANIE M MILLER SR ENV CONSULTANT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6860
AI Number:	8021
Self Certification Date:	02/21/2008
Signature Name/Title:	STEPHANIE MILLER SR ENV CONSULTANT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6859
AI Number:	8021
Self Certification Date:	10/23/2006
Signature Name/Title:	STEPHANIE M MILLER SR ENV CONSULTANT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6858
AI Number:	8021
Self Certification Date:	12/21/2005
Signature Name/Title:	GRANT RANEY SENIOR VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6857
AI Number:	8021
Self Certification Date:	01/10/2005
Signature Name/Title:	GRANT RANEY SENIOR VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6856
AI Number:	8021
Self Certification Date:	09/22/2004
Signature Name/Title:	GRANT RANEY SENIOR VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6855
AI Number:	8021
Self Certification Date:	12/19/2001
Signature Name/Title:	MITCH STUBBLEFIELD VP OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40079
Cert ID:	6854
AI Number:	8021
Self Certification Date:	07/24/2001
Signature Name/Title:	MITCH STUBBLEFIELD VP OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	20889
Facility ID:	40079
Ai Number:	8021
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1980
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

TCPM(Ext Nonmetallic Jacket):	Y
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	6372
UST ID:	20889
AI Number:	8021
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	VALOR TELECOMMUNICATIONS OF TEXAS LP
Contact Mailing Address (Delivery):	4001 N RODNEY PARHAM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	LITTLE ROCK, AR 72212 2459
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	40079
Additional ID:	549530672002087
Princ ID:	680283442002031
AI Number:	8021
Facility Name:	TEXARKANA CENTRAL OFFICE
AR Number:	56391
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	STEPHANIE M MILLER/

TX Financial Assurance 2:

Region:	2
Facility ID:	40079
Finass ID:	189741
AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2017
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	Not reported
Policy Number:	CST1520931-17
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/17/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Region:	2
Facility ID:	40079
Finass ID:	174314
AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2016
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	Not reported
Policy Number:	cst152093116
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/17/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Region:	2
Facility ID:	40079
Finass ID:	155811
AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2015
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	1 800 8428972
Policy Number:	CST152093115
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/17/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Region:	2
Facility ID:	40079
Finass ID:	138847
AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2014
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	Not reported
Policy Number:	CST152093114
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/17/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Region:	2
Facility ID:	40079
Finass ID:	122038

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2013
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	Not reported
Policy Number:	CST152093103
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/17/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Region:	2
Facility ID:	40079
Finass ID:	692
AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2012
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	1 800 3822150
Policy Number:	CST152093102
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/17/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Region:	2
Facility ID:	40079
Finass ID:	19877
AI:	8021
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/17/2010
Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	1 800 3822150
Policy Number:	CST152093100
Coverage Amount:	1000000
Coverage Expiration Date:	09/17/2011

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Ins Premium Pre-Paid For Entire Yr: Yes
Proof of Financial Assurance: No

Region: 2
Facility ID: 40079
Finass ID: 19878
AI: 8021
Mechanism Type Other: Not reported
Multiple Mechanism Types: N
Coverage Amt per Annual Aggregate: Not reported
Meets Financial Assurance Req Flag: Not reported
Financial Responsibility Type: INSURANCE OR RISK RETENTION
Corrective Action MET Flag: Y
3rd Party MET Flag: Y
Financial Assurance Begin Date: 09/17/2008
Date Financial Assurance Form Rec: 12/27/2017
Issuer Name: ZURICH AMERICAN INS CO
Issuer Phone: 1 800 3822150
Policy Number: USC9419456-02
Coverage Amount: 1000000
Coverage Expiration Date: 09/17/2009
Ins Premium Pre-Paid For Entire Yr: Yes
Proof of Financial Assurance: Yes

Region: 2
Facility ID: 40079
Finass ID: 19879
AI: 8021
Mechanism Type Other: Not reported
Multiple Mechanism Types: N
Coverage Amt per Annual Aggregate: Not reported
Meets Financial Assurance Req Flag: Not reported
Financial Responsibility Type: INSURANCE OR RISK RETENTION
Corrective Action MET Flag: Y
3rd Party MET Flag: Y
Financial Assurance Begin Date: 09/17/2007
Date Financial Assurance Form Rec: 12/27/2017
Issuer Name: ZURICH AMERICAN INS CO
Issuer Phone: 1 800 3822150
Policy Number: USC9419456-00
Coverage Amount: 1000000
Coverage Expiration Date: 09/17/2008
Ins Premium Pre-Paid For Entire Yr: Yes
Proof of Financial Assurance: No

Region: 2
Facility ID: 40079
Finass ID: 19880
AI: 8021
Mechanism Type Other: Not reported
Multiple Mechanism Types: N
Coverage Amt per Annual Aggregate: Not reported
Meets Financial Assurance Req Flag: Not reported
Financial Responsibility Type: INSURANCE OR RISK RETENTION
Corrective Action MET Flag: Y
3rd Party MET Flag: Y
Financial Assurance Begin Date: 12/31/1992

TEXARKANA CENTRAL OFFICE (Continued) **U004119043**

Date Financial Assurance Form Rec:	12/27/2017
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

F27 **MAIN ST AND TEXAS BLVD PARKING LOTS** **TX BROWNFIELDS** **S117323901**
WSW **301 MAIN ST & 302 TEXAS BLVD** **N/A**
< 1/8 **TEXARKANA, TX 75501**
0.125 mi.
658 ft. **Site 3 of 3 in cluster F**

Relative: **Lower**

Actual: **312 ft.**

BROWNFIELDS:

BF Site Assessment Received:	09/12/2014
PCA number:	99690
BF Grant Number:	G168
Facility Type:	Commercial
Lead Type:	City
Project manager:	KLIVINGS
Phase:	INVESTIGATION
Lat/Long:	33.421944 / -94.045555
Lat/Long (deg):	33.421944 / -94.045555
Acres:	0.53
TCEQ Region:	5
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Texarkana
Applicant Title:	Housing/Demolition Specialist
Applicant Address:	PO Box 1967
Applicant City,St,Zip:	Texarkana, TX 75504
Applicant Phone:	903-798-3904
Applicant Fax:	903-798-3913
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported

H28 **203 WEST BROAD STREET** **US BROWNFIELDS** **1012090635**
SSW **203 WEST BRAOD STREET** **FINDS** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.132 mi.
698 ft. **Site 2 of 3 in cluster H**

Relative:
Lower

Actual:
311 ft.

US BROWNFIELDS:

Property Name:	203 WEST BROAD STREET
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.08
Latitude:	33.420699
Longitude:	-94.044104
HCM Label:	GPS (Pseudo Range) Differential
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	72421
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3914.51
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	4000000
Redev. Funding Source:	Private/Other Funding
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	09/01/2010 00:00:00
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97642001
Start Date:	04/07/2008 00:00:00
Ownership Entity:	Private
Completion Date:	08/01/2008 00:00:00
Current Owner:	Josh R. Morris III
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported

203 WEST BROAD STREET (Continued) **1012090635**

Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.08
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

203 WEST BROAD STREET (Continued) **1012090635**

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	3,000-squere foot, single storey office buidling. Past uses include a furniture store, men's clothing shop, optometrists, and tobacco shop.
Below Poverty Number:	301
Below Poverty Percent:	19.2%
Meidan Income:	9459
Meidan Income Number:	470
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	31.0%
Unemployed Number:	66
Unemployed Percent:	4.2%

FINDS:

Registry ID: 110038761658

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

H29 **203 W BROAD ST TEXARKANA** **TX BROWNFIELDS** **S109028570**
SSW **203 W BROAD ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.132 mi.
698 ft. **Site 3 of 3 in cluster H**

Relative:
Lower

Actual:
311 ft.

BROWNFIELDS:

BF Site Assessment Received:	04/03/2008
PCA number:	78226
BF Grant Number:	G099
Facility Type:	Abandoned Building
Lead Type:	Owner
Project manager:	KLIVINGS
Phase:	COMPLETED
Lat/Long:	33.251490 / -94.238920

203 W BROAD ST TEXARKANA (Continued) **S109028570**

Lat/Long (deg):	33.251490 / -94.238920
Acres:	.08
TCEQ Region:	05
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Texarkana
Applicant Title:	Director, Community Redevelopment
Applicant Address:	200 Texas Boulevard
Applicant City,St,Zip:	Texarkana, TX 75501
Applicant Phone:	903-798-3903
Applicant Fax:	903-798-3913
Consultant Attorney:	Shaw
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported

J30 **205 W BROAD ST TEXARKANA** **TX BROWNFIELDS** **S109028571**
SSW **205 W BROAD ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.136 mi.
717 ft. **Site 1 of 2 in cluster J**

Relative:
Lower

Actual:
311 ft.

BROWNFIELDS:

BF Site Assessment Received:	04/15/2008
PCA number:	78226
BF Grant Number:	G100
Facility Type:	Abandioned Building
Lead Type:	Owner
Project manager:	KLIVINGS
Phase:	COMPLETED
Lat/Long:	33.251400 / -94.239190
Lat/Long (deg):	33.251400 / -94.239190
Acres:	.08
TCEQ Region:	05
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Texarkana
Applicant Title:	Director, Community Redevelopment
Applicant Address:	200 Texas Boulevard
Applicant City,St,Zip:	Texarkana, TX 75501
Applicant Phone:	903-798-3903
Applicant Fax:	903-798-3913
Consultant Attorney:	Shaw

205 W BROAD ST TEXARKANA (Continued) **S109028571**

Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported

J31 **205 WEST BROAD STREET** **US BROWNFIELDS** **1011813542**
SSW **205 WEST BROAD STREET** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.136 mi.
717 ft. **Site 2 of 2 in cluster J**

Relative: US BROWNFIELDS:
Lower

Property Name:	205 WEST BROAD STREET
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.08
Latitude:	33.420659
Longitude:	-94.044186
HCM Label:	GPS (Pseudo Range) Differential
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	72441
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3772.14
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97642001
Start Date:	04/07/2008 00:00:00
Ownership Entity:	Private

Actual:
311 ft.

205 WEST BROAD STREET (Continued) **1011813542**

Completion Date:	08/01/2008 00:00:00
Current Owner:	Josh R Morris III
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.08
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported

205 WEST BROAD STREET (Continued) **1011813542**

Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Y
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	301
Below Poverty Percent:	19.2%
Meidan Income:	9459
Meidan Income Number:	470
Meidan Income Percent:	29.9%
Vacant Housing Number:	111
Vacant Housing Percent:	31.0%
Unemployed Number:	66
Unemployed Percent:	4.2%

---

32 **ABANDONED RITCHIE GROCERY BUILDING** **US BROWNFIELDS** **1023619040**
SSE **215 EAST FRONT STREET** **FINDS** **N/A**
1/8-1/4 **TEXARKANA, AR 75504**
0.148 mi.
781 ft.

Relative: **Lower**
Actual: **301 ft.**

US BROWNFIELDS:

Property Name:	ABANDONED RITCHIE GROCERY BUILDING
Recipient Name:	Southwest Arkansas Planning and Development District Inc
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	1

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Latitude:	33.4210267
Longitude:	-94.0418836
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	231341
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2500
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F72201
Start Date:	04/28/2017 00:00:00
Ownership Entity:	Not reported
Completion Date:	06/15/2017 00:00:00
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Y
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	320
Below Poverty Percent:	19.5%
Meidan Income:	9902
Meidan Income Number:	496
Meidan Income Percent:	30.2%
Vacant Housing Number:	117
Vacant Housing Percent:	31.3%
Unemployed Number:	67
Unemployed Percent:	4.1%

Property Name:	ABANDONED RITCHIE GROCERY BUILDING
Recipient Name:	Southwest Arkansas Planning and Development District Inc
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	1
Latitude:	33.4210267
Longitude:	-94.0418836
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	231341
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	850
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F72201
Start Date:	03/30/2017 00:00:00
Ownership Entity:	Not reported
Completion Date:	04/28/2017 00:00:00
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Y
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	320
Below Poverty Percent:	19.5%
Meidan Income:	9902
Meidan Income Number:	496
Meidan Income Percent:	30.2%
Vacant Housing Number:	117
Vacant Housing Percent:	31.3%
Unemployed Number:	67
Unemployed Percent:	4.1%

Property Name:	ABANDONED RITCHIE GROCERY BUILDING
Recipient Name:	Southwest Arkansas Planning and Development District Inc
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	1
Latitude:	33.4210267
Longitude:	-94.0418836
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	231341
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F72201
Start Date:	03/09/2017 00:00:00
Ownership Entity:	Not reported
Completion Date:	03/28/2017 00:00:00
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Y
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	320
Below Poverty Percent:	19.5%
Meidan Income:	9902

ABANDONED RITCHIE GROCERY BUILDING (Continued) **1023619040**

Meidan Income Number:	496
Meidan Income Percent:	30.2%
Vacant Housing Number:	117
Vacant Housing Percent:	31.3%
Unemployed Number:	67
Unemployed Percent:	4.1%

FINDS:

Registry ID: 110070057708

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

K33 **UNION STATION** **US BROWNFIELDS** **1018164095**
South **100 W. FRONT STREET** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.159 mi.
840 ft. **Site 1 of 5 in cluster K**

Relative: **Lower**

Actual: **303 ft.**

US BROWNFIELDS:

Property Name:	UNION STATION
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	03841068400
Parcel size:	1.08
Latitude:	33.4201744
Longitude:	-94.04288480000002
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	208663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	15725
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment

UNION STATION (Continued) **1018164095**

Accomplishment Count:	0
Cooperative Agreement Number:	00F20201
Start Date:	06/10/2014 00:00:00
Ownership Entity:	Not reported
Completion Date:	09/05/2014 00:00:00
Current Owner:	Jeff Sandefur
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported

UNION STATION (Continued) **1018164095**

Past use commercial acreage:	1.08
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Y
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Y
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site consist of approximately 1.08 acres that sits both in Arkansas and Texas. The structure is vacant, approximately 44,000 square feet, three-story, and was a former train station constructed in 1929 and served as a train depot until the 1970s. Amtrak continues daily operations in the eastern most portion of the building and is considered adjacent to the site.
Below Poverty Number:	300
Below Poverty Percent:	19.3%
Meidan Income:	9376
Meidan Income Number:	467
Meidan Income Percent:	30.0%
Vacant Housing Number:	110
Vacant Housing Percent:	31.0%
Unemployed Number:	65
Unemployed Percent:	4.2%
Property Name:	UNION STATION
Recipient Name:	Texarkana Texas and Arkansas, City of

UNION STATION (Continued) **1018164095**

Grant Type:	Assessment
Property Number:	03841068400
Parcel size:	1.08
Latitude:	33.4201744
Longitude:	-94.04288480000002
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	208663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1250
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F20201
Start Date:	07/16/2013 00:00:00
Ownership Entity:	Not reported
Completion Date:	09/19/2013 00:00:00
Current Owner:	Jeff Sandefur
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y

UNION STATION (Continued) **1018164095**

Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	1.08
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Y
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported

UNION STATION (Continued) **1018164095**

Selenium contaminant found:	Not reported
SVOCs contaminant found:	Y
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site consist of approximately 1.08 acres that sits both in Arkansas and Texas. The structure is vacant, approximately 44,000 square feet, three-story, and was a former train station constructed in 1929 and served as a train depot until the 1970s. Amtrak continues daily operations in the eastern most portion of the building and is considered adjacent to the site.
Below Poverty Number:	300
Below Poverty Percent:	19.3%
Meidan Income:	9376
Meidan Income Number:	467
Meidan Income Percent:	30.0%
Vacant Housing Number:	110
Vacant Housing Percent:	31.0%
Unemployed Number:	65
Unemployed Percent:	4.2%

L34 **TEXARKANA UNIFORM** **TX UST** **U003406814**
WSW **315 TEXAS BLVD** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.161 mi.
849 ft. **Site 1 of 4 in cluster L**

Relative: UST:
Lower

Actual:
311 ft.

AI Number:	8926
Facility Type:	UNKNOWN
Facility Begin Date:	07/15/1986
Facility Status:	INACTIVE
Additional ID:	518589292002275
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	,
Contact Organization Name:	TEXARKANA UNIFORM
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5017728251
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	FRED MILLER,OWNER

TEXARKANA UNIFORM (Continued) **U003406814**

Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601468119
Owner Last Name:	MILLER-CLABORN OIL DISTRIBUTING COMPANY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	31820442002268
Additional ID:	518589292002275
AI Number:	8926
Owner Effective Begin Date:	07/15/1986
State Tax ID:	17104179902
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	23545
Facility ID:	48736
Ai Number:	8926
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

TEXARKANA UNIFORM (Continued) **U003406814**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/25/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	28883
UST ID:	23545
AI Number:	8926
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

TEXARKANA UNIFORM (Continued) **U003406814**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	3633
Cert ID:	10253
UST Comprt ID:	44308
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A

Self Cert ID:	3633
Cert ID:	10262
UST Comprt ID:	44301
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A

Self Cert ID:	3633
Cert ID:	10261
UST Comprt ID:	44302
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A

Self Cert ID:	3633
Cert ID:	10260
UST Comprt ID:	44303
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A

TEXARKANA UNIFORM (Continued) **U003406814**

Self Cert ID:	3633
Cert ID:	10259
UST Comprt ID:	44304
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A
Self Cert ID:	3633
Cert ID:	10258
UST Comprt ID:	44305
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A
Self Cert ID:	3633
Cert ID:	10257
UST Comprt ID:	44306
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A
Self Cert ID:	3633
Cert ID:	10256
UST Comprt ID:	44307
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A
Self Cert ID:	3633
Cert ID:	10255
UST Comprt ID:	44310
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A
Self Cert ID:	3633
Cert ID:	10254
UST Comprt ID:	44309
UST ID:	14131
AI Number:	8926
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	MILLER-CLABORN OIL CO
Contact Mailing Address (Delivery):	1113 DUDLEY ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, AR 71854 6461
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

TEXARKANA UNIFORM (Continued) **U003406814**

Contact Address Deliverable:	Y
Facility ID:	48736
Additional ID:	518589292002275
Princ ID:	31820442002268
AI Number:	8926
Facility Name:	TEXARKANA UNIFORM
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RANDAL CLABORN/

L35 **TEXARKANA UNIFORM** **TX LPST** **S109514735**
WSW **315 TEXAS BLVD** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.161 mi.
849 ft. **Site 2 of 4 in cluster L**

Relative: **Lower**
Actual: **311 ft.**

LPST:

Facility ID:	0008926
LPST Id:	103637
Facility Location:	315 TEXAS BLVD NEAR 3RD 4TH TEXAS & SPRUCE
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	01/27/1998
Entered Date:	06/29/1992
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/3/1
Coordinators RPR:	VYF
Responsible Party Name:	TEX ARK PROPERTIES
Responsible Party Contact:	DOUGLAS PARRISH,
Responsible Party Address:	PO BOX 2635
Responsible Party City,St,Zip:	LITTLE ROCK, AR 72203
Responsible Party Telephone:	501/376-3331
Reported Date:	06/15/1992
Case Start Date:	06/29/1992

M36 **UPTOWN ANTIQUES** **US BROWNFIELDS** **1024079570**
SW **221 TEXAS BLVD.** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.163 mi.
863 ft. **Site 1 of 2 in cluster M**

Relative: **Lower**
Actual: **312 ft.**

US BROWNFIELDS:

Property Name:	UPTOWN ANTIQUES
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.89
Latitude:	33.4211201
Longitude:	-94.0459501

UPTOWN ANTIQUES (Continued) **1024079570**

HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	235932
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6269
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F67501
Start Date:	05/03/2017 00:00:00
Ownership Entity:	Private
Completion Date:	07/12/2017 00:00:00
Current Owner:	Downtown Texarkana, LLC
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	04/19/2017 00:00:00
State/tribal program ID:	G182
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported

UPTOWN ANTIQUES (Continued) **1024079570**

Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.89
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	.89
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported

UPTOWN ANTIQUES (Continued) **1024079570**

Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	288
Below Poverty Percent:	18.9%
Meidan Income:	7629
Meidan Income Number:	465
Meidan Income Percent:	30.5%
Vacant Housing Number:	107
Vacant Housing Percent:	30.6%
Unemployed Number:	67
Unemployed Percent:	4.4%

M37 **UPTOWN ANTIQUES** **TX BROWNFIELDS** **S120691703**
SW **221 TEXAS BLVD** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.163 mi.
863 ft. **Site 2 of 2 in cluster M**

Relative: **Lower**

Actual: **312 ft.**

BROWNFIELDS:

BF Site Assessment Received:	04/06/2017
PCA number:	99690
BF Grant Number:	G182
Facility Type:	VACANT ANTIQUE STORE
Lead Type:	CITY
Project manager:	KLIVINGS
Phase:	COMPLETED
Lat/Long:	33.421063 / -94.046009
Lat/Long (deg):	33.421063 / -94.046009
Acres:	0.89
TCEQ Region:	5
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	CITY OF TEXARKANA
Applicant Title:	BROWNFIELDS PM
Applicant Address:	PO BOX 1967
Applicant City,St,Zip:	TEXARKANA, TX 75504
Applicant Phone:	903-798-3934
Applicant Fax:	903-798-3913
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported

UPTOWN ANTIQUES (Continued) **S120691703**

Institutional Controls: Not reported
Type Remedy: Not reported

K38 **RED RIVER army DEPOT** **TX AST** **U003420268**
South **100 MAIN ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.169 mi.
892 ft. **Site 2 of 5 in cluster K**

Relative:
Lower

Actual:
303 ft.

AST:

Facility ID:	58196
Additional ID:	79642062002205
AI Number:	21468
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/15/1986
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	17
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	BOWIE
Site Location (TCEQ region):	5
Site Location (location zip):	75507
Contact Name/Title:	RON WILLIAMS/
Contact Organization Name:	RED RIVER ARMY DEPOT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	9033344103
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	04/01/1986
Signature First Name on Earliest Reg Form:	C R
Application Received Date on Earliest Reg Form:	04/04/1986
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	WILCOX
Signature Title on Earliest Reg Form:	FACIL ENGINEER
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	58196
Tank ID:	383
AST ID:	152451
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980

RED RIVER ARMY DEPOT (Continued) **U003420268**

Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	524B
AST ID:	152452
AI Number:	21468
Install Date:	01/01/1987
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1987
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	20000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	503
AST ID:	152453
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10927
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported

RED RIVER ARMY DEPOT (Continued) **U003420268**

Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	384
AST ID:	152454
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	17500
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	390
AST ID:	152455
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	9950
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N

RED RIVER ARMY DEPOT (Continued) **U003420268**

Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	381
AST ID:	152456
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	283
AST ID:	152457
AI Number:	21468
Install Date:	01/01/1974
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	5000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported

RED RIVER ARMY DEPOT (Continued) **U003420268**

Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	385
AST ID:	152458
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	386
AST ID:	152459
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	17500
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	524C
AST ID:	152460

RED RIVER ARMY DEPOT (Continued) **U003420268**

AI Number:	21468
Install Date:	01/01/1987
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1987
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	5000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	382
AST ID:	152461
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	17500
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	524F
AST ID:	152462
AI Number:	21468
Install Date:	01/01/1987
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE

RED RIVER ARMY DEPOT (Continued) **U003420268**

Tank Status Date:	01/01/1987
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	387
AST ID:	152463
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1980
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	13000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	504
AST ID:	152464
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10038
Substance:	DIESEL
Other Substance B:	Not reported

RED RIVER ARMY DEPOT (Continued) **U003420268**

Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	515
AST ID:	152465
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	7066
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	513
AST ID:	152466
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10046
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N

RED RIVER ARMY DEPOT (Continued) **U003420268**

Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	514
AST ID:	152467
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10056
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	524A
AST ID:	152468
AI Number:	21468
Install Date:	01/01/1987
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1987
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	5000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N

RED RIVER ARMY DEPOT (Continued) **U003420268**

Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	512
AST ID:	152469
AI Number:	21468
Install Date:	01/01/1980
Tank Registration Date:	04/04/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	02/12/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10039
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	524D
AST ID:	152470
AI Number:	21468
Install Date:	01/01/1987
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1987
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	30000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	58196
Tank ID:	524E

RED RIVER ARMY DEPOT (Continued) **U003420268**

AST ID:	152471
AI Number:	21468
Install Date:	01/01/1987
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1987
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	5000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	1027
AST ID:	152472
AI Number:	21468
Install Date:	01/01/1990
Tank Registration Date:	01/03/1990
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	06/01/1990
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	4000
Substance:	EMPTY
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	343A1
AST ID:	213268
AI Number:	21468
Install Date:	05/01/2007
Tank Registration Date:	03/22/2010
Mult Comp:	N

RED RIVER ARMY DEPOT (Continued) **U003420268**

Tank Status:	IN USE
Tank Status Date:	05/01/2007
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	1200
Substance:	AVIATION GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	9361
AST ID:	213269
AI Number:	21468
Install Date:	04/01/2007
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	04/01/2007
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	58196
Tank ID:	1651
AST ID:	213270
AI Number:	21468
Install Date:	02/01/2008
Tank Registration Date:	03/22/2010
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	02/01/2008
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000
Substance:	DIESEL

RED RIVER ARMY DEPOT (Continued) **U003420268**

Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

K39 **RED RIVER ARMY DEPOT LANDFILL** **TX SWF/LF** **S109515351**
South **100 MAIN DRIVE AMSTA RR C** **N/A**
1/8-1/4 **TEXARKANA, TX**
0.169 mi.
892 ft. **Site 3 of 5 in cluster K**

Relative: SWF/LF:
Lower

Region:	5
Permit Number:	1313
Facility Status:	CLOSED
Facility Type:	1
Permit Status:	REVOKED
Status Date:	01/25/1994
Mailing Address:	Not reported
Client Name:	CN600126262, US Department of the Army
Client Address:	GENERAL DELIVERY TEXARKANA, TX 75501-9999
Client Telephone:	(214) 838 - 2111
Business Type:	03
Area Served:	Not reported
Estimated Closure Date:	6/1/1984
Permit Acreage:	30
Permit Start:	06/25/1979
Permit End:	02/14/1995
Polution Served:	5000
Tons per Day:	20
Yards per Day:	Not reported
Application:	NEW APPLICATION
Lat/Long:	33.439999999999998 / -94.2900000000

Actual:
303 ft.

K40 **UNITED STATES MILITARY - ENVIRONMENTAL** **NY MANIFEST** **S117565363**
South **100 JAMES CARLOW DR** **N/A**
1/8-1/4 **TEXARKANA, TX 75507**
0.169 mi.
892 ft. **Site 4 of 5 in cluster K**

Relative: NY MANIFEST:
Lower

Country:	USA
EPA ID:	TX3213820738
Facility Status:	Not reported
Location Address 1:	CONTROL OFFICE RED RIVER ARMY
Code:	BP

Actual:
303 ft.

UNITED STATES MILITARY - ENVIRONMENTAL (Continued) **S117565363**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	DEPOT TEXAUROUA
Location State:	TX
Location Zip:	25507
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	TX3213820738
Mailing Name:	UNITED STATES MILITARY - ENVIRONMENTAL
Mailing Contact:	CHARLES A DILLARD
Mailing Address 1:	RED DEVIL ARMY DEPOT-ENVIRON
Mailing Address 2:	Not reported
Mailing City:	CONTROL TEXAUROUA
Mailing State:	TX
Mailing Zip:	25507
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2148383177

NY MANIFEST:

Document ID:	NYG1209816
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	HQ23234
Trans2 State ID:	Not reported
Generator Ship Date:	01/12/2000
Trans1 Recv Date:	01/12/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	TX3213820738
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD067919340
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00097

UNITED STATES MILITARY - ENVIRONMENTAL (Continued) **S117565363**

Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00098
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

I41 **EAST FUNERAL HOME** **TX UST** **U001274806**
North **120 W 6TH ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.170 mi.
895 ft. **Site 2 of 2 in cluster I**

Relative: UST:
Higher

Actual: AI Number:	42685
324 ft. Facility Type:	FLEET REFUELING
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	875183462002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	DAVID MALLABY,OWNER
Contact Organization Name:	EAST FUNERAL HOME
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2147933141
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/07/1986
Signature Name/Title On Earliest Reg Form:	DOROTHY ROWLAND,OFFICE MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

EAST FUNERAL HOME (Continued) **U001274806**

Owner:

Owner CN:	CN600134480
Owner Last Name:	TRUMAN ARNOLD COMPANIES
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	558326112001221
Additional ID:	875183462002139
AI Number:	42685
Owner Effective Begin Date:	09/01/1988
State Tax ID:	17512891726
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	112869
Facility ID:	82131
Ai Number:	42685
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

EAST FUNERAL HOME (Continued) **U001274806**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	133424
UST ID:	112869
AI Number:	42685
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

EAST FUNERAL HOME (Continued) **U001274806**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TRUMAN ARNOLD COMPANIES
Contact Mailing Address (Delivery):	701 S ROBISON RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75501 6747
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	82131
Additional ID:	875183462002139
Princ ID:	558326112001221
AI Number:	42685
Facility Name:	EAST FUNERAL HOME
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RICK SHINGLAR/

K42 **SANDEFUR PARKING LOT** **US BROWNFIELDS** **1016159263**
South **202, 208 AND 222 FRONT STREET** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.180 mi.
950 ft. **Site 5 of 5 in cluster K**

Relative: **Lower**

Actual: **301 ft.**

US BROWNFIELDS:

Property Name:	SANDEFUR PARKING LOT
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.72
Latitude:	33.4198649
Longitude:	-94.0437142
HCM Label:	Address Matching-House Number
Map Scale:	1
Point of Reference:	Center of a Facility or Station

SANDEFUR PARKING LOT (Continued) **1016159263**

Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133213
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F19501
Start Date:	07/07/2011 00:00:00
Ownership Entity:	Not reported
Completion Date:	08/31/2011 00:00:00
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported

SANDEFUR PARKING LOT (Continued) **1016159263**

Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported

SANDEFUR PARKING LOT (Continued) **1016159263**

Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	293
Below Poverty Percent:	19.2%
Meidan Income:	9177
Meidan Income Number:	457
Meidan Income Percent:	30.0%
Vacant Housing Number:	108
Vacant Housing Percent:	31.1%
Unemployed Number:	64
Unemployed Percent:	4.2%

43
SSW
1/8-1/4
0.185 mi.
977 ft.

VACANT LOT AT 301 W BROAD **US BROWNFIELDS** **1011855503**
301 W. BROAD STREET **N/A**
TEXARKANA, TX 75501

Relative:
Lower

Actual:
311 ft.

US BROWNFIELDS:

Property Name:	VACANT LOT AT 301 W BROAD
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.08
Latitude:	33.42056
Longitude:	-94.0433
HCM Label:	Not reported
Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69821
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	96656301
Start Date:	11/15/2007 00:00:00
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Mr. Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U

VACANT LOT AT 301 W BROAD (Continued) **1011855503**

Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.08
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported

VACANT LOT AT 301 W BROAD (Continued) **1011855503**

Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Y
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Previously businesses The Courier (printing), Meier the Tailor, Aycock Distributing Company, Hotel Courier, Academy of Beauty and Lucille's rooms. Now vacant.
Below Poverty Number:	281
Below Poverty Percent:	19.0%
Meidan Income:	8923
Meidan Income Number:	441
Meidan Income Percent:	29.7%
Vacant Housing Number:	104
Vacant Housing Percent:	30.7%
Unemployed Number:	64
Unemployed Percent:	4.3%
Property Name:	VACANT LOT AT 301 W BROAD
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.08
Latitude:	33.42056
Longitude:	-94.0433
HCM Label:	Not reported
Map Scale:	1:24000
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69821

VACANT LOT AT 301 W BROAD (Continued) **1011855503**

IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3800
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	11/19/2007 00:00:00
Ownership Entity:	Private
Completion Date:	01/15/2008 00:00:00
Current Owner:	Mr. Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported

VACANT LOT AT 301 W BROAD (Continued) **1011855503**

PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.08
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Y
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Previously businesses The Courier (printing), Meier the Tailor, Aycock

VACANT LOT AT 301 W BROAD (Continued) **1011855503**

Distributing Company, Hotel Courier, Academy of Beauty and Lucille's rooms. Now vacant.

Below Poverty Number:	281
Below Poverty Percent:	19.0%
Meidan Income:	8923
Meidan Income Number:	441
Meidan Income Percent:	29.7%
Vacant Housing Number:	104
Vacant Housing Percent:	30.7%
Unemployed Number:	64
Unemployed Percent:	4.3%

L44 **THE T R A H C BUILDING** **TX LPST** **S116703420**
SW **410 W 3RD ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.189 mi.
998 ft. **Site 3 of 4 in cluster L**

Relative: LPST:
Lower

Actual:
310 ft.

Facility ID:	0056052
LPST Id:	96254
Facility Location:	321 4TH ST @ TEXAS BLVD
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	03/07/2003
Entered Date:	07/26/1990
Priority:	3.5 - A DESIGNATED MAJOR OR MINOR AQUIFER IS IMPACTED
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	A designated major or minor groundwater aquifer is affected or immediately threatened.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/3/1/3/1/3
Coordinators RPR:	PWW
Responsible Party Name:	ENGINEERING ASSOCIATES INC
Responsible Party Contact:	RUSSELL THOMAS
Responsible Party Address:	110 W ENNIS AVE
Responsible Party City,St,Zip:	ENNIS, TX 75119
Responsible Party Telephone:	972/878-4500
Reported Date:	07/25/1990
Case Start Date:	07/26/1990

L45 **PJ MATHEWS** **TX UST** **U001286160**
SW **410 W 3RD ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.189 mi.
998 ft. **Site 4 of 4 in cluster L**

Relative: UST:
Lower

Actual:
310 ft.

AI Number:	56052
Facility Type:	RETAIL
Facility Begin Date:	10/04/1990
Facility Status:	INACTIVE
Additional ID:	405622272002087
Facility Exempt Status:	N
Records Off-Site:	No

PJ MATHEWS (Continued) **U001286160**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	P J MATHEWS,OWNER
Contact Organization Name:	PJ MATHEWS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2147947194
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/26/1990
Signature Name/Title On Earliest Reg Form:	P J MATHEWS,OWNER
Application Received Date On Earliest Reg Form:	08/30/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600983589
Owner Last Name:	MATHEWS P J
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	395622262002087
Additional ID:	405622272002087
AI Number:	56052
Owner Effective Begin Date:	10/04/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1950
Tank Registration Date:	08/30/1990
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N

PJ MATHEWS (Continued) **U001286160**

Pipe Type:	Not reported
UST ID:	135903
Facility ID:	85886
Ai Number:	56052
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

PJ MATHEWS (Continued) **U001286160**

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	133749
UST ID:	135903
AI Number:	56052
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21825
Cert ID:	93897
UST Comprt ID:	275586
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93896
UST Comprt ID:	275585
UST ID:	108311

PJ MATHEWS (Continued) **U001286160**

AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93898
UST Comprt ID:	275582
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93894
UST Comprt ID:	275583
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93895
UST Comprt ID:	275584
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1950
Tank Registration Date:	08/30/1990
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	135904
Facility ID:	85886
Ai Number:	56052
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

PJ MATHEWS (Continued) **U001286160**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	133750
UST ID:	135904
AI Number:	56052
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

PJ MATHEWS (Continued) **U001286160**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21825
Cert ID:	93897
UST Comprt ID:	275586
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93896
UST Comprt ID:	275585
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93898
UST Comprt ID:	275582
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93894
UST Comprt ID:	275583
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93895
UST Comprt ID:	275584
UST ID:	108311

PJ MATHEWS (Continued) **U001286160**

AI Number:	56052
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1950
Tank Registration Date:	08/30/1990
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	135905
Facility ID:	85886
Ai Number:	56052
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

PJ MATHEWS (Continued) **U001286160**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	133751
UST ID:	135905
AI Number:	56052
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21825
Cert ID:	93897

PJ MATHEWS (Continued) **U001286160**

UST Comprt ID:	275586
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93896
UST Comprt ID:	275585
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93898
UST Comprt ID:	275582
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93894
UST Comprt ID:	275583
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93895
UST Comprt ID:	275584
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1950
Tank Registration Date:	08/30/1990
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	135906
Facility ID:	85886
Ai Number:	56052
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

PJ MATHEWS (Continued) **U001286160**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	500
UST Comprt ID:	133752
UST ID:	135906
AI Number:	56052
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

PJ MATHEWS (Continued) **U001286160**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21825
Cert ID:	93897
UST Comprt ID:	275586
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93896
UST Comprt ID:	275585
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93898
UST Comprt ID:	275582
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93894

PJ MATHEWS (Continued) **U001286160**

UST Comprt ID:	275583
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A
Self Cert ID:	21825
Cert ID:	93895
UST Comprt ID:	275584
UST ID:	108311
AI Number:	56052
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	MATHEWS P J
Contact Mailing Address (Delivery):	412 W 3RD ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75501 5639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85886
Additional ID:	405622272002087
Princ ID:	395622262002087
AI Number:	56052
Facility Name:	PJ MATHEWS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PJ MATHEWS/

---

46 **BURCH MOTOR** **TX UST** **U001247826**
West **501 TEXAS BLVD** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.191 mi.
1006 ft.

Relative: **Lower**
Actual: **303 ft.**

UST:

AI Number:	11989
Facility Type:	UNKNOWN
Facility Begin Date:	07/31/1986
Facility Status:	INACTIVE
Additional ID:	914446992002087
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	L M BURCH,PRESIDENT

BURCH MOTOR (Continued) **U001247826**

Contact Organization Name:	BURCH MOTOR CO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2147933711
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	L M BURCH,PRESIDENT
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600974406
Owner Last Name:	BURCH MOTOR CO INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	924446992002087
Additional ID:	914446992002087
AI Number:	11989
Owner Effective Begin Date:	07/31/1986
State Tax ID:	17507221012
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	31372
Facility ID:	51079
Ai Number:	11989
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/07/1991
Empty:	N

BURCH MOTOR (Continued) **U001247826**

Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	46977
UST ID:	31372
AI Number:	11989
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported

BURCH MOTOR (Continued) **U001247826**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	4945
Cert ID:	94846
UST Comprt ID:	277535
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A

Self Cert ID:	4945
Cert ID:	94845
UST Comprt ID:	277536
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A

Self Cert ID:	4945
Cert ID:	94844
UST Comprt ID:	277539
UST ID:	105727
AI Number:	11989
Tank ID:	2

BURCH MOTOR (Continued) **U001247826**

Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94843
UST Comprt ID:	277538
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94842
UST Comprt ID:	277537
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94854
UST Comprt ID:	277527
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	299267
UST Comprt ID:	864797
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	283638
UST Comprt ID:	818393
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	266740
UST Comprt ID:	768319
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	250363
UST Comprt ID:	719836
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A

BURCH MOTOR (Continued) **U001247826**

Self Cert ID:	4945
Cert ID:	232424
UST Comprt ID:	667332
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94853
UST Comprt ID:	277528
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94852
UST Comprt ID:	277529
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94851
UST Comprt ID:	277530
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94850
UST Comprt ID:	277531
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94849
UST Comprt ID:	277532
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945
Cert ID:	94848
UST Comprt ID:	277533
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A
Self Cert ID:	4945

BURCH MOTOR (Continued) **U001247826**

Cert ID:	94847
UST Comprt ID:	277534
UST ID:	105727
AI Number:	11989
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	BURCH MOTOR CO INC
Contact Mailing Address (Delivery):	PO BOX 1034
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75504 1034
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	51079
Additional ID:	914446992002087
Princ ID:	924446992002087
AI Number:	11989
Facility Name:	BURCH MOTOR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

N47 **WILSON TIRE CENTER** **TX UST** **U003187994**
North **601 N STATE LINE AVE** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.192 mi.
1014 ft. **Site 1 of 2 in cluster N**

Relative: **Higher**
Actual: **325 ft.**

UST:

AI Number:	43572
Facility Type:	RETAIL
Facility Begin Date:	08/31/1988
Facility Status:	INACTIVE
Additional ID:	245311312002086
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	BRUCE WILSON,OWNER
Contact Organization Name:	WILSON TIRE CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9037942154
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported

WILSON TIRE CENTER (Continued) **U003187994**

Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/19/1986
Signature Name/Title On Earliest Reg Form:	C L KRZYSIAK,SEC. MGR.
Application Received Date On Earliest Reg Form:	05/27/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600924823
Owner Last Name:	WILSON BRUCE E
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	235311302002086
Additional ID:	245311312002086
AI Number:	43572
Owner Effective Begin Date:	08/31/1994
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1941
Tank Registration Date:	05/27/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	114903
Facility ID:	86292
Ai Number:	43572
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/19/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

WILSON TIRE CENTER (Continued) **U003187994**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	136455
UST ID:	114903
AI Number:	43572
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

WILSON TIRE CENTER (Continued) **U003187994**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17141
Cert ID:	53679
UST Comprt ID:	156344
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53678
UST Comprt ID:	156345
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53677
UST Comprt ID:	156346
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53676
UST Comprt ID:	156347
UST ID:	51220
AI Number:	43572

WILSON TIRE CENTER (Continued) **U003187994**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53675
UST Comprt ID:	156348
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53674
UST Comprt ID:	156349
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53673
UST Comprt ID:	156350
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53672
UST Comprt ID:	156351
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	220918
UST Comprt ID:	633514
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	237458
UST Comprt ID:	681939
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	253760
UST Comprt ID:	729717
UST ID:	51220
AI Number:	43572
Tank ID:	4

WILSON TIRE CENTER (Continued) **U003187994**

Compartment ID:	A
Self Cert ID:	17141
Cert ID:	262228
UST Comprt ID:	755127
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	276089
UST Comprt ID:	795880
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	281895
UST Comprt ID:	813167
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	299430
UST Comprt ID:	865291
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53671
UST Comprt ID:	156354
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53670
UST Comprt ID:	156353
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53680
UST Comprt ID:	156343
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

WILSON TIRE CENTER (Continued) **U003187994**

Self Cert ID:	17141
Cert ID:	53669
UST Comprt ID:	156352
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1941
Tank Registration Date:	05/27/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	114904
Facility ID:	86292
Ai Number:	43572
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/19/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

WILSON TIRE CENTER (Continued) **U003187994**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	136456
UST ID:	114904
AI Number:	43572
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

WILSON TIRE CENTER (Continued) **U003187994**

More Self Certification:

Self Cert ID:	17141
Cert ID:	53679
UST Comprt ID:	156344
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53678
UST Comprt ID:	156345
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53677
UST Comprt ID:	156346
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53676
UST Comprt ID:	156347
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53675
UST Comprt ID:	156348
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53674
UST Comprt ID:	156349
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53673
UST Comprt ID:	156350
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

WILSON TIRE CENTER (Continued) **U003187994**

Self Cert ID:	17141
Cert ID:	53672
UST Comprt ID:	156351
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	220918
UST Comprt ID:	633514
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	237458
UST Comprt ID:	681939
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	253760
UST Comprt ID:	729717
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	262228
UST Comprt ID:	755127
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	276089
UST Comprt ID:	795880
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	281895
UST Comprt ID:	813167
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141

WILSON TIRE CENTER (Continued) **U003187994**

Cert ID:	299430
UST Comprt ID:	865291
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53671
UST Comprt ID:	156354
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53670
UST Comprt ID:	156353
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53680
UST Comprt ID:	156343
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53669
UST Comprt ID:	156352
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

Install Date:	01/01/1941
Tank Registration Date:	05/27/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	114905
Facility ID:	86292
Ai Number:	43572
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/18/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

WILSON TIRE CENTER (Continued) **U003187994**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	1000
UST Comprt ID:	136457
UST ID:	114905
AI Number:	43572
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

WILSON TIRE CENTER (Continued) **U003187994**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17141
Cert ID:	53679
UST Comprt ID:	156344
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17141
Cert ID:	53678
UST Comprt ID:	156345
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17141
Cert ID:	53677
UST Comprt ID:	156346
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17141

WILSON TIRE CENTER (Continued) **U003187994**

Cert ID:	53676
UST Comprt ID:	156347
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53675
UST Comprt ID:	156348
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53674
UST Comprt ID:	156349
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53673
UST Comprt ID:	156350
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53672
UST Comprt ID:	156351
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	220918
UST Comprt ID:	633514
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	237458
UST Comprt ID:	681939
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	253760

WILSON TIRE CENTER (Continued) **U003187994**

UST Comprt ID:	729717
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	262228
UST Comprt ID:	755127
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	276089
UST Comprt ID:	795880
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	281895
UST Comprt ID:	813167
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	299430
UST Comprt ID:	865291
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53671
UST Comprt ID:	156354
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53670
UST Comprt ID:	156353
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53680
UST Comprt ID:	156343

WILSON TIRE CENTER (Continued) **U003187994**

UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53669
UST Comprt ID:	156352
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1941
Tank Registration Date:	05/27/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	114906
Facility ID:	86292
Ai Number:	43572
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/13/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

WILSON TIRE CENTER (Continued) **U003187994**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	136458
UST ID:	114906
AI Number:	43572
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

WILSON TIRE CENTER (Continued) **U003187994**

Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:
Self Cert ID: 17141
Cert ID: 53679
UST Comprt ID: 156344
UST ID: 51220
AI Number: 43572
Tank ID: 4
Compartment ID: A

Self Cert ID: 17141
Cert ID: 53678
UST Comprt ID: 156345
UST ID: 51220
AI Number: 43572
Tank ID: 4
Compartment ID: A

Self Cert ID: 17141
Cert ID: 53677
UST Comprt ID: 156346
UST ID: 51220
AI Number: 43572
Tank ID: 4
Compartment ID: A

Self Cert ID: 17141
Cert ID: 53676
UST Comprt ID: 156347
UST ID: 51220
AI Number: 43572
Tank ID: 4
Compartment ID: A

Self Cert ID: 17141
Cert ID: 53675
UST Comprt ID: 156348
UST ID: 51220
AI Number: 43572
Tank ID: 4
Compartment ID: A

Self Cert ID: 17141
Cert ID: 53674
UST Comprt ID: 156349
UST ID: 51220
AI Number: 43572
Tank ID: 4
Compartment ID: A

Self Cert ID: 17141
Cert ID: 53673
UST Comprt ID: 156350

WILSON TIRE CENTER (Continued) **U003187994**

UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53672
UST Comprt ID:	156351
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	220918
UST Comprt ID:	633514
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	237458
UST Comprt ID:	681939
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	253760
UST Comprt ID:	729717
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	262228
UST Comprt ID:	755127
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	276089
UST Comprt ID:	795880
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	281895
UST Comprt ID:	813167
UST ID:	51220

WILSON TIRE CENTER (Continued) **U003187994**

AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	299430
UST Comprt ID:	865291
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53671
UST Comprt ID:	156354
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53670
UST Comprt ID:	156353
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53680
UST Comprt ID:	156343
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53669
UST Comprt ID:	156352
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1941
Tank Registration Date:	05/27/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	114907
Facility ID:	86292
Ai Number:	43572
Tank Id:	5
Tank Status (Current):	PERM FILLED IN PLACE

WILSON TIRE CENTER (Continued) **U003187994**

Tank Status Date:	05/19/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	Not reported
UST Comprt ID:	136459
UST ID:	114907
AI Number:	43572
Compartment ID:	A

WILSON TIRE CENTER (Continued) **U003187994**

Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17141
Cert ID:	53679
UST Comprt ID:	156344
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53678
UST Comprt ID:	156345
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53677
UST Comprt ID:	156346
UST ID:	51220

WILSON TIRE CENTER (Continued) **U003187994**

AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53676
UST Comprt ID:	156347
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53675
UST Comprt ID:	156348
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53674
UST Comprt ID:	156349
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53673
UST Comprt ID:	156350
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53672
UST Comprt ID:	156351
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	220918
UST Comprt ID:	633514
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	237458
UST Comprt ID:	681939
UST ID:	51220
AI Number:	43572

WILSON TIRE CENTER (Continued) **U003187994**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	253760
UST Comprt ID:	729717
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	262228
UST Comprt ID:	755127
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	276089
UST Comprt ID:	795880
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	281895
UST Comprt ID:	813167
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	299430
UST Comprt ID:	865291
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53671
UST Comprt ID:	156354
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53670
UST Comprt ID:	156353
UST ID:	51220
AI Number:	43572
Tank ID:	4

WILSON TIRE CENTER (Continued) **U003187994**

Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53680
UST Comprt ID:	156343
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53669
UST Comprt ID:	156352
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1941
Tank Registration Date:	05/27/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	114908
Facility ID:	86292
Ai Number:	43572
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/19/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

WILSON TIRE CENTER (Continued) **U003187994**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	136460
UST ID:	114908
AI Number:	43572
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

WILSON TIRE CENTER (Continued) **U003187994**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17141
Cert ID:	53679
UST Comprt ID:	156344
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53678
UST Comprt ID:	156345
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53677
UST Comprt ID:	156346
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53676
UST Comprt ID:	156347
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53675
UST Comprt ID:	156348
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53674
UST Comprt ID:	156349
UST ID:	51220
AI Number:	43572
Tank ID:	4

WILSON TIRE CENTER (Continued) **U003187994**

Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53673
UST Comprt ID:	156350
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53672
UST Comprt ID:	156351
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	220918
UST Comprt ID:	633514
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	237458
UST Comprt ID:	681939
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	253760
UST Comprt ID:	729717
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	262228
UST Comprt ID:	755127
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	276089
UST Comprt ID:	795880
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

WILSON TIRE CENTER (Continued) **U003187994**

Self Cert ID:	17141
Cert ID:	281895
UST Comprt ID:	813167
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	299430
UST Comprt ID:	865291
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53671
UST Comprt ID:	156354
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53670
UST Comprt ID:	156353
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53680
UST Comprt ID:	156343
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17141
Cert ID:	53669
UST Comprt ID:	156352
UST ID:	51220
AI Number:	43572
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	WILSON BRUCE E
Contact Mailing Address (Delivery):	PO BOX 1921
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75504 1921
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

WILSON TIRE CENTER (Continued) **U003187994**

Contact Address Deliverable:	Y
Facility ID:	86292
Additional ID:	245311312002086
Princ ID:	235311302002086
AI Number:	43572
Facility Name:	WILSON TIRE CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BRUCE WILSON/

O48 **UNION PACIFIC RAILROAD TEXARKANA** **TX Ind. Haz Waste** **S105835463**
NW **612 MAIN ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.194 mi.
1025 ft. **Site 1 of 5 in cluster O**

Relative:
Lower

Actual:
304 ft.

Ind. Haz Waste:

Registration Number:	67024
Registration Initial Notification Date:	02/14/2001
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TXT490011194
Primary NAICS Code:	Not reported
Status Change Date:	20010214
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Site Primary SIC Description:	Not reported
Registration is Generator of Waste:	Yes
Registration is Receivers of Waste:	No
Registration is Transporter of Waste:	No
Registration is Transfer Facility:	No
Facility is STEERS Reporter:	No
Reqired to Submit Annual Waste Summary:	No
Facility Involved In Recycling:	No
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator:	NON INDUS
TNRCC Region:	Not reported
Company Name:	UNION PACIFIC RAILROAD COMPANY
Contact Name:	DOWNING B JENKS
Contact Telephone Number:	281-3507495
Mailing Address:	1416 DODGE ST
Mailing Address2:	Not reported
Mailing City,St,Zip:	OMAHA, NE 681790001
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22175
Site Owner Tax ID:	946001323
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031021
Ind. waste permit Number:	Not reported
Mun waste permit Number:	Not reported
Non Notifier:	No

Business Records Not Found for this RegNo/Year:

UNION PACIFIC RAILROAD TEXARKANA (Continued) **S105835463**

Owner:
- Owner Mailing Address: Not reported
- Owner Mailing Address2: Not reported
- Owner Mailing Address3: Not reported
- Owner City,St,Zip: Not reported
- Owner Country: Not reported
- Owner Phone Number: Not reported
- Owner Fax Number: Not reported
- Owner Email Address: Not reported
- Owner Business Type: Corporation
- Owner Tax Id: 19460013238
- Owner Bankruptcy Code: Not reported

Operator:
- Operator Last Name: UNION PACIFIC RAILROAD
- Operator First Name: Not reported
- Operator Name: UNION PACIFIC RAILROAD
- Operator Mailing Address: Not reported
- Operator Mailing Address 2: Not reported
- Operator Mailing City,St,Zip: Not reported
- Operator Country: Not reported
- Operator Phone: Not reported
- Operator Fax: Not reported
- Operator Email: Not reported
- Operator Business Type: Corporation
- Operator Tax Id: 19460013238
- Operator Bankruptcy Code: Not reported

Contact:
- Contact Name: DOWNING JENKS
- Contact Title: MGR COMPLIANCE MEASUREMEN
- Contact Role: PRICONT
- Contact Address: 1416 DODGE ST
- Contact Address2: Not reported
- Conact City,St,Zip: OMAHA, NE 68179 0001
- Contact Phone: 1-281-3507495
- Contact Fax: Not reported
- Contact Email: Not reported

Contact:
- Contact Name: Not reported
- Contact Title: Not reported
- Contact Role: OPRCON
- Contact Address: 1416 DODGE ST ENVIRONMENTAL MANAGEMENT
- Contact Address2: Not reported
- Conact City,St,Zip: OMAHA, NE 68179 0001
- Contact Phone: 1-402-2716571
- Contact Fax: Not reported
- Contact Email: Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:
- Receiver Type: Not reported
- Transporter for hire: 0
- Transport own waste: 0
- Eq 01, if transport waste type = 1: Not reported
- Eq 02, if transport waste type = 2: Not reported
- Eq 03, if transport waste type = 3: Not reported

UNION PACIFIC RAILROAD TEXARKANA (Continued) **S105835463**

Eq 04, if transport waste type = H: Not reported
Target TCEQ unique facid for discarded(merged) facility: 12793

Waste Records Not Found for this RegNo/Year:

O49 **SOUTHERN PACIFIC TRANSPORTATION** **RCRA NonGen / NLR** **1004788509**
NW **612 MAIN STREET** **FINDS** **TXT490011194**
1/8-1/4 **TEXARKANA, TX 75501** **ECHO**
0.194 mi.
1025 ft. **Site 2 of 5 in cluster O**

Relative:
Lower

Actual:
304 ft.

RCRA NonGen / NLR:
Date form received by agency: 07/27/2001
Facility name: SOUTHERN PACIFIC TRANSPORTATION
Facility address: 612 MAIN STREET
TEXARKANA, TX 75501
EPA ID: TXT490011194
Mailing address: MAIN STREET
TEXARKANA, TX 75501
Contact: ENVIRONMENTAL MANAGER
Contact address: MAIN STREET
TEXARKANA, TX 75501
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 06
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: SOUTHERN PACIFIC TRANSPORTATION
Owner/operator address: MAIN STREET
TEXARKANA, TX 75501
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/27/2001
Owner/Op end date: Not reported

Owner/operator name: SOUTHERN PACIFIC TRANSPORTATION
Owner/operator address: MAIN STREET
TEXARKANA, TX 75501
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/27/2001
Owner/Op end date: Not reported

Handler Activities Summary:

SOUTHERN PACIFIC TRANSPORTATION (Continued) **1004788509**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/20/1980
Site name: SOUTHERN PACIFIC TRANSPORTATION CO
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110005192512

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004788509
Registry ID: 110005192512
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005192512

O50 **SOUTHERN PACIFIC TRANSPORTATION** **TX Ind. Haz Waste** **S103602285**
NW **612 MAIN ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.194 mi.
1025 ft. **Site 3 of 5 in cluster O**

Relative: Ind. Haz Waste:
Lower
Registration Number: 35726
Actual: Registration Initial Notification Date: 07/27/2001
304 ft. Registration Last Amendment Date: 07/27/2001
EPA Identification: TXT490011194
Primary NAICS Code: Not reported
Status Change Date: 20010727

SOUTHERN PACIFIC TRANSPORTATION (Continued) **S103602285**

Land Type:	PRIVATE
Description of Facility Site Location:	612 Main Street, Texarkana, TX
Site Primary Standard Industrial Code:	Not reported
Site Primary SIC Description:	Not reported
Registration is Generator of Waste:	Yes
Registration is Receivers of Waste:	No
Registration is Transporter of Waste:	No
Registration is Transfer Facility:	No
Facility is STEERS Reporter:	No
Reqired to Submit Annual Waste Summary:	No
Facility Involved In Recycling:	No
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator:	LQG
TNRCC Region:	Not reported
Company Name:	SOUTHERN PACIFIC TRANSPORTATION
Contact Name:	ENVIRONMENTAL MANAGER
Contact Telephone Number:	Not reported
Mailing Address:	612 MAIN ST
Mailing Address2:	Not reported
Mailing City,St,Zip:	TEXARKANA, TX 755015506
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	12793
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110408
Ind. waste permit Number:	Not reported
Mun waste permit Number:	Not reported
Non Notifier:	No

Business Records Not Found for this RegNo/Year:

Owner:

Owner Mailing Address:	612 MAIN ST
Owner Mailing Address2:	Not reported
Owner Mailing Address3:	Not reported
Owner City,St,Zip:	TEXARKANA, TX 75501 5506
Owner Country:	UNITED STA
Owner Phone Number:	Not reported
Owner Fax Number:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax Id:	Not reported
Owner Bankruptcy Code:	Not reported

Operator:

Operator Last Name:	SOUTHERN PACIFIC TRANSPORTATION
Operator First Name:	Not reported
Operator Name:	SOUTHERN PACIFIC TRANSPORTATION
Operator Mailing Address:	612 MAIN ST
Operator Mailing Address 2:	Not reported
Operator Mailing City,St,Zip:	TEXARKANA, TX 75501 5506
Operator Country:	UNITED STA
Operator Phone:	Not reported
Operator Fax:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation

SOUTHERN PACIFIC TRANSPORTATION (Continued) **S103602285**

Operator Tax Id: Not reported
Operator Bankruptcy Code: Not reported

Contact:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OPRCON
Contact Address: 612 MAIN ST
Contact Address2: Not reported
Conact City,St,Zip: TEXARKANA, TX 75501 5506
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Contact:
Contact Name: Not reported
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 612 MAIN ST
Contact Address2: Not reported
Conact City,St,Zip: TEXARKANA, TX 75501 5506
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Contact:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: 612 MAIN ST
Contact Address2: Not reported
Conact City,St,Zip: TEXARKANA, TX 75501 5506
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Contact:
Contact Name: ENVIRONMENTAL MANAGER
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 612 MAIN ST
Contact Address2: Not reported
Conact City,St,Zip: TEXARKANA, TX 75501 5506
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:
Receiver Type: Not reported
Transporter for hire: 0
Transport own waste: 0
Eq 01, if transport waste type = 1: Not reported
Eq 02, if transport waste type = 2: Not reported
Eq 03, if transport waste type = 3: Not reported
Eq 04, if transport waste type = H: Not reported
Target TCEQ unique facid for discarded(merged) facility: Not reported

Waste Records Not Found for this RegNo/Year:

51
NNE
1/8-1/4
0.202 mi.
1067 ft.

SOUTHWEST ARK COMMUNITY PUNISH
506 WALNUT CENTE
TEXARKANA, AR 71854

AR UST FINDS **1009594394** **N/A**

Relative: Higher

Actual: 339 ft.

UST:

Facility Id:	46000084
ADEQ Facility ID:	46-00425
Active Site:	Not reported
Above Ground:	Not reported
Below Ground:	Yes
Aboveground in Use:	UST
Underground in Use:	UST
Date Reg Cert Issued:	05/28/1998
Lust Flag:	UST
Leak ID Number:	Not reported
Date Received:	12/14/1998
Location SIC:	Not reported
Federal Flag:	Yes
Contact Name:	STEVE ARNOLD
Contact Title:	SUPERVISOR
Contact Phone:	870-779-2036
Certified Name:	RICK HART
Certified Title:	DEPUTY DIRECTOR
Date Signed:	12/10/1998
Amended:	Yes
No Bill:	Not reported
Facility Entry Clerk:	TT
Facility Update Date:	01/08/1999
Facility Update Clerk:	BATEMAN
Latitude:	Not reported
Longitude:	Not reported

Owner:

Owner ID:	007359
Owner Name:	SOUTHWEST ARK COMMUNITY PUNISHMT
Owner Address:	506 WALNUT CENTER
Owner City,St,Zip:	TEXARKANA, AR 71854
Owner County:	MILLER
Owner Phone:	5017792036
Owner Type:	Private Industry

AST/UST Eligible:

Facility Id:	46000084
Date Eligible:	12/4/1991
Transaction Code:	CIOU
Entry Clerk:	GCRAGG
Entry Date:	12/4/1991
Update Clerk:	Not reported
Update Date:	Not reported
Eligibility Description:	Certificate issued, original, UST

Facility Id:	46000084
Date Eligible:	12/16/1991
Transaction Code:	CIOU
Entry Clerk:	GCRAGG
Entry Date:	12/16/1991
Update Clerk:	Not reported

SOUTHWEST ARK COMMUNITY PUNISH (Continued) **1009594394**

Update Date: Not reported
Eligibility Description: Certificate issued, original, UST

Tank Info:
Facility ID: 46000084
Record Created By: Not reported
Record Created Date: Not reported
Record Modified By: MARSH
Record Modified Date: 6/9/1999
Site Assessment Date: Not reported
Site Assessment Leak: Not reported
Certificate of Compliance Final Test Date: Not reported
Certificate of Compliance Test Company License: Not reported
Certificate of Compliance Tester License: Not reported
Certificate of Compliance Installation Date: Not reported
Certificate of Compliance Install Company License: Not reported
Certificate of Compliance Installer License: Not reported

Tank ID: 1
Tank Status: **Permanently Out of Service 09/01/1998**
Install Date: Not reported
Tank Contents: Unknown
Cerclis Name: Not reported
Tank Material: Unknown
GIS Location: Not reported
Federal Flag: Not reported
Hazardous: Not reported
Capacity in Gallons: 1000
Number of Compartments: 1
Decode for Tstatus: Permanently Out of Use
Release Detection: Unknown
Release Detection Install Date: Not reported
Tank External Corrosion Protection: Unknown
Tank Ext Corrosion Protection Install Date: Not reported
Pipe Material: Unknown
Pipe Type: Unknown
Pipe Release Detection: Unknown
Pipe Corrosion Protection: Unknown
Tank Spill and Overfill Protection: Unknown
Pipe Repaired: Not reported
Pipe Corrosion Protection: Unknown
Corrosion Protection: Not reported
Spill and Overflow: Not reported
Release Detection: Not reported
Tank Comments: Not reported

Facility ID: 46000084
Record Created By: Not reported
Record Created Date: 12/20/1990
Record Modified By: TERESA
Record Modified Date: 6/16/1999
Site Assessment Date: 12/15/1995
Site Assessment Leak: Not reported
Certificate of Compliance Final Test Date: 09/18/1998
Certificate of Compliance Test Company License: 000115
Certificate of Compliance Tester License: 000752
Certificate of Compliance Installation Date: Not reported

SOUTHWEST ARK COMMUNITY PUNISH (Continued) **1009594394**

Certificate of Compliance Install Company License: 000115
Certificate of Compliance Installer License: 000613

Tank ID: 2
Tank Status: Permanently Out of Service 09/01/1998
Install Date: Not reported
Tank Contents: Diesel
Cerclis Name: Not reported
Tank Material: Epoxy
GIS Location: Not reported
Federal Flag: Not reported
Hazardous: Not reported
Capacity in Gallons: 1000
Number of Compartments: 1
Decode for Tstatus: Permanently Out of Use
Release Detection: Tightness, Ground Water Monitoring, Ground Water Monitoring
Release Detection Install Date: Not reported
Tank External Corrosion Protection: Diesel
Tank Ext Corrosion Protection Install Date: Not reported
Pipe Material: Fiberglass Reinforced Plastic, Double Walled
Pipe Type: Suction TCV
Pipe Release Detection: Intersti Flag
Pipe Corrosion Protection: Fiberglass Reinforced Plastic
Tank Spill and Overfill Protection: Basin, Auto Flow
Pipe Repaired: Not reported
Pipe Corrosion Protection: Fiberglass Reinforced Plastic
Corrosion Protection: X
Spill and Overflow: X
Release Detection: Yes
Tank Comments: Not reported

FINDS:

Registry ID: 110025136396

Environmental Interest/Information System
Arkansas Permit Data System (PDS) is a system maintaining data on air quality, mining, tires, solid waste, tank, water and hazardous waste, as well as inspections, invoicing and complaints.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P52 **TIRE CITY** **TX UST** **U003420294**
WSW **418 W 4TH ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.203 mi.
1072 ft. **Site 1 of 2 in cluster P**

Relative: UST:
Lower
Actual: AI Number: 71137
301 ft. Facility Type: RETAIL
Facility Begin Date: 08/31/1987
Facility Status: INACTIVE
Additional ID: 561788582002087
Facility Exempt Status: Y

TIRE CITY (Continued) **U003420294**

Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	BRUCE WILSON,
Contact Organization Name:	TIRE CITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9037942154
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/05/1998
Signature Name/Title On Earliest Reg Form:	BRUCE WILSON,OWNER
Application Received Date On Earliest Reg Form:	11/02/1998
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600924823
Owner Last Name:	WILSON BRUCE E
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	235311302002086
Additional ID:	561788582002087
AI Number:	71137
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	11/02/1998
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y

TIRE CITY (Continued) **U003420294**

Tank Doublewall:	N
Pipe Type:	S
UST ID:	188038
Facility ID:	108340
Ai Number:	71137
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/14/1998
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

TIRE CITY (Continued) **U003420294**

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	177422
UST ID:	188038
AI Number:	71137
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	11/02/1998
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	188039
Facility ID:	108340
Ai Number:	71137
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/14/1998

TIRE CITY (Continued) **U003420294**

Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	177423
UST ID:	188039
AI Number:	71137
Compartment ID:	A
Substance Stored1:	GASOLINE

TIRE CITY (Continued) **U003420294**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WILSON BRUCE E
Contact Mailing Address (Delivery):	PO BOX 1921
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75504 1921
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	108340
Additional ID:	561788582002087
Princ ID:	235311302002086
AI Number:	71137
Facility Name:	TIRE CITY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BRUCE WILSON/

O53 **DANG GOOD USED CARS** **TX LPST** **U001246672**
NW **401 W 7TH ST** **TX UST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501** **TX Financial Assurance**
0.213 mi. **TX GCC**
1122 ft. **Site 4 of 5 in cluster O**

Relative:
Lower

Actual:
307 ft.

LPST:

Facility ID:	0010627
LPST Id:	96657
Facility Location:	401 W 7TH ST
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	12/31/3000
Entered Date:	09/06/1990
Priority:	3.5 - A DESIGNATED MAJOR OR MINOR AQUIFER IS IMPACTED
Program:	1 - RPR
CA Status:	1 - RELEASE DETERMINATION
Priority Description:	A designated major or minor groundwater aquifer is affected or immediately threatened.
Status:	**PREASSESSMENT/RELEASE DETERMINATION**
Coordinators Primary:	1/1P/1/2
Coordinators RPR:	KLM
Responsible Party Name:	LESHER MARK
Responsible Party Contact:	MARK LESHER
Responsible Party Address:	524 SPRUCE ST
Responsible Party City,St,Zip:	TEXARKANA, TX 75501
Responsible Party Telephone:	903/794-3309
Reported Date:	08/30/1990
Case Start Date:	09/06/1990

UST:

AI Number:	10627
Facility Type:	RETAIL
Facility Begin Date:	01/01/1971
Facility Status:	ACTIVE
Additional ID:	587426792002089
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	5
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	TAMMIE PATRICK,
Contact Organization Name:	DANG GOOD USED CARS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9032235263
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	OTHO CROMER,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported

DANG GOOD USED CARS (Continued) **U001246672**

Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	845347442003364
Additional ID:	587426792002089
Ai Number:	10627
Operator CN:	CN602529307
Operator Name:	TAMMIE PATRICK
Operator Effective Begin Date:	03/03/2003
Operator Type:	IN
Operator Role:	OPRCON
Contact Name:	/
Contact Organization Name:	PATRICK TAMMIE
Contact Mailing Address (Delivery):	28 CLEM RANCH RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA TX 75503-9604
Contact Phone Country Code:	1
Contact Phone Area Code:	903
Contact Phone Number:	2235263
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602529307
Owner Last Name:	PATRICK
Owner First Name:	TAMMIE
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	401 W 7TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	TEXARKANA
Contact Mailing State:	TX
Contact Mailing Zip:	75501
Contact Mailing Zip5:	5527
Contact Phone Number/Ext:	1 903 2235263/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	845347442003364
Additional ID:	587426792002089
AI Number:	10627
Owner Effective Begin Date:	03/03/2003
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	TAMMIE PATRICK/
Contact Organization Name:	PATRICK TAMMIE

Self Certification:

Self Cert ID:	49968
Cert ID:	42138

DANG GOOD USED CARS (Continued) **U001246672**

AI Number:	10627
Self Certification Date:	01/09/2004
Signature Name/Title:	TAMMIE PATRICK OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27994
Facility ID:	49968
Ai Number:	10627
Tank Id:	1
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	12/04/1998
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

DANG GOOD USED CARS (Continued) **U001246672**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	36113
UST ID:	27994
AI Number:	10627
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

DANG GOOD USED CARS (Continued) **U001246672**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27995
Facility ID:	49968
Ai Number:	10627
Tank Id:	5
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	12/04/1998
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

DANG GOOD USED CARS (Continued) **U001246672**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	Not reported
UST Comprt ID:	36114
UST ID:	27995
AI Number:	10627
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

DANG GOOD USED CARS (Continued) **U001246672**

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27999
Facility ID:	49968
Ai Number:	10627
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/11/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

DANG GOOD USED CARS (Continued) **U001246672**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	6
Tank Capacity:	9999
UST Comprt ID:	36118
UST ID:	27999
AI Number:	10627
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27997

DANG GOOD USED CARS (Continued) **U001246672**

Facility ID:	49968
Ai Number:	10627
Tank Id:	4
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	12/04/1998
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported

DANG GOOD USED CARS (Continued) **U001246672**

UST Comprt ID:	36116
UST ID:	27997
AI Number:	10627
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27998
Facility ID:	49968
Ai Number:	10627
Tank Id:	3
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	12/04/1998
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

DANG GOOD USED CARS (Continued) **U001246672**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	36117
UST ID:	27998
AI Number:	10627
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

DANG GOOD USED CARS (Continued) **U001246672**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3750
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27996
Facility ID:	49968
Ai Number:	10627
Tank Id:	2
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	12/04/1998
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

DANG GOOD USED CARS (Continued) **U001246672**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	36115
UST ID:	27996
AI Number:	10627
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

DANG GOOD USED CARS (Continued) **U001246672**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PATRICK TAMMIE
Contact Mailing Address (Delivery):	401 W 7TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75501 5527
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	49968
Additional ID:	587426792002089
Princ ID:	845347442003364
AI Number:	10627
Facility Name:	DANG GOOD USED CARS
AR Number:	61970
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	TAMMIE PATRICK/

TX Financial Assurance 2:

Region:	2
Facility ID:	49968
Finass ID:	32979
AI:	10627
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

DANG GOOD USED CARS (Continued) **U001246672**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Division:	REM/PST
New Cases:	Not reported
File Number:	96657
Contamination Description:	WASTE OIL
Date Of Earliest Known Contamination Confirmation:	8/30/1990
Enforcement Status - Level Of Agency Response:	1B
Enforcement Status - Site Activity Status:	1A
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Division:	RMD/PST
New Cases:	Not reported
File Number:	096657
Contamination Description:	WASTE OIL
Date Of Earliest Known Contamination Confirmation:	9/6/1990
Enforcement Status - Level Of Agency Response:	1A
Enforcement Status - Site Activity Status:	1A
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Division:	RMD/PST
New Cases:	Not reported
File Number:	096657
Contamination Description:	WASTE OIL
Date Of Earliest Known Contamination Confirmation:	9/6/1990
Enforcement Status - Level Of Agency Response:	2
Enforcement Status - Site Activity Status:	2A
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported

DANG GOOD USED CARS (Continued) **U001246672**

Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: RMD/PST
New Cases: Not reported
File Number: 096657
Contamination Description: WASTE OIL
Date Of Earliest Known Contamination Confirmation: 9/6/1990
Enforcement Status - Level Of Agency Response: 2A
Enforcement Status - Site Activity Status: 2A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: REM/PST
New Cases: Not reported
File Number: 96657
Contamination Description: WASTE OIL
Date Of Earliest Known Contamination Confirmation: 8/30/1990
Enforcement Status - Level Of Agency Response: 1B
Enforcement Status - Site Activity Status: Not reported
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: RMD/PST
New Cases: Not reported
File Number: 096657
Contamination Description: WASTE OIL
Date Of Earliest Known Contamination Confirmation: 9/6/1990
Enforcement Status - Level Of Agency Response: 2
Enforcement Status - Site Activity Status: 2A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: REM/PST

DANG GOOD USED CARS (Continued) **U001246672**

New Cases: Not reported
File Number: 096657
Contamination Description: WASTE OIL
Date Of Earliest Known Contamination Confirmation: 9/6/1990
Enforcement Status - Level Of Agency Response: 1B
Enforcement Status - Site Activity Status: 1A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: REM/PST
New Cases: Not reported
File Number: 096657
Contamination Description: WASTE OIL
Date Of Earliest Known Contamination Confirmation: 9/6/1990
Enforcement Status - Level Of Agency Response: 1B
Enforcement Status - Site Activity Status: 1A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: REM/PST
New Cases: Not reported
File Number: 96657
Contamination Description: WASTE OIL
Date Of Earliest Known Contamination Confirmation: 9/6/1990
Enforcement Status - Level Of Agency Response: 1B
Enforcement Status - Site Activity Status: 1A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

O54 **CAL WILLIAMS USED CAR LOT** **TX UST** **U003420288**
NW **423 W 7TH ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.219 mi.
1154 ft. **Site 5 of 5 in cluster O**

Relative: **Lower**

Actual: **304 ft.**

UST:

AI Number:	60808
Facility Type:	FLEET REFUELING
Facility Begin Date:	10/24/1991
Facility Status:	INACTIVE
Additional ID:	114384602002089
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	,
Contact Organization Name:	CAL WILLIAMS USED CAR LOT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9037923311
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/10/1991
Signature Name/Title On Earliest Reg Form:	CHUCK NEWTON,ATTORNEY OF RECORD
Application Received Date On Earliest Reg Form:	10/16/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601032741
Owner Last Name:	N & N LEASING
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	124384602002089
Additional ID:	114384602002089
AI Number:	60808
Owner Effective Begin Date:	10/24/1991
State Tax ID:	30118249389

CAL WILLIAMS USED CAR LOT (Continued) **U003420288**

Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/16/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142787
Facility ID:	91169
Ai Number:	60808
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/12/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

CAL WILLIAMS USED CAR LOT (Continued) **U003420288**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	141973
UST ID:	142787
AI Number:	60808
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	23556
Cert ID:	56507

CAL WILLIAMS USED CAR LOT (Continued) **U003420288**

UST Comprt ID:	178841
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56670
UST Comprt ID:	178837
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56506
UST Comprt ID:	178842
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56505
UST Comprt ID:	178843
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56504
UST Comprt ID:	178846
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56503
UST Comprt ID:	178845
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56669
UST Comprt ID:	178838
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56672
UST Comprt ID:	178835

CAL WILLIAMS USED CAR LOT (Continued) **U003420288**

UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56502
UST Comprt ID:	178844
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	240781
UST Comprt ID:	691606
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	256117
UST Comprt ID:	736842
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	223315
UST Comprt ID:	640485
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56671
UST Comprt ID:	178836
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56668
UST Comprt ID:	178839
UST ID:	59468
AI Number:	60808
Tank ID:	3
Compartment ID:	A
Self Cert ID:	23556
Cert ID:	56667
UST Comprt ID:	178840
UST ID:	59468

CAL WILLIAMS USED CAR LOT (Continued) **U003420288**

AI Number:	60808
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	N & N LEASING
Contact Mailing Address (Delivery):	7837 HIGHWAY 100
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	NASHVILLE, TN 37221 4117
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91169
Additional ID:	114384602002089
Princ ID:	124384602002089
AI Number:	60808
Facility Name:	CAL WILLIAMS USED CAR LOT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHUCK NEWTON/

Q55 **ROBBINS TOYOTA** **TX UST** **U003406817**
WNW **601 TEXAS BLVD** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.228 mi.
1204 ft. **Site 1 of 4 in cluster Q**

Relative: **Lower**

Actual: **298 ft.**

UST:

AI Number:	10522
Facility Type:	UNKNOWN
Facility Begin Date:	07/23/1986
Facility Status:	INACTIVE
Additional ID:	330689992002088
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	,
Contact Organization Name:	ROBBINS TOYOTA INC
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2147945121
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/18/1986
Signature Name/Title On Earliest Reg Form:	EDDIE E ROBBINS,PRES

ROBBINS TOYOTA (Continued) **U003406817**

Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601006752
Owner Last Name:	ROBBINS MOTOR COMPANY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	340689982002088
Additional ID:	330689992002088
AI Number:	10522
Owner Effective Begin Date:	07/23/1986
State Tax ID:	17515630212
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	27784
Facility ID:	49889
Ai Number:	10522
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/31/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

ROBBINS TOYOTA (Continued) **U003406817**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	35293
UST ID:	27784
AI Number:	10522
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

ROBBINS TOYOTA (Continued) **U003406817**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ROBBINS TOYOTA INC
Contact Mailing Address (Delivery):	3103 SUMMERHILL RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75503 3965
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	49889
Additional ID:	330689992002088
Princ ID:	340689982002088
AI Number:	10522
Facility Name:	ROBBINS TOYOTA
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

N56 **BEALS SERVICE** **TX LPST** **U001279941**
North **201 W 7TH ST** **TX UST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.229 mi.
1209 ft. **Site 2 of 2 in cluster N**

Relative: LPST:
Higher

Facility ID:	0048891
LPST Id:	113938
Facility Location:	201 W 7TH ST
TCEQ Region# and City:	5
Region City:	TYLER

Actual:
319 ft.

BEALS SERVICE (Continued) **U001279941**

Reported Date:	06/29/2007
Entered Date:	01/05/1999
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1
Coordinators RPR:	KJM
Responsible Party Name:	WREN OIL CO
Responsible Party Contact:	MARGARET CHANDLER
Responsible Party Address:	702 DES MOINES
Responsible Party City,St,Zip:	TEXARKANA, TX 71854
Responsible Party Telephone:	870/774-9151
Reported Date:	12/07/1998
Case Start Date:	01/05/1999

UST:

AI Number:	48891
Facility Type:	RETAIL
Facility Begin Date:	08/17/1989
Facility Status:	INACTIVE
Additional ID:	682623882003100
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75502
Contact Name/Title:	RICHARD CHANDLER,
Contact Organization Name:	BEALS SERVICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8707749151
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/09/1989
Signature Name/Title On Earliest Reg Form:	SAME,SAME
Application Received Date On Earliest Reg Form:	08/16/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601617020
Owner Last Name:	H B WREN OIL DISTRIBUTING COMPANY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

BEALS SERVICE (Continued) **U001279941**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	745623292003100
Additional ID:	682623882003100
AI Number:	48891
Owner Effective Begin Date:	08/17/1989
State Tax ID:	17193577156
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	08/16/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	127089
Facility ID:	80612
Ai Number:	48891
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

BEALS SERVICE (Continued) **U001279941**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	133108
UST ID:	127089
AI Number:	48891
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

BEALS SERVICE (Continued) **U001279941**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	08/16/1989
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	127090
Facility ID:	80612
Ai Number:	48891
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

BEALS SERVICE (Continued) **U001279941**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	133109
UST ID:	127090
AI Number:	48891
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

BEALS SERVICE (Continued) **U001279941**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1981
Tank Registration Date:	08/16/1989
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	127091
Facility ID:	80612
Ai Number:	48891
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

BEALS SERVICE (Continued) **U001279941**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	2000
UST Comprt ID:	133110
UST ID:	127091
AI Number:	48891
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	08/16/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y

BEALS SERVICE (Continued) **U001279941**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	127092
Facility ID:	80612
Ai Number:	48891
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1991

BEALS SERVICE (Continued) **U001279941**

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	133111
UST ID:	127092
AI Number:	48891
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	08/16/1989
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	127093
Facility ID:	80612
Ai Number:	48891
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/23/1998

BEALS SERVICE (Continued) **U001279941**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	12000
UST Comprt ID:	133112
UST ID:	127093
AI Number:	48891
Compartment ID:	A
Substance Stored1:	GASOLINE

BEALS SERVICE (Continued) **U001279941**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	H B WREN OIL DISTRIBUTING COMPANY INC
Contact Mailing Address (Delivery):	PO BOX 329
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75504 0329
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	80612
Additional ID:	682623882003100
Princ ID:	745623292003100
AI Number:	48891
Facility Name:	BEALS SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RICHARD CHANDLER/

R57
East
1/8-1/4
0.230 mi.
1212 ft.

SWIFT BUILDING
410 E. BROAD ST.
TEXARKANA, AR 71854

Site 1 of 4 in cluster R

US BROWNFIELDS FINDS **1016159292 N/A**

Relative:
Lower

Actual:
305 ft.

US BROWNFIELDS:

Property Name:	SWIFT BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.21
Latitude:	33.4229745
Longitude:	-94.0395221
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94602
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10013
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	96656301
Start Date:	12/04/2007 00:00:00
Ownership Entity:	Private
Completion Date:	04/21/2008 00:00:00
Current Owner:	Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported

SWIFT BUILDING (Continued) **1016159292**

Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.21
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported

SWIFT BUILDING (Continued) **1016159292**

Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Meat Packing Plant.
Below Poverty Number:	316
Below Poverty Percent:	20.0%
Meidan Income:	9555
Meidan Income Number:	484
Meidan Income Percent:	30.6%
Vacant Housing Number:	113
Vacant Housing Percent:	31.5%
Unemployed Number:	62
Unemployed Percent:	3.9%

Property Name:	SWIFT BUILDING
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.21
Latitude:	33.4229745
Longitude:	-94.0395221
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94602
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10013
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum

SWIFT BUILDING (Continued) **1016159292**

Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	12/04/2007 00:00:00
Ownership Entity:	Private
Completion Date:	04/21/2008 00:00:00
Current Owner:	Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported

SWIFT BUILDING (Continued) **1016159292**

Surface Water:	Not reported
Past use commercial acreage:	.21
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Meat Packing Plant.
Below Poverty Number:	316
Below Poverty Percent:	20.0%
Meidan Income:	9555
Meidan Income Number:	484
Meidan Income Percent:	30.6%
Vacant Housing Number:	113
Vacant Housing Percent:	31.5%
Unemployed Number:	62
Unemployed Percent:	3.9%

FINDS:

Registry ID: 110039689049

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES)

SWIFT BUILDING (Continued) **1016159292**

is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q58 **MONTGOMERY WARD** **TX LPST** **S103394521**
WNW **10 OAKLAWN SHOPPING CTR** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.237 mi.
1251 ft. **Site 2 of 4 in cluster Q**

Relative: LPST:
Lower

Facility ID:	0019051
LPST Id:	93895
Facility Location:	OAKLAWN SHOPPING CENTER ON HWY 67
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	03/11/1991
Entered Date:	11/06/1989
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RAY YORK
Responsible Party Name:	MONTGOMERY WARD LLC
Responsible Party Contact:	DAVID JANSKY
Responsible Party Address:	2600 W 7TH ST
Responsible Party City,St,Zip:	FORT WORTH, TX 76107
Responsible Party Telephone:	817/338-3098
Reported Date:	10/11/1989
Case Start Date:	11/06/1989

Actual:
299 ft.

S59 **GRIFFIN SHELL** **TX LPST** **U001243149**
NW **404 W 7TH ST** **TX UST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.237 mi.
1253 ft. **Site 1 of 2 in cluster S**

Relative: LPST:
Lower

Facility ID:	0006689
LPST Id:	114099
Facility Location:	404 W 7TH ST
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	04/19/2007
Entered Date:	01/06/1999
Priority:	2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**

Actual:
305 ft.

GRIFFIN SHELL (Continued) **U001243149**

Coordinators Primary:	1/1P/1
Coordinators RPR:	DWP
Responsible Party Name:	GRIFFIN, ROBERT
Responsible Party Contact:	ROBERT GRIFFIN
Responsible Party Address:	404 W 7TH ST
Responsible Party City,St,Zip:	TEXARKANA, TX 75501
Responsible Party Telephone:	903/792-5081
Reported Date:	12/21/1998
Case Start Date:	01/06/1999

UST:

AI Number:	6689
Facility Type:	RETAIL
Facility Begin Date:	06/06/1986
Facility Status:	ACTIVE
Additional ID:	11290792002087
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	JAMES GIRFFIN,OWNER
Contact Organization Name:	GRIFFIN SHELL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7925080001
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/21/1986
Signature Name/Title On Earliest Reg Form:	JAMES GIRFFIN,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600966915
Owner Last Name:	GRIFFIN JAMES W
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/

GRIFFIN SHELL (Continued) **U001243149**

Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	2290792002087
Additional ID:	11290792002087
AI Number:	6689
Owner Effective Begin Date:	06/06/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	7943
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	17204
Facility ID:	45667
Ai Number:	6689
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1969
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

GRIFFIN SHELL (Continued) **U001243149**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	7943
UST Comprt ID:	23461
UST ID:	17204
AI Number:	6689
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

GRIFFIN SHELL (Continued) **U001243149**

Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:
Self Cert ID: 2699
Cert ID: 117294
UST Comprt ID: 344076
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117548
UST Comprt ID: 344071
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117547
UST Comprt ID: 344072
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117546
UST Comprt ID: 344073
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117298
UST Comprt ID: 344074
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117297
UST Comprt ID: 344075
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117296
UST Comprt ID: 344078
UST ID: 121860
AI Number: 6689

GRIFFIN SHELL (Continued) **U001243149**

Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117295
UST Comprt ID:	344077
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	7943
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	17205
Facility ID:	45667
Ai Number:	6689
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1969
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

GRIFFIN SHELL (Continued) **U001243149**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	7943
UST Comprt ID:	23462
UST ID:	17205
AI Number:	6689
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

GRIFFIN SHELL (Continued) **U001243149**

Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:
Self Cert ID: 2699
Cert ID: 117294
UST Comprt ID: 344076
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117548
UST Comprt ID: 344071
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117547
UST Comprt ID: 344072
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117546
UST Comprt ID: 344073
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117298
UST Comprt ID: 344074
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117297
UST Comprt ID: 344075
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117296
UST Comprt ID: 344078
UST ID: 121860
AI Number: 6689

GRIFFIN SHELL (Continued) **U001243149**

Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117295
UST Comprt ID:	344077
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Install Date:	01/01/1953
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	17206
Facility ID:	45667
Ai Number:	6689
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1953
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

GRIFFIN SHELL (Continued) **U001243149**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	500
UST Comprt ID:	23463
UST ID:	17206
AI Number:	6689
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

GRIFFIN SHELL (Continued) **U001243149**

Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:
Self Cert ID: 2699
Cert ID: 117294
UST Comprt ID: 344076
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117548
UST Comprt ID: 344071
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117547
UST Comprt ID: 344072
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117546
UST Comprt ID: 344073
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117298
UST Comprt ID: 344074
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117297
UST Comprt ID: 344075
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117296
UST Comprt ID: 344078
UST ID: 121860
AI Number: 6689

GRIFFIN SHELL (Continued) **U001243149**

Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117295
UST Comprt ID:	344077
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3992
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	17207
Facility ID:	45667
Ai Number:	6689
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

GRIFFIN SHELL (Continued) **U001243149**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3992
UST Comprt ID:	23464
UST ID:	17207
AI Number:	6689
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

GRIFFIN SHELL (Continued) **U001243149**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	2699
Cert ID:	117294
UST Comprt ID:	344076
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117548
UST Comprt ID:	344071
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117547
UST Comprt ID:	344072
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117546
UST Comprt ID:	344073
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117298
UST Comprt ID:	344074
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117297
UST Comprt ID:	344075
UST ID:	121860
AI Number:	6689
Tank ID:	1A
Compartment ID:	A
Self Cert ID:	2699
Cert ID:	117296
UST Comprt ID:	344078
UST ID:	121860
AI Number:	6689

GRIFFIN SHELL (Continued) **U001243149**

Tank ID: 1A
Compartment ID: A

Self Cert ID: 2699
Cert ID: 117295
UST Comprt ID: 344077
UST ID: 121860
AI Number: 6689
Tank ID: 1A
Compartment ID: A

Construction Notification:
NOC ID: 2161
Facility ID: 45667
AI Number: 6689
Application Received Date: 07/18/2004
Scheduled Construction Date: 07/26/2004
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M40718003
Waiver Flag: N
Late Filing Flag: Y
Form Received Date: Not reported
Signature Date On Form: Not reported
Signature Name On Form: Not reported
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 3803
General Desc Of Proposed Construction: Not reported

Facility Billing Contacts:
Contact Organization Name: GRIFFIN JAMES W
Contact Mailing Address (Delivery): 404 W 7TH ST
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: TEXARKANA, TX 75501 5528
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 45667
Additional ID: 11290792002087
Princ ID: 2290792002087
AI Number: 6689
Facility Name: GRIFFIN SHELL

GRIFFIN SHELL (Continued) **U001243149**

AR Number: 3803
AR UST Number Suffix: Not reported
AR AST Number Suffix: U
Contact Name/Title: JAMES GRIFFIN/

T60 **UNION PACIFIC RAILROAD** **AR UST** **U004117660**
ESE **WALNUT & FRONT ST** **N/A**
1/8-1/4 **TEXARKANA, AR 75504**
0.242 mi.
1279 ft. **Site 1 of 2 in cluster T**

Relative: **Lower**

Actual: **298 ft.**

UST:
Facility Id: 46001660
ADEQ Facility ID: 46-00589
Active Site: Not reported
Above Ground: Not reported
Below Ground: Yes
Aboveground in Use: UST
Underground in Use: UST
Date Reg Cert Issued: Not reported
Lust Flag: UST
Leak ID Number: 46-0011
Date Received: 04/02/1993
Location SIC: Not reported
Federal Flag: Yes
Contact Name: TONY IVASKEVICIUS
Contact Title: ENGINEER
Contact Phone: 401-271-3453
Certified Name: TONY IVASKEVICIUS
Certified Title: ENV ENGINEER
Date Signed: 03/29/1993
Amended: No
No Bill: Not reported
Facility Entry Clerk: schenk
Facility Update Date: Not reported
Facility Update Clerk: Not reported
Latitude: Not reported
Longitude: Not reported

Owner:
Owner ID: 000116
Owner Name: UNION PACIFIC RAILROAD
Owner Address: 1000 W FOURTH STREET
Owner Address 2: ATTN: JOHN STEWART
Owner City,St,Zip: NORTH LITTLE ROCK, AR 72114
Owner County: Not reported
Owner Phone: 5013732304
Owner Type: Private Industry

Tank Info:
Facility ID: 46001660
Record Created By: schenk
Record Created Date: 01/30/2008
Record Modified By: Not reported
Record Modified Date: Not reported
Site Assessment Date: Not reported
Site Assessment Leak: Not reported

UNION PACIFIC RAILROAD (Continued) **U004117660**

Certificate of Compliance Final Test Date: Not reported
Certificate of Compliance Test Company License: Not reported
Certificate of Compliance Tester License: Not reported
Certificate of Compliance Installation Date: Not reported
Certificate of Compliance Install Company License: Not reported
Certificate of Compliance Installer License: Not reported

Tank ID: 1
Tank Status: **Permanently Out of Service 02/24/1993**
Install Date: Not reported
Tank Contents: Empty, Gasoline
Cerclis Name: Not reported
Tank Material: Steel
GIS Location: Not reported
Federal Flag: Not reported
Hazardous: Not reported
Capacity in Gallons: 675
Number of Compartments: 1
Decode for Tstatus: Permanently Out of Use
Release Detection: Unknown
Release Detection Install Date: Not reported
Tank External Corrosion Protection: Unknown
Tank Ext Corrosion Protection Install Date: Not reported
Pipe Material: Bare Steel
Pipe Type: Unknown
Pipe Release Detection: Unknown
Pipe Corrosion Protection: Unknown
Tank Spill and Overfill Protection: Unknown
Pipe Repaired: Not reported
Pipe Corrosion Protection: Unknown
Corrosion Protection: Not reported
Spill and Overflow: Not reported
Release Detection: Not reported
Tank Comments: Not reported

Facility ID: 46001660
Record Created By: schenk
Record Created Date: 01/30/2008
Record Modified By: Not reported
Record Modified Date: Not reported
Site Assessment Date: Not reported
Site Assessment Leak: Not reported
Certificate of Compliance Final Test Date: Not reported
Certificate of Compliance Test Company License: Not reported
Certificate of Compliance Tester License: Not reported
Certificate of Compliance Installation Date: Not reported
Certificate of Compliance Install Company License: Not reported
Certificate of Compliance Installer License: Not reported

Tank ID: 2
Tank Status: **Permanently Out of Service 02/24/1993**
Install Date: Not reported
Tank Contents: Empty, WATER
Cerclis Name: Not reported
Tank Material: Steel
GIS Location: Not reported
Federal Flag: Not reported

UNION PACIFIC RAILROAD (Continued) **U004117660**

Hazardous:	Not reported
Capacity in Gallons:	1000
Number of Compartments:	1
Decode for Tstatus:	Permanently Out of Use
Release Detection:	Unknown
Release Detection Install Date:	Not reported
Tank External Corrosion Protection:	Unknown
Tank Ext Corrosion Protection Install Date:	Not reported
Pipe Material:	Bare Steel
Pipe Type:	Unknown
Pipe Release Detection:	Unknown
Pipe Corrosion Protection:	Unknown
Tank Spill and Overfill Protection:	Unknown
Pipe Repaired:	Not reported
Pipe Corrosion Protection:	Unknown
Corrosion Protection:	Not reported
Spill and Overflow:	Not reported
Release Detection:	Not reported
Tank Comments:	Not reported

T61 **UNION PACIFIC RAILROAD** **AR LTANKS** **S106570973**
ESE **WALNUT & FRONT ST** **N/A**
1/8-1/4 **TEXARKANA, AR 75504**
0.242 mi.
1279 ft. **Site 2 of 2 in cluster T**

Relative: LTANKS:
Lower

RST Facility ID:	46001660
Facility Telephone:	Not reported

Actual:
298 ft.

Owner:	UNION PACIFIC RAILROAD
Lust Owner:	000116
Leak Date:	Not reported
Leak Volume:	Not reported
Substance Stored:	Unknown
Release Status:	Confirmed
Release Confirmed:	4/2/1993
Damage Description:	Sub Surface Soils/Groundwater
Lust Tank Type:	Underground Tank
Lust Dicovery:	Other (See Comments Tab)
Notification Date:	4/2/1993 2:00:00 PM
Cleanup Initiated:	2/24/1993
Notification Name:	IAN BROUSSARD, GEOLOGIST
Notification Address:	USPCI
Notification Address2:	5665 FLATIRON PARKWAY
Notification City,St,Zip:	BOULDER, CO 80301
Notification Telephone:	3039385500
Notice Number:	460011
Tech Branch:	Not reported
AFIN Number:	4600589
Emergency Response:	Not reported
Emergency Response 2:	Not reported
Hazard Abatement:	Not reported
Remedial Action:	Excv Disp, Excv Trt
ISC Date:	Not reported
Priority Score:	Not reported
SAR Date:	Not reported
Cap Submit:	Not reported

UNION PACIFIC RAILROAD (Continued) **S106570973**

Public Notify:	Not reported
Cap Approve:	Not reported
NFA Issued:	1993-08-20 00:00:00
Funding Source:	Not reported
Cleanup Lead:	Not reported
Gis Location:	Not reported
Lust Tank Type 2:	Underground Tank
RST Modified Date:	Not reported
Leak Damage:	ROUTINE TANK CLOSURE REVEALED EXTENSIVE CONTAMINATION IN EXCAVATION
Memo:	METHOD OF DISCOVERY: EXCAVATION OF TANKSTANKS REMOVED. SITE ASSESSMENT WILL BE DONE. 1100 YARDS OF SOIL REMOVED.7/22/93 L. EASTMANPC&E RECEIVED COPY OF THE CAP PROPOSED BY IAN BROUSSARD, USPCI. THE FILE WILLBE TRANSFERRED TO THE TECHNICAL BRANCH FOR FURTHER CONSIDERATION.8/20/93 L. EASTMANRECEIVED A REQUEST FROM MR. I. BROUSSARD FOR A REIMBURSMENT FORM, I DIRECTEDHIM TO MR. ED DUNN.8/23/93 L. EASTMANCONTAMINATED SOILS GENERATED AT THE TWO SITES OF UST REMOVALS WILL BE STAGEDAND TREATED AT THE UPRR TEXARKANA RAILYARD, SOILS WILL BE TREATED AND RE-SAMPLED AFTER A PERIOD OF TREATMENT. NFA LETTER ISSUED 8/20/93.[lynda 1/28/2008 3:53:55 PM].

S62 **AAA AUTO & TRUCK SALES** **TX UST** **U003420289**
NW **420 W 7TH ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.243 mi.
1281 ft. **Site 2 of 2 in cluster S**

Relative: **Lower**
Actual: **303 ft.**

UST:

AI Number:	61157
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	502666072002087
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75503
Contact Name/Title:	STEPHEN A RAFFAELLI,OWNER
Contact Organization Name:	AAA AUTO & TRUCK SALES
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9037943322
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/05/1991
Signature Name/Title On Earliest Reg Form:	STEPHEN A RAFFAELLI,OWNER
Application Received Date On Earliest Reg Form:	10/21/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Owner:

Owner CN:	CN600985907
Owner Last Name:	MURRAH JOE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	493666072002087
Additional ID:	502666072002087
AI Number:	61157
Owner Effective Begin Date:	09/01/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/21/1991
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143445
Facility ID:	95387
Ai Number:	61157
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/24/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	160480
UST ID:	143445
AI Number:	61157
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/21/1991
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143446
Facility ID:	95387
Ai Number:	61157
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/24/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	550
UST Comprt ID:	160481
UST ID:	143446
AI Number:	61157
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/21/1991
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143447
Facility ID:	95387
Ai Number:	61157
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	160482
UST ID:	143447
AI Number:	61157
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	08/31/1987
Tank Registration Date:	10/21/1991
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143448
Facility ID:	95387
Ai Number:	61157
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

AAA AUTO & TRUCK SALES (Continued) **U003420289**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	160483
UST ID:	143448
AI Number:	61157
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/21/1991
Number of Compartments:	1
Tank Capacity:	4000

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143449
Facility ID:	95387
Ai Number:	61157
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Installation Signature Date:	10/14/1991
Compartment Records:	
Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	160484
UST ID:	143449
AI Number:	61157
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:	
Contact Organization Name:	MURRAH JOE
Contact Mailing Address (Delivery):	2212 N FM 2148
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75501 0359
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95387
Additional ID:	502666072002087

AAA AUTO & TRUCK SALES (Continued) **U003420289**

Princ ID:	493666072002087
AI Number:	61157
Facility Name:	AAA AUTO & TRUCK SALES
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOE MURIAH/

P63 **SWBT TEXARKANA TOLL CENTRAL OFF** **TX UST** **U003406834**
West **429 SPRUCE ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.244 mi.
1289 ft. **Site 2 of 2 in cluster P**

Relative: **Lower**

Actual: **296 ft.**

UST:

AI Number:	19488
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	803770622002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	,
Contact Organization Name:	SWBT TEXARKANA TOLL CENTRAL OFF
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9032361000
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	G BEAN,ASST SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600261663
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

SWBT TEXARKANA TOLL CENTRAL OFF (Continued) **U003406834**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	35290742001297
Additional ID:	803770622002150
AI Number:	19488
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	50254
Facility ID:	76598
Ai Number:	19488
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/05/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

SWBT TEXARKANA TOLL CENTRAL OFF (Continued) **U003406834**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	114041
UST ID:	50254
AI Number:	19488
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

SWBT TEXARKANA TOLL CENTRAL OFF (Continued) **U003406834**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7463
Cert ID:	24964
UST Comprt ID:	68947
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24972
UST Comprt ID:	68940
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24976
UST Comprt ID:	68936
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24966
UST Comprt ID:	68946
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24973
UST Comprt ID:	68939
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24963
UST Comprt ID:	68950
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463

SWBT TEXARKANA TOLL CENTRAL OFF (Continued) **U003406834**

Cert ID:	24977
UST Comprt ID:	68935
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24962
UST Comprt ID:	68949
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24969
UST Comprt ID:	68943
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24961
UST Comprt ID:	68948
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24975
UST Comprt ID:	68937
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	304420
UST Comprt ID:	880526
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24971
UST Comprt ID:	68941
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	247953

SWBT TEXARKANA TOLL CENTRAL OFF (Continued) **U003406834**

UST Comprt ID:	712858
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24974
UST Comprt ID:	68938
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	288510
UST Comprt ID:	832950
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24968
UST Comprt ID:	68944
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	264194
UST Comprt ID:	760979
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24970
UST Comprt ID:	68942
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	24967
UST Comprt ID:	68945
UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A
Self Cert ID:	7463
Cert ID:	230603
UST Comprt ID:	661980

SWBT TEXARKANA TOLL CENTRAL OFF (Continued) **U003406834**

UST ID:	19813
AI Number:	19488
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP
Contact Mailing Address (Delivery):	308 S AKARD ST RM 1700
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76598
Additional ID:	803770622002150
Princ ID:	35290742001297
AI Number:	19488
Facility Name:	SWBT TEXARKANA TOLL CENTRAL OFF
AR Number:	22573
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	/

64
NE
1/8-1/4
0.245 mi.
1293 ft.

QUINNS MODEL CLEANER
411 HAZEL
TEXARKANA, AR 71854

RCRA NonGen / NLR **1001486063**
FINDS **ARD103970778**
ECHO

Relative:
Higher

Actual:
330 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/09/1999
Facility name:	QUINNS MODEL CLEANERS
Facility address:	411 HAZEL TEXARKANA, AR 75502
EPA ID:	ARD103970778
Mailing address:	HAZEL TEXARKANA, AR 75502
Contact:	JOHN QUINN
Contact address:	411 HAZEL TEXARKANA, AR 75502
Contact country:	US
Contact telephone:	870-774-5521
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	QUINN JOHN
Owner/operator address:	411 HAZEL TEXARKANA, AR 75502
Owner/operator country:	Not reported
Owner/operator telephone:	870-774-5521
Owner/operator email:	Not reported

QUINNS MODEL CLEANER (Continued) **1001486063**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110006378598

Environmental Interest/Information System

Arkansas Permit Data System (PDS) is a system maintaining data on air quality, mining, tires, solid waste, tank, water and hazardous waste, as well as inspections, invoicing and complaints.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

QUINNS MODEL CLEANER (Continued) **1001486063**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001486063
Registry ID:	110006378598
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006378598

R65 **UNION SUPPLY GROCERY** **US BROWNFIELDS** **1016159298**
East **418 E. BROAD ST.** **FINDS** **N/A**
1/8-1/4 **TEXARKANA, AR 71854**
0.246 mi.
1301 ft. **Site 2 of 4 in cluster R**

Relative: **Lower**

Actual: **304 ft.**

US BROWNFIELDS:

Property Name:	UNION SUPPLY GROCERY
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.21
Latitude:	33.42301
Longitude:	-94.03943779999997
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94603
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10013
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	12/04/2007 00:00:00
Ownership Entity:	Private
Completion Date:	04/21/2008 00:00:00
Current Owner:	Tom Morrissey
Did Owner Change:	N

UNION SUPPLY GROCERY (Continued) **1016159298**

Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.21
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported

UNION SUPPLY GROCERY (Continued) **1016159298**

Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Grocery Store
Below Poverty Number:	317
Below Poverty Percent:	19.9%
Meidan Income:	8214
Meidan Income Number:	491
Meidan Income Percent:	30.9%
Vacant Housing Number:	115
Vacant Housing Percent:	31.5%
Unemployed Number:	62
Unemployed Percent:	3.9%

Property Name:	UNION SUPPLY GROCERY
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.21
Latitude:	33.42301
Longitude:	-94.03943779999997
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94603
IC Data Access:	Not reported

UNION SUPPLY GROCERY (Continued) **1016159298**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10013
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	96656301
Start Date:	12/04/2007 00:00:00
Ownership Entity:	Private
Completion Date:	04/21/2008 00:00:00
Current Owner:	Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported

UNION SUPPLY GROCERY (Continued) **1016159298**

PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.21
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Grocery Store
Below Poverty Number:	317

UNION SUPPLY GROCERY (Continued) **1016159298**

Below Poverty Percent:	19.9%
Meidan Income:	8214
Meidan Income Number:	491
Meidan Income Percent:	30.9%
Vacant Housing Number:	115
Vacant Housing Percent:	31.5%
Unemployed Number:	62
Unemployed Percent:	3.9%

FINDS:

Registry ID: 110039689058

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

U66 **MODERN CLEANERS** **TX DRYCLEANERS** **S109361695**
North **210 W 7TH ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.248 mi.
1312 ft. **Site 1 of 3 in cluster U**

Relative: **Higher**
Actual: **318 ft.**

DRYCLEANERS:

RN Number:	RN101804904
Region:	5
CN Number:	CN600281836
DCR Number:	Not reported
AR Number:	24002065
Principal Name:	LUFKIN CLEANERS INC
Bill Addr1:	210 W 7TH ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5524
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MODERN CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

RN Number:	RN101804904
Region:	5
CN Number:	CN600281836
DCR Number:	Not reported
AR Number:	24002065
Principal Name:	LUFKIN CLEANERS INC
Bill Addr1:	210 W 7TH ST
Bill Addr2:	Not reported

MODERN CLEANERS (Continued) **S109361695**

Bill City/State/Zip:	TEXARKANA, TX 75501 5524
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MODERN CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	500
Part Stat:	NO
Gross Receipts:	$100,000 OR LESS
RN Number:	RN101804904
Region:	5
CN Number:	CN602985467
DCR Number:	Not reported
AR Number:	24003619
Principal Name:	REBECCA J CLEM DBA MODERN CLEANERS
Bill Addr1:	210 W 7TH ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5524
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MODERN CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS
RN Number:	RN101804904
Region:	5
CN Number:	CN602985467
DCR Number:	Not reported
AR Number:	24003619
Principal Name:	REBECCA J CLEM DBA MODERN CLEANERS
Bill Addr1:	210 W 7TH ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5524
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MODERN CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	220
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS
RN Number:	RN101804904
Region:	5
CN Number:	CN602985467
DCR Number:	Not reported
AR Number:	24003619

MODERN CLEANERS (Continued) **S109361695**

Principal Name:	REBECCA J CLEM DBA MODERN CLEANERS
Bill Addr1:	210 W 7TH ST
Bill Addr2:	Not reported
Bill City/State/Zip:	TEXARKANA, TX 75501 5524
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MODERN CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

U67 **MODERN CLEANERS** **TX UST** **U001238818**
North **210 W 7TH ST** **N/A**
1/8-1/4 **TEXARKANA, TX 75501**
0.248 mi.
1312 ft. **Site 2 of 3 in cluster U**

Relative: **Higher**
Actual: **318 ft.**

UST:

AI Number:	1686
Facility Type:	FLEET REFUELING
Facility Begin Date:	06/05/1986
Facility Status:	INACTIVE
Additional ID:	392540552002087
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BOWIE
Site Location (Tceq Region):	5
Site Location (Location Zip):	75501
Contact Name/Title:	F H THOMAS,OWNER
Contact Organization Name:	MODERN CLEANERS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2147946872
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/28/1986
Signature Name/Title On Earliest Reg Form:	F H THOMAS,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN603906827
Owner Last Name:	MODERN CLEANERS
Owner First Name:	Not reported
Owner Middle Name:	Not reported

MODERN CLEANERS (Continued) **U001238818**

Owner Type:	OT
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	185519812011177
Additional ID:	392540552002087
AI Number:	1686
Owner Effective Begin Date:	06/05/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1968
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	400
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	4196
Facility ID:	39638
Ai Number:	1686
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	09/30/1974
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

MODERN CLEANERS (Continued) **U001238818**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	5620
UST ID:	4196
AI Number:	1686
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

MODERN CLEANERS (Continued) **U001238818**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MODERN CLEANERS
Contact Mailing Address (Delivery):	210 W 7TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEXARKANA, TX 75501 5524
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	39638
Additional ID:	392540552002087
Princ ID:	185519812011177
AI Number:	1686
Facility Name:	MODERN CLEANERS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

---

68 **SOUTHERN PACIFIC TRANSPORTATION** **TX LPST S104957736**
SSW **319 W FRONT ST** **TX GCC N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.254 mi.
1340 ft.

Relative:
Lower

Actual:
295 ft.

LPST:

Facility ID:	0053907
LPST Id:	118317
Facility Location:	319 W FRONT ST
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	12/31/3000
Entered Date:	05/24/2010
Priority:	1.5 - FP ON/IN: GROUND SURFACE/SW/UTILITY (NOT WATER SUPPLY LINE)
Program:	1 - RPR
CA Status:	5 - REMEDIAL ACTION PLAN
Priority Description:	NAPL is present at the ground surface, on surface water bodies, surface water runoff, or in utilities other than water supply lines.
Status:	**CORRECTIVE ACTION PLAN**
Coordinators Primary:	1/1P
Coordinators RPR:	EAE
Responsible Party Name:	SOUTHERN PACIFIC TRANSPORTATION COMPANY

SOUTHERN PACIFIC TRANSPORTATION (Continued) **S104957736**

Responsible Party Contact: GEOFFREY REEDER
Responsible Party Address: 24125 ALDINE WESTFIELD RD 3
Responsible Party City,St,Zip: SPRING, TX 77373 9015
Responsible Party Telephone: 281/350-7197
Reported Date: 04/05/2010
Case Start Date: 05/24/2010

Facility ID: 0053907
LPST Id: 102408
Facility Location: 319 WEST FRONT ST
TCEQ Region# and City: 5
Region City: TYLER
Reported Date: 01/16/1998
Entered Date: 04/27/1992
Priority: 4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program: 1P - PRIVATIZATION CONTRACTOR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: 4.0
Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary: 1P/1/2
Coordinators RPR: MWB
Responsible Party Name: SOUTHER PACIFIC LINES
Responsible Party Contact: CRAIG DENNY
Responsible Party Address: 913 FRANKING ST RM 712
Responsible Party City,St,Zip: HOUSTON, TX 77002
Responsible Party Telephone: 713/223-7640
Reported Date: 05/22/1990
Case Start Date: 04/27/1992

GCC:
Division: REM/PST
New Cases: Not reported
File Number: 118317
Contamination Description: UNKNOWN
Date Of Earliest Known Contamination Confirmation: 4/5/2010
Enforcement Status - Level Of Agency Response: 2
Enforcement Status - Site Activity Status: 4
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: RMD/PST
New Cases: *
File Number: 118317
Contamination Description: DIESEL, DIST F OIL
Date Of Earliest Known Contamination Confirmation: 5/24/2010
Enforcement Status - Level Of Agency Response: 2
Enforcement Status - Site Activity Status: 2A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION

SOUTHERN PACIFIC TRANSPORTATION (Continued) **S104957736**

ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: REM/PST
New Cases: Not reported
File Number: 118317
Contamination Description: DIESEL, DIST F OIL
Date Of Earliest Known Contamination Confirmation: 4/5/2010
Enforcement Status - Level Of Agency Response: 2
Enforcement Status - Site Activity Status: 4
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: RMD/PST
New Cases: *
File Number: 118317
Contamination Description: DIESEL, DIST F OIL
Date Of Earliest Known Contamination Confirmation: 5/24/2010
Enforcement Status - Level Of Agency Response: 2
Enforcement Status - Site Activity Status: 2A
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Division: REM/PST
New Cases: Not reported
File Number: 118317
Contamination Description: DIESEL, DIST F OIL
Date Of Earliest Known Contamination Confirmation: 5/24/2010
Enforcement Status - Level Of Agency Response: 2
Enforcement Status - Site Activity Status: 4
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

SOUTHERN PACIFIC TRANSPORTATION (Continued) **S104957736**

Division:	REM/PST
New Cases:	Not reported
File Number:	118317
Contamination Description:	DIESEL, DIST F OIL
Date Of Earliest Known Contamination Confirmation:	5/24/2010
Enforcement Status - Level Of Agency Response:	2
Enforcement Status - Site Activity Status:	2A
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Division:	WPD/MSW
New Cases:	Not reported
File Number:	118317
Contamination Description:	DIESEL, DIST F OIL
Date Of Earliest Known Contamination Confirmation:	5/24/2010
Enforcement Status - Level Of Agency Response:	2
Enforcement Status - Site Activity Status:	4
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Q69 **ANTIQUE MALL** **US BROWNFIELDS** **1023619100**
WNW **621 TEXAS BLVD** **FINDS** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.254 mi.
1341 ft. **Site 3 of 4 in cluster Q**

Relative: **Lower**

Actual: **297 ft.**

US BROWNFIELDS:

Property Name:	ANTIQUE MALL
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.32
Latitude:	33.4243764
Longitude:	-94.0475044
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	151362
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported

ANTIQUE MALL (Continued) **1023619100**

Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Not reported
Accomplishment Count:	0
Cooperative Agreement Number:	00F19501
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported

ANTIQUE MALL (Continued) **1023619100**

Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	322
Below Poverty Percent:	19.3%
Meidan Income:	338
Meidan Income Number:	548

ANTIQUE MALL (Continued) **1023619100**

Meidan Income Percent:	32.8%
Vacant Housing Number:	116
Vacant Housing Percent:	29.3%
Unemployed Number:	78
Unemployed Percent:	4.7%

FINDS:

Registry ID: 110070068654

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q70 **621 TEXAS** **US BROWNFIELDS** **1016159079**
WNW **621 TEXAS BLVD.** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.254 mi.
1341 ft. **Site 4 of 4 in cluster Q**

Relative:
Lower

Actual:
297 ft.

US BROWNFIELDS:

Property Name:	621 TEXAS
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.32
Latitude:	33.4243698
Longitude:	-94.04751999999996
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	158582
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1

621 TEXAS (Continued) **1016159079**

Cooperative Agreement Number:	00F19501
Start Date:	10/24/2012 00:00:00
Ownership Entity:	Private
Completion Date:	11/14/2012 00:00:00
Current Owner:	Patrick Hill
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported

621 TEXAS (Continued) **1016159079**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	.32
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site consists of a 0.32-acre parcel located at 621 Texas Boulevard in Texarkana, Bowie County, Texas. The parcel is developed with a vacant 13,000 square foot, single-story building which was most recently utilized as a flea market until approximately 2011. Historical information indicates the site was developed with residences sometime prior to 1896. The site appears to have remained residential development until sometime prior to 1948. The site was redeveloped as a furniture store until approximately the mid-1990s. Shops that build or repair furniture commonly use varnishes, paints, solvents, and adhesives in shop operations. These chemicals could be potential sources of contamination at these facilities. Based on the age of the former furniture store and the possibility of furniture building or repair operations having occurred at the site, the former furniture store represents a REC to the site at this time.
Below Poverty Number:	322
Below Poverty Percent:	19.3%
Meidan Income:	338
Meidan Income Number:	548
Meidan Income Percent:	32.8%

621 TEXAS (Continued) **1016159079**

Vacant Housing Number:	116
Vacant Housing Percent:	29.3%
Unemployed Number:	78
Unemployed Percent:	4.7%

R71 **UPRR** **US BROWNFIELDS** **1016159299**
East **E. BROAD ST. BETWEEN HAZEL ST. AND WALNUT ST.** **FINDS** **N/A**
1/4-1/2 **TEXARKANA, AR 71854**
0.259 mi.
1366 ft. **Site 3 of 4 in cluster R**

Relative: **Lower**

Actual: **299 ft.**

US BROWNFIELDS:

Property Name:	UPRR
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	1.26
Latitude:	33.422630
Longitude:	-94.038742
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94601
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10013
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	12/04/2007 00:00:00
Ownership Entity:	Private
Completion Date:	04/21/2008 00:00:00
Current Owner:	Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported

UPRR (Continued) **1016159299**

IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	1.26
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported

UPRR (Continued) **1016159299**

Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Union Pacific Railroad Property.
Below Poverty Number:	309
Below Poverty Percent:	20.1%
Meidan Income:	9322
Meidan Income Number:	472
Meidan Income Percent:	30.6%
Vacant Housing Number:	111
Vacant Housing Percent:	31.7%
Unemployed Number:	60
Unemployed Percent:	3.9%

Property Name:	UPRR
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	1.26
Latitude:	33.422630
Longitude:	-94.038742
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	94601
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10013
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported

UPRR (Continued) **1016159299**

Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	96656301
Start Date:	12/04/2007 00:00:00
Ownership Entity:	Private
Completion Date:	04/21/2008 00:00:00
Current Owner:	Tom Morrissey
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported

UPRR (Continued) **1016159299**

VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	1.26
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Union Pacific Railroad Property.
Below Poverty Number:	309
Below Poverty Percent:	20.1%
Meidan Income:	9322
Meidan Income Number:	472
Meidan Income Percent:	30.6%
Vacant Housing Number:	111
Vacant Housing Percent:	31.7%
Unemployed Number:	60
Unemployed Percent:	3.9%

UPRR (Continued) **1016159299**

FINDS:

Registry ID: 110039689030

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

R72 **COMBINED MORRISSEY PROPERTY** **US BROWNFIELDS** **1016349496**
East **EAST BROAD AND EAST FRONT STREETS** **FINDS** **N/A**
1/4-1/2 **TEXARKANA, AR 71854**
0.269 mi.
1419 ft. **Site 4 of 4 in cluster R**

Relative: **Lower**
Actual: **306 ft.**

US BROWNFIELDS:

Property Name:	COMBINED MORRISSEY PROPERTY
Recipient Name:	Ark-Tex Council of Governments
Grant Type:	Assessment
Property Number:	00358400 00361400
Parcel size:	1.68
Latitude:	33.4227
Longitude:	-94.0386
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	69841
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	29087.5
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97699701
Start Date:	12/06/2007 00:00:00
Ownership Entity:	Private
Completion Date:	12/31/2008 00:00:00
Current Owner:	Mr. Thomas F. Morrissey
Did Owner Change:	N

COMBINED MORRISSEY PROPERTY (Continued) **1016349496**

Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	1.68
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported

COMBINED MORRISSEY PROPERTY (Continued) **1016349496**

Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The property consists of three adjoining properties including the former Swift & Co. Meats building, the former Union Supply Co. Grocery and Feed, and the vacant UPRR lot.
Below Poverty Number:	331
Below Poverty Percent:	19.7%
Meidan Income:	8186
Meidan Income Number:	533
Meidan Income Percent:	31.7%
Vacant Housing Number:	124
Vacant Housing Percent:	31.2%
Unemployed Number:	63
Unemployed Percent:	3.8%

FINDS:

Registry ID: 110038760524

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

U73 **999 STATION** **TX LPST** **S116699119**
North **102 W 7TH ST** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.271 mi.
1432 ft. **Site 3 of 3 in cluster U**

Relative: **Higher**
Actual: **324 ft.**

LPST:

Facility ID:	0068781
LPST Id:	111842
Facility Location:	102 7TH ST
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	11/01/1996
Entered Date:	11/01/1996
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	FOSTER C W ESTATE
Responsible Party Contact:	JEANNE BASS
Responsible Party Address:	3025 RED BLUFF CIR
Responsible Party City,St,Zip:	SAN ANGELO, TX 76904
Responsible Party Telephone:	915/944-4968
Reported Date:	12/31/3000
Case Start Date:	11/01/1996

---

74 **ROBBINS VACANT LOT** **US BROWNFIELDS** **1018273335**
West **521 SPRUCE STREET** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.274 mi.
1445 ft.

Relative: **Lower**
Actual: **294 ft.**

US BROWNFIELDS:

Property Name:	ROBBINS VACANT LOT
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	038400035300
Parcel size:	.16
Latitude:	33.422986
Longitude:	-94.0481002
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	208661
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported

ROBBINS VACANT LOT (Continued) **1018273335**

Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F20201
Start Date:	10/02/2012 00:00:00
Ownership Entity:	Private
Completion Date:	12/21/2012 00:00:00
Current Owner:	Robbins Motor Company, Inc.
Did Owner Change:	Y
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported

ROBBINS VACANT LOT (Continued) **1018273335**

VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	.16
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Site consist of approximately 0.16 acres of vacant land enclosed by a chain-link fence. Historical information indicates that the site was developed with a dwelling since at least 1896 but has been vacant since at least the 1960s. New and used automobiles owned by Robbins Automotive were stored onsite from the 1960s until approximately 1985.
Below Poverty Number:	336
Below Poverty Percent:	19.4%
Meidan Income:	4051
Meidan Income Number:	640
Meidan Income Percent:	37.0%
Vacant Housing Number:	118

ROBBINS VACANT LOT (Continued) **1018273335**

Vacant Housing Percent:	28.1%
Unemployed Number:	92
Unemployed Percent:	5.3%

V75 **523 W 3RD STREET** **US BROWNFIELDS** **1012091329**
SW **523 W 3RD STREET** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.294 mi.
1553 ft. **Site 1 of 3 in cluster V**

Relative: **Lower**
Actual: **294 ft.**

US BROWNFIELDS:

Property Name:	523 W 3RD STREET
Recipient Name:	Texas Commission on Environmental Quality
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.16
Latitude:	33.4208071
Longitude:	-94.0470369
HCM Label:	GPS Code (Pseudo Range) Standard-Service Correction
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	88341
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4106
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97642001
Start Date:	07/16/2008 00:00:00
Ownership Entity:	Private
Completion Date:	08/31/2008 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported

523 W 3RD STREET (Continued) **1012091329**

State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported

523 W 3RD STREET (Continued) **1012091329**

Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Y
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	178
Below Poverty Percent:	16.8%
Meidan Income:	756
Meidan Income Number:	373
Meidan Income Percent:	35.2%
Vacant Housing Number:	70
Vacant Housing Percent:	27.1%
Unemployed Number:	65
Unemployed Percent:	6.1%

V76 **JAMESON BUILDING** **US BROWNFIELDS** **1016159196**
SW **523 WEST 3RD STREET OAK AND 3RD STREETS** **FINDS** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.294 mi.
1553 ft. **Site 2 of 3 in cluster V**

Relative: **Lower**

Actual: **294 ft.**

US BROWNFIELDS:

Property Name:	JAMESON BUILDING
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7982
Parcel size:	.16
Latitude:	33.4207938
Longitude:	-94.04702909999997
HCM Label:	Address Matching-Nearest Intersection
Map Scale:	1
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133214
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported

JAMESON BUILDING (Continued) **1016159196**

Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	27248
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	00F19501
Start Date:	07/17/2012 00:00:00
Ownership Entity:	Private
Completion Date:	10/08/2012 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported

JAMESON BUILDING (Continued) **1016159196**

Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site (Jameson Building) is located at 523 West 3rd Street, (southeast corner of West 3rd and Oak Streets), in Texarkana, Texas. The site consists of a 0.16 acre parcel of land improved with a two-story vacant office building. It appears the site was vacant until approximately 1905. Two buildings were developed around this time, and the current building was constructed around 1951. Former

JAMESON BUILDING (Continued) **1016159196**

offices/businesses in the Jameson Building include a pharmacy, hair salon, pool hall, dry cleaners and caf . The Jameson Building is currently in poor condition with large holes in the walls and ceiling, chipping paint, broken windows and loose floor and ceiling tiles. Due to the deteriorated state of the building and location near blighted parts of the City, the structure is under-used within the context of a Brownfield. The Jameson family has plans to restore the property into commercial businesses and add an entertainment venue on the second floor, which would provide improved use and community benefit.

Below Poverty Number:	178
Below Poverty Percent:	16.8%
Meidan Income:	756
Meidan Income Number:	373
Meidan Income Percent:	35.2%
Vacant Housing Number:	70
Vacant Housing Percent:	27.1%
Unemployed Number:	65
Unemployed Percent:	6.1%

Property Name:	JAMESON BUILDING
Recipient Name:	Texarkana Texas and Arkansas, City of
Grant Type:	Assessment
Property Number:	7982
Parcel size:	.16
Latitude:	33.4207938
Longitude:	-94.04702909999997
HCM Label:	Address Matching-Nearest Intersection
Map Scale:	1
Point of Reference:	Center of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	133214
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	00F19501
Start Date:	07/07/2011 00:00:00
Ownership Entity:	Private
Completion Date:	08/31/2011 00:00:00
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	Y

JAMESON BUILDING (Continued) **1016159196**

Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.16
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported

JAMESON BUILDING (Continued) **1016159196**

Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The site (Jameson Building) is located at 523 West 3rd Street, (southeast corner of West 3rd and Oak Streets), in Texarkana, Texas. The site consists of a 0.16 acre parcel of land improved with a two-story vacant office building. It appears the site was vacant until approximately 1905. Two buildings were developed around this time, and the current building was constructed around 1951. Former offices/businesses in the Jameson Building include a pharmacy, hair salon, pool hall, dry cleaners and caf . The Jameson Building is currently in poor condition with large holes in the walls and ceiling, chipping paint, broken windows and loose floor and ceiling tiles. Due to the deteriorated state of the building and location near blighted parts of the City, the structure is under-used within the context of a Brownfield. The Jameson family has plans to restore the property into commercial businesses and add an entertainment venue on the second floor, which would provide improved use and community benefit.
Below Poverty Number:	178
Below Poverty Percent:	16.8%
Meidan Income:	756
Meidan Income Number:	373
Meidan Income Percent:	35.2%
Vacant Housing Number:	70
Vacant Housing Percent:	27.1%
Unemployed Number:	65
Unemployed Percent:	6.1%

JAMESON BUILDING (Continued) **1016159196**

FINDS:

Registry ID: 110038763745

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

V77 **CITY OF TEXARKANA** **TX BROWNFIELDS** **S109145450**
SW **523 W 3RD ST** **N/A**
1/4-1/2 **TEXARKANA, TX 75501**
0.294 mi.
1553 ft. **Site 3 of 3 in cluster V**

Relative: **Lower**

Actual: **294 ft.**

BROWNFIELDS:

BF Site Assessment Received:	07/02/2008
PCA number:	78226
BF Grant Number:	G104
Facility Type:	Office Building
Lead Type:	Purchaser
Project manager:	KLIVINGS
Phase:	COMPLETED
Lat/Long:	33.251354 / -94.025200
Lat/Long (deg):	33.251354 / -94.025200
Acres:	.16
TCEQ Region:	05
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Texarkana
Applicant Title:	Director, Community Redevelopment
Applicant Address:	200 Texas Boulevard
Applicant City,St,Zip:	Texarkana, TX 75501
Applicant Phone:	903-798-3903
Applicant Fax:	903-798-3913
Consultant Attorney:	Shaw
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported

78
WNW
1/4-1/2
0.323 mi.
1706 ft.

USED CAR LOT
706 W 7TH ST
TEXARKANA, TX 75505

TX LPST **S116704335**
N/A

Relative:
Lower

Actual:
292 ft.

LPST:

Facility ID:	0057970
LPST Id:	98795
Facility Location:	SPRUCE NW CORNER @ W 7TH AVE
TCEQ Region# and City:	5
Region City:	TYLER
Reported Date:	06/23/1997
Entered Date:	05/02/1991
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/2
Coordinators RPR:	DLB
Responsible Party Name:	COMMERCIAL NATIONAL BANK
Responsible Party Contact:	S G RHINEHART
Responsible Party Address:	PO BOX 1998
Responsible Party City,St,Zip:	TEXARKANA, AR 75502
Responsible Party Telephone:	501/773-4561
Reported Date:	05/01/1991
Case Start Date:	05/02/1991

79
SSE
1/4-1/2
0.340 mi.
1796 ft.

TEXARKANA ELECTRIC LIGHT AND GAS WORKS
JEFFERSON RD
TEXARKANA, AR 71854

EDR MGP **1008408959**
N/A

Relative:
Lower

Actual:
282 ft.

Manufactured Gas Plants:

Alternate Name:TEXARKANA GAS AND ELECTRIC CP; SOUTHWESTERN GAS AND ELECTRIC CO.
No additional information available

80
NNE
1/4-1/2
0.400 mi.
2113 ft.

E - Z MART #167
424 E. 7TH ST.
TEXARKANA, AR

AR LTANKS **S103808086**
N/A

Relative:
Higher

Actual:
331 ft.

LTANKS:

RST Facility ID:	46000033
Facility Telephone:	Not reported
Owner:	E - Z MART STORES, INC.
Lust Owner:	Not reported
Leak Date:	9/23/1996
Leak Volume:	Not reported
Substance Stored:	Unknown
Release Status:	Suspected
Release Confirmed:	Not reported
Damage Description:	Not reported
Lust Tank Type:	Unknown
Lust Dicovery:	Other (See Comments Tab)

E - Z MART #167 (Continued) **S103808086**

Notification Date:	9/24/1996 8:00:00 AM
Cleanup Initiated:	Not reported
Notification Name:	LIFF S. LUTHRINGER
Notification Address:	602 WEST FALVEY
Notification Address2:	P.O. BOX 1426
Notification City,St,Zip:	TEXARKANA, TX 75504
Notification Telephone:	9038326502
Notice Number:	460023
Tech Branch:	Not reported
AFIN Number:	4600376
Emergency Response:	Not reported
Emergency Response 2:	Not reported
Hazard Abatement:	Not reported
Remedial Action:	Not reported
ISC Date:	Not reported
Priority Score:	Not reported
SAR Date:	Not reported
Cap Submit:	Not reported
Public Notify:	Not reported
Cap Approve:	Not reported
NFA Issued:	Not reported
Funding Source:	Not reported
Cleanup Lead:	Not reported
Gis Location:	Not reported
Lust Tank Type 2:	Unknown
RST Modified Date:	Not reported
Leak Damage:	UNK
Memo:	METHOD OF DISCOVERY: SIR PROGRAM "OTHER THAN TIGHT"INVESTIGATINGDENY/CONFIRM:

Owner:	E-Z MART STORES, INC.
Lust Owner:	Not reported
Leak Date:	11/1/1996
Leak Volume:	Not reported
Substance Stored:	Unknown
Release Status:	Denied
Release Confirmed:	Not reported
Damage Description:	Not reported
Lust Tank Type:	Unknown
Lust Dicovery:	Other (See Comments Tab)
Notification Date:	11/21/1996 12:00:00 PM
Cleanup Initiated:	Not reported
Notification Name:	LIFF LUTHRINGER
Notification Address:	602 WEST FALVEY
Notification Address2:	P.O. BOX 1426
Notification City,St,Zip:	TEXARKANA, TX 75504
Notification Telephone:	9038326502
Notice Number:	460025
Tech Branch:	Not reported
AFIN Number:	4600376
Emergency Response:	Not reported
Emergency Response 2:	Not reported
Hazard Abatement:	Not reported
Remedial Action:	Not reported
ISC Date:	Not reported
Priority Score:	Not reported

E - Z MART #167 (Continued) **S103808086**

SAR Date:	Not reported
Cap Submit:	Not reported
Public Notify:	Not reported
Cap Approve:	Not reported
NFA Issued:	Not reported
Funding Source:	Not reported
Cleanup Lead:	Not reported
Gis Location:	Not reported
Lust Tank Type 2:	Unknown
RST Modified Date:	Not reported
Leak Damage:	UNK
Memo:	METHOD OF DISCOVERY: MONTHLY S I R PROGRAM "OTHER THAN TIGHT" STATUSINVESTIGATEDENY/CONFIRM: DENY 12/27/96 (ELLIS)IRR RECD: 12/30/96 (ELLIS)IMPROPER STICKING, CORRECTEDCLOSED: 01/02/97 (ELLIS)NFA ISSUED: 01/02/97 (ELLIS)

Count: 3 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
TEXARKANA	S117313240	KOPPERS CO., INC. (TEXARKANA PLANT	WEST 3RD ST	75501	TX SHWS
TEXARKANA	S105050100	TEXARKANA GAZETTE PROPERTY	MAIN ST	75501	TX LPST
TEXARKANA	1003875952	ABANDINED LANDFILL	N.E. OF TEXARKANA WOOD SITE	75501	SEMS-ARCHIVE

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/17/2018
Date Data Arrived at EDR: 08/09/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 29

Source: EPA
Telephone: N/A
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 07/17/2018
Date Data Arrived at EDR: 08/09/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 29

Source: EPA
Telephone: N/A
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 07/17/2018
Date Data Arrived at EDR: 08/09/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 29

Source: EPA
Telephone: N/A
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 07/17/2018
Date Data Arrived at EDR: 08/09/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 29

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 07/17/2018
Date Data Arrived at EDR: 08/09/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 29

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/14/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 07/16/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 07/31/2018
Date Data Arrived at EDR: 08/28/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/28/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 07/31/2018
Date Data Arrived at EDR: 08/28/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/28/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/18/2018
Date Data Arrived at EDR: 06/27/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 79

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/27/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

TX SHWS: State Superfund Registry

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 03/31/2018
Date Data Arrived at EDR: 05/02/2018
Date Made Active in Reports: 05/09/2018
Number of Days to Update: 7

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5680
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Semi-Annually

AR SHWS: Hazardous Substance Remedial Action Trust Fund Priority List

A partial prioritized listing of sites at which remedial actions and/or investigations shall be provided by the Hazardous Substance Remedial Action Trust Fund.

Date of Government Version: 06/11/2018
Date Data Arrived at EDR: 06/13/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 40

Source: Department of Environmental Quality
Telephone: 501-682-0850
Last EDR Contact: 09/11/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

TX SWF/LF: Permitted Solid Waste Facilities

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/12/2018
Number of Days to Update: 48

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6706
Last EDR Contact: 08/31/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Quarterly

AR SWF/LF: Solid Waste Facility Permit Database

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 08/02/2018
Date Data Arrived at EDR: 08/06/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 17

Source: Department of Environmental Quality
Telephone: 501-682-0597
Last EDR Contact: 08/03/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Quarterly

TX H-GAC CLI: Houston-Galveston Closed Landfill Inventory

Closed Landfill Inventory for the Houston-Galveston Area Council Region. In 1993, the Texas Legislature passed House Bill (HB) 2537, which required Councils of Governments (COGs) to develop an inventory of closed municipal solid waste landfills for their regional solid waste management plans.

Date of Government Version: 10/31/2017
Date Data Arrived at EDR: 11/01/2017
Date Made Active in Reports: 12/11/2017
Number of Days to Update: 40

Source: Houston-Galveston Area Council
Telephone: 832-681-2518
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

TX DEBRIS: DEBRIS

A listing of temporary debris management sites and MSW landfills for debris resulting from Hurricane Harvey.

Date of Government Version: 03/27/2018
Date Data Arrived at EDR: 04/04/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 65

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6840
Last EDR Contact: 09/06/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Varies

TX CLI: Closed Landfill Inventory

Closed and abandoned landfills (permitted as well as unauthorized) across the state of Texas. For current information regarding any of the sites included in this database, contact the appropriate Council of Governments agency.

Date of Government Version: 08/30/1999
Date Data Arrived at EDR: 09/28/2000
Date Made Active in Reports: 10/30/2000
Number of Days to Update: 32

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

TX WASTE MGMT: Commercial Hazardous & Solid Waste Management Facilities

This list contains commercial recycling facilities and facilities permitted or authorized (interim status) by the Texas Natural Resource Conservation Commission.

Date of Government Version: 02/02/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/13/2018
Number of Days to Update: 68

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2920
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

State and tribal leaking storage tank lists

AR LTANKS: Leaking Underground Storage Tank Data

A listing of leaking underground and aboveground storage tank locations.

Date of Government Version: 06/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 33

Source: Department of Environmental Quality
Telephone: 501-682-0984
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/10/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/08/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/01/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/24/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

TX LPST: Leaking Petroleum Storage Tank Database
An inventory of reported leaking petroleum storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 06/08/2018
Date Data Arrived at EDR: 06/22/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 32
Source: Texas Commission on Environmental Quality
Telephone: 512-239-2200
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/11/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Varies

TX UST: Petroleum Storage Tank Database
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 06/01/2018
Date Data Arrived at EDR: 06/28/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 25
Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

AR UST: Underground Storage Tank Data
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 06/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 33
Source: Department of Environmental Quality
Telephone: 501-682-0984
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Quarterly

TX AST: Petroleum Storage Tank Database
Registered Aboveground Storage Tanks.

Date of Government Version: 06/01/2018
Date Data Arrived at EDR: 06/28/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 25
Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

AR AST: Aboveground Tank Database
Aboveground storage tank locations.

Date of Government Version: 06/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 33
Source: Department of Environmental Quality
Telephone: 501-682-0984
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/24/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/01/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/08/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/10/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

TX AUL: Sites with Controls

Activity and use limitations include both engineering controls and institutional controls.

Date of Government Version: 07/03/2018
Date Data Arrived at EDR: 07/10/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 57

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5891
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

TX VCP RRC: Voluntary Cleanup Program Sites

The Voluntary Cleanup Program (RRC-VCP) provides an incentive to remediate Oil & Gas related pollution by participants as long as they did not cause or contribute to the contamination. Applicants to the program receive a release of liability to the state in exchange for a successful cleanup.

Date of Government Version: 04/11/2018
Date Data Arrived at EDR: 07/06/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 18

Source: Railroad Commission of Texas
Telephone: 512-463-6969
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

TX VCP TCEQ: Voluntary Cleanup Program Database

The Texas Voluntary Cleanup Program was established to provide administrative, technical, and legal incentives to encourage the cleanup of contaminated sites in Texas.

Date of Government Version: 06/15/2018
Date Data Arrived at EDR: 07/03/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 21

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5891
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Quarterly

AR VCP: Voluntary Cleanup Program Sites

A listing of Voluntary Cleanup Program projects.

Date of Government Version: 04/30/2018
Date Data Arrived at EDR: 05/17/2018
Date Made Active in Reports: 06/21/2018
Number of Days to Update: 35

Source: Department of Environmental Quality
Telephone: 501-682-0867
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/22/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Varies

State and tribal Brownfields sites

TX BROWNFIELDS: Brownfields Site Assessments
Brownfield site assessments that are being cleaned under EPA grant monies.

Date of Government Version: 06/21/2018
Date Data Arrived at EDR: 07/06/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 17

Source: TCEQ
Telephone: 512-239-5872
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Semi-Annually

AR BROWNFIELDS: Brownfields Projects
Projects that the Department of Environmental Quality has received Brownfields applications for.

Date of Government Version: 08/08/2018
Date Data Arrived at EDR: 08/10/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 13

Source: Department of Environmental Quality
Telephone: 501-682-0867
Last EDR Contact: 08/10/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

TX NCTCOG LI: North Central Landfill Inventory
North Central Texas Council of Governments landfill database.

Date of Government Version: 07/02/2018
Date Data Arrived at EDR: 07/06/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 18
Source: North Central Texas Council of Governments
Telephone: 817-695-9223
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

TX CAPCOG LI: Capitol Area Landfill Inventory
Permitted and unpermitted landfills for the CAPCOG region. Serving Bastrop, Blanco, Burnet, Caldwell, Fayette, Hays, Lee, Llano, Travis, and Williamson Counties.

Date of Government Version: 01/06/2017
Date Data Arrived at EDR: 01/10/2017
Date Made Active in Reports: 03/15/2017
Number of Days to Update: 64
Source: Capital Area Council of Governments
Telephone: 512-916-6000
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

TX SWRCY: Recycling Facility Listing
A listing of recycling facilities in the state.

Date of Government Version: 08/10/2018
Date Data Arrived at EDR: 08/10/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 26
Source: TCEQ
Telephone: 512-239-6700
Last EDR Contact: 08/08/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Varies

AR SWRCY: Recycling Directory
A listing of recycling facilities.

Date of Government Version: 08/03/2018
Date Data Arrived at EDR: 08/06/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 17
Source: Department of Environmental Quality
Telephone: 501-682-0865
Last EDR Contact: 08/06/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/30/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/17/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 08/03/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 86

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/30/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: No Update Planned

TX CDL: Clandestine Drug Site Locations Listing

A listing of former clandestine drug site locations

Date of Government Version: 08/07/2017
Date Data Arrived at EDR: 08/15/2017
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 269

Source: Department of Public Safety
Telephone: 512-424-2144
Last EDR Contact: 07/25/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Varies

AR CDL: Methamphetamine Contaminated Properties Listing

A listing of properties believed to be contaminated by the illegal manufacture of drugs.

Date of Government Version: 07/23/2018
Date Data Arrived at EDR: 07/25/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 29

Source: Department of Environmental Quality
Telephone: 501-683-1552
Last EDR Contact: 07/25/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

TX PRIORITY CLEANERS: Dry Cleaner Remediation Program Prioritization List

A listing of dry cleaner related contaminated sites.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/08/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 32

Source: Texas Commisision on Environmenatl Quality
Telephone: 512-239-5658
Last EDR Contact: 09/07/2018
Next Scheduled EDR Contact: 06/18/2108
Data Release Frequency: Varies

TX DEL SHWS: Deleted Superfund Registry Sites

Sites have been deleted from the state Superfund registry in accordance with the Act, ?361.189

Date of Government Version: 03/31/2018
Date Data Arrived at EDR: 05/02/2018
Date Made Active in Reports: 05/09/2018
Number of Days to Update: 7

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0666
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 86

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/28/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Quarterly

Local Land Records

TX HIST LIENS: Environmental Liens Listing

This listing contains information fields that are no longer tracked in the LIENS database.

Date of Government Version: 03/23/2007
Date Data Arrived at EDR: 03/23/2007
Date Made Active in Reports: 05/02/2007
Number of Days to Update: 40

Source: Texas Commission on Environmental Qualilty
Telephone: 512-239-2209
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

TX LIENS: Environmental Liens Listing

The listing covers TCEQ liens placed against either State Superfund sites or Federal Superfund sites to recover cost incurred by TCEQ.

Date of Government Version: 07/03/2018
Date Data Arrived at EDR: 07/10/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 57

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2209
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 05/13/2018
Date Data Arrived at EDR: 05/30/2018
Date Made Active in Reports: 06/29/2018
Number of Days to Update: 30

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/27/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 73

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

TX SPILLS: Spills Database

Spills reported to the Emergency Response Division.

Date of Government Version: 08/01/2018
Date Data Arrived at EDR: 08/02/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 34

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2507
Last EDR Contact: 07/13/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Quarterly

AR SPILLS: Emergency Response Incidents

Spills and releases notified to the Department of Environmental Quality

Date of Government Version: 07/08/2018
Date Data Arrived at EDR: 07/11/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 43

Source: Department of Environmental Quality
Telephone: 501-682-0716
Last EDR Contact: 07/11/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Quarterly

TX SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 10/23/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

AR SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 05/08/2011
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/06/2013
Number of Days to Update: 62

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

TX SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 05/15/2005
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

AR SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/06/2013
Number of Days to Update: 62

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 06/28/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/24/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/11/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/13/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/17/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/27/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 87

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/27/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 08/03/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/10/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/22/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/24/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 05/13/2018
Date Data Arrived at EDR: 05/30/2018
Date Made Active in Reports: 06/29/2018
Number of Days to Update: 30

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/07/2018
Next Scheduled EDR Contact: 12/17/2018
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/01/2018
Date Data Arrived at EDR: 05/17/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 113

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/20/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2017
Date Data Arrived at EDR: 06/09/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 126

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/13/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 07/09/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/23/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 09/07/2018
Next Scheduled EDR Contact: 12/17/2018
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 09/04/2018
Next Scheduled EDR Contact: 12/17/2018
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 07/27/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/03/2018
Date Data Arrived at EDR: 04/05/2018
Date Made Active in Reports: 06/29/2018
Number of Days to Update: 85
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/05/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2018
Date Data Arrived at EDR: 04/16/2018
Date Made Active in Reports: 06/29/2018
Number of Days to Update: 74

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/09/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 08/24/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/11/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 09/11/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/20/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 05/13/2018
Date Data Arrived at EDR: 05/30/2018
Date Made Active in Reports: 06/29/2018
Number of Days to Update: 30

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/03/2018
Date Data Arrived at EDR: 05/31/2018
Date Made Active in Reports: 06/29/2018
Number of Days to Update: 29

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/29/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/31/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/31/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/10/2018
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/10/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/21/2018
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 28

Source: EPA
Telephone: (214) 665-2200
Last EDR Contact: 09/05/2018
Next Scheduled EDR Contact: 12/17/2018
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/02/2018
Date Data Arrived at EDR: 09/05/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 9

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 09/05/2018
Next Scheduled EDR Contact: 12/17/2018
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 01/04/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/31/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 06/19/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 87

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/13/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/21/2018
Date Data Arrived at EDR: 05/23/2018
Date Made Active in Reports: 09/07/2018
Number of Days to Update: 107

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/22/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Quarterly

TX AIRS: Current Emission Inventory Data

The database lists by company, along with their actual emissions, the TNRCC air accounts that emit EPA criteria pollutants.

Date of Government Version: 03/21/2018
Date Data Arrived at EDR: 04/10/2018
Date Made Active in Reports: 06/07/2018
Number of Days to Update: 58

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 09/06/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Semi-Annually

AR AIRS: Permitted Facility Emission & Stack Data

Permitted facility emissions and stack data for the state.

Date of Government Version: 06/25/2018
Date Data Arrived at EDR: 06/27/2018
Date Made Active in Reports: 07/25/2018
Number of Days to Update: 28

Source: Department of Environmental Quality
Telephone: 501-682-0726
Last EDR Contact: 06/27/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Quarterly

TX APAR: Affected Property Assessment Report Site Listing

Listing of Sites That Have Received an APAR (Affected Property Assessment Report)

Date of Government Version: 07/10/2018
Date Data Arrived at EDR: 07/13/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 54

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5872
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Varies

TX ASBESTOS: Asbestos Notification Listing

A listing of asbestos notification site locations.

Date of Government Version: 06/12/2018
Date Data Arrived at EDR: 06/22/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 31

Source: Department of State Health Services
Telephone: 512-834-6787
Last EDR Contact: 09/04/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Varies

AR ASBESTOS: Asbestos Notification of Intent Database

The database contains all properties/facilities that have submitted a Notice of Intent for renovation or demolition activities.

Date of Government Version: 07/23/2018
Date Data Arrived at EDR: 07/25/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 29

Source: Department of Environmental Quality
Telephone: 501-682-0717
Last EDR Contact: 07/25/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Quarterly

TX COAL ASH: Coal Ash Disposal Sites

A listing of facilities that use surface impoundments or landfills to dispose of coal ash.

Date of Government Version: 05/02/2018
Date Data Arrived at EDR: 05/07/2018
Date Made Active in Reports: 06/07/2018
Number of Days to Update: 31

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6624
Last EDR Contact: 07/25/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Varies

AR COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 05/16/2018
Date Data Arrived at EDR: 05/22/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 62
Source: Department of Environmental Quality
Telephone: 501-682-0600
Last EDR Contact: 08/01/2018
Next Scheduled EDR Contact: 11/19/2018
Data Release Frequency: Varies

TX DRYCLEANERS: Drycleaner Registration Database Listing
A listing of drycleaning facilities.

Date of Government Version: 05/01/2018
Date Data Arrived at EDR: 05/31/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 53
Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 08/29/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Varies

TX ED AQUIF: Edwards Aquifer Permits
A listing of permits in the Edwards Aquifer Protection Program database. The information provided is for the counties located in the Austin Region (Hays, Travis, and Williamson counties).

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 27
Source: Texas Commission on Environmental Quality, Austin Region
Telephone: 512-339-2929
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Varies

TX ENFORCEMENT: Notice of Violations Listing
A listing of permit violations.

Date of Government Version: 07/20/2018
Date Data Arrived at EDR: 07/25/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 42
Source: Texas Commission on Environmental Quality
Telephone: 512-239-6012
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Semi-Annually

AR ENFORCEMENT: Consent Administrative Order, Notice of Violation Information Database
Violations issued to facilities in various Department of Environmental Quality programs, including Air, Hazardous Waste, Storage Tanks, Solid Waste and Water.

Date of Government Version: 07/23/2018
Date Data Arrived at EDR: 07/25/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 29
Source: Department of Environmental Quality
Telephone: 501-682-0892
Last EDR Contact: 07/25/2018
Next Scheduled EDR Contact: 11/05/2018
Data Release Frequency: Varies

TX Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 06/25/2018
Date Data Arrived at EDR: 06/29/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 25
Source: Texas Commission on Environmental Quality
Telephone: 512-239-6239
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/08/2018
Data Release Frequency: Varies

AR Financial Assurance 1: Financial Assurance Information Listing
Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/14/2018
Date Data Arrived at EDR: 06/19/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 34

Source: Department of Environmental Quality
Telephone: 501-682-0876
Last EDR Contact: 06/13/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Varies

TX Financial Assurance 2: Financial Assurance Information Listing

Financial Assurance information for underground storage tank facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/10/2018
Number of Days to Update: 13

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0986
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

AR Financial Assurance 2: Financial Assurance Information Listing

Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 03/31/2014
Date Data Arrived at EDR: 04/18/2014
Date Made Active in Reports: 05/13/2014
Number of Days to Update: 25

Source: Department of Environmental Quality
Telephone: 501-682-0589
Last EDR Contact: 08/01/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Quarterly

AR Financial Assurance 3: Financial Assurance Information Listing

A listing of financial assurance information for underground storage tank facilities.

Date of Government Version: 06/18/2018
Date Data Arrived at EDR: 06/20/2018
Date Made Active in Reports: 07/23/2018
Number of Days to Update: 33

Source: Department of Environmental Quality
Telephone: 501-682-0979
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 10/01/2018
Data Release Frequency: Quarterly

TX GCC: Groundwater Contamination Cases

Texas Water Code, Section 26.406 requires the annual report to describe the current status of groundwater monitoring activities conducted or required by each agency at regulated facilities or associated with regulated activities. The report is required to contain a description of each case of groundwater contamination documented during the previous calendar year. Also to be included, is a description of each case of contamination documented during previous periods for which voluntary clean up action was incomplete at the time the preceding report was issued. The report is also required to indicate the status of enforcement action for each listed case.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 09/08/2017
Date Made Active in Reports: 09/11/2017
Number of Days to Update: 3

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5690
Last EDR Contact: 08/28/2018
Next Scheduled EDR Contact: 12/10/2018
Data Release Frequency: Annually

TX Ind. Haz Waste: Industrial & Hazardous Waste Database

Summary reports reported by waste handlers, generators and shippers in Texas.

Date of Government Version: 07/06/2018
Date Data Arrived at EDR: 07/20/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 47

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0985
Last EDR Contact: 07/20/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Annually

TX IHW CORR ACTION: IHW CORR ACTION
Industrial hazardous waste facilities with corrective actions.

Date of Government Version: 06/15/2018
Date Data Arrived at EDR: 07/03/2018
Date Made Active in Reports: 07/30/2018
Number of Days to Update: 27
Source: Texas Commission on Environmental Quality
Telephone: 512-239-5872
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

TX IOP: Innocent Owner/Operator Program
Contains information on all sites that are in the IOP. An IOP is an innocent owner or operator whose property is contaminated as a result of a release or migration of contaminants from a source or sources not located on the property, and they did not cause or contribute to the source or sources of contamination.

Date of Government Version: 06/15/2018
Date Data Arrived at EDR: 07/03/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 21
Source: Texas Commission on Environmental Quality
Telephone: 512-239-5894
Last EDR Contact: 06/29/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Quarterly

TX LEAD: Lead Inspection Listing
Lead inspection sites

Date of Government Version: 05/24/2018
Date Data Arrived at EDR: 05/25/2018
Date Made Active in Reports: 07/24/2018
Number of Days to Update: 60
Source: Department of State Health Services
Telephone: 512-834-6600
Last EDR Contact: 08/20/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Varies

TX MSD: Municipal Settings Designations Database
An MSD is an official state designation given to property within a municipality or its extraterritorial jurisdiction that certifies that designated groundwater at the property is not use as potable water, and is prohibited from future use as potatable water because that groundwater is contaminated in excess of the applicable potable-water protective concentration level.

Date of Government Version: 07/25/2018
Date Data Arrived at EDR: 07/31/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 36
Source: Texas Commission on Environmental Quality
Telephone: 512-239-4982
Last EDR Contact: 07/25/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Varies

TX NPDES: NPDES Facility List
Permitted wastewater outfalls.

Date of Government Version: 08/10/2018
Date Data Arrived at EDR: 08/10/2018
Date Made Active in Reports: 09/05/2018
Number of Days to Update: 26
Source: Texas Commission on Environmental Quality
Telephone: 512-239-4591
Last EDR Contact: 08/10/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Varies

TX RWS: Radioactive Waste Sites
Sites in the State of Texas that have been designated as Radioactive Waste sites.

Date of Government Version: 07/24/2006
Date Data Arrived at EDR: 12/14/2006
Date Made Active in Reports: 01/23/2007
Number of Days to Update: 40
Source: Texas Commission on Environmental Quality
Telephone: 512-239-0859
Last EDR Contact: 08/10/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: Semi-Annually

TX TIER 2: Tier 2 Chemical Inventory Reports
A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 06/07/2013
Date Made Active in Reports: 07/22/2013
Number of Days to Update: 45
Source: Department of State Health Services
Telephone: 512-834-6603
Last EDR Contact: 08/20/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Annually

AR TIER 2: Tier 2 Information Listing
A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 09/24/2014
Date Made Active in Reports: 10/29/2014
Number of Days to Update: 35
Source: Department of Environmental Management
Telephone: 501-683-6700
Last EDR Contact: 06/20/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

TX UIC: Underground Injection Wells Database Listing
Class V injection wells regulated by the TCEQ. Class V wells are used to inject non-hazardous fluids underground. Most Class V wells are used to dispose of wastes into or above underground sources of drinking water and can pose a threat to ground water quality, if not managed properly.

Date of Government Version: 05/01/2018
Date Data Arrived at EDR: 05/01/2018
Date Made Active in Reports: 05/09/2018
Number of Days to Update: 8
Source: Texas Commission on Environmental Quality
Telephone: 512-239-6627
Last EDR Contact: 07/13/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Varies

AR UIC: Underground Injection Wells Database Listing
A listing of wells identified as Underground Injection Wells, in the Arkansas Oil and Gas Wells data base.

Date of Government Version: 07/02/2018
Date Data Arrived at EDR: 07/18/2018
Date Made Active in Reports: 08/23/2018
Number of Days to Update: 36
Source: Arkansas Oil & Gas Commission
Telephone: 870-862-4965
Last EDR Contact: 07/18/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A
Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

TX RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Texas Commission of Environmental Quality in Texas formerly known as Texas Natural Resources Conservation Commission which changed in 2002.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/26/2013
Number of Days to Update: 178

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

AR RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Arkansas.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/02/2014
Number of Days to Update: 185

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

TX RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Texas Commission of Environmental Quality in Texas formerly known as Texas Natural Resources Conservation Commission which changed in 2002.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

AR RGA LF: Recovered Government Archive Solid Waste Facilities List
The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Arkansas.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/16/2014
Number of Days to Update: 199
Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

TRAVIS COUNTY:

TX HIST UST AUSTIN: Historic Tank Records
A listing of historic records from the City of Austin.

Date of Government Version: 06/25/2012
Date Data Arrived at EDR: 06/29/2012
Date Made Active in Reports: 08/23/2012
Number of Days to Update: 55
Source: Department of Planning & Development Review
Telephone: 512-974-2715
Last EDR Contact: 08/30/2018
Next Scheduled EDR Contact: 12/17/2018
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 08/10/2018
Date Data Arrived at EDR: 08/10/2018
Date Made Active in Reports: 09/10/2018
Number of Days to Update: 31
Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/09/2018
Next Scheduled EDR Contact: 11/26/2018
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 07/13/2018
Date Made Active in Reports: 08/01/2018
Number of Days to Update: 19
Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/13/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 07/01/2018
Date Data Arrived at EDR: 08/01/2018
Date Made Active in Reports: 08/31/2018
Number of Days to Update: 30
Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 08/01/2018
Next Scheduled EDR Contact: 11/12/2018
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 07/25/2017
Date Made Active in Reports: 09/25/2017
Number of Days to Update: 62

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/12/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/21/2018
Next Scheduled EDR Contact: 12/03/2018
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 05/16/2018
Date Data Arrived at EDR: 05/23/2018
Date Made Active in Reports: 07/03/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/16/2018
Next Scheduled EDR Contact: 10/29/2018
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/15/2018
Date Made Active in Reports: 07/09/2018
Number of Days to Update: 24

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/06/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.
Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.
Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Child Care Facility List
Source: Department of Protective & Regulatory Services
Telephone: 512-438-3269

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Texas General Land Office
Telephone: 512-463-0745

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

GRIM HOTEL
301 NORTH STATE LINE
TEXARKANA, TX 75501

TARGET PROPERTY COORDINATES

Latitude (North):	33.422959 - 33° 25' 22.65''
Longitude (West):	94.043511 - 94° 2' 36.64''
Universal Tranverse Mercator:	Zone 15
UTM X (Meters):	402983.0
UTM Y (Meters):	3698472.0
Elevation:	316 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5934377 TEXARKANA, TX
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
48037C0370D	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
Not Reported	

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
TEXARKANA	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Tertiary
Series:	Eocene Wilcox Group
Code:	Te1 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 5425918.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Grim Hotel	CLIENT:	Swift Creek Environmental, Inc
ADDRESS:	301 North State Line Texarkana TX 75501	CONTACT:	B Houghton
LAT/LONG:	33.422959 / 94.043511	INQUIRY #:	5425918.2s
		DATE:	September 17, 2018 12:49 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Eylau

Soil Surface Texture: very fine sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 76 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	very fine sandy loam	Not reported	Not reported	Max: 14 Min: 4	Max: 5.5 Min: 4.5
2	11 inches	35 inches	sandy clay loam	Not reported	Not reported	Max: 14 Min: 4	Max: 5.5 Min: 4.5
3	35 inches	55 inches	sandy clay loam	Not reported	Not reported	Max: 14 Min: 4	Max: 5.5 Min: 4.5
4	55 inches	79 inches	sandy clay loam	Not reported	Not reported	Max: 14 Min: 4	Max: 5.5 Min: 4.5

Soil Map ID: 2

Soil Component Name: Eylau

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class:

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 46 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 5.5 Min: 4.5
2	5 inches	38 inches	sandy clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 5.5 Min: 4.5
3	38 inches	72 inches	sandy clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 5.5 Min: 4.5

Soil Map ID: 3

Soil Component Name: Urban land

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 92 inches

No Layer Information available.

Soil Map ID: 4

Soil Component Name: Amy

Soil Surface Texture: silt loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Poorly drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 15 inches

Soil Layer Information

	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 4 Min: 1.4	Max: 5.5 Min: 4.5
2	5 inches	14 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 4 Min: 1.4	Max: 5.5 Min: 4.5
3	14 inches	53 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 4 Min: 1.4	Max: 5.5 Min: 4.5
4	53 inches	72 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 4 Min: 1.4	Max: 5.5 Min: 4.5

Soil Map ID: 5

Soil Component Name: Sacul

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 92 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	fine sandy loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 5.5 Min: 3.6
2	1 inches	22 inches	fine sandy loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 5.5 Min: 3.6
3	22 inches	48 inches	clay	Not reported	Not reported	Max: 4 Min: 1.4	Max: 5.5 Min: 3.6
4	48 inches	64 inches	clay loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 5.5 Min: 3.6

Soil Map ID: 6

Soil Component Name: Amy

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 15 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	18 inches	silt loam	Not reported	Not reported	Max: 1.4 Min: 0.42	Max: 5.5 Min: 3.6
2	18 inches	64 inches	loam	Not reported	Not reported	Max: 1.4 Min: 0.42	Max: 5.5 Min: 3.6
3	64 inches	68 inches	silt loam	Not reported	Not reported	Max: 1.4 Min: 0.42	Max: 5.5 Min: 3.6

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
123	USGS40000114305	1/2 - 1 Mile NE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	TXPLU3000089448	1/8 - 1/4 Mile South

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	TXPLU3000089449	1/8 - 1/4 Mile South
A3	TXPLU3000089450	1/8 - 1/4 Mile South
A4	TXMON3000289893	1/8 - 1/4 Mile SSE
A5	TXMON3000289892	1/8 - 1/4 Mile SSE
A6	TXMON3000289891	1/8 - 1/4 Mile SSE
A7	TXMON3000341789	1/8 - 1/4 Mile SSW
A8	TXMON3000341788	1/8 - 1/4 Mile SSW
A9	TXMON3000341787	1/8 - 1/4 Mile SSW
B10	TXDOL2000013574	1/8 - 1/4 Mile WSW
B11	TXPLU3000056585	1/8 - 1/4 Mile WSW
B12	TXMON3000174202	1/8 - 1/4 Mile WSW
C13	TXMON3000231359	1/8 - 1/4 Mile SSW
C14	TXMON3000242231	1/8 - 1/4 Mile SSW
A15	TXMON3000363149	1/8 - 1/4 Mile South
D16	TXPLU3000089447	1/8 - 1/4 Mile SW
D17	TXPLU3000089446	1/8 - 1/4 Mile SW
D18	TXPLU3000089445	1/8 - 1/4 Mile SW
D19	TXMON3000289887	1/8 - 1/4 Mile SW
D20	TXMON3000289886	1/8 - 1/4 Mile SW
D21	TXMON3000289885	1/8 - 1/4 Mile SW
E22	TXMON3000054659	1/8 - 1/4 Mile NW
E23	TXMON3000061115	1/8 - 1/4 Mile NW
E24	TXMON3000061116	1/8 - 1/4 Mile NW
E25	TXDOL2000013970	1/8 - 1/4 Mile NW
E26	TXDOL2000013971	1/8 - 1/4 Mile NW
E27	TXDOL2000013977	1/8 - 1/4 Mile NW
E28	TXMON3000044715	1/4 - 1/2 Mile NNW
E29	TXDOL2000014068	1/4 - 1/2 Mile NNW
F30	TXMON3000070718	1/4 - 1/2 Mile North
F31	TXDOL2000013940	1/4 - 1/2 Mile North
G32	TXMON3000047301	1/4 - 1/2 Mile WNW
G33	TXMON3000047302	1/4 - 1/2 Mile WNW
G34	TXMON3000047314	1/4 - 1/2 Mile WNW
G35	TXMON3000047290	1/4 - 1/2 Mile WNW
G36	TXMON3000047291	1/4 - 1/2 Mile WNW
G37	TXMON3000047292	1/4 - 1/2 Mile WNW
G38	TXMON3000047289	1/4 - 1/2 Mile WNW
G39	TXMON3000046844	1/4 - 1/2 Mile WNW
G40	TXMON3000047287	1/4 - 1/2 Mile WNW
G41	TXMON3000047288	1/4 - 1/2 Mile WNW
G42	TXMON3000047293	1/4 - 1/2 Mile WNW
G43	TXMON3000047298	1/4 - 1/2 Mile WNW
G44	TXMON3000047299	1/4 - 1/2 Mile WNW
G45	TXMON3000047300	1/4 - 1/2 Mile WNW
G46	TXMON3000047297	1/4 - 1/2 Mile WNW
G47	TXMON3000047294	1/4 - 1/2 Mile WNW
G48	TXMON3000047295	1/4 - 1/2 Mile WNW
G49	TXMON3000047296	1/4 - 1/2 Mile WNW
G50	TXDOL2000014049	1/4 - 1/2 Mile WNW
G51	TXDOL2000014048	1/4 - 1/2 Mile WNW
G52	TXDOL2000014051	1/4 - 1/2 Mile WNW
G53	TXDOL2000014050	1/4 - 1/2 Mile WNW

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
G54	TXDOL2000014047	1/4 - 1/2 Mile WNW
G55	TXDOL2000014044	1/4 - 1/2 Mile WNW
G56	TXDOL2000014043	1/4 - 1/2 Mile WNW
G57	TXDOL2000014046	1/4 - 1/2 Mile WNW
G58	TXDOL2000014045	1/4 - 1/2 Mile WNW
G59	TXDOL2000014058	1/4 - 1/2 Mile WNW
G60	TXDOL2000014057	1/4 - 1/2 Mile WNW
G61	TXDOL2000014060	1/4 - 1/2 Mile WNW
G62	TXDOL2000014059	1/4 - 1/2 Mile WNW
G63	TXDOL2000014056	1/4 - 1/2 Mile WNW
G64	TXDOL2000014053	1/4 - 1/2 Mile WNW
G65	TXDOL2000014052	1/4 - 1/2 Mile WNW
G66	TXDOL2000014055	1/4 - 1/2 Mile WNW
G67	TXDOL2000014054	1/4 - 1/2 Mile WNW
E68	TXMON3000070719	1/4 - 1/2 Mile NNW
E69	TXDOL2000013939	1/4 - 1/2 Mile NNW
H70	TXMON3000212018	1/4 - 1/2 Mile South
H71	TXMON3000212017	1/4 - 1/2 Mile SSW
I72	TXMON3000211912	1/2 - 1 Mile SSW
J73	TXPLU3000074595	1/2 - 1 Mile SW
J74	TXPLU3000074593	1/2 - 1 Mile SW
J75	TXPLU3000074597	1/2 - 1 Mile SW
J76	TXMON3000212020	1/2 - 1 Mile SW
I77	TXMON3000212015	1/2 - 1 Mile SSW
J78	TXMON3000250960	1/2 - 1 Mile SSW
J79	TXMON3000250820	1/2 - 1 Mile SSW
J80	TXMON3000250817	1/2 - 1 Mile SSW
J81	TXMON3000250962	1/2 - 1 Mile SSW
J82	TXMON3000250961	1/2 - 1 Mile SSW
I83	TXMON3000212019	1/2 - 1 Mile SSW
K84	TXPLU3000011116	1/2 - 1 Mile WNW
K85	TXPLU3000011117	1/2 - 1 Mile WNW
K86	TXPLU3000011115	1/2 - 1 Mile WNW
K87	TXPLU3000011129	1/2 - 1 Mile WNW
K88	TXPLU3000011114	1/2 - 1 Mile WNW
K89	TXPLU3000011125	1/2 - 1 Mile WNW
K90	TXPLU3000011124	1/2 - 1 Mile WNW
K91	TXPLU3000011126	1/2 - 1 Mile WNW
K92	TXPLU3000011128	1/2 - 1 Mile WNW
K93	TXPLU3000011127	1/2 - 1 Mile WNW
K94	TXPLU3000011123	1/2 - 1 Mile WNW
K95	TXPLU3000011119	1/2 - 1 Mile WNW
K96	TXPLU3000011118	1/2 - 1 Mile WNW
K97	TXPLU3000011120	1/2 - 1 Mile WNW
K98	TXPLU3000011122	1/2 - 1 Mile WNW
K99	TXPLU3000011121	1/2 - 1 Mile WNW
L100	TXMON3000260507	1/2 - 1 Mile NNW
L101	TXMON3000260506	1/2 - 1 Mile NNW
L102	TXMON3000260509	1/2 - 1 Mile NNW
L103	TXMON3000260512	1/2 - 1 Mile NNW
L104	TXMON3000260511	1/2 - 1 Mile NNW
M105	TXPLU3000070040	1/2 - 1 Mile WNW

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
M106	TXPLU3000070042	1/2 - 1 Mile WNW
M107	TXPLU3000070043	1/2 - 1 Mile WNW
M108	TXPLU3000070038	1/2 - 1 Mile WNW
N109	TXMON3000237977	1/2 - 1 Mile West
M110	TXPLU3000070044	1/2 - 1 Mile WNW
M111	TXPLU3000070036	1/2 - 1 Mile WNW
M112	TXPLU3000070035	1/2 - 1 Mile WNW
N113	TXMON3000237972	1/2 - 1 Mile West
M114	TXPLU3000070037	1/2 - 1 Mile WNW
M115	TXPLU3000070041	1/2 - 1 Mile WNW
M116	TXPLU3000070045	1/2 - 1 Mile WNW
M117	TXPLU3000070034	1/2 - 1 Mile WNW
M118	TXPLU3000070039	1/2 - 1 Mile WNW
O119	TXPLU3000015165	1/2 - 1 Mile SW
O120	TXMON3000099477	1/2 - 1 Mile SW
O121	TXDOL2000013860	1/2 - 1 Mile SW
122	TXMON3000237967	1/2 - 1 Mile West
P124	TXMON3000187965	1/2 - 1 Mile NNW
P125	TXMON3000216338	1/2 - 1 Mile NNW

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	TXOG60000111743	1/2 - 1 Mile SW

PHYSICAL SETTING SOURCE MAP - 5425918.2s



- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil or gas wells

SITE NAME:	Grim Hotel	CLIENT:	Swift Creek Environmental, Inc
ADDRESS:	301 North State Line Texarkana TX 75501	CONTACT:	B Houghton
		INQUIRY #:	5425918.2s
LAT/LONG:	33.422959 / 94.043511	DATE:	September 17, 2018 12:49 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
South
1/8 - 1/4 Mile
Lower

TX WELLS **TXPLU3000089448**

Plugtrackn:	90845	Dateentere:	08-NOV-13
Ownname:	City of Texarkana	Ownstreet:	P.O. Box 1967
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	100 W. Broad
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332516
Lat dec:	33.42111	Longitude:	940236
Long dec:	-94.043333	Brmod:	Google Earth
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	04-NOV-13
Plugmethco:	Plugged in place.	Plugopname:	Robert L. Flair
Plugoplic:	2948	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1 Concrete	Cbfrom2:	2
Cbto2:	25	Cbsacks2:	8 Bentonite
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Sunbelt Industrial Services
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Nameassig:	Robert L. Flair	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000089448		

A2
South
1/8 - 1/4 Mile
Lower

TX WELLS **TXPLU3000089449**

Plugtrackn:	90846	Dateentere:	08-NOV-13
Ownname:	City of Texarkana	Ownstreet:	P.O. Box 1967
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	100 W. Broad
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332516
Lat dec:	33.42111	Longitude:	940236
Long dec:	-94.043333	Brmod:	Google Earth
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5

Ownwellno:	MW-2	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	04-NOV-13
Plugmethco:	Plugged in place.	Plugopname:	Robert L. Flair
Plugoplic:	2948	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1 Concrete	Cbfrom2:	2
Cbto2:	25	Cbsacks2:	8 Bentonite
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Sunbelt Industrial Services
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Nameassig:	Robert L. Flair	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000089449		

A3
South
1/8 - 1/4 Mile
Lower

TX WELLS **TXPLU3000089450**

Plugtrackn:	90847	Dateentere:	08-NOV-13
Ownname:	City of Texarkana	Ownstreet:	P.O. Box 1967
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	100 W. Broad
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332516
Lat dec:	33.42111	Longitude:	940236
Long dec:	-94.043333	Brmod:	Google Earth
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-3	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	04-NOV-13
Plugmethco:	Plugged in place.	Plugopname:	Robert L. Flair
Plugoplic:	2948	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1 Concrete	Cbfrom2:	2

Cbto2:	25	Cbsacks2:	8 Bentonite
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Sunbelt Industrial Services
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Nameassig:	Robert L. Flair	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000089450		

A4
SSE **TX WELLS** **TXMON3000289893**
1/8 - 1/4 Mile
Lower

Dateentere:	26-JUL-12	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Tekarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	100 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75503
Own:	MW-3	Lat dec:	33.42111
Long dec:	-94.043055	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	18-JUL-12	Datecomp:	18-JUL-12
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	13	Nosacks2:	5 Bentonite
Cemfrom3:	13	Cemto3:	25
Nosacks3:	7 Sand	Cementmeth:	Gravity
Cementby:	Mark W. Hickox	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported

Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	58780
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Mark W. Hickox	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE11902
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000289893	Latitude:	33.42111
Longitude:	-94.043055		

A5
SSE
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000289892**

Dateentere:	26-JUL-12	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Tekarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	100 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75503
Own:	MW-1	Lat dec:	33.42111
Long dec:	-94.043055	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	18-JUL-12	Datecomp:	18-JUL-12
Dia1:	8.25	Dia1to:	30
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0

Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	18	Nosacks2:	9 Bentonite
Cemfrom3:	18	Cemto3:	30
Nosacks3:	7 Sand	Cementmeth:	Gravity
Cementby:	Mark W. Hickox	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	58780
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Mark W. Hickox	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE11902
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000289892	Latitude:	33.42111
Longitude:	-94.043055		

A6
SSE
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000289891**

Dateentere:	26-JUL-12	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Tekarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	100 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75503
Own:	MW-2	Lat dec:	33.42111
Long dec:	-94.043055	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0

Pby:	0	Pbn:	0
Datestart:	18-JUL-12	Datecomp:	18-JUL-12
Dia1:	8.25	Dia1to:	30
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	18	Nosacks2:	9 Bentonite
Cemfrom3:	18	Cemto3:	30
Nosacks3:	7 Sand	Cementmeth:	Gravity
Cementby:	Mark W. Hickox	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	58780
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Mark W. Hickox	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE11902
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000289891	Latitude:	33.42111
Longitude:	-94.043055		

A7
SSW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000341789**

Dateentere:	08-NOV-13	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	213 Main St
Wellcity:	Texarkana	Wellzip:	75503

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Own:	MW-3	Lat dec:	33.42111
Long dec:	-94.044166	Elev:	322
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	05-NOV-13	Datecomp:	05-NOV-13
Dia1:	8.25	Dia1to:	30
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	16/30 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	18	Nosacks2:	8 Bentonite
Cemfrom3:	18	Cemto3:	30
Nosacks3:	10 Sand	Cementmeth:	Gravity
Cementby:	Robert L. Flair	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	2948
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Robert L. Flair	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE13337
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000341789	Latitude:	33.42111

Longitude: -94.044166

A8
SSW **TX WELLS** **TXMON3000341788**
1/8 - 1/4 Mile
Lower

Dateentere:	08-NOV-13	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	213 Main St
Wellcity:	Texarkana	Wellzip:	75503
Own:	MW-2	Lat dec:	33.42111
Long dec:	-94.044166	Elev:	322
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	05-NOV-13	Datecomp:	05-NOV-13
Dia1:	8.25	Dia1to:	30
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	16/30 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	18	Nosacks2:	8 Bentonite
Cemfrom3:	18	Cemto3:	30
Nosacks3:	10 Sand	Cementmeth:	Gravity
Cementby:	Robert L. Flair	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported

Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	2948
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Robert L. Flair	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE13337
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000341788	Latitude:	33.42111
Longitude:	-94.044166		

A9
SSW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000341787**

Dateentere:	08-NOV-13	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	213 Main St
Wellcity:	Texarkana	Wellzip:	75503
Own:	MW-1	Lat dec:	33.42111
Long dec:	-94.044166	Elev:	322
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	04-NOV-13	Datecomp:	04-NOV-13
Dia1:	8.25	Dia1to:	30
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	16/30 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	18	Nosacks2:	8 Bentonite
Cemfrom3:	18	Cemto3:	30
Nosacks3:	10 Sand	Cementmeth:	Gravity
Cementby:	Robert L. Flair	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported

Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	2948
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Robert L. Flair	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE13337
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000341787	Latitude:	33.42111
Longitude:	-94.044166		

B10
WSW
1/8 - 1/4 Mile
Lower

TX WELLS **TXDOL2000013574**

Database:	Well Report Database	Fid:	13573
Rec id:	13629	Edr site i:	176693
Owner:	City of Texarkana	Ownerwell:	MW-1
Address:	303 Texas Blvd., Texarkana , TX 75504		
Grid:	16-40-5	Waddress:	303 Texas Blvd., Texarkana , TX 75504
Lat:	33 25 18 N	County:	Bowie
Long:	094 02 45 W	Elevation:	314 ft.
Gpsused:	Garmin	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	6 in From Surface To 25 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	8 ft to 25 ft	Packsize:	20/40 sand
Finterval:	From 6 ft to 8 ft with 1 - Bentonite p (#sacks and material)		
Sinterval:	From 0 ft to 6 ft with 1 - Portland (#sacks and material)		
Tinterval:	No Data	Usedmethod:	Tremie pipe
Cementedby:	Walker-Hill Environmental	Contaminat:	N/A ft
Propertyli:	8 ft	Verrimetho:	tagged
Varriance:	N/A	Surface:	Surface Slab Installed
Staticleve:	17 ft. below land surface on 4/28/2009		
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	Bailer
Yield:	(No Data) GPM with (No Data) ft drawdown after (No Data) hours		
Watertype:	good	Stratadept:	N/A ft.
Chemicalma:	Yes	Undesirabl:	No
Companynam:	Walker-Hill Environmental, Inc.	Companyadd:	PO Box 1147
Ccitystate:	Foxworth , MS 39483	Licensenum:	58141
Wsignature:	Gary P. Hill	Dsignature:	No Data

Regnum:	No Data	Comments:	No Data
Site id:	TXDOL2000013574		

B11
WSW
1/8 - 1/4 Mile
Lower

TX WELLS **TXPLU3000056585**

Plugtrackn:	57558	Dateentere:	12-AUG-09
Ownname:	City of Texarkana	Ownstreet:	303 Texas Blvd
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	303 Texas Blvd
Wellcity:	Texarkana	Wellzip:	75504
County:	Bowie	Latitude:	332518
Lat dec:	33.421666	Longitude:	940245
Long dec:	-94.045833	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Walker-Hill Environmental
Histdrllic:	58141	Histdatedr:	28-APR-09
Histtracki:	176693	Histdiamin:	2
Histdepth:	25	Plugdate:	22-JUL-09
Plugmethco:	No Data	Plugopname:	Walker-Hill Environmental, Inc
Plugoplic:	58141	Plugmeth1:	1
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	25
Cbsacks1:	2 - Portland	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Walker-Hill Environmental, Inc.
Compstreet:	PO Box 1147	Compcity:	Foxworth
Compstate:	MS	Compzip:	39483
Nameassig:	Gary P. Hill	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000056585		

B12
WSW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000174202**

Dateentere:	30-APR-09	Ownname:	City of Texarkana
Ownstreet:	303 Texas Blvd.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	303 Texas Blvd.
Wellcity:	Texarkana	Wellzip:	75504
Own:	MW-1	Lat dec:	33.421666
Long dec:	-94.045833	Elev:	314

Brandmodel:	Garmin	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-APR-09	Datecomp:	28-APR-09
Dia1:	6	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	1
Bcgs:	20/40 sand	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	8	Gpt:	25
Cemfrom1:	6	Cemto1:	8
Nosacks1:	1 - Bentonite p	Cemfrom2:	0
Cemto2:	6	Nosacks2:	1 - Portland
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Tremie pipe
Cementby:	Walker-Hill Environmental	Ds:	N/A
Dpl:	8	Dsv:	tagged
Appvar:	N/A	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	17
Watlevdate:	28-APR-09	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	1
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	good
Stratdepth:	N/A	Chemanaly:	1
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Walker-Hill Environmental, Inc.	Drllicno:	58141
Compstreet:	PO Box 1147	Compcity:	Foxworth
Compstate:	MS	Compzip:	39483
Drillernam:	Gary P. Hill	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000174202	Latitude:	33.421666
Longitude:	-94.045833		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database: **TX WELLS** EDR ID Number: **TXMON3000231359**

C13
SSW
1/8 - 1/4 Mile
Lower

Dateentere:	01-NOV-10	Ownname:	The Silvermoon
Ownstreet:	211 West Broad Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	211 West Broad Street
Wellcity:	Texarkana	Wellzip:	75501
Own:	Not Reported	Lat dec:	33.420277
Long dec:	-94.044721	Elev:	0
Brandmodel:	Magellan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	0	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	1
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	07-OCT-10	Datecomp:	08-OCT-10
Dia1:	4	Dia1to:	250
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	1	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	1	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	250
Nosacks1:	10	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Pressured Grout BH20
Cementby:	William McPike	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Geothermal Drilling, Inc.	Drllicno:	3166
Compstreet:	8840 Highway 75 South	Compcity:	Huntsville
Compstate:	TX	Compzip:	77340
Drillernam:	William McPike	Traineenam:	Jose Lira
Tnum:	57326	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000231359	Latitude:	33.420277
Longitude:	-94.044721		

C14
SSW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000242231**

Dateentere:	03-MAR-11	Ownname:	The Silvermoon
Ownstreet:	211 West Broad Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	211 West Broad Street
Wellcity:	Texarkana	Wellzip:	75501
Own:	Not Reported	Lat dec:	33.420277
Long dec:	-94.044721	Elev:	0
Brandmodel:	Magellan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	0	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	1
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	24-JAN-11	Datecomp:	02-MAR-11
Dia1:	4	Dia1to:	250
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	1	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	1	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	250
Nosacks1:	450	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Pressured Grout BH20
Cementby:	William McPike	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0

Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Geothermal Drilling, Inc.	Drllicno:	3166
Compstreet:	8840 Highway 75 South	Compcity:	Huntsville
Compstate:	TX	Compzip:	77340
Drillernam:	William McPike	Traineenam:	Jose Lira
Tnum:	57326	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000242231	Latitude:	33.420277
Longitude:	-94.044721		

A15
South
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000363149**

Dateentere:	01-JUL-14	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	Union Station
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW-1	Lat dec:	33.419999
Long dec:	-94.043333	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	24-JUN-14	Datecomp:	24-JUN-14
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0

Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	16/30 Sand Pack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	3
Nosacks1:	1 Concrete	Cemfrom2:	3
Cemto2:	8	Nosacks2:	3 Bentonite
Cemfrom3:	8	Cemto3:	20
Nosacks3:	6 Sand	Cementmeth:	Gravity
Cementby:	Juan R. Alcala	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	15
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	59430
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Juan R. Alcala	Traineenam:	Not Reported
Tnum:	Not Reported		
Comments:	DE14150 MW-2 and MW-3 on the Arkansas side of the street.		
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000363149	Latitude:	33.419999
Longitude:	-94.043333		

D16
SW
1/8 - 1/4 Mile
Lower

TX WELLS **TXPLU3000089447**

Plugtrackn:	90844	Dateentere:	08-NOV-13
Ownname:	City of Texarkana	Ownstreet:	P.O. Box 1967
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	523 W. 3rd Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332515
Lat dec:	33.420832	Longitude:	940249
Long dec:	-94.046944	Brmod:	Google Earth
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-3	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported

Histdepth:	Not Reported	Plugdate:	04-NOV-13
Plugmethco:	Removed all 2" PVC well casing from well. plugged to 2' bgs with bentonite. 0-2' concrete.		
Plugopname:	Robert L. Flair	Plugoplic:	2948
Plugmeth1:	0	Plugmeth2:	0
Plugmeth3:	0	Plugmeth4:	0
Plugmethot:	1	Plugvar:	Not Reported
Cdiam1:	Not Reported	Cfrom1:	Not Reported
Cto1:	Not Reported	Cdiam2:	Not Reported
Cfrom2:	Not Reported	Cto2:	Not Reported
Cdiam3:	Not Reported	Cfrom3:	Not Reported
Cto3:	Not Reported	Cbfrom1:	0
Cbto1:	2	Cbsacks1:	1 Concrete
Cbfrom2:	2	Cbto2:	25
Cbsacks2:	6 Bentonite	Cbfrom3:	Not Reported
Cbto3:	Not Reported	Cbsacks3:	Not Reported
Cbfrom4:	Not Reported	Cbto4:	Not Reported
Cbsacks4:	Not Reported	Cbfrom5:	Not Reported
Cbto5:	Not Reported	Cbsacks5:	Not Reported
Compname:	Sunbelt Industrial Services	Compstreet:	2415 Cullen St
Compcity:	Fort Worth	Compstate:	TX
Compzip:	76107	Nameassig:	Robert L. Flair
Traineenam:	Not Reported	Tnum:	Not Reported
Deleted:	0	Site id:	TXPLU3000089447

D17
SW
1/8 - 1/4 Mile
Lower

TX WELLS **TXPLU3000089446**

Plugtrackn:	90843	Dateentere:	08-NOV-13
Ownname:	City of Texarkana	Ownstreet:	P.O. Box 1967
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	523 W. 3rd Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332515
Lat dec:	33.420832	Longitude:	940249
Long dec:	-94.046944	Brmod:	Google Earth
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-2	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	04-NOV-13
Plugmethco:	Removed all 2" PVC well casing from well. plugged to 2' bgs with bentonite. 0-2' concrete.		
Plugopname:	Robert L. Flair	Plugoplic:	2948
Plugmeth1:	0	Plugmeth2:	0
Plugmeth3:	0	Plugmeth4:	0
Plugmethot:	1	Plugvar:	Not Reported
Cdiam1:	Not Reported	Cfrom1:	Not Reported
Cto1:	Not Reported	Cdiam2:	Not Reported
Cfrom2:	Not Reported	Cto2:	Not Reported
Cdiam3:	Not Reported	Cfrom3:	Not Reported
Cto3:	Not Reported	Cbfrom1:	0
Cbto1:	2	Cbsacks1:	1 Concrete
Cbfrom2:	2	Cbto2:	25
Cbsacks2:	6 Bentonite	Cbfrom3:	Not Reported
Cbto3:	Not Reported	Cbsacks3:	Not Reported
Cbfrom4:	Not Reported	Cbto4:	Not Reported
Cbsacks4:	Not Reported	Cbfrom5:	Not Reported

Cbto5:	Not Reported	Cbsacks5:	Not Reported
Compname:	Sunbelt Industrial Services	Compstreet:	2415 Cullen St
Compcity:	Fort Worth	Compstate:	TX
Compzip:	76107	Nameassig:	Robert L. Flair
Traineenam:	Not Reported	Tnum:	Not Reported
Deleted:	0	Site id:	TXPLU3000089446

D18
SW **TX WELLS** **TXPLU3000089445**
1/8 - 1/4 Mile
Lower

Plugtrackn:	90842	Dateentere:	08-NOV-13
Ownname:	City of Texarkana	Ownstreet:	P.O. Box 1967
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75504	Wellstreet:	523 W. 3rd Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332515
Lat dec:	33.420832	Longitude:	940249
Long dec:	-94.046944	Brmod:	Google Earth
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	04-NOV-13
Plugmethco:	Removed all 2" PVC well casing from well. plugged to 2' bgs with bentonite. 0-2' concrete.		
Plugopname:	Robert L. Flair	Plugoplic:	2948
Plugmeth1:	0	Plugmeth2:	0
Plugmeth3:	0	Plugmeth4:	0
Plugmethot:	1	Plugvar:	Not Reported
Cdiam1:	Not Reported	Cfrom1:	Not Reported
Cto1:	Not Reported	Cdiam2:	Not Reported
Cfrom2:	Not Reported	Cto2:	Not Reported
Cdiam3:	Not Reported	Cfrom3:	Not Reported
Cto3:	Not Reported	Cbfrom1:	0
Cbto1:	2	Cbsacks1:	1 Concrete
Cbfrom2:	2	Cbto2:	25
Cbsacks2:	6 Bentonite	Cbfrom3:	Not Reported
Cbto3:	Not Reported	Cbsacks3:	Not Reported
Cbfrom4:	Not Reported	Cbto4:	Not Reported
Cbsacks4:	Not Reported	Cbfrom5:	Not Reported
Cbto5:	Not Reported	Cbsacks5:	Not Reported
Compname:	Sunbelt Industrial Services	Compstreet:	2415 Cullen St
Compcity:	Fort Worth	Compstate:	TX
Compzip:	76107	Nameassig:	Robert L. Flair
Traineenam:	Not Reported	Tnum:	Not Reported
Deleted:	0	Site id:	TXPLU3000089445

D19
SW **TX WELLS** **TXMON3000289887**
1/8 - 1/4 Mile
Lower

Dateentere:	26-JUL-12	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	523 W. 3rd St

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Wellcity:	Texarkana	Wellzip:	75501
Own:	MW-3	Lat dec:	33.420832
Long dec:	-94.046944	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-JUL-12	Datecomp:	17-JUL-12
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sandpack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	13	Nosacks2:	4 Bentonite
Cemfrom3:	13	Cemto3:	25
Nosacks3:	6 Sand	Cementmeth:	Gravity
Cementby:	Mark W.Hickox	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	58780
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Mark W. Hicox	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE11903
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported

Site id:	TXMON3000289887	Latitude:	33.420832
Longitude:	-94.046944		

D20
SW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000289886**

Dateentere:	26-JUL-12	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	523 W. 3rd St
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW-1	Lat dec:	33.420832
Long dec:	-94.046944	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-JUL-12	Datecomp:	17-JUL-12
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sandpack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	13	Nosacks2:	4 Bentonite
Cemfrom3:	13	Cemto3:	25
Nosacks3:	6 Sand	Cementmeth:	Gravity
Cementby:	Mark W.Hickox	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0

Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	58780
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Mark W. Hicox	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE11903
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000289886	Latitude:	33.420832
Longitude:	-94.046944		

D21
SW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000289885**

Dateentere:	26-JUL-12	Ownname:	City of Texarkana
Ownstreet:	P.O. Box 1967	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75504
County:	Bowie	Wellstreet:	523 W. 3rd St
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW-2	Lat dec:	33.420832
Long dec:	-94.046944	Elev:	0
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-JUL-12	Datecomp:	17-JUL-12
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sandpack
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Concrete	Cemfrom2:	2
Cemto2:	13	Nosacks2:	4 Bentonite
Cemfrom3:	13	Cemto3:	25
Nosacks3:	6 Sand	Cementmeth:	Gravity
Cementby:	Mark W.Hickox	Ds:	Not Reported

Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Sunbelt Industrial Services	Drllicno:	58780
Compstreet:	2415 Cullen St	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76107
Drillernam:	Mark W. Hicox	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	DE11903
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000289885	Latitude:	33.420832
Longitude:	-94.046944		

E22
NW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000054659**

Dateentere:	28-MAR-05	Ownname:	Robert Griffen
Ownstreet:	404 west 7th street	Owncity:	texarkana
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	404 west 7th street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	MW-6, SB	Lat dec:	33.425832
Long dec:	-94.04611	Elev:	0
Brandmodel:	Etrex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-MAR-05	Datecomp:	28-MAR-05
Dia1:	8.25	Dia1to:	25
Dia2:	2.25	Dia2from:	0
Dia2to:	15	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0

Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	1
Dmother:	geoprobe 6610	Bco:	1
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	sand 20/40
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	2	Cemto1:	25
Nosacks1:	sand 20/40	Cemfrom2:	1
Cemto2:	2	Nosacks2:	bentinite
Cemfrom3:	0	Cemto3:	1
Nosacks3:	concrete	Cementmeth:	gravity
Cementby:	Rodney Swann	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	1	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Precision Probe and Drilling	Drllicno:	54661
Compstreet:	6133 Verona Lane	Compcity:	Shreveport
Compstate:	LA	Compzip:	71105
Drillernam:	Rodney Swann	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000054659	Latitude:	33.425832
Longitude:	-94.04611		

E23
NW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000061115**

Dateentere:	07-JUL-05	Ownname:	Robert Griffen
Ownstreet:	404 West 7TH Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	404 West 7th Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	MW-6	Lat dec:	33.425832
Long dec:	-94.04611	Elev:	0
Brandmodel:	Etrex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0

Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-MAR-05	Datecomp:	28-MAR-05
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	1
Dmother:	Geoprobe 6620DT	Bco:	1
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	sand 20/40
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	1
Nosacks1:	concrete	Cemfrom2:	1
Cemto2:	2	Nosacks2:	bentinite
Cemfrom3:	2	Cemto3:	25
Nosacks3:	sand 20/40	Cementmeth:	gravity
Cementby:	Rodney Brian Swann	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Precision Probe and Drilling	Drllicno:	54661
Compstreet:	6133 Verona Lane	Compcity:	Shreveport
Compstate:	LA	Compzip:	71105
Drillernam:	Rodney Brian Swann	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000061115	Latitude:	33.425832
Longitude:	-94.04611		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E24
NW
1/8 - 1/4 Mile
Lower

TX WELLS **TXMON3000061116**

Dateentere:	07-JUL-05	Ownname:	Robert Griffen
Ownstreet:	404 West 7th Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	404 West 7th Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	SB-2	Lat dec:	33.425832
Long dec:	-94.04611	Elev:	0
Brandmodel:	Etrex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	0	Ue:	1
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-MAR-05	Datecomp:	28-MAR-05
Dia1:	2.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	1	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	1
Dmother:	Geoprobe 6620DT	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	Not Reported	Cemto1:	Not Reported
Nosacks1:	Not Reported	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Not Reported
Cementby:	Not Reported	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	1	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Precision Probe and Drilling	Drllicno:	54661
Compstreet:	6133 Verona Lane	Compcity:	Shreveport
Compstate:	LA	Compzip:	71105
Drillernam:	Rodney Brian Swann	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000061116	Latitude:	33.425832
Longitude:	-94.04611		

E25
NW
1/8 - 1/4 Mile
Lower

TX WELLS **TXDOL2000013970**

Database:	Well Report Database	Fid:	13969
Rec id:	13969	Edr site i:	62186
Owner:	Robert Griffen	Ownerwell:	SB-2
Address:	404 West 7th Street, Texarkana , TX	Grid:	16-40-5
Waddress:	404 West 7th Street, Texarkana , TX	Lat:	33 25 33 N
County:	Bowie	Long:	094 02 46 W
Elevation:	No Data	Gpsused:	Etrex
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	Not Reported	Completedd:	Not Reported
Diameter:	2.25 in From Surface To 15 ft	Dmethod:	Driven
Bcompletio:	No Data	Packedfrom:	Not Reported
Packsize:	Not Reported	Finterval:	No Data
Sinterval:	No Data	Tinterval:	No Data
Usedmethod:	Not Reported	Cementedby:	Not Reported
Contaminat:	Not Reported	Propertyli:	Not Reported
Verrimetho:	Not Reported	Varriance:	Not Reported
Surface:	No Data	Staticleve:	No Data
Flow:	No Data	Packers:	none
Cementinwe:	Not Reported	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	Precision Probe and Drilling
Companyadd:	6133 Verona Lane	Ccitystate:	Shreveport , LA 71105
Licensenum:	54661	Wsignature:	Rodney Brian Swann
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000013970

E26
NW
1/8 - 1/4 Mile
Lower

TX WELLS **TXDOL2000013971**

Database:	Well Report Database	Fid:	13970
Rec id:	13970	Edr site i:	62185
Owner:	Robert Griffen	Ownerwell:	MW-6
Address:	404 West 7TH Street, Texarkana , TX	Grid:	16-40-5
Waddress:	404 West 7th Street, Texarkana , TX	Lat:	33 25 33 N
County:	Bowie	Long:	094 02 46 W
Elevation:	No Data	Gpsused:	Etrex

Typeofwork:	New Well	Propuse:	Monitor
Sdate:	Not Reported	Completedd:	Not Reported
Diameter:	8.25 in From Surface To 25 ft	Dmethod:	Hollow Stem Auger
Bcompletio:	Open Hole	Packedfrom:	Not Reported
Packsize:	Not Reported		
Finterval:	From 0 ft to 1 ft with concrete (#sacks and material)		
Sinterval:	From 1 ft to 2 ft with bentinite (#sacks and material)		
Tinterval:	From 2 ft to 25 ft with sand 20/40 (#sacks and material)		
Usedmethod:	gravity	Cementedby:	Rodney Brian Swann
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	none
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	Precision Probe and Drilling
Companyadd:	6133 Verona Lane	Ccitystate:	Shreveport , LA 71105
Licensenum:	54661	Wsignature:	Rodney Brian Swann
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000013971

E27
NW
1/8 - 1/4 Mile
Lower

TX WELLS **TXDOL2000013977**

Database:	Well Report Database	Fid:	13976
Rec id:	13976	Edr site i:	55676
Owner:	Robert Griffen	Ownerwell:	MW-6, SB
Address:	404 west 7th street, texarkana , TX	Grid:	16-40-5
Waddress:	404 west 7th street, Texarkana , TX	Lat:	33 25 33 N
County:	Bowie	Long:	094 02 46 W
Elevation:	No Data	Gpsused:	Etrex
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	Not Reported	Completedd:	Not Reported
Diameter:	8.25 in From Surface To 25 ft	Dmethod:	Hollow Stem Auger
Bcompletio:	Open Hole	Packedfrom:	Not Reported
Packsize:	Not Reported		
Finterval:	From 2 ft to 25 ft with sand 20/40 (#sacks and material)		
Sinterval:	From 1 ft to 2 ft with bentinite (#sacks and material)		
Tinterval:	From 0 ft to 1 ft with concrete (#sacks and material)		
Usedmethod:	gravity	Cementedby:	Rodney Swann
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	none
Cementinwe:	Not Reported	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	Precision Probe and Drilling
Companyadd:	6133 Verona Lane	Ccitystate:	Shreveport , LA 71105
Licensenum:	54661	Wsignature:	Rodney Swann
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000013977

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
TX WELLS	**TXMON3000044715**

E28
NNW
1/4 - 1/2 Mile
Lower

Dateentere:	29-SEP-04	Ownname:	Robert Griffin
Ownstreet:	404 W. 7th Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	404 W. 7th Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	MW-1-5	Lat dec:	33.42611
Long dec:	-94.045833	Elev:	0
Brandmodel:	Not Reported	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	09-SEP-04	Datecomp:	10-SEP-04
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	1
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	1
Bcgs:	0.020	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	1.5	Gpt:	5
Cemfrom1:	0.5	Cemto1:	1.5
Nosacks1:	.4 bentonite	Cemfrom2:	.5
Cemto2:	0	Nosacks2:	.5 sackcrete
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	mixed by hand
Cementby:	Johnny Body	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	10
Watlevdate:	09-SEP-04	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	dba Universal Drilling Services	Drllicno:	3060
Compstreet:	3532 Maggie Boulevard	Compcity:	Orlando
Compstate:	FL	Compzip:	32811
Drillernam:	Johnny Body	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000044715	Latitude:	33.42611
Longitude:	-94.045833		

E29
NNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014068**

Database:	Well Report Database	Fid:	14067
Rec id:	14069	Edr site i:	45668
Owner:	Robert Griffin	Ownerwell:	MW-1-5
Address:	404 W. 7th Street, Texarkana , TX 75501		
Grid:	16-40-5	Waddress:	404 W. 7th Street, Texarkana , TX
Lat:	33 25 34 N	County:	Bowie
Long:	094 02 45 W	Elevation:	No Data
Gpsused:	No Data	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	8.25 in From Surface To 25 ft
Dmethod:	Air Rotary	Bcompletio:	Not Reported
Packedfrom:	1.5 ft to 5 ft	Packsize:	0.020
Finterval:	From 0.5 ft to 1.5 ft with .4 bentonite (#sacks and material)		
Sinterval:	From .5 ft to 0 ft with .5 sackcrete (#sacks and material)		
Tinterval:	No Data	Usedmethod:	mixed by hand
Cementedby:	Johnny Body	Contaminat:	No Data
Propertyli:	No Data	Verrimetho:	No Data
Varriance:	No Data	Surface:	Surface Slab Installed
Staticleve:	10 ft. below land surface on 9/9/2004		
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	dba Universal Drilling Services
Companyadd:	3532 Maggie Boulevard	Ccitystate:	Orlando , FL 32811
Licensenum:	3060	Wsignature:	Johnny Body
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014068

F30
North
1/4 - 1/2 Mile
Higher

TX WELLS **TXMON3000070718**

Dateentere:	06-DEC-05	Ownname:	Mrs. Margaret Chandler
Ownstreet:	201 west 7th street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	201 west 7th street
Wellcity:	Texarkana	Wellzip:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Own:	MW-10	Lat dec:	33.426666
Long dec:	-94.043888	Elev:	0
Brandmodel:	Garmin Etrex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	06-DEC-05	Datecomp:	06-DEC-05
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	1
Dmother:	geoprobe 6620	Bco:	1
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	sand 20/40
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	1
Nosacks1:	concrete	Cemfrom2:	1
Cemto2:	1.5	Nosacks2:	bentinite
Cemfrom3:	1.5	Cemto3:	20
Nosacks3:	sand 20/40	Cementmeth:	gravity
Cementby:	Rodney Swann	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Precision Porbe and Drilling	Drllicno:	54661
Compstreet:	6133 Verona Lane	Compcity:	Shreveport
Compstate:	LA	Compzip:	71105
Drillernam:	Rodney Swann	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000070718	Latitude:	33.426666

Longitude: -94.043888

F31
North
1/4 - 1/2 Mile
Higher

TX WELLS **TXDOL2000013940**

Database:	Well Report Database	Fid:	13939
Rec id:	13929	Edr site i:	71868
Owner:	Mrs. Margaret Chandler	Ownerwell:	MW-10
Address:	201 west 7th street, Texarkana , TX	Grid:	16-40-5
Waddress:	201 west 7th street, Texarkana , TX	Lat:	33 25 36 N
County:	Bowie	Long:	094 02 38 W
Elevation:	No Data	Gpsused:	Garmin Etrex
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	Not Reported	Completedd:	Not Reported
Diameter:	8.25 in From Surface To 20 ft	Dmethod:	Hollow Stem Auger
Bcompletio:	Open Hole	Packedfrom:	Not Reported
Packsize:	Not Reported		
Finterval:	From 0 ft to 1 ft with concrete (#sacks and material)		
Sinterval:	From 1 ft to 1.5 ft with bentinite (#sacks and material)		
Tinterval:	From 1.5 ft to 20 ft with sand 20/40 (#sacks and material)		
Usedmethod:	gravity	Cementedby:	Rodney Swann
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	none
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	Precision Porbe and Drilling
Companyadd:	6133 Verona Lane	Ccitystate:	Shreveport , LA 71105
Licensenum:	54661	Wsignature:	Rodney Swann
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000013940

G32
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047301**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB05	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0

Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	20-OCT-04	Datecomp:	20-OCT-04
Dia1:	2.125	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	1 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047301	Latitude:	33.424721
Longitude:	-94.047777		

G33
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047302**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street

Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB06	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	27-OCT-04	Datecomp:	27-OCT-04
Dia1:	2.125	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	15	Cemto1:	8
Nosacks1:	1 Sand	Cemfrom2:	8
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported

Site id:	TXMON3000047302	Latitude:	33.424721
Longitude:	-94.047777		

G34
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047314**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB07	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	27-OCT-04	Datecomp:	27-OCT-04
Dia1:	2.125	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	1 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0

Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047314	Latitude:	33.424721
Longitude:	-94.047777		

G35
WNW **TX WELLS** **TXMON3000047290**
1/4 - 1/2 Mile
Lower

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-IN01	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	25-OCT-04	Datecomp:	25-OCT-04
Dia1:	8.25	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	5 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	5 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	2 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported

Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047290	Latitude:	33.424721
Longitude:	-94.047777		

G36
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047291**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-IN02	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	25-OCT-04	Datecomp:	25-OCT-04
Dia1:	8.25	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0

Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	5 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	5 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	2 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047291	Latitude:	33.424721
Longitude:	-94.047777		

G37
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047292**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	Test 1	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0

Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	21-OCT-04	Datecomp:	21-OCT-04
Dia1:	2.125	Dia1to:	14.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	14.5	Cemto1:	7.5
Nosacks1:	1 Sand	Cemfrom2:	7.5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047292	Latitude:	33.424721
Longitude:	-94.047777		

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
G38 **WNW** **1/4 - 1/2 Mile** **Lower**	**TX WELLS**	**TXMON3000047289**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-IN02	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	26-OCT-04	Datecomp:	26-OCT-04
Dia1:	8.25	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	3 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	3 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	2 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047289	Latitude:	33.424721
Longitude:	-94.047777		

G39
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000046844**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-OB05	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	21-OCT-04	Datecomp:	21-OCT-04
Dia1:	2.125	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	1 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1

Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000046844	Latitude:	33.424721
Longitude:	-94.047777		

G40
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047287**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	Test 2	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	26-OCT-04	Datecomp:	26-OCT-04
Dia1:	8.25	Dia1to:	14.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0

Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	14.5	Cemto1:	7.5
Nosacks1:	3 Sand	Cemfrom2:	7.5
Cemto2:	2	Nosacks2:	3 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	2 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047287	Latitude:	33.424721
Longitude:	-94.047777		

G41
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047288**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-IN01	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0

Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	25-OCT-04	Datecomp:	25-OCT-04
Dia1:	8.25	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	3 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	3 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	2 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047288	Latitude:	33.424721
Longitude:	-94.047777		

G42
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047293**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-OB01	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	20-OCT-04	Datecomp:	20-OCT-04
Dia1:	2.125	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	1 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported

Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047293	Latitude:	33.424721
Longitude:	-94.047777		

G43
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047298**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB02	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	19-OCT-04	Datecomp:	19-OCT-04
Dia1:	2.125	Dia1to:	18
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	18	Cemto1:	11
Nosacks1:	1 Sand	Cemfrom2:	11
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported

Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047298	Latitude:	33.424721
Longitude:	-94.047777		

G44
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047299**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB03	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	19-OCT-04	Datecomp:	19-OCT-04
Dia1:	2.125	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	1 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix

Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047299	Latitude:	33.424721
Longitude:	-94.047777		

G45
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047300**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB04	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	19-OCT-04	Datecomp:	19-OCT-04
Dia1:	2.125	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0

Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	1 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047300	Latitude:	33.424721
Longitude:	-94.047777		

G46
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047297**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	K7-OB01	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0

Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	20-OCT-04	Datecomp:	20-OCT-04
Dia1:	2.125	Dia1to:	17
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	17	Cemto1:	10
Nosacks1:	1 Sand	Cemfrom2:	10
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047297	Latitude:	33.424721
Longitude:	-94.047777		

Map ID
Direction
Distance
Elevation

Database: TX WELLS
EDR ID Number: TXMON3000047294

G47
WNW
1/4 - 1/2 Mile
Lower

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-OB02	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	21-OCT-04	Datecomp:	21-OCT-04
Dia1:	2.125	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	1 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047294	Latitude:	33.424721
Longitude:	-94.047777		

G48
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047295**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-OB03	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	20-OCT-04	Datecomp:	20-OCT-04
Dia1:	2.125	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	1 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1

Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047295	Latitude:	33.424721
Longitude:	-94.047777		

G49
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000047296**

Dateentere:	11-NOV-04	Ownname:	TCEQ
Ownstreet:	Not Reported	Owncity:	Austin
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	Dead End of Lubbock Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	G16-OB04	Lat dec:	33.424721
Long dec:	-94.047777	Elev:	0
Brandmodel:	Magelan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	21-OCT-04	Datecomp:	21-OCT-04
Dia1:	2.125	Dia1to:	12
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0

Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 Sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	12	Cemto1:	5
Nosacks1:	1 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement Slurry	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	54834
Compstreet:	5524 Midway Road, Suite 3	Compcity:	Ft. Worth
Compstate:	TX	Compzip:	76117
Drillernam:	Michael Bridges	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000047296	Latitude:	33.424721
Longitude:	-94.047777		

G50
WNW **TX WELLS** **TXDOL2000014049**
1/4 - 1/2 Mile
Lower

Database:	Well Report Database	Fid:	14048
Rec id:	14044	Edr site i:	48263
Owner:	TCEQ	Ownerwell:	K7-OB01
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 1 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI

Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014049

G51
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014048**

Database:	Well Report Database	Fid:	14047
Rec id:	14043	Edr site i:	48264
Owner:	TCEQ	Ownerwell:	K7-OB02
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 18 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 18 ft to 11 ft with 1 Sand (#sacks and material)		
Sinterval:	From 11 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014048

G52
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014051**

Database:	Well Report Database	Fid:	14050
Rec id:	14046	Edr site i:	48260
Owner:	TCEQ	Ownerwell:	G16-OB04
Address:	Austin , TX	Grid:	16-40-5

Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 1 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014051

G53
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014050**

Database:	Well Report Database	Fid:	14049
Rec id:	14045	Edr site i:	48261
Owner:	TCEQ	Ownerwell:	G16-OB05
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 1 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014050

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G54
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014047**

Database:	Well Report Database	Fid:	14046
Rec id:	14042	Edr site i:	48265
Owner:	TCEQ	Ownerwell:	K7-OB03
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 1 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014047

G55
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014044**

Database:	Well Report Database	Fid:	14043
Rec id:	14039	Edr site i:	48268
Owner:	TCEQ	Ownerwell:	K7-OB06
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 15 ft to 8 ft with 1 Sand (#sacks and material)		
Sinterval:	From 8 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data

Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014044

G56
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014043**

Database:	Well Report Database	Fid:	14042
Rec id:	14038	Edr site i:	48270
Owner:	TCEQ	Ownerwell:	K7-OB07
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 1 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014043

G57
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014046**

Database:	Well Report Database	Fid:	14045
Rec id:	14041	Edr site i:	48266
Owner:	TCEQ	Ownerwell:	K7-OB04
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie

Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 1 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014046

G58
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014045**

Database:	Well Report Database	Fid:	14044
Rec id:	14040	Edr site i:	48267
Owner:	TCEQ	Ownerwell:	K7-OB05
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 1 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014045

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G59
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014058**

Database:	Well Report Database	Fid:	14057
Rec id:	14053	Edr site i:	48253
Owner:	TCEQ	Ownerwell:	G16-IN02
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	8.25 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 3 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 3 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 2 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014058

G60
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014057**

Database:	Well Report Database	Fid:	14056
Rec id:	14052	Edr site i:	48254
Owner:	TCEQ	Ownerwell:	K7-IN01
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	8.25 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 5 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 5 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 2 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data

Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014057

G61
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014060**

Database:	Well Report Database	Fid:	14059
Rec id:	14055	Edr site i:	48251
Owner:	TCEQ	Ownerwell:	Test 2
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	8.25 in From Surface To 14.5 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 14.5 ft to 7.5 ft with 3 Sand (#sacks and material)		
Sinterval:	From 7.5 ft to 2 ft with 3 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 2 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014060

G62
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014059**

Database:	Well Report Database	Fid:	14058
Rec id:	14054	Edr site i:	48252
Owner:	TCEQ	Ownerwell:	G16-IN01
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie

Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	8.25 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 3 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 3 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 2 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014059

G63
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014056**

Database:	Well Report Database	Fid:	14055
Rec id:	14051	Edr site i:	48255
Owner:	TCEQ	Ownerwell:	K7-IN02
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	8.25 in From Surface To 17 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 17 ft to 10 ft with 5 Sand (#sacks and material)		
Sinterval:	From 10 ft to 2 ft with 5 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 2 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014056

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G64
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014053**

Database:	Well Report Database	Fid:	14052
Rec id:	14048	Edr site i:	48258
Owner:	TCEQ	Ownerwell:	G16-OB02
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 1 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014053

G65
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014052**

Database:	Well Report Database	Fid:	14051
Rec id:	14047	Edr site i:	48259
Owner:	TCEQ	Ownerwell:	G16-OB03
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 1 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data

Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014052

G66
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014055**

Database:	Well Report Database	Fid:	14054
Rec id:	14050	Edr site i:	48256
Owner:	TCEQ	Ownerwell:	Test 1
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie
Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 14.5 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 14.5 ft to 7.5 ft with 1 Sand (#sacks and material)		
Sinterval:	From 7.5 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014055

G67
WNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000014054**

Database:	Well Report Database	Fid:	14053
Rec id:	14049	Edr site i:	48257
Owner:	TCEQ	Ownerwell:	G16-OB01
Address:	Austin , TX	Grid:	16-40-5
Waddress:	Dead End of Lubbock Street, Texarkana , TX		
Lat:	33 25 29 N	County:	Bowie

Long:	094 02 52 W	Elevation:	No Data
Gpsused:	Magelan	Typeofwork:	New Well
Propuse:	Monitor	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	2.125 in From Surface To 12 ft
Dmethod:	Hollow Stem Auger	Bcompletio:	Not Reported
Packedfrom:	Not Reported	Packsize:	Not Reported
Finterval:	From 12 ft to 5 ft with 1 Sand (#sacks and material)		
Sinterval:	From 5 ft to 2 ft with 1 Bentonite (#sacks and material)		
Tinterval:	From 2 ft to 0 ft with 1 Cement Slurry (#sacks and material)		
Usedmethod:	Mix	Cementedby:	SCI
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data	Packers:	No Data
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	SCI
Companyadd:	5524 Midway Road, Suite 3	Ccitystate:	Ft. Worth , TX 76117
Licensenum:	54834	Wsignature:	Michael Bridges
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000014054

E68
NNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000070719**

Dateentere:	06-DEC-05	Ownname:	Mr. Robert Griffen
Ownstreet:	404 West 7th Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	Not Reported
County:	Bowie	Wellstreet:	404 West 7th Street
Wellcity:	Texarkana	Wellzip:	Not Reported
Own:	SB-3	Lat dec:	33.426388
Long dec:	-94.04611	Elev:	0
Brandmodel:	Garmin Etrex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	0	Ue:	1
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	06-DEC-05	Datecomp:	06-DEC-05
Dia1:	2.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	1	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	1
Dmother:	Geoprobe 6620	Bco:	0
Bcs:	0	Bcg:	0

Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	Not Reported	Cemto1:	Not Reported
Nosacks1:	Not Reported	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Not Reported
Cementby:	Not Reported	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	1	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Precision Probe and Drilling	Drllicno:	54661
Compstreet:	6133 verona lane	Compcity:	Shreveport
Compstate:	LA	Compzip:	71105
Drillernam:	Rodney Swann	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000070719	Latitude:	33.426388
Longitude:	-94.04611		

E69
NNW
1/4 - 1/2 Mile
Lower

TX WELLS **TXDOL2000013939**

Database:	Well Report Database	Fid:	13938
Rec id:	13928	Edr site i:	71869
Owner:	Mr. Robert Griffen	Ownerwell:	SB-3
Address:	404 West 7th Street, Texarkana , TX	Grid:	16-40-5
Waddress:	404 West 7th Street, Texarkana , TX	Lat:	33 25 35 N
County:	Bowie	Long:	094 02 46 W
Elevation:	No Data	Gpsused:	Garmin Etrex
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	Not Reported	Completedd:	Not Reported
Diameter:	2.25 in From Surface To 15 ft	Dmethod:	Driven
Bcompletio:	No Data	Packedfrom:	Not Reported
Packsize:	Not Reported	Finterval:	No Data
Sinterval:	No Data	Tinterval:	No Data
Usedmethod:	Not Reported	Cementedby:	Not Reported
Contaminat:	Not Reported	Propertyli:	Not Reported
Verrimetho:	Not Reported	Varriance:	Not Reported
Surface:	No Data	Staticleve:	No Data
Flow:	No Data	Packers:	none

Cementinwe:	Not Reported	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported	Watertype:	No Data
Stratadept:	No Data	Chemicalma:	No Data
Undesirabl:	No	Companynam:	Precision Probe and Drilling
Companyadd:	6133 verona lane	Ccitystate:	Shreveport , LA 71105
Licensenum:	54661	Wsignature:	Rodney Swann
Dsignature:	No Data	Regnum:	No Data
Comments:	No Data	Site id:	TXDOL2000013939

H70
South
1/4 - 1/2 Mile
Lower

TX WELLS **TXMON3000212018**

Dateentere:	04-MAY-10	Ownname:	Union Pacific Railroad
Ownstreet:	100 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
Own:	MW-4	Lat dec:	33.418054
Long dec:	-94.043888	Elev:	0
Brandmodel:	Magellan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-APR-10	Datecomp:	28-APR-10
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	2 Cement	Cemfrom2:	2
Cemto2:	5	Nosacks2:	3 Bentonite
Cemfrom3:	5	Cemto3:	20
Nosacks3:	9 Sand	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported

Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	56033
Compstreet:	5066 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	William Fields	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000212018	Latitude:	33.418054
Longitude:	-94.043888		

H71
SSW **TX WELLS** **TXMON3000212017**
1/4 - 1/2 Mile
Lower

Dateentere:	04-MAY-10	Ownname:	Union Pacific Railroad
Ownstreet:	100 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
Own:	MW-5	Lat dec:	33.417499
Long dec:	-94.044999	Elev:	0
Brandmodel:	Magellan	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-APR-10	Datecomp:	28-APR-10
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0

Bcoc:	1	Bcot:	20/40 sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	1
Nosacks1:	1 Cement	Cemfrom2:	1
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	15
Nosacks3:	8 Sand	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	56033
Compstreet:	5066 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	William Fields	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000212017	Latitude:	33.417499
Longitude:	-94.044999		

I72
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000211912**

Dateentere:	04-MAY-10	Ownname:	Union Pacific Railroad
Ownstreet:	100 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
Own:	MW-2	Lat dec:	33.416388
Long dec:	-94.047499	Elev:	0
Brandmodel:	Magellan	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0

Datestart:	28-APR-10	Datecomp:	28-APR-10
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	1
Nosacks1:	1 Cement	Cemfrom2:	1
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	15
Nosacks3:	8 Sand	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	56033
Compstreet:	5066 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	William Fields	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000211912	Latitude:	33.416388
Longitude:	-94.047499		

J73
SW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000074595**

Plugtrackn:	75807	Dateentere:	29-AUG-11
Ownname:	Union Pacific RR	Ownstreet:	101 Front St.
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332459

Lat dec:	33.416388	Longitude:	940256
Long dec:	-94.048888	Brmod:	Google Earth
Gn:	16408	Gn1:	16
Gn75:	40	Gn25:	8
Ownwellno:	MW# 8	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	15	Plugdate:	17-AUG-11
Plugmethco:	No Data	Plugopname:	Joseph Ray
Plugoplic:	58794	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	1
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	0
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	15	Cbto1:	2
Cbsacks1:	1 Hole Plug	Cbfrom2:	2
Cbto2:	0	Cbsacks2:	1 Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Strata Core Services
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Nameassig:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000074595		

J74
SW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000074593**

Plugtrackn:	75805	Dateentere:	29-AUG-11
Ownname:	Union Pacific RR	Ownstreet:	101 Front St.
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332459
Lat dec:	33.416388	Longitude:	940256
Long dec:	-94.048888	Brmod:	Google Earth
Gn:	16408	Gn1:	16
Gn75:	40	Gn25:	8
Ownwellno:	MW# 7	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	25	Plugdate:	17-AUG-11
Plugmethco:	No Data	Plugopname:	Joseph Ray
Plugoplic:	58794	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	1
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	0
Cdiam2:	Not Reported	Cfrom2:	Not Reported

Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	25	Cbto1:	2
Cbsacks1:	1 Hole Plug	Cbfrom2:	2
Cbto2:	0	Cbsacks2:	1 Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Strata Core Services
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Nameassig:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000074593		

J75
SW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000074597**

Plugtrackn:	75809	Dateentere:	29-AUG-11
Ownname:	Union Pacific RR	Ownstreet:	101 Front St.
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332459
Lat dec:	33.416388	Longitude:	940256
Long dec:	-94.048888	Brmod:	Google Earth
Gn:	16408	Gn1:	16
Gn75:	40	Gn25:	8
Ownwellno:	1R, PZ-8, PZ-9, MW# 10	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	20	Plugdate:	17-AUG-11
Plugmethco:	No Data Amended 9/7/11 Ref.# 9454	Plugopname:	Joseph Ray
Plugoplic:	58794	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	1
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	0
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	20	Cbto1:	2
Cbsacks1:	1 Hole Plug	Cbfrom2:	2
Cbto2:	0	Cbsacks2:	1 Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Strata Core Services
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Nameassig:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000074597		

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
TX WELLS	**TXMON3000212020**

J76
SW
1/2 - 1 Mile
Lower

Dateentere:	04-MAY-10	Ownname:	Union Pacific Railroad
Ownstreet:	100 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
Own:	MW-6	Lat dec:	33.416388
Long dec:	-94.048888	Elev:	0
Brandmodel:	Magellan	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	29-APR-10	Datecomp:	29-APR-10
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	2 Cement	Cemfrom2:	2
Cemto2:	4	Nosacks2:	2 Bentonite
Cemfrom3:	4	Cemto3:	15
Nosacks3:	8 Sand	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	56033
Compstreet:	5066 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	William Fields	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000212020	Latitude:	33.416388
Longitude:	-94.048888		

I77
SSW **TX WELLS** **TXMON3000212015**
1/2 - 1 Mile
Lower

Dateentere:	04-MAY-10	Ownname:	Union Pacific Railroad
Ownstreet:	100 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
Own:	MW-1	Lat dec:	33.416111
Long dec:	-94.04861	Elev:	0
Brandmodel:	Magellan	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-APR-10	Datecomp:	28-APR-10
Dia1:	8.25	Dia1to:	17.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	1 Cement	Cemfrom2:	2
Cemto2:	4	Nosacks2:	2 Bentonite
Cemfrom3:	4	Cemto3:	17.5
Nosacks3:	8 Sand	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1

Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	56033
Compstreet:	5066 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	William Fields	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000212015	Latitude:	33.416111
Longitude:	-94.04861		

J78
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000250960**

Dateentere:	23-MAY-11	Ownname:	Union Pacific Railroad
Ownstreet:	101 W. Broad St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75503
County:	Bowie	Wellstreet:	101 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 9,10	Lat dec:	33.416111
Long dec:	-94.048888	Elev:	286
Brandmodel:	Google Earth	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-MAY-11	Datecomp:	17-MAY-11
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0

Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	20	Cemto1:	5
Nosacks1:	10 Sand	Cemfrom2:	5
Cemto2:	2	Nosacks2:	1 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	52694
Compstreet:	5070 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000250960	Latitude:	33.416111
Longitude:	-94.048888		

J79
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000250820**

Dateentere:	23-MAY-11	Ownname:	Union Pacific Railroad
Ownstreet:	101 W. Broad St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75503
County:	Bowie	Wellstreet:	101 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 8	Lat dec:	33.416111
Long dec:	-94.048888	Elev:	286
Brandmodel:	Google Earth	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0

Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-MAY-11	Datecomp:	17-MAY-11
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	15	Cemto1:	3
Nosacks1:	8 Sand	Cemfrom2:	3
Cemto2:	1	Nosacks2:	1 Bentonite
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	52694
Compstreet:	5070 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000250820	Latitude:	33.416111
Longitude:	-94.048888		

J80
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000250817**

Dateentere:	23-MAY-11	Ownname:	Union Pacific Railroad
Ownstreet:	101 W. Broad St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75503

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

County:	Bowie	Wellstreet:	101 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 7	Lat dec:	33.416111
Long dec:	-94.048888	Elev:	286
Brandmodel:	Google Earth	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-MAY-11	Datecomp:	17-MAY-11
Dia1:	8.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	25	Cemto1:	8
Nosacks1:	12 Sand	Cemfrom2:	8
Cemto2:	2	Nosacks2:	3 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	52694
Compstreet:	5070 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported

Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000250817	Latitude:	33.416111
Longitude:	-94.048888		

J81
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000250962**

Dateentere:	23-MAY-11	Ownname:	Union Pacific Railroad
Ownstreet:	101 W. Broad St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75503
County:	Bowie	Wellstreet:	101 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	PZ# 8,9	Lat dec:	33.416111
Long dec:	-94.048888	Elev:	286
Brandmodel:	Google Earth	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-MAY-11	Datecomp:	17-MAY-11
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	20	Cemto1:	3
Nosacks1:	12 Sand	Cemfrom2:	3
Cemto2:	1	Nosacks2:	1 Bentonite
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported

Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	52694
Compstreet:	5070 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000250962	Latitude:	33.416111
Longitude:	-94.048888		

J82
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000250961**

Dateentere:	23-MAY-11	Ownname:	Union Pacific Railroad
Ownstreet:	101 W. Broad St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75503
County:	Bowie	Wellstreet:	101 W. Broad St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 1A	Lat dec:	33.416111
Long dec:	-94.048888	Elev:	286
Brandmodel:	Google Earth	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	17-MAY-11	Datecomp:	17-MAY-11
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	20	Cemto1:	8
Nosacks1:	8 Sand	Cemfrom2:	8
Cemto2:	2	Nosacks2:	3 Bentonite
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards

Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	52694
Compstreet:	5070 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000250961	Latitude:	33.416111
Longitude:	-94.048888		

I83
SSW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000212019**

Dateentere:	04-MAY-10	Ownname:	Union Pacific Railroad
Ownstreet:	100 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
Own:	MW-3	Lat dec:	33.415555
Long dec:	-94.048333	Elev:	0
Brandmodel:	Magellan	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	28-APR-10	Datecomp:	28-APR-10
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0

Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	20/40 sand
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	0	Cemto1:	2
Nosacks1:	2 Cement	Cemfrom2:	2
Cemto2:	4	Nosacks2:	2 Bentonite
Cemfrom3:	4	Cemto3:	15
Nosacks3:	8 Sand	Cementmeth:	Mix
Cementby:	SCI	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	SCI	Drllicno:	56033
Compstreet:	5066 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	William Fields	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000212019	Latitude:	33.415555
Longitude:	-94.048333		

K84
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011116**

Plugtrackn:	11298	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	T-3	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported

Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	20	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	20
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011116		

K85
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011117**

Plugtrackn:	11299	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported

Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011117		

K86
WNW **TX WELLS** **TXPLU3000011115**
1/2 - 1 Mile
Lower

Plugtrackn:	11297	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	T-2	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	20	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	20
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011115		

K87
WNW **TX WELLS** **TXPLU3000011129**
1/2 - 1 Mile
Lower

Plugtrackn:	11311	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar

Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-13	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	6
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011129		

K88
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011114**

Plugtrackn:	11296	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	T-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	20	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0

Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	20
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011114		

K89
WNW **TX WELLS** **TXPLU3000011125**
1/2 - 1 Mile
Lower

Plugtrackn:	11307	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-9	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	6
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported

Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011125		

K90
WNW **TX WELLS** **TXPLU3000011124**
1/2 - 1 Mile
Lower

Plugtrackn:	11306	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-8	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	6
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011124		

K91
WNW **TX WELLS** **TXPLU3000011126**
1/2 - 1 Mile
Lower

Plugtrackn:	11308	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported

Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-10	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	6
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011126		

K92
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011128**

Plugtrackn:	11310	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-12	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	6
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported

Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011128		

K93
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011127**

Plugtrackn:	11309	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-11	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	6
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011127		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K94
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011123**

Plugtrackn:	11305	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-7	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011123		

K95
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011119**

Plugtrackn:	11301	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5

Ownwellno:	R-3	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011119		

K96
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011118**

Plugtrackn:	11300	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-2	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported

Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011118		

K97
WNW **TX WELLS** **TXPLU3000011120**
1/2 - 1 Mile
Lower

Plugtrackn:	11302	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-4	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011120		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K98
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011122**

Plugtrackn:	11304	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	R-6	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011122		

K99
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000011121**

Plugtrackn:	11303	Dateentere:	05-APR-03
Ownname:	Engineering Associates	Ownstreet:	704 S. Lamar
Owncity:	Austin	Ownstate:	TX
Ownzip:	78704	Wellstreet:	317 Main
Wellcity:	Texarkana	Wellzip:	Not Reported
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940275
Long dec:	-94.054166	Brmod:	Not Reported
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5

Ownwellno:	R-5	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	4
Histdepth:	25	Plugdate:	01-APR-03
Plugmethco:	Not Reported	Plugopname:	Todd Wages
Plugoplic:	4978	Plugmeth1:	0
Plugmeth2:	1	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	0	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	Not Reported
Cbto2:	Not Reported	Cbsacks2:	Not Reported
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Todd Wages
Compstreet:	P.O. Box 6655	Compcity:	Tyler
Compstate:	TX	Compzip:	75711
Nameassig:	Todd Wages	Traineenam:	Not Reported
Tnum:	Not Reported	Deleted:	0
Site id:	TXPLU3000011121		

L100
NNW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000260507**

Dateentere:	29-AUG-11	Ownname:	Union Pacific RR
Ownstreet:	101 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 8R	Lat dec:	33.433054
Long dec:	-94.048333	Elev:	312
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	16-AUG-11	Datecomp:	16-AUG-11
Dia1:	8.25	Dia1to:	15.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0

Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	15.5	Cemto1:	2
Nosacks1:	9 Sand	Cemfrom2:	2
Cemto2:	1	Nosacks2:	1 Hole Plug
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core Services	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	58794
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000260507	Latitude:	33.433054
Longitude:	-94.048333		

L101
NNW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000260506**

Dateentere:	29-AUG-11	Ownname:	Union Pacific RR
Ownstreet:	101 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 7R	Lat dec:	33.433054
Long dec:	-94.048333	Elev:	312
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0

Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	16-AUG-11	Datecomp:	16-AUG-11
Dia1:	8.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	20	Cemto1:	5.5
Nosacks1:	10 Sand	Cemfrom2:	5.5
Cemto2:	2	Nosacks2:	2 Hole Plug
Cemfrom3:	2	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core Services	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	58794
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Amended 9/7/11 Ref.# 9450
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000260506	Latitude:	33.433054
Longitude:	-94.048333		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database | EDR ID Number

L102
NNW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000260509**

Dateentere:	29-AUG-11	Ownname:	Union Pacific RR
Ownstreet:	101 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 1R, MW# 10	Lat dec:	33.433054
Long dec:	-94.048333	Elev:	312
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	16-AUG-11	Datecomp:	16-AUG-11
Dia1:	8.25	Dia1to:	16.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	16.5	Cemto1:	2
Nosacks1:	9 Sand	Cemfrom2:	2
Cemto2:	1	Nosacks2:	1 Hole Plug
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core Services	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	58794
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Amended 9/7/11 Ref.# 9451
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000260509	Latitude:	33.433054
Longitude:	-94.048333		

L103
NNW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000260512**

Dateentere:	29-AUG-11	Ownname:	Union Pacific RR
Ownstreet:	101 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 14, 15	Lat dec:	33.433054
Long dec:	-94.048333	Elev:	312
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	16-AUG-11	Datecomp:	16-AUG-11
Dia1:	8.25	Dia1to:	16.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	16.5	Cemto1:	2
Nosacks1:	6 Sand	Cemfrom2:	2
Cemto2:	1	Nosacks2:	1 Hole Plug
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core Services	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0

Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	58794
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Amended 9/7/11 Ref.# 9453
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000260512	Latitude:	33.433054
Longitude:	-94.048333		

L104
NNW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000260511**

Dateentere:	29-AUG-11	Ownname:	Union Pacific RR
Ownstreet:	101 Front St.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	101 Front St.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW#11, 12, 13	Lat dec:	33.433054
Long dec:	-94.048333	Elev:	312
Brandmodel:	Google Earth	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	16-AUG-11	Datecomp:	16-AUG-11
Dia1:	8.25	Dia1to:	16.5
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0

Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	16.5	Cemto1:	2
Nosacks1:	6 Sand	Cemfrom2:	2
Cemto2:	1	Nosacks2:	1 Hole Plug
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core Services	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Services	Drllicno:	58794
Compstreet:	5070 Brush Creek Rd	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Joseph Ray	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Amended 9/7/11 Ref.# 9452
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000260511	Latitude:	33.433054
Longitude:	-94.048333		

M105
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070040**

Plugtrackn:	71188	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332537
Lat dec:	33.426943	Longitude:	940321
Long dec:	-94.055833	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-7	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11

Plugmethco:	Amended 5-2-11 Ref# 9048 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	15
Cbsacks1:	4-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1-Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070040		

M106
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070042**

Plugtrackn:	71190	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332537
Lat dec:	33.426943	Longitude:	940321
Long dec:	-94.055833	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	RW-2	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9050 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	5	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	25
Cbsacks1:	1-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1 cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.

Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070042		

M107
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070043**

Plugtrackn:	71191	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940321
Long dec:	-94.055833	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	RW-3	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9051 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	5	Cto1:	20
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	20
Cbsacks1:	2-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1-Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070043		

M108
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070038**

Plugtrackn:	71186	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501

County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940321
Long dec:	-94.055833	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-5	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9046 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	25
Cbsacks1:	1-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1-Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070038		

N109
West
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000237977**

Dateentere:	13-JAN-11	Ownname:	Capital One Bank, NA
Ownstreet:	3840 Highway 22, Suite 203	Owncity:	Mandeville
Ownstate:	LA	Ownzip:	70471
County:	Bowie	Wellstreet:	1401 West 7th Street.
Wellcity:	Texarkana	Wellzip:	75501
Own:	PH-3	Lat dec:	33.423054
Long dec:	-94.056944	Elev:	0
Brandmodel:	Garmin e-trex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	06-JAN-11	Datecomp:	06-JAN-11
Dia1:	2.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported

Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	1	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	1
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	Not Reported	Cemto1:	Not Reported
Nosacks1:	Not Reported	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Not Reported
Cementby:	Not Reported	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	1	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	1	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	ETTL Engineers & Consultants Inc.	Drllicno:	58271
Compstreet:	1717 E. Erwin	Compcity:	Tyler
Compstate:	TX	Compzip:	75702
Drillernam:	Jeanie M. Odom	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000237977	Latitude:	33.423054
Longitude:	-94.056944		

M110
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070044**

Plugtrackn:	71192	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332537
Lat dec:	33.426943	Longitude:	940322
Long dec:	-94.056111	Brmod:	Garmin
Gn:	16405	Gn1:	16

Gn75:	40	Gn25:	5
Ownwellno:	RW-4	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9052 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	25
Cbsacks1:	2-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1 cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070044		

M111
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070036**

Plugtrackn:	71184	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940322
Long dec:	-94.056111	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-3	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9044 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	9

Cbsacks1:	1-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1-Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070036		

M112
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070035**

Plugtrackn:	71183	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940322
Long dec:	-94.056111	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-2	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9043 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	3	Cto1:	8
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	8
Cbsacks1:	2-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1-Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070035		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
TX WELLS	**TXMON3000237972**

N113
West
1/2 - 1 Mile
Lower

Dateentere:	13-JAN-11	Ownname:	Capital One Bank, NA
Ownstreet:	3840 Highway 22, Suite 203	Owncity:	Mandeville
Ownstate:	LA	Ownzip:	70471
County:	Bowie	Wellstreet:	1401 West 7th Street.
Wellcity:	Texarkana	Wellzip:	75501
Own:	PH-2	Lat dec:	33.423054
Long dec:	-94.057222	Elev:	0
Brandmodel:	Garmin e-trex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	06-JAN-11	Datecomp:	06-JAN-11
Dia1:	2.25	Dia1to:	20
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	1	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	1
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	Not Reported	Cemto1:	Not Reported
Nosacks1:	Not Reported	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Not Reported
Cementby:	Not Reported	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	1	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	1

Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	ETTL Engineers & Consultants Inc.	Drllicno:	58271
Compstreet:	1717 E. Erwin	Compcity:	Tyler
Compstate:	TX	Compzip:	75702
Drillernam:	Jeanie M. Odom	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000237972	Latitude:	33.423054
Longitude:	-94.057222		

M114
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070037**

Plugtrackn:	71185	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332539
Lat dec:	33.427499	Longitude:	940322
Long dec:	-94.056111	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-4	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9045 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	23
Cbsacks1:	1-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1- Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070037		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M115
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070041**

Plugtrackn:	71189	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332539
Lat dec:	33.427499	Longitude:	940322
Long dec:	-94.056111	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	RW-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9049 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	5	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	25
Cbsacks1:	2-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1 cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070041		

M116
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070045**

Plugtrackn:	71193	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940323
Long dec:	-94.056388	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5

Ownwellno:	RW-5	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9053 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	2	Cto1:	25
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	25
Cbsacks1:	3-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1 cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070045		

M117
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070034**

Plugtrackn:	71182	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940323
Long dec:	-94.056388	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-1	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9042 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	2
Cfrom1:	8	Cto1:	13
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	13
Cbsacks1:	5-Bentonite	Cbfrom2:	0

Cbto2:	2	Cbsacks2:	1-Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070034		

M118
WNW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000070039**

Plugtrackn:	71187	Dateentere:	15-APR-11
Ownname:	Humco Holding Group, Inc.	Ownstreet:	7400 Alumax Drive
Owncity:	Texarkana	Ownstate:	TX
Ownzip:	75501	Wellstreet:	1008 Whitaker Street
Wellcity:	Texarkana	Wellzip:	75501
County:	Bowie	Latitude:	332538
Lat dec:	33.427221	Longitude:	940325
Long dec:	-94.056944	Brmod:	Garmin
Gn:	16405	Gn1:	16
Gn75:	40	Gn25:	5
Ownwellno:	MW-6	Typewater:	0
Typemon:	1	Typeinj:	0
Typedw:	0	Histdrille:	Not Reported
Histdrllic:	Not Reported	Histdatedr:	Not Reported
Histtracki:	Not Reported	Histdiamin:	Not Reported
Histdepth:	Not Reported	Plugdate:	05-APR-11
Plugmethco:	Amended 5-2-11 Ref# 9047 ~DG	Plugopname:	James Byrd
Plugoplic:	50089	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	0
Plugmeth4:	0	Plugmethot:	1
Plugvar:	Not Reported	Cdiam1:	Not Reported
Cfrom1:	Not Reported	Cto1:	Not Reported
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	2	Cbto1:	25
Cbsacks1:	1-Bentonite	Cbfrom2:	0
Cbto2:	2	Cbsacks2:	1 Cement
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	Apex Geoscience Inc.
Compstreet:	2120 Brandon Drive	Compcity:	Tyler
Compstate:	TX	Compzip:	75703
Nameassig:	Buford E. Collier	Traineenam:	James D. Byrd Jr.
Tnum:	58540	Deleted:	0
Site id:	TXPLU3000070039		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O119
SW
1/2 - 1 Mile
Lower

TX WELLS **TXPLU3000015165**

Plugtrackn:	15422	Dateentere:	26-FEB-04
Ownname:	CARANSTAR	Ownstreet:	112 SILELIA
Owncity:	TEXARKANA	Ownstate:	TX
Ownzip:	75501	Wellstreet:	SAME
Wellcity:	Not Reported	Wellzip:	Not Reported
County:	Bowie	Latitude:	332456
Lat dec:	33.415555	Longitude:	940319
Long dec:	-94.055277	Brmod:	GPS
Gn:	16408	Gn1:	16
Gn75:	40	Gn25:	8
Ownwellno:	1	Typewater:	1
Typemon:	0	Typeinj:	0
Typedw:	0	Histdrille:	JASON MARCHAND
Histdrllic:	54399	Histdatedr:	01-OCT-03
Histtracki:	Not Reported	Histdiamin:	7.875
Histdepth:	90	Plugdate:	02-JAN-04
Plugmethco:	DG	Plugopname:	JOHN ENGLE
Plugoplic:	50137	Plugmeth1:	0
Plugmeth2:	0	Plugmeth3:	1
Plugmeth4:	0	Plugmethot:	0
Plugvar:	Not Reported	Cdiam1:	4
Cfrom1:	2	Cto1:	90
Cdiam2:	Not Reported	Cfrom2:	Not Reported
Cto2:	Not Reported	Cdiam3:	Not Reported
Cfrom3:	Not Reported	Cto3:	Not Reported
Cbfrom1:	0	Cbto1:	2
Cbsacks1:	1	Cbfrom2:	2
Cbto2:	90	Cbsacks2:	5 BEN
Cbfrom3:	Not Reported	Cbto3:	Not Reported
Cbsacks3:	Not Reported	Cbfrom4:	Not Reported
Cbto4:	Not Reported	Cbsacks4:	Not Reported
Cbfrom5:	Not Reported	Cbto5:	Not Reported
Cbsacks5:	Not Reported	Compname:	W.E. PENDER & SONS, INC.
Compstreet:	8200 STATELINE HWY	Compcity:	TEXARKANA
Compstate:	TX	Compzip:	75503
Nameassig:	SID MCILVEEN	Traineenam:	JOHN ENGLE
Tnum:	1813	Deleted:	0
Site id:	TXPLU3000015165		

O120
SW
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000099477**

Dateentere:	27-DEC-06	Ownname:	Caran Star
Ownstreet:	112 S. Lelia Street	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	112 S. Lelia Street
Wellcity:	Texarkana	Wellzip:	75501
Own:	Not Reported	Lat dec:	33.415555
Long dec:	-94.055555	Elev:	0
Brandmodel:	Not Reported	Gn:	16408
Gn1:	16	Gn75:	40
Gn25:	8	Twn:	1

Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	0	Ue:	0
Ud:	0	Uin:	1
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	30-SEP-03	Datecomp:	01-OCT-03
Dia1:	7.875	Dia1to:	94
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	1	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	1
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	20	Gpt:	90
Cemfrom1:	0	Cemto1:	20
Nosacks1:	6	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Tremmie
Cementby:	Pender Water Wells	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	1	Scp:	0
Sca:	0	Watlev:	14
Watlevdate:	01-OCT-03	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	1	Wtestimate:	0
Welltestyi:	30	Welltestdr:	53
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Pender Water Wells	Drllicno:	54399
Compstreet:	8201 North Stateline	Compcity:	Texarana
Compstate:	TX	Compzip:	75503
Drillernam:	Jason Marchand	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	$dfs
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000099477	Latitude:	33.415555
Longitude:	-94.055555		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O121
SW
1/2 - 1 Mile
Lower

TX WELLS **TXDOL2000013860**

Database:	Well Report Database	Fid:	13859
Rec id:	13854	Edr site i:	100925
Owner:	Caran Star	Ownerwell:	No Data
Address:	112 S. Lelia Street, Texarkana , TX 75501		
Grid:	16-40-8	Waddress:	112 S. Lelia Street, Texarkana , TX 75501
Lat:	33 24 56 N	County:	Bowie
Long:	094 03 20 W	Elevation:	No Data
Gpsused:	No Data	Typeofwork:	New Well
Propuse:	Industrial	Sdate:	Not Reported
Completedd:	Not Reported	Diameter:	7 7/8 in From Surface To 94 ft
Dmethod:	Mud Rotary	Bcompletio:	Not Reported
Packedfrom:	20 ft to 90 ft	Packsize:	Not Reported
Finterval:	From 0 ft to 20 ft with 6 (#sacks and material)		
Sinterval:	No Data	Tinterval:	No Data
Usedmethod:	Tremmie	Cementedby:	Pender Water Wells
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Varriance:	No Data
Surface:	Surface Sleeve Installed	Staticleve:	14 ft. below land surface on 10/1/2003
Flow:	No Data	Packers:	None
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	Jetted
Yield:	30 GPM with 53 ft drawdown after (No Data) hours		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No Data	Undesirabl:	No
Companynam:	Pender Water Wells	Companyadd:	8201 North Stateline
Ccitystate:	Texarana , TX 75503	Licensenum:	54399
Wsignature:	Jason Marchand	Dsignature:	No Data
Regnum:	No Data	Comments:	$dfs
Site id:	TXDOL2000013860		

122
West
1/2 - 1 Mile
Lower

TX WELLS **TXMON3000237967**

Dateentere:	13-JAN-11	Ownname:	Capital One Bank, NA
Ownstreet:	3840 Highway 22, suite 203	Owncity:	Mandeville
Ownstate:	LA	Ownzip:	70471
County:	Bowie	Wellstreet:	1401 West 7th Street.
Wellcity:	Texarkana	Wellzip:	75501
Own:	PH-1	Lat dec:	33.422777
Long dec:	-94.059166	Elev:	0
Brandmodel:	Garmin e-trex	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	0	Ue:	1
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0

Pby:	0	Pbn:	0
Datestart:	06-JAN-11	Datecomp:	06-JAN-11
Dia1:	2.25	Dia1to:	25
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	1	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	0
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	0	Bcot:	Not Reported
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	Not Reported	Cemto1:	Not Reported
Nosacks1:	Not Reported	Cemfrom2:	Not Reported
Cemto2:	Not Reported	Nosacks2:	Not Reported
Cemfrom3:	Not Reported	Cemto3:	Not Reported
Nosacks3:	Not Reported	Cementmeth:	Not Reported
Cementby:	Not Reported	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	0
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	1	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	0	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	ETTL Engineers & Consultants Inc.	Drllicno:	58271
Compstreet:	1717 E. Erwin	Compcity:	Tyler
Compstate:	TX	Compzip:	75702
Drillernam:	Jeanie M. Odom	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000237967	Latitude:	33.422777
Longitude:	-94.059166		

123
NE
1/2 - 1 Mile
Lower

FED USGS **USGS40000114305**

Organization ID:	USGS-AR	Organization Name:	USGS Arkansas Water Science Center
Monitor Location:	15S28W19DDD1	Type:	Well
Description:	Not Reported	HUC:	11140302
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported

Aquifer:	Alluvial aquifers	Formation Type:	Quaternary Alluvium
Aquifer Type:	Not Reported	Construction Date:	18991231
Well Depth:	50	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1951-07-25
Feet below surface:	25.95	Feet to sea level:	Not Reported
Note:	Not Reported		

P124
NNW
1/2 - 1 Mile
Higher

TX WELLS **TXMON3000187965**

Dateentere:	20-AUG-09	Ownname:	E-Z Mart Stores
Ownstreet:	2116 Texas Blvd.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	2116 Texas Blvd.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 1,2,3,4	Lat dec:	33.435555
Long dec:	-94.051944	Elev:	0
Brandmodel:	Garmin	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	18-AUG-09	Datecomp:	18-AUG-09
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed
Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	15	Cemto1:	2
Nosacks1:	9 Sacks Sand	Cemfrom2:	2
Cemto2:	1	Nosacks2:	1 Bentonite
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0

Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Drilling Co.	Drllicno:	3121
Compstreet:	5066 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Roddy Qualls	Traineenam:	Joseph Ray
Tnum:	58017	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000187965	Latitude:	33.435555
Longitude:	-94.051944		

P125
NNW
1/2 - 1 Mile
Higher

TX WELLS **TXMON3000216338**

Dateentere:	10-JUN-10	Ownname:	EZ Mart #64
Ownstreet:	2116 Texas Blvd.	Owncity:	Texarkana
Ownstate:	TX	Ownzip:	75501
County:	Bowie	Wellstreet:	2116 Texas Blvd.
Wellcity:	Texarkana	Wellzip:	75501
Own:	MW# 5,6,7	Lat dec:	33.435555
Long dec:	-94.051944	Elev:	0
Brandmodel:	Garmin	Gn:	16405
Gn1:	16	Gn75:	40
Gn25:	5	Twn:	1
Twd:	0	Twr:	0
Twrp:	0	Twrg:	0
Um:	1	Ue:	0
Ud:	0	Uin:	0
Uir:	0	Ug:	0
Uij:	0	Up:	0
Udw:	0	Ut:	0
Us:	0	Uf:	0
Pby:	0	Pbn:	0
Datestart:	08-JUN-10	Datecomp:	08-JUN-10
Dia1:	8.25	Dia1to:	15
Dia2:	Not Reported	Dia2from:	Not Reported
Dia2to:	Not Reported	Dia3:	Not Reported
Dia3from:	Not Reported	Dia3to:	Not Reported
Dmdriven:	0	Dmairrotar:	0
Dmmudrotar:	0	Dmbored:	0
Dmairham:	0	Dmcabletoo:	0
Dmjetted:	0	Dmhollowst:	1
Dmrevcirc:	0	Dmotherck:	0
Dmother:	Not Reported	Bco:	0
Bcs:	0	Bcg:	0
Bcgs:	Not Reported	Bcu:	0
Bcoc:	1	Bcot:	Sand Packed

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Gpf:	Not Reported	Gpt:	Not Reported
Cemfrom1:	15	Cemto1:	2
Nosacks1:	9 Sand	Cemfrom2:	2
Cemto2:	1	Nosacks2:	1 Bentonite
Cemfrom3:	1	Cemto3:	0
Nosacks3:	1 Cement	Cementmeth:	TCEQ Standards
Cementby:	Strata Core	Ds:	Not Reported
Dpl:	Not Reported	Dsv:	Not Reported
Appvar:	Not Reported	Scs:	1
Scsv:	0	Scp:	0
Sca:	0	Watlev:	Not Reported
Watlevdate:	Not Reported	Artflow:	Not Reported
Wellplug48:	0	Tpturbine:	0
Tpjet:	0	Tpsubmersi:	0
Tpcylinder:	0	Tpotherck:	0
Tpother:	Not Reported	Pumpbowlde:	Not Reported
Wtpump:	0	Wtbailer:	0
Wtjetted:	0	Wtestimate:	0
Welltestyi:	Not Reported	Welltestdr:	Not Reported
Welltesthr:	Not Reported	Watqualund:	0
Watqualu 1:	1	Watertype:	Not Reported
Stratdepth:	Not Reported	Chemanaly:	0
Chemanaln:	0	Undnatural:	0
Untype:	Not Reported	Undhydro:	0
Undhaz:	0	Undotherck:	0
Undother:	Not Reported	Undcertify:	0
Compname:	Strata Core Drilling Co.	Drllicno:	52694
Compstreet:	5066 Brush Creek Rd.	Compcity:	Fort Worth
Compstate:	TX	Compzip:	76119
Drillernam:	Gilbert Mario Robles	Traineenam:	Not Reported
Tnum:	Not Reported	Comments:	Not Reported
Confidenti:	0	Letterrecv:	Not Reported
Deleted:	0	Insdate:	Not Reported
Site id:	TXMON3000216338	Latitude:	33.435555
Longitude:	-94.051944		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
SW
1/2 - 1 Mile

OIL_GAS **TXOG60000111743**

Surface id:	790819.00000	Symnum:	3
Api:	037	Reliab:	15
Longn:	-94.05017	Latn:	33.41563
Site id:	TXOG60000111743		
Bottom id:	790819	Surface id:	790819
Symnum:	3	Apinum:	42037
Out fips:	N	Reliab:	15
Cwellnum:	Not Reported	Radioact:	Not Reported
Longn:	-94.0501748	Latn:	33.4156277

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: TX Radon

Radon Test Results

County	Mean	Total Sites	%>4 pCi/L	%>20 pCi/L	Min pCi/L	Max pCi/L
BOWIE	.5	24	.0	.0	<.5	1.8

Federal EPA Radon Zone for BOWIE County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 75501

Number of sites tested: 5

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.280 pCi/L	100%	0%	0%
Living Area - 2nd Floor	0.800 pCi/L	100%	0%	0%
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Texas General Land Office
Telephone: 512-463-0745

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Public Water Supply Sources Databases
Source: Texas Commission on Environmental Quality
Telephone: 512-239-6199
Locations of public drinking water sources maintained by the TCEQ

Groundwater Database
Source: Texas Water Development Board
Telephone: 512-936-0837

Well Report Database
Source: Department of Licensing and Regulation
Telephone: 512-936-0833

Water Well Database
Source: Harris-Galveston Coastal Subsidence District
Telephone: 281-486-1105

Submitted Driller's Reports Database
Source: Texas Water Development Board
Telephone: 512-936-0833
The Submitted Driller's Reports Database is populated from the online Texas Well Report Submission and Retrieval System which is a cooperative Texas Department of Licensing and Regulation (TDLR) and Texas Water Development Board (TWDB) application that registered water-well drillers use to submit their required reports.

Brackish Resources Aquifer Characterization System Database
Source: Texas Water Development Board
TWDB's Brackish Resources Aquifer Characterization System (BRACS) designed to map and characterize the brackish aquifers of Texas in greater detail than previous studies. The information is contained in the BRACS Database and project data are summarized in a project report with companion geographic information system data files.

OTHER STATE DATABASE INFORMATION

Texas Oil and Gas Wells:
Source: Texas Railroad Commission
Telephone: 512-463-6882
Oil and gas well locations

PHYSICAL SETTING SOURCE RECORDS SEARCHED

RADON

State Database: TX Radon
Source: Department of Health
Telephone: 512-834-6688
Rinal Report of the Texas Indoor Radon Survey

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.